

Unit Nb	Complete	Job Desc.
103054	08/15/2005	Replace transmission
103054	01/04/2006	LIGHT (01/04/2006 10:57:40, DINEFF,AE)
103054	01/04/2006	ABSORBER (01/04/2006 11:15:23, DINEFF,AE)
103054	01/12/2006	FRONT SHOCKS. (11/29/2005 08:23:15, GRAHAM,GR)
103054	01/12/2006	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	01/19/2006	BOLTS IN WIRE BUTTERFLY MISSING (01/19/2006 13:46:09, FAR
103054	01/19/2006	DAMAGE TO LR. (01/19/2006 17:10:41, GRAHAM,GR)
103054	01/20/2006	TRUCK STUCK (01/20/2006 08:08:02, FARROW,TM)
103054	01/26/2006	CALLOUT SERVICE CALL HYD HOSE LEAK (01/26/2006 15:22:00,
103054	01/26/2006	CK HYD HOSES FOR RUBBING ON FIBERGLASS COVER (01/26/2006
103054	01/27/2006	CHAINS ON REAR BIN BOX BROKEN (01/27/2006 13:17:51, FARRO
103054	01/27/2006	TRANS. WIRING HARNESS LAYING ON EXHAUST (01/27/2006 13:52
103054	01/31/2006	BOLTS MISSING IN JIB PIN HOLDER (01/31/2006 15:05:46, FAR
103054	02/07/2006	BUCKET REST. (02/07/2006 17:01:28, GRAHAM,GR)
103054	02/23/2006	B/U ALARM N/W. (02/22/2006 16:16:22, GRAHAM,GR)
103054	02/24/2006	JIB BLEEDS OFF. (07/08/2005 16:43:40, GRAHAM,GR)
103054	03/02/2006	OIL FILTER (03/02/2006 10:47:36, DINEFF,AE)
103054	03/15/2006	Dielectric Test Dielectric Test ATA Code 500-500-022
103054	03/20/2006	TRANS. FLUID LEAKING UNDER TRUCK (03/20/2006 10:06:09, F
103054	03/27/2006	ENGINE OIL LEAK. (03/27/2006 16:20:01, GRAHAM,GR)
103054	03/28/2006	WON'T START (03/28/2006 13:05:00, FARROW,TM)
103054	03/28/2006	BOLT MISSING IN FRONT SEAL RETAINER. (03/28/2006 23:52:06
103054	03/29/2006	REAR STEP. (03/29/2006 19:15:57, GRAHAM,GR)
103054	04/07/2006	START- STOP NOT WORKING (04/07/2006 15:21:25, FARROW,TM)
103054	04/11/2006	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	04/11/2006	Aerial Inspection
103054	04/11/2006	START/STOP AT BUCKET N/C. (04/10/2006 16:33:46, GRAHAM,G
103054	05/24/2006	WATER CASK HOLDER. (05/23/2006 21:12:26, GRAHAM,GR)
103054	05/26/2006	BUCKET COVER (05/04/2006 10:19:33, FARROW,TM)
103054	06/02/2006	BUCKET (06/02/2006 13:35:52, DINEFF,AE)
103054	06/06/2006	REAR DIFFERENTIAL NOISE (06/05/2006 15:10:16, FARROW,TM)
103054	06/14/2006	NOISY HYD PUMP (06/14/2006 23:52:48, GRAHAM,GR)
103054	06/15/2006	REAR DIFF BLOWN. (06/05/2006 20:06:48, GRAHAM,GR)
103054	06/20/2006	VENDOR FUEL JOB: HOLDS COSTS FOR MISC FUEL
103054	06/21/2006	LT. BIN VENT MISSING (05/23/2006 15:26:58, FARROW,TM)
103054	06/21/2006	B/U LIGHTS N/W. CHECK BELTS. (06/20/2006 16:19:31, GRAHAM
103054	06/22/2006	TAIL LIGHT, BU LIGHTS, AND BEEPER. (06/22/2006 17:18:02
103054	06/30/2006	NO BRAKE, TURN & FLASHER LIGHTS (06/30/2006 11:03:32, FAR
103054	06/30/2006	NO RIGHT TURN SIGNAL, (06/30/2006 23:22:09, KELLY,GB)
103054	07/03/2006	SHAFT (07/03/2006 08:46:05, DINEFF,AE)
103054	07/03/2006	TOW (07/03/2006 08:47:07, DINEFF,AE)
103054	07/03/2006	D/B (07/03/2006 15:07:16, GRAHAM,GR)
103054	07/06/2006	FUEL LEAK (07/06/2006 12:37:11, FARROW,TM)

103054	07/11/2006	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	07/11/2006	FULE LEAK. (07/11/2006 21:33:29, GRAHAM,GR)
103054	07/11/2006	HYD TOOL HOSES. (07/11/2006 21:46:42, GRAHAM,GR)
103054	07/13/2006	TURN SIGALS BLOWING FUSES. (06/30/2006 20:58:17, GRAHAM,G
103054	07/14/2006	ROAD TAR. (07/14/2006 17:15:59, GRAHAM,GR)
103054	07/19/2006	TRUCK RUNNING HOT ON HWY (07/19/2006 16:28:57, KELLY,GB)
103054	07/31/2006	REPLACE SEAT AND VICE (07/31/2006 23:24:37, KELLY,GB)
103054	08/01/2006	PTO NOISY. (08/01/2006 16:21:03, GRAHAM,GR)
103054	08/02/2006	OIL LEAK ON RT SIDE OF ENGINE. (08/02/2006 16:28:48, GRAH
103054	08/03/2006	STROBE LIGHT. (08/03/2006 16:59:57, GRAHAM,GR)
103054	08/25/2006	TRUCK LEANS. (08/25/2006 16:15:50, GRAHAM,GR)
103054	09/01/2006	CUSHION/COVER (09/01/2006 16:05:20, DINEFF,AE)
103054	09/13/2006	ENG. OIL LEAK (09/13/2006 12:47:37, FARROW,TM)
103054	09/19/2006	W/R (09/19/2006 14:58:57, GRAHAM,GR)
103054	09/22/2006	TRUCK STUCK (09/22/2006 15:01:24, FARROW,TM)
103054	09/29/2006	DOT Inspection Check off symbols: /=ok x=adjustment ma
103054	09/29/2006	DOT Inspection Check off symbols: /=ok x=adjustment ma
103054	09/29/2006	NO BRAKE LIGHTS OR TURN SIGNALS (09/29/2006 15:44:43, FAR
103054	10/02/2006	BIN DOOR SPRING. (10/02/2006 16:30:06, GRAHAM,GR)
103054	10/02/2006	ELECTRICAL PROBLEM. (10/02/2006 16:29:26, GRAHAM,GR)
103054	10/04/2006	Aerial Inspection
103054	10/05/2006	DOT Inspection Check off symbols: /=ok x=adjustment ma
103054	10/20/2006	HYD OIL LEAK. (10/20/2006 18:46:22, GRAHAM,GR)
103054	10/23/2006	W/W FLUID. (10/23/2006 20:07:37, GRAHAM,GR)
103054	11/06/2006	ENGINE OIL LEAK. (09/11/2006 16:49:02, GRAHAM,GR)
103054	11/07/2006	FRONT AND REAR TIRES. (11/06/2006 21:39:51, GRAHAM,GR)
103054	11/15/2006	Dielectric Test Dielectric Test ATA Code 500-500-022
103054	11/15/2006	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	11/17/2006	HEAD LIGHT OUT (11/17/2006 09:42:32, KELLY,GB)
103054	11/21/2006	LEFT DOOR PANEL POUCH. (11/20/2006 21:12:18, GRAHAM,GR)
103054	11/21/2006	DOOR PANEL POUCH (11/20/2006 17:10:50, GRAHAM,GR)
103054	11/29/2006	LEFT TURN SIGNAL. (11/29/2006 16:45:10, GRAHAM,GR)
103054	12/11/2006	BUMBER GUIDE (12/11/2006 23:23:58, KELLY,GB)
103054	12/11/2006	ANNUAL FIRE EXT INSP. (12/11/2006 23:30:42, GRAHAM,GR)
103054	12/12/2006	WASH TRUCK (12/12/2006 23:25:48, KELLY,GB)
103054	12/15/2006	HYD TOOL HOSE LEAK (12/15/2006 14:59:12, KELLY,GB)
103054	12/18/2006	LICENSE (12/18/2006 17:17:37, KELLY,GB)
103054	12/20/2006	HYD OIL LEAK. (11/22/2006 16:22:16, GRAHAM,GR)
103054	12/21/2006	ENGINE N/C. (12/21/2006 17:03:56, GRAHAM,GR)
103054	12/21/2006	ENGINE DIES (12/21/2006 22:59:54, KELLY,GB)
103054	01/08/2007	ENG. MAKING LOAD NOISE (01/08/2007 08:07:26, FARROW,TM)
103054	01/22/2007	ENGINE BLOWN. (01/04/2007 23:12:21, GRAHAM,GR)
103054	01/23/2007	ENG. NOISE & COOLANT LOW (01/23/2007 14:05:21, FARROW,TM)
103054	01/23/2007	ATF LEAK, REVERSE LIGHTS. (01/23/2007 23:50:13, GRAHAM,GR

103054	01/24/2007	OPERATOR REPORTS UNUSUAL ENGINE NOISE. (01/24/2007 23:37:
103054	01/24/2007	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	01/30/2007	ENGINE NOISE. (01/30/2007 23:57:36, GRAHAM,GR)
103054	02/01/2007	TOW (02/01/2007 08:45:41, DINEFF,AE)
103054	02/01/2007	ANTI FREEZE UNDER TRUCK (02/01/2007 13:52:11, FARROW,TM)
103054	02/02/2007	COOLANT LEAK. (02/02/2007 23:13:31, GRAHAM,GR)
103054	02/09/2007	COOLANT LEAK (02/09/2007 15:09:17, FARROW,TM)
103054	02/12/2007	BACK - UP LIGHT,PLEASE WASH (02/12/2007 21:19:38, KELLY
103054	02/15/2007	HEADLIGHT N/W. (02/15/2007 15:34:51, GRAHAM,GR)
103054	03/03/2007	STUCK (03/03/2007 13:49:09, GRAHAM,GR)
103054	03/14/2007	Dielectric Test Dielectric Test ATA Code 500-500-022
103054	03/14/2007	EVACUATE AND CHARGE AC. (01/23/2007 17:16:21, GRAHAM,GR)
103054	03/16/2007	RF TURN SIGNAL. (03/16/2007 08:03:40, GRAHAM,GR)
103054	03/20/2007	LADDER RACK (03/20/2007 15:22:44, GRAHAM,GR)
103054	03/26/2007	HYD LEAK (03/26/2007 15:33:56, GRAHAM,GR)
103054	03/28/2007	HYD HOSE (03/28/2007 11:06:37, GRAHAM,GR)
103054	04/03/2007	ENGINE OIL LEAK (04/03/2007 14:39:20, GRAHAM,GR)
103054	04/04/2007	ENGINE OIL LEAK. (04/03/2007 15:38:58, GRAHAM,GR)
103054	04/04/2007	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	04/04/2007	PTO SHAFT. (04/04/2007 15:43:32, GRAHAM,GR)
103054	04/04/2007	START/STOP N/C. (04/04/2007 15:45:56, GRAHAM,GR)
103054	04/12/2007	NO EMERGENCY POWER FROM BUCKET CONTROLS (04/12/2007 14:43
103054	04/20/2007	Aerial Inspection
103054	04/25/2007	CHANGE BUCKET, ADD STEPS. (10/31/2005 16:33:15, GRAHAM,G
103054	04/26/2007	TRUCK STUCK (04/17/2007 15:19:21, GRAHAM,GR)
103054	04/26/2007	OIL ON REAR OF TRUCK FROM HYD. LEAK (04/26/2007 15:37:17,
103054	04/27/2007	OIL LEAKS. CUT TIRE. (04/27/2007 15:45:31, GRAHAM,GR)
103054	04/27/2007	TIRES (04/27/2007 15:47:55, GRAHAM,GR)
103054	05/04/2007	BROKEN AXLE ? (05/03/2007 20:01:14, FARROW,TM)
103054	05/21/2007	ENGINE RUNNING HOT. (04/30/2007 17:55:29, GRAHAM,GR)
103054	05/21/2007	ATF LEAK. (05/21/2007 23:43:41, GRAHAM,GR)
103054	05/24/2007	EMERGENCY SHUTOFF AT BASKET. (05/24/2007 23:41:47, GRAHAM
103054	05/31/2007	FRONT TIRES SHAKE AND PULL. (05/31/2007 20:12:56, GRAHAM,
103054	06/05/2007	TRUCK STUCK (06/05/2007 14:00:10, GRAHAM,GR)
103054	06/13/2007	START/STOP, TRANS FLUID LEAK, PTO SHAFT. (06/13/2007 23:
103054	06/15/2007	WON'T START (06/14/2007 15:43:11, KELLY,GB)
103054	06/28/2007	TRUCK STUCK (05/07/2007 08:19:46, FARROW,TM)
103054	07/03/2007	TOW (07/03/2007 09:36:21, DINEFF,AE)
103054	07/05/2007	LT. REAR DUAL FLAT (07/02/2007 15:22:47, FARROW,TM)
103054	07/06/2007	ELECTRIC HORN N/W (07/05/2007 21:18:29, KELLY,GB)
103054	07/09/2007	HORN N/W. (07/05/2007 17:51:03, GRAHAM,GR)
103054	07/09/2007	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	07/10/2007	TRUCK STUCK (07/02/2007 11:02:16, FARROW,TM)
103054	07/10/2007	QUIT RUNNING (07/10/2007 17:04:43, GRAHAM,GR)

103054	07/17/2007	RT. FENDER BROKE & GAS TANK SHIFTED (07/06/2007 15:26:27,
103054	07/20/2007	PARTS AT MILLER AUTO (07/20/2007 09:58:30, FARROW,TM)
103054	07/25/2007	CHECK FOR LOOSE BOLTS PER E-MAIL. (07/25/2007 16:43:33, G
103054	07/29/2007	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - UNK-APPLI
103054	07/29/2007	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - UNK-APPLI
103054	07/30/2007	TRANS FLUID LEAK. (07/27/2007 16:47:55, GRAHAM,GR)
103054	08/01/2007	INTERMITTANT NO CRANK. (07/25/2007 23:11:30, GRAHAM,GR)
103054	08/07/2007	Acoustic Emission Testing ACOUSTIC EMISSION TEST ATA COD
103054	08/29/2007	B/U LIGHT N/W (08/27/2007 17:36:36, GRAHAM,GR)
103054	08/31/2007	FIRST AID KIT STICKER DOESN'T MATCH KITS LOCATION (08/31/
103054	09/06/2007	A/C DRAIN (09/06/2007 16:11:31, GRAHAM,GR)
103054	09/07/2007	BATTERY BOX LATCH BROKE (09/04/2007 09:04:21, FARROW,TM)
103054	09/07/2007	MUDFLAPS (09/07/2007 16:31:04, GRAHAM,GR)
103054	09/12/2007	Dielectric Test Dielectric Test ATA Code 500-500-022
103054	09/27/2007	replaced turn signal lights front and rear (09/27/2007 13
103054	10/03/2007	PM DOT INSPECTION Check off symbols: /=ok x=adjustment
103054	10/04/2007	LT. STROBE LIGHT NOT WORKING (10/04/2007 12:29:31, FARROW
103054	10/05/2007	State Inspection 24 Month Check off symbols: /=ok x=ad
103054	10/05/2007	PM DOT INSPECTION Check off symbols: /=ok x=adjustment
103054	10/05/2007	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	10/05/2007	Aerial Inspection
103054	10/05/2007	JIB COVER (10/05/2007 23:51:49, GRAHAM,GR)
103054	10/31/2007	W/W RESERVOIR. (10/05/2007 20:04:19, GRAHAM,GR)
103054	10/31/2007	TRANS CHATTERS DURING SHIFT (08/03/2007 17:02:36, GRAHAM,
103054	10/31/2007	START/STOP/EP FROM BUCKET (10/31/2007 20:25:48, GRAHAM,GR
103054	11/05/2007	REAR STEP BROKE OFF. (11/05/2007 22:43:35, GRAHAM,GR)
103054	11/26/2007	LIGHTS N'W,ENGINE LOW ON OIL, (11/26/2007 23:08:13, KELLY
103054	11/27/2007	LICENSE (11/27/2007 13:21:49, FARROW,TM)
103054	11/27/2007	BUCKET COVER HOLD DOWN STRAP BROKE (11/27/2007 17:57:58,
103054	12/04/2007	COOLANT LEAK (12/04/2007 20:45:20, GRAHAM,GR)
103054	12/10/2007	TIRE CHAINS (12/10/2007 16:17:13, KELLY,GB)
103054	12/11/2007	TIRE CHAINS (12/11/2007 21:52:19, KELLY,GB)
103054	12/12/2007	TRUCK DIES WHEN IN MACHINE (12/11/2007 19:08:12, KELLY,GB
103054	12/12/2007	SPOT LIGHTS (12/12/2007 14:42:32, KELLY,GB)
103054	12/19/2007	BLOCK HEATER (12/19/2007 15:43:37, GRAHAM,GR)
103054	12/21/2007	HYD. HOSES FRAYED ; REPAIR JIB COVERS (12/21/2007 10:08:5
103054	12/21/2007	BUCKET COVER (12/21/2007 14:28:38, FARROW,TM)
103054	12/21/2007	INSTALL NEW JIB COVERS & DECALS (12/21/2007 14:32:58, FAR
103054	12/28/2007	FUEL CARD (12/28/2007 14:44:42, GRAHAM,GR)
103054	01/02/2008	TRUCK DIES IN MACHINE (12/12/2007 13:44:55, KELLY,GB)
103054	01/04/2008	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	01/07/2008	COOLANT LEAK (01/07/2008 09:26:40, FARROW,TM)

103054	01/08/2008	ANTI-FREEZE LEAKING (01/02/2008 15:40:52, FARROW,TM)
103054	01/15/2008	RF BODY MOUNT LOOSE. (01/14/2008 23:56:55, GRAHAM,GR)
103054	01/22/2008	P/S HOSES OILY (01/18/2008 16:29:17, GRAHAM,GR)
103054	01/22/2008	BUMPER GUIDE, ANNUAL FIRE EXT INSP (01/22/2008 23:36:46,
103054	01/22/2008	Install Driving Lights (12/07/2007 17:42:58, ROBBINS,SE)
103054	01/25/2008	BROKEN AXLE (01/25/2008 14:34:31, FARROW,TM)
103054	02/07/2008	stopped on side of road (01/31/2008 16:11:13, BARTON,LE)
103054	02/07/2008	INSERVICE & STORE NEW AXLE (02/07/2008 15:20:17, FARROW,T
103054	02/11/2008	fan in radiator (02/06/2008 17:05:56, COLLIER,L)
103054	02/14/2008	Repair the A/C... (02/13/2008 07:46:51, SLAY,AJ)
103054	02/14/2008	chk and top off fluids (02/12/2008 22:57:43, PLAISTED,HE)
103054	02/20/2008	Repaired the A/C. (02/13/2008 07:28:30, SLAY,AJ)
103054	02/21/2008	LOWER BOOM CYL TRUNNIONS. (02/21/2008 23:52:53, GRAHAM,GR)
103054	02/22/2008	ANTI FREEZE LEAK ; TRANS. FLUID ; WIRING HARNESS HANGING
103054	02/22/2008	TRUCK STUCK (02/22/2008 12:48:20, FARROW,TM)
103054	02/23/2008	TRUCK STUCK (02/23/2008 15:52:01, KELLY,GB)
103054	03/01/2008	CALL OUT, TRUCK STUCK (03/01/2008 11:00:51, KELLY,GB)
103054	03/03/2008	TOW (03/03/2008 10:56:21, DINEFF,AE)
103054	03/03/2008	TRANS N/C. (02/19/2008 16:25:46, GRAHAM,GR)
103054	03/05/2008	ANTI FREEZE LEAK IN CAB (01/28/2008 16:19:37, GRAHAM,GR)
103054	03/06/2008	SIX TIRES. (11/20/2007 15:25:17, GRAHAM,GR)
103054	03/07/2008	COOLANT LEAK (03/06/2008 16:20:16, GRAHAM,GR)
103054	03/07/2008	WATER IN FUEL LIGHT ON ; LT. BACK UP LIGHT OUT ; B/U ALAR
103054	03/17/2008	SWITCH (03/17/2008 13:12:33, DINEFF,AE)
103054	03/17/2008	TANK (03/17/2008 13:13:33, DINEFF,AE)
103054	03/17/2008	SPRING (03/17/2008 13:14:52, DINEFF,AE)
103054	03/17/2008	PUMP (03/17/2008 13:15:44, DINEFF,AE)
103054	03/17/2008	BOLT (03/17/2008 13:16:38, DINEFF,AE)
103054	03/17/2008	PULLEY (03/17/2008 13:17:29, DINEFF,AE)
103054	03/17/2008	RADIATOR (03/17/2008 13:20:14, DINEFF,AE)
103054	03/18/2008	Dielectric Test Dielectric Test ATA Code 500-500-022
103054	03/28/2008	COOLANT LEAK (03/28/2008 12:43:58, GRAHAM,GR)
103054	04/03/2008	TRUCK STUCK (04/03/2008 08:17:07, FARROW,TM)
103054	04/04/2008	BOOM REST-WELD BROKE AT FLOOR (04/03/2008 21:54:59, GRAHA
103054	04/11/2008	TRUCK STUCK (04/11/2008 15:08:58, FARROW,TM)
103054	04/15/2008	vac down and charge AC system (02/08/2008 19:24:02, DENU,
103054	04/16/2008	Vehicle Inspection 6 Month PM Vehicle 6 Check off symbo
103054	04/16/2008	MUFFLER AND TAILPIPE (10/05/2007 17:04:58, GRAHAM,GR)
103054	04/17/2008	START/STOP N/C. (04/17/2008 23:35:25, GRAHAM,GR)
103054	04/17/2008	Aerial Inspection
103054	05/09/2008	AC N/W (05/09/2008 07:43:33, KELLY,GB)
103054	05/13/2008	COOLANT LOW & A/C COMPRESSOR NOT TURNING (05/13/2008 15:1
103054	05/19/2008	COOLANT LEAK (05/19/2008 07:58:39, GRAHAM,GR)
103054	05/20/2008	PTO WON'T ENGAGE (05/20/2008 14:37:40, KELLY,GB)

103054	05/29/2008	LOW ON ANTIFREEZE,CK MOTOR OIL FOR WATER (05/22/2008 15:3
103054	05/29/2008	AC NOT WORKING ALL THE TIME (05/29/2008 12:55:04, KELLY,G
103054	05/30/2008	CK AC STOP WORKING (05/14/2008 20:20:50, KELLY,GB)
103054	06/09/2008	COOLANT LOW ; TREE STUCK UNDER FRT. OF TRUCK (05/21/2008
103054	06/09/2008	ANTIFREEZE LEAK (06/09/2008 12:44:11, KELLY,GB)
103054	06/10/2008	TRUCK STUCK (06/10/2008 12:13:25, KELLY,GB)
103054	06/14/2008	TRUCK STUCK IN MUD (06/14/2008 13:07:45, KELLY,GB)
103054	06/16/2008	AC STOPS WORKING AT TIMES (06/02/2008 15:25:06, KELLY,GB)
103054	06/17/2008	BASKET COVER (06/10/2008 12:10:31, KELLY,GB)
103054	06/17/2008	EXHAUST LEAK (06/11/2008 15:01:56, KELLY,GB)
103054	06/18/2008	FOG LIGHT N/W (06/18/2008 19:22:53, GRAHAM,GR)
103054	06/20/2008	REPAIR LT. WIPER ARM,LT TURN LIGHT & SPOT LIGHT (06/20/20
103054	06/23/2008	TRUCK STUCK. (06/23/2008 09:50:51, GRAHAM,GR)
103054	06/28/2008	PTO N/W (06/28/2008 07:28:27, GRAHAM,GR)
103054	07/01/2008	LIGHT OUT (07/01/2008 17:43:23, KELLY,GB)
103054	07/11/2008	DRIVERS SEAT BELT BROKEN (07/11/2008 14:52:45, FARROW,TM)
103054	07/14/2008	Acoustic Emission Testing ACOUSTIC EMISSION TEST ATA COD
103054	07/21/2008	COOLANT & OIL LOW (07/21/2008 15:01:13, FARROW,TM)
103054	07/29/2008	TRANS NOT SHIFTING (07/29/2008 16:06:50, KELLY,GB)
103054	07/31/2008	REAR DIFFERENTIAL POPPING (07/31/2008 08:42:07, FARROW,TM)
103054	07/31/2008	12vlt. connections for equipment (07/31/2008 15:34:12, FA
103054	08/05/2008	TRANS N/C. (07/30/2008 17:27:37, GRAHAM,GR)
103054	08/05/2008	ATF LEAK-SHIFTER SHAFT SEAL (08/01/2007 22:40:34, GRAHAM,
103054	08/07/2008	LF TURN SIGNAL N/W. (08/07/2008 16:34:11, GRAHAM,GR)
103054	08/08/2008	LT. TIRE FLAT & TRUCK PULLS RT. (08/08/2008 16:37:04, FAR
103054	09/02/2008	REPLACE U-JOINTS ON P.T.O. SHAFT (09/02/2008 15:45:15, FA
103054	09/02/2008	NOISE W/PTO ENGAGED (09/02/2008 16:15:15, GRAHAM,GR)
103054	09/03/2008	Dielectric Test Dielectric Test ATA Code 500-500-022
103054	09/04/2008	P.T.O. MAKING LOAD RATTLE (09/03/2008 08:24:52, FARROW,TM)
103054	09/04/2008	P.T.O. MAKING LOUD NOISE (09/04/2008 13:35:58, FARROW,TM)
103054	09/04/2008	TRUCK STUCK (09/04/2008 12:50:26, KELLY,GB)
103054	09/09/2008	TRAN (09/09/2008 15:48:39, LAWS,TV)
103054	09/11/2008	IN SERVICE SPARE AXLE (09/11/2008 13:11:05, FARROW,TM)
103054	09/15/2008	TRANSMISSION FLUID LOW & CK. OVER FOR STORM AT CAPE (09/1
103054	09/29/2008	COOLANT LEAK & TRANSMISSION LOW (09/26/2008 14:31:17, FAR
103054	10/01/2008	JIB COVER (10/01/2008 23:25:43, GRAHAM,GR)
103054	10/02/2008	LT. TURN NOT WORKING (10/01/2008 09:50:39, FARROW,TM)
103054	10/03/2008	State Inspection 24 Month Check off symbols: /=ok x=ad
103054	10/03/2008	Vehicle Inspection 6 Month Metro
103054	10/06/2008	Aerial Inspection
103054	10/09/2008	ABS LIGHT ON (10/09/2008 16:46:27, GRAHAM,GR)
103054	10/10/2008	abs brake light on (10/10/2008 13:17:48, FARROW,TM)
103054	10/20/2008	DASH LIGHTS N/W. (10/20/2008 16:36:16, GRAHAM,GR)
103054	10/20/2008	MIRROR BRACKET BROKE. THROTTLE CONTROLS. (10/20/2008 23:4

103054	11/07/2008	COOLANT LEAK. (11/07/2008 15:02:54, GRAHAM,GR)
103054	11/14/2008	trans. low & lt. frt. turn out (11/14/2008 15:22:56, FARR
103054	11/17/2008	FOG LIGHT AND MARKER LIGHT N/W. (11/17/2008 07:42:50, GRA
103054	11/20/2008	FUEL LEAK (11/20/2008 10:08:18, GRAHAM,GR)
103054	11/26/2008	CK FLUIDS (11/26/2008 14:35:45, KELLY,GB)
103054	12/05/2008	TRANS. & FLUIDS LOW (12/05/2008 12:23:42, FARROW,TM)
103054	12/08/2008	JIB COVER, INSTRUMENT PANEL LIGHTING. (12/08/2008 23:22:2
103054	12/11/2008	REAR END BOUNCING (12/10/2008 14:54:24, KELLY,GB)
103054	12/17/2008	FUEL TANK SLID BACK (12/17/2008 11:11:28, GRAHAM,GR)
103054	12/18/2008	TRANS FLUID (12/18/2008 07:58:06, GRAHAM,GR)
103054	12/26/2008	WASH (12/26/2008 10:02:27, GRAHAM,GR)
103054	12/26/2008	TRANSMISSION FLUID LEAK. (12/23/2008 10:14:47, GRAHAM,GR)
103054	12/26/2008	SPOTLIGHTS N/W (12/23/2008 10:16:50, GRAHAM,GR)
103054	12/26/2008	BUMPER GUIDE (12/26/2008 14:57:55, GRAHAM,GR)
103054	12/26/2008	FUEL LEAK. (12/26/2008 15:01:16, GRAHAM,GR)
103054	12/26/2008	B/U LIGHTS N/W (12/23/2008 10:17:24, GRAHAM,GR)
103054	01/06/2009	LF TURN SIGNAL (01/02/2009 13:40:35, GRAHAM,GR)
103054	01/08/2009	REPLACE TIRES (01/06/2009 21:28:42, KELLY,GB)
103054	01/08/2009	TRANS FLUID LEAK. (01/08/2009 16:16:15, GRAHAM,GR)
103054	01/15/2009	ENGINE QUIT RUNNING. (01/15/2009 20:47:09, GRAHAM,GR)
103054	01/20/2009	TRANS. FLUID LOW (01/20/2009 11:14:31, FARROW,TM)
103054	01/27/2009	SEAT COVER TORN (01/07/2009 15:41:19, FARROW,TM)
103054	01/27/2009	Install Tire Chains (01/27/2009 14:47:40, ROBBINS,SE)
103054	01/27/2009	TRANS FLUID LEAK. (01/27/2009 18:20:56, GRAHAM,GR)
103054	01/30/2009	CHANGE TIRE (01/30/2009 15:35:29, KELLY,GB)
103054	02/03/2009	TRANS FLUID. (02/03/2009 20:31:04, GRAHAM,GR)
103054	02/05/2009	Engine Died, Won't start (02/05/2009 08:24:14, ROBBINS,SE)
103054	02/12/2009	TRANS LEAK (02/12/2009 09:28:22, KELLY,GB)
103054	02/23/2009	Won't start. transmission low. (02/23/2009 08:14:31, ROB
103054	03/09/2009	Repair transmission leak (02/24/2009 07:38:49, ROBBINS,SE)
103054	03/11/2009	PM-DIELECTRIC-S Dielectric Test ATA Code 500-500-022
103054	03/11/2009	STUCK (03/11/2009 12:08:56, GRAHAM,GR)
103054	04/01/2009	Won't stay running (03/27/2009 11:01:29, ROBBINS,SE)
103054	04/01/2009	PM-VEHICLE-6S Level B Vehicle Inspection ATA Code 500-5
103054	04/02/2009	Rear step broke and dragging the ground (04/02/2009 09:27
103054	04/02/2009	Replace rear step (04/02/2009 10:13:25, ROBBINS,SE)
103054	04/20/2009	Won't start from upper controls. AC not working (04/16/20
103054	04/20/2009	PM-AERIAL-6S Level B Aerial Inspection ATA Code 500-500
103054	04/30/2009	Check tire (04/30/2009 08:07:15, ROBBINS,SE)
103054	05/21/2009	replace bolt in side step (05/21/2009 08:08:34, ROBBINS,S
103054	05/27/2009	RT. SIDE STEP BROKEN & LT. FRT. BUMPER MARKER (05/26/2009
103054	05/27/2009	Pass side step fell off (05/27/2009 09:13:57, RUHR,ME)
103054	05/28/2009	TIRE (05/28/2009 12:08:36, GRAHAM,GR)
103054	06/15/2009	BLOWN HYD HOSE. (06/12/2009 16:47:53, GRAHAM,GR)

103054	06/19/2009	Engine light came on (06/19/2009 10:18:22, ROBBINS,SE)
103054	06/19/2009	Low air pressure alarm not working (06/19/2009 06:58:55,
103054	07/01/2009	replace seal on fire extinguisher (07/01/2009 08:05:12, R
103054	07/06/2009	Engine died, ABS light on (07/02/2009 12:28:01, ROBBINS,S
103054	07/10/2009	Throttle goes up and down when operating stiff legs (07/0
103054	07/15/2009	PM-ACOUSTIC-S Acoustic Emission Test ATA CODE 500-500-
103054	07/21/2009	LOWER BOOM CYL PIN. (07/16/2009 07:40:10, GRAHAM,GR)
103054	07/22/2009	HYD CYL (07/22/2009 09:25:24, GRAHAM,GR)
103054	07/28/2009	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - AL SCHEPP
103054	07/28/2009	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - AL SCHEPP
103054	07/28/2009	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - AL SCHEPP
103054	07/31/2009	THROTTLE CONTROL. (07/31/2009 15:46:56, GRAHAM,GR)
103054	08/10/2009	driving lights not working (08/10/2009 15:36:51, ROBBINS,
103054	08/20/2009	TRUCK STUCK AND AXLE BROKEN. (08/20/2009 00:22:08, GRAHAM
103054	08/25/2009	Engine died (08/25/2009 09:28:03, ROBBINS,SE)
103054	08/26/2009	replace seat belt (08/26/2009 08:54:35, ROBBINS,SE)
103054	08/26/2009	BROKEN AXLE FROM SC043117 (08/20/2009 16:53:55, GRAHAM,GR
103054	09/02/2009	PM-DIELECTRIC-S Dielectric Test ATA Code 500-500-022
103054	09/04/2009	WON'T RUN. (09/02/2009 20:08:20, GRAHAM,GR)
103054	09/04/2009	TRUCK STUCK (09/04/2009 15:49:33, GRAHAM,GR)
103054	09/21/2009	AC not working (09/21/2009 16:25:17, ROBBINS,SE)
103054	09/28/2009	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - AL SCHEPP
103054	10/03/2009	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - C.H.A.S.N
103054	10/12/2009	AOC VENDOR MAINTENANCE JOB WORK PERFORMED BY - AL SCHEPP
103054	10/12/2009	PM-VEHICLE-6S Level B Vehicle Inspection ATA Code 500-5
103054	10/12/2009	PM-DOT-INSPECT-S DOT Inspection ATA Code 500-500-017
103054	10/13/2009	RECHARGE FIRE EXT
103054	10/13/2009	PM-AERIAL-6S Level B Aerial Inspection ATA Code 500-500
103054	10/15/2009	Oil leak between stiff legs
103054	10/29/2009	Left turn light on fender not working, seat belt hard to
103054	11/03/2009	right front tire rubbing fender
103054	11/06/2009	Replace missing bolt in jib cover
103054	11/10/2009	Check cooling system
103054	11/10/2009	PM-ST-INSPECT-24S Missouri State Inspection 24 Month ATA
103054	11/16/2009	replace wiring harness socket for tuns signal light.
103054	11/19/2009	103054 STUCK.
103054	11/27/2009	Truck Stuck, No Crews Available
103054	12/09/2009	TRUCK STUCK

103054	01/05/2010	Coolant leak Check P/S leak One of the right tail lights
103054	01/06/2010	Install tire chains
103054	01/12/2010	FLUID LEVELS
103054	01/12/2010	Probable broken axle or locker
103054	01/26/2010	Truck Stuck
103054	01/27/2010	reair and store tire chains
103054	01/29/2010	lower boom lift cylinder seems weak
103054	01/29/2010	LIGHTS N/W, STEP BENT.
103054	02/01/2010	W/W FLUID.
103054	02/05/2010	Check rear tires, repair lights, straighten fuel tank ste
103054	02/16/2010	spot lights work part time
103054	02/18/2010	TRUCK STUCK
103054	02/19/2010	Power steering fluid low
103054	02/22/2010	REPLACE TIRES
103054	03/03/2010	PM-DIELECTRIC-S Dielectric Test ATA Code 500-500-022
103054	04/13/2010	right turn signal on fender out
103054	04/13/2010	A/C NOT COOLING.
103054	04/13/2010	PM-VEHICLE-6S Level B Vehicle Inspection ATA Code 500-5
103054	04/13/2010	PM-AERIAL-6S Level B Aerial Inspection ATA Code 500-500
103054	04/13/2010	FOUND ON PMI
103054	04/15/2010	Repair wirring to left strobe light
103054	04/26/2010	AERIAL INSPECTION. (04/13/2010 09:20:13, GRAHAM,GR) CAT 3
103054	04/26/2010	Check Windshield. Check Hydraulic leak.
103054	05/03/2010	Replace windshield
103054	05/06/2010	hose clamp broke at air box
103054	05/25/2010	Check lug nuts
103054	05/26/2010	OUTRIGGER CONTROLS STICKING
103054	06/02/2010	Two Speed not working properly.
103054	06/10/2010	Truck Stuck
103054	06/14/2010	Speedometer quit working
103054	06/23/2010	CAP MISSING OFF STORAGE TUBE
103054	06/24/2010	INSTRUMENT CLUSTER AND SPEEDOMETER N/C.
103054	07/06/2010	REMOVE FROM SERVICE.