

DATE ARRIVED		DATE INVOICE	SALES TYPE
1/25/2016 10:54:03AM		1/28/2016	SRET
YEAR	MAKE	MODEL	VIN
2005	WILSON	HOPPER	5A241655

JOB #1 GENRI GENERAL REPAIR

COMPLAINT REPAIR FRONT SLOPE SHEET FRAME ABOVE LEGS BOTH SIDES
REPAIR REAR SLOPE SHEET FRAME OVER FRONT EDGE OF SUSPENSION BOTH SIDES
V-OUT AND WELD CRACKS IN BOGIE BEAMS
REPLACE CROSSMEMBER OVER REAR AXLE AIR BAGS
R&R SHOCK MOUNTS FOR REPAIRS

CAUSE
CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	100C/9010	PRIMER		
4	100K/4X3X1/4 STEEL	STEEL 4 X 3 RECT TUBE		
1	100M/032-06590	HUCK 3/8" BOMB		
5	100M/03239388	HUCK 1/4 MULTI GRIP		
2	100M/0750350H8	BOLT 3/4 X 3.5 HHCS GR8 Z/Y		
2	100M/075NF8	NUT 3/4" GR8 Z/Y		
2	100M/075WS8	WASHER 3/4" LOCK GR8 Z/Y		
5	100M/50-B18K-45	COLLAR 1/4 HUCK		
5	100M/700-50-30	MONOBOLT 1/4 X 1/2		
1	100X/1615	PAINT BLACK (SPRAY)		
	LABOR GENREPAIR	GENERAL REPAIR		

Parts: \$88.81 Labor: \$864.00 Misc: \$0 Sublet: \$0 \$952.81

LABOR	\$864.00
PARTS	\$88.81
MISC	\$0.00
<u>SUBLET</u>	<u>\$0.00</u>
<u>SUBTOTAL</u>	<u>\$952.81</u>
SHOP SUPPLIES	\$86.40
MISC SUPPLIES	\$0.00
TAX	\$0
<u>TOTAL</u>	<u>\$1,039.21</u>

2005 Wilson Hopper Bottom
 Plate : PR3 939
 ODO : 0
 V.I.N.: 1W1MAFYA55A241655
 Unit #:
 Engine:

INV # : 31757
 Date : 03/06/2014
 Time :
 PO # :
 REG # : 21412065
 Tech. : TONY/

Qty	Description	Parts Ea.	Tot. Parts	Labor	Ex Total	C
4.00	Brake drum					
4.00	Brake shoes, Rockwell Q plus					
2.00	Scam LH					
2.00	Scam RH					
4.00	Slack adj automatic 5-1/2"					
	Remove And Replace all four					
	s cams, s cam bushings, brake					
	shoes, drums.					
	Shop Supplies					

WC# 19270

Sub Tot.	1,446.44	1,080.00	2,526.44
	ST		82.88
	Deductible		0.00
	Total		2,609.32

DATE ARRIVED		DATE INVOICE	SALES TYPE
5/23/2017 1:32:28PM		5/24/2017	SRET
YEAR	MAKE	MODEL	VIN
2006	WILSON	HOPPER	6A243758

JOB #1 GENRI GENERAL REPAIR

COMPLAINT REMOVE INSIDE LEG BRACE ON CURBSIDE LEG
 STRAIGHTEN LEGS
 STRAIGHTEN CROSS MEMBER AND WELD IN SUPPORT

CAUSE

CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR GENREPAIR	GENERAL REPAIR		

LABOR	\$144.00
PARTS	\$0.00
MISC	\$0.00
SUBLET	\$0.00
SUBTOTAL	\$144.00
SHOP SUPPLIES	\$14.40
MISC SUPPLIES	\$0.00
TAX	\$0
TOTAL	\$158.40

DATE ARRIVED		DATE INVOICE	SALES TYPE
5/30/2017 1:30:36PM		6/20/2017	SRET
YEAR	MAKE	MODEL	VIN
2005	WILSON	HOPPER	5A241655

JOB #1 GENRI GENERAL REPAIR

COMPLAINT REWELD C/S REAR SHOCK BRACKET
 PLATE AND WELD CENTER CROSS MEMBER WHERE CRACKED
 V-OUT AND WELD CROSS MEMBER OVER FRONT AXLE R/S AT SHOCK MOUNT

CAUSE
 CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR GENREPAIR	GENERAL REPAIR		

LABOR	\$878.40
PARTS	\$0.00
MISC	\$0.00
SUBLET	\$0.00
SUBTOTAL	\$878.40
SHOP SUPPLIES	\$87.84
MISC SUPPLIES	\$0.00
TAX	\$0
TOTAL	\$966.24

DATE SHIPPED	SHIP VIA	DATE INVOICE
7/14/2017	CUSTOMER PICKUP	7/14/2017

QTY SHP	QTY B/O	ITEM	DESCRIPTION	BIN	UNIT PRICE	EXTD PRICE
1		100M/9935	9935 AIR BAG			

SUB-TOTAL	\$ 156.20
TAX	\$ 0.00
SHIPPING	\$ 0.00
TOTAL	\$ 156.20

DATE ARRIVED	DATE INVOICE	SALES TYPE	
1/7/2016 1:36:26PM	1/12/2016	SRET	
YEAR	MAKE	MODEL	VIN
2005	WILSON	HOPPER	5A241655

JOB #1 GENRI GENERAL REPAIR

COMPLAINT REMOVE ALUM CORNER BRACKETS ON CROSSMEMBER AT FRONT OF SUSPENSION REPLACE WITH STEEL
ANGLE
REPLACE MISSING RIVETS ON FRONT HOPPER LONG SLOPE
REPAIR BOTTOM CORNERS OF FRONT LONG SLOPE ABOVE LEGS

CAUSE
CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	100C/MAN65A	BUTLE CAULK		
12	100M/50-B18K-40	COLLAR 3/8 HUCK		
6	100M/50-B18Q-19	HUCK 3/8" BOLT		
6	100M/8-MGPTC-R12-14G	HUCK 3/8 MULTIGRIP SS		
	LABOR GENREPAIR	GENERAL REPAIR		

Parts: \$39.64 Labor: \$648.00 Misc: \$0 Sublet: \$0 \$687.64

LABOR	\$648.00
PARTS	\$39.64
MISC	\$0.00
SUBLET	\$0.00
SUBTOTAL	\$687.64
SHOP SUPPLIES	\$64.80
MISC SUPPLIES	\$0.00
TAX	\$0
TOTAL	\$752.44