

# Invoice

Date	Invoice #
11/12/2017	77580

Bill To

BACKER PRODUCE LLC

P.O. No.

Terms

Project

Net due in 30 days

Quantity

Description

Rate

Amount

John Deere 710

Resealed top of backhoe control valve and added 5 gal. of hydraulic oil.

Parts, hydraulic oil and supplies

Labor

Sales Tax

Total



Account No: 100004119

BACKER PRODUCE

Deliver to Account No: 100004119

BACKER PRODUCE LLC

# SALES INVOICE

Invoice No: 24  
Date: 6/29

Page:

Cust PO No:

Tax Exempt No:

Payment Type:

Bus Ph: 515-777-6768 Priv Ph:

Bus Ph: 515-777-6768 Priv Ph:

## STOCK UNIT DETAILS

STOCK No.

TYPE

CLASS

ATTCH-TO

MAKE

MODEL

Eq ID

PIN

SALE

60261

New

Att

C&P

BH BKT

NB3021

976-107413-10

## INVOICE ALLOCATION DESCRIPTION

Transfer to BACKER PRODUCE, LLC, customer number 100004119

## INVOICE NOTES

THANK YOU FOR YOUR BUSINESS

Salesperson: KRIS BLUM

Total Selling Price	
Plus Freight and Handling:	
Plus Insurance:	
Less Discount:	
Plus Stamp Duty:	
Plus Registration Fee:	
Plus Additional Charges:	
Plus Parts/Attachments:	
Plus Agreements:	
Plus Sales Tax:	
Total Invoice:	

Less Net Equity from Trade In(s):	
Plus Refund:	
Less Pre-Trade Payment:	
Less Deposit:	
Less From Finance Contract:	
Less Invoice Payment:	
Amount Due:	\$1



## Invoice

Date	Invoice #
6/14/2017	47571

Bill To
cker Produce

Ship To
---------

P.O. Number	Terms	Due Date	Rep	Via	Job #
		6/29/2017		customer pickup	88745
Quantity	Description			Price Each	Amount
	Repair 2 John Deere 710D Backhoe Cylinders Disassemble, Reseal, Assemble, Test Machine 2 New Rods (Rods Scored)				
	Sales Tax				
Pd ck 5071					
Thank you for your business				Total	\$1,925.91



# Invoice

Date	Invoice #
7/5/2017	87483

ER PRODUCE LLC

P.O. No.

Terms

Project

Net Due 10 Days

Description

Rate

Amount

Deere 710D

Inspected the machine and made a list of needed repairs. Removed loader bucket cylinder and right outrigger cylinder to be repaired and installed them after repair. Repaired several lights, replaced the flasher. Serviced engine oil and all filters. Replaced the transmission and hydraulic filters. Replaced the antifreeze. Replaced a hose from hydraulic pump to the cooler. Repaired the backhoe transport lock. Adjusted the door latch and adjusted the back window. Washed the radiator area and washed the back area where the backhoe attaches. Added hydraulic oil. Removed and rebuilt park brake caliper and installed it with new pads and installed the hydraulic hose from the valve to the caliper.

Parts, fluids and supplies

Labor

Sales Tax

Total