

combine

"Partnering Together to Nurture The Land"

SERVICE INVOICE

Invoice To Account No: 11533

Deliver To:

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

Bus Phone: |

Prv Phone: |

Mob Phone: |

Bus Phone:

Prv Phone:

Mob Phone:

Invoice Number: **1278704**

Invoice Date: 5/16/2016

Location: 4

Work Order Number: 201792

Payment Type: Finance

Page: 1 of 10

Technician Number: T444

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

1994 JOHN DEERE 9600

3580

H09600X660571

37393W

//9600 CMBW334 Retail

CORRECTION:

01 Combine PerformMax Inspection (Walker)

3580 Engine Hours

2409 Separator Hours

Performed the combine Performmax Inspection. Made a list of needed repairs to go over with the customer. Figured an estimate of the needed repairs. Went over the list of needed repairs with the customer to see what he wanted us to fix. Adjusted the belts and chains as needed. Greased the machine completely. Installed the shields removed for the inspection. Ran out the machine after the repairs had been made.

Labor:

//9600 CMBWPU* Retail

CORRECTION:

02 Customer furnished transportation

\$100.00 Credit when customer brings equipment in & back for scheduled Winter Service versus PLP hauling.

Miscellaneous
S4906

Description

Quantity

List Price

Net Price

Extended Price

Taxed Ind

Labor: \$0.00

Parts: \$0.00

OL&M: \$0.00

Misc:

//9600 CMBW789 Retail

CORRECTION:

03 Header lift switch, Replace

Disconnected and removed the header lift switch. Replaced the header lift switch. Installed and connected the header lift switch. Checked the header lift switch operations.

Part Number

Description

Quantity

List Price

Net Price

Extended Price

Taxed Ind

CONTINUED ON NEXT PAGE->

"Partnering Together to Nurture The Land"

SERVICE INVOICE

Invoice To Account No: 11533

Deliver To:

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

Bus Phone:

Prv Phone:

Mob Phone

Bus Phone:

Prv Phone:

Mob Phone

Invoice Number: **1278704**

Invoice Date: 5/16/2016

Location: 4

Work Order Number: 201792

Payment Type: Finance

Page: 2 of 10

Technician Number: T444

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

1994 JOHN DEERE 9600

3580

H09600X660571

37393W

//9600 CMBW789 Retail

AH140161

SWITCH

N

Labor:

//9600 CMBW45 Retail

CORRECTION:

04 Shoe supply auger front bearings, R&R

Disconnected and removed the shoe auger drive shaft. Replaced all seven shoe augers front bearings, flanges, lock collars, and sprocket roll pins. Replaced the shoe auger drive shaft bearings, flanges, lock collars, wooden blocks, and sprocket keys. Installed and connected the shoe auger drive shaft.

Part Number	Description	Quantitv	List Price	Net Price	Extended Price	Taxed Ind
11M7015	1/8 X 1					N
24M7047	WASHER					N
AH129451	BRG-9600, 9760STS					N
AH129452	ECCENTRIC-96, 9760STS					N
AH214862	BRG-9750STS					N
E10018	PRESSED FL-9760STS					N
E63018	SPRING PIN					N
H103264	PRESSED FL-9760STS					N
H135475	BRG-WOOD					N
H167587	KEY					N
JD7797	LUBRICATIO					N
JD8554	ECCENTRIC-					N
JD8665	BALL BEARI					N

Labor:

CONTINUED ON NEXT PAGE->

"Partnering Together to Nurture The Land"

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICE

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

Bus Phone:

Prv Phone:

Mob Phone:

Invoice Number: **1278704**

Invoice Date: 5/16/2016

Location: 4

Work Order Number: 201792

Payment Type: Finance

Page: 3 of 10

Technician Number: T444

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

1994 JOHN DEERE 9600

3580

H09600X660571

37393W

//9600 CMBW111 Retail

CORRECTION:

05 Feeder house conveyor chain, Remove half links

Disconnected and removed the feeder house drive chain and front enclosure. Disconnected the feeder house conveyor chain. Cut out one row of half links from the feeder house conveyor chain. Reconnected and adjusted the feeder house conveyor chain using new "J" hooks. Installed and connected the feeder house front enclosure and drive chain. Installed a new connector link and adjusted the feeder house drive chain.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7192	M10 X 30					N
B5235H	60 CONNECTOR					N
H84026	HOOK-9600					N

Labor:

//9600 CMBW187 Retail

CORRECTION:

06 Reverser gear case, Change oil

Drained the reverser gear case oil. Filled the reverser gear case with new synthetic gear oil.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26408	GREASE	1.00				N

Labor:

//9600 CMBW424 Retail

CORRECTION:

07 Service: Primary gear case

Drained the primary countershaft gear case oil. Filled the primary countershaft gear case with new synthetic gear oil.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

CONTINUED ON NEXT PAGE->

"Partnering Together to Nurture The Land"

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICE

JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012	JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012	Invoice Number: 1278704
		Invoice Date: 5/16/2016
		Location: 4
		Work Order Number: 201792
		Payment Type: Finance
Bus Phone:		
Prv Phone:		Page: 4 of 10
Mob Phone:		Technician Number: T444

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
1994 JOHN DEERE 9600	3580	H09600X660571	37393W	

//9600 CMBW424 Retail
TY26408

GREASE

N

Labor

//9600 CMBW183 Retail

CORRECTION:

08 Straw walker front LH crankshaft bearings, Replace

Supported the straw walker front crankshaft left hand side. Disconnected and removed the straw walker speed sensor and magnet. Disconnected and removed the straw walker front crankshaft left hand bearing. Replaced the straw walker front crankshaft left hand bearing, flanges, and lock collar. Installed and connected the straw walker front crankshaft left hand bearing, speed sensor, and magnet.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH133191	COLLAR-9600, 9760STS					N
AZ19427	BALL BEARING					N
H103265	PRESSED FL-9760STS					N

Labor:

//9600 CMBW32 Retail

CORRECTION:

09 Straw walker front blocks, R&R (w/greaseable metal blocks)

Disconnected and removed the upper grain pan and cross brace. Disconnected and removed the straw walker front metal blocks, seals, and locking rings. Replaced all five of the straw walkers front metal blocks, seals, and locking rings. Installed, positioned, and secured the locking rings for proper clearance and to minimize side play. Installed one grease line fitting that was damaged and one that was missing. Packed the straw walker front metal blocks with grease. Installed the straw walker front metal blocks and seals. Tightened the hardware to the proper specs. Rotated the straw walkers through the stroke several times to be sure there were no tight spots or binding. Installed and connected the upper grain pan. Welded the mounting flange back on the cross brace. Installed and connected the cross brace.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH141393	LOCKING CO					N

CONTINUED ON NEXT PAGE->

"Partnering Together to Nurture The Land"

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICE

JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012 Bus Phone: Prv Phone: Mob Phone:	JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012 Bus Phone: - - - - - Prv Phone: Mob Phone:	Invoice Number: 1278704 Invoice Date: 5/16/2016 Location: 4 Work Order Number: 201792 Payment Type: Finance Page: 5 of 10 Technician Number: T444
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
1994 JOHN DEERE 9600	3580	H09600X660571	37393W	

//9600 CMBW32 Retail

AH168158	BRG KIT-9600	N
AN71222	ADAPTER	N
H154216	SEAL-STRAW W	N
TY6341	GREASE	N

Labor:

//9600 CMBW354 Retail

CORRECTION:

10 Unloading auger limit switch update kit, Install

Disconnected the hydraulic valve logic module. Installed th unloading auger limit switch update kit. Routed and connected the wiring. I had to lengthen the wire at the limit switch area because it was not long enough to reach. Checked the unloading auger swing timer operations.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH163979	KIT-9600					N

Labor:

//DIAG150 Retail

CORRECTION:

11 Diagnose: The cleaning fan speed adjuster is not working

Cause:

Recommendation:

Checked the cleaning fan speed adjuster motor voltage and ground to the motor. Replaced the relays and retested the voltage and ground. Had good voltage and ground for proper operations. Disconnected and removed the cleaning fan speed adjuster motor. Checked the adjuster bolt to be sure it worked easily. Checked the motor operations. The motor would not run in either direction. Replaced the cleaning fan speed adjuster motor, Installed and connected the cleaning fan speed adjuster motor. Checked the cleaning fan speed adjuster operations, working fine now. Also replaced the tailings elevator paddle chain adjusting bolt on the outside of the elevator that was broken.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

"Partnering Together to Nurture The Land"

SERVICE INVOICE

Invoice To Account No: 11533

Deliver To:

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

Bus Phone:

Prv Phone:

Mob Phone:

Bus Phone:

Prv Phone:

Mob Phone:

Invoice Number: **1278704**

Invoice Date: 5/16/2016

Location: 4

Work Order Number: 201792

Payment Type: Finance

Page: 10 of 10

Technician Number: T444

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

1994 JOHN DEERE 9600

3580

H09600X660571

37393W

//9600 CMBW101 Retail
TY6342

LOW-VIS 5-GAL

N

Labor:

//9600 CMBW268 Retail
CORRECTION:

20 Cab air filters, Replace (Includes vacuuming outside air filter box & cleaning pre-cleaner)

Replaced the cab air filters. Cleaned the outside air filter housing and pre-cleaner.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH115833	FILTER					N
AH115836	FILTER					N

Labor:

INVOICE CONTAINS \$1.35 DISCOUNT

Miscellaneous Charges:
Service Accessories

Finance Information

Customer PO No:

Tax Exempt No: 2009

Advisor: LINDA FRANCIS

Type: Multi-use Acct US Auth. No: 456828

Merchant No: 37000228

Card No: :

Bill Code: 705 - JD COMBINE PARTS/SERVICE

Credit Plan: 11338 - NO PAYMENTS/NO INTEREST

Labor:

Parts:

OL&M:

Misc:

Sales Tax:

Grand Total: \$10,619.26

TERMS AND CONDITIONS

Repayment Terms: Customer Disclosure - This form must be signed by the customer to process the multi-use account transaction.

The following special terms, as described in the multi-use account credit agreement, apply to the attached invoice.

No Payments and No Interest until July 1, 2016. Following the deferral period, the ANNUAL PERCENTAGE RATE (APR) applicable to your Account will apply to this purchase.

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Returned goods must be accompanied with this invoice. A 15% handling fee will be charged unless due to defective goods or our error. Goods cut to length or special order goods are not returnable. NO RETURNS OR REFUNDS AFTER 30 DAYS.

Received by: _____ Date: _____

"Partnering Together to Nurture The Land"

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICE

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012

Bus Phone:

Prv Phone:

Mob Phone:

Bus Phone:

Prv Phone:

Mob Phone:

Invoice Number: **1278704**

Invoice Date: 5/16/2016

Location: 4

Work Order Number: 201792

Payment Type: Finance

Page: 6 of 10

Technician Number: T444

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

1994 JOHN DEERE 9600

3580

H09600X660571

37393W

//DIAG150 Retail

19M7596	16M X 160	N
AA77820	ELECTRIC M	N
AH201526	RELAY-9750,9760STS	N

Labor: _____

//DIAG75 Retail

CORRECTION:

12 Diagnose: The straw chopper upper door is damaged and needs replaced

Cause:

Recommendation:

Disconnected and removed the straw chopper upper door. Replaced the straw chopper upper door. Installed and connected the straw chopper upper door.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH142777	Extension					N

Labor: _____

//9600 CMBW724 Retail

CORRECTION:

13 Straw chopper floor, Replace

Disconnected and removed the straw chopper knifebank and floor. Replaced the straw chopper floor. Installed and connected the straw chopper floor and knifebank.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH143047	SHEET-9600					N

Labor: _____

CONTINUED ON NEXT PAGE->

"Partnering Together to Nurture The Land"

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICE

JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012	JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012	Invoice Number: 1278704
		Invoice Date: 5/16/2016
		Location: 4
		Work Order Number: 201792
		Payment Type: Finance
Bus Phone: -----	Bus Phone: -----	
Prv Phone: -----	Prv Phone: -----	Page: 7 of 10
Mob Phone: -----	Mob Phone: -----	Technician Number: T444
Make/Model:	Meter:	Serial Number:
1994 JOHN DEERE 9600	3580	H09600X660571
		Eq ID: 37393W
		Fleet No:

//9600 CMBW455 Retail

CORRECTION:

14 Straw walker metal blocks, Replace X5

Disconnected and removed all five of the straw walkers rear metal blocks, seals, and locking rings. Replaced the straw walker rear metal blocks, seals, locking rings, and grease zerks. Installed, positioned, and secured the locking rings for proper clearance and to minimize side play. Packed the straw walker rear metal blocks with grease. Installed and connected the straw walker rear metal blocks and seals. Tightened the hardware to the proper specs. Rotated the straw walkers through the stroke several times to be sure there were no tight spots or binding.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH141393	LOCKING CO					N
AH168158	BRG KIT-9600					N
H154216	SEAL-STRAW W					N
JD7759	LUBRICATIO					N
TY6341	GREASE					N

Labor:

//9600 CMBW158 Retail

CORRECTION:

15 Clean grain elevator lower RH bearing, Replace

Disconnected and removed the clean grain elevator lower right hand bearing cover and bearing. Replaced the clean grain elevator lower right hand bearing, flanges, and lock collar. Installed and connected the clean grain elevator lower right hand bearing and cover.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
E10018	PRESSED FL-9760STS					N
JD39103X	BEARING-TIMKEN--SMA					N

Labor:

CONTINUED ON NEXT PAGE->

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICEJELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012JELINEK FARMS
761 SE 110th AVE
BLUFF CITY KS 67018-9012Invoice Number: **1278704**

Invoice Date: 5/16/2016

Location: 4

Work Order Number: 201792

Payment Type: Finance

Bus Phone:

Prv Phone:

Mob Phone:

Page: 8 of 10

Technician Number: T444

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

1994 JOHN DEERE 9600

3580

H09600X660571

37393W

//9600 CMBW674 Retail

CORRECTION:

16 Straw walker front RH crankshaft bearings, Replace

Disconnected and removed the straw walker drive gear case. I had to pull the straw walker drive gear case off the shaft, it was rusted tight to the shaft. Supported the straw walker front crankshaft. Disconnected and removed the straw walker front crankshaft right hand bearing. Replaced the straw walker front crankshaft right hand bearing, spacer, and flanges. Cleaned the rust from the shaft and the gear case input gear bore. Installed and connected the straw walker front crankshaft right hand bearing and spacer, pressing the bearing to the proper location. Installed and connected the straw walker drive gear case.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH132823	BALL BRG-961	1				N
H103265	PRESSED FL-9760STS	1				N
H135519	SPACER	1				N

Labor: 1.00

//DIAG50 Retail

CORRECTION:

17 Diagnose: Transmission oil level is low and needs filled

Cause:

Recommendation:

Removed the transmission fill plug. Filled the transmission with new 80W90 gear oil. Installed the transmission fill plug.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6296	80/90 QTS	1				Y

Labor:

//9600 CMBW211 Retail

CORRECTION:

CONTINUED ON NEXT PAGE->

Invoice To Account No: 11533

Deliver To:

SERVICE INVOICE

JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012	JELINEK FARMS 761 SE 110th AVE BLUFF CITY KS 67018-9012	Invoice Number: 1278704
		Invoice Date: 5/16/2016
		Location: 4
		Work Order Number: 201792
		Payment Type: Finance
		Page: 9 of 10
		Technician Number: T444
Make/Model:	Meter:	Serial Number:
1994 JOHN DEERE 9600	3580	H09600X660571
		Eq ID: 37393W
		Fleet No:

//9600 CMBW211 Retail

18 Final drive axle couplers, R&R X2

Disconnected and removed both of the final drive couplers and drive shafts. Replaced both of the final drive outer couplers and drive shafts. Installed and connected both of the final drive couplers and drive shafts.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H165509	Shaft					N
HXE30611	SPLINED CO					N

Labor:

//9600 CMBW101 Retail

CORRECTION:

19 Service engine: Includes changing engine oil/filter, engine air filters, & fuel filters (bleed fuel system)

Changed the engine oil and filter. Replaced the engine air filters. Replaced the fuel filter and water separator filter. Bled the fuel system. Checked and filled the hydraulic/hydrostat oil reservoir.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR70106	FILTER ELE	1.00	60.00	60.00	60.00	N
AR70107	FILTER ELE					N
AR86745	FILTER ELE					N
AT81478	FILTER ELE					N
DZ101880	FILTER KIT					N
TY22000	1 GAL LOW VISC					N
TY26673	15W40 PLUS-50 II 1 GAL.					N
TY26675	PLUS-50 II 2 1/2 GAL 15W40					N
TY6341	GREASE					N

CONTINUED ON NEXT PAGE->

Combine

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Bus: 6;
Mobile

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 1 of 13

//9600 CMBW334 Retail

CORRECTION:

01 - Combine PerforMax Inspection (Walker)

___3400___ Engine Hours

___2274___ Separator Hours

Technician Comments: Performed the combine inspection. Made a list of the needed repairs to go over with the customer.
Figured an estimate of the needed repairs. Went over the list of needed repairs with the customer to see what he wanted us to fix.

Adjusted the belts and chains as needed. Greased the machine completely. Installed the shields removed for the inspection.
Ran out the machine after the repairs had been made.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
S4906	Service Promotion				N

Labor:

//9600 CMBWPU* Retail

CORRECTION:

02 - Customer furnished transportation

\$100.00 Credit when customer brings equipment in & back for scheduled Winter Service versus PLP hauling.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
S4906	Service Promotion				N

Labor:

//9600 CMBW655 Retail

CORRECTION:

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 2 of 13

//9600 CMBW655 Retail

03 - Concaves & cylinder bars, R&R (includes feeder house R&R)

Technician Comments: Installed the feeder house stand. Disconnected and removed the feeder house. Moved the feeder house out of the way.

Disconnected and removed the threshing door and hinge assembly, the shoe auger clean out door, and the stone trap door and deflector. The machine was packed with debris from the shoe augers to the concave. Cleaned out the debris between the concave and shoe augers. Removed every other cylinder bar to be able to remove the concave easier. Disconnected and removed the concave. Replaced the concave, the concave angle, and the missing beater grate eyebolt, cotter keys, and lock nuts for the eyebolts. Moved the concave adjuster shaft from the old concave to the new concave. Installed the concave angle. Installed and connected the concave.

Replaced the cylinder bars and hardware. Torqued the hardware to the specifications. Leveled and adjusted the concave. Set the concave stop and zero point. Installed and connected the feeder house. Removed the feeder house stand.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
11M7015	1/8 X 1				N
14M7400	M10 LOCK NUT				Y
14M7401	M12 LOCK NUT				Y
AH136604	CONCAVE-9600				N
AH151118	ANGLE-9600				N
AH205124	RASP BAR-960				N
AH205125	RASP BAR-960				N
AH205781	BOLT KIT-RAS				N
H144742	EYEBOLT-9600				N

Labor

//9600 CMBW8 Retail

CORRECTION:

04 - Feeder house wear strips, Replace (Plastic)

Technician Comments: Replaced the feeder house plastic wear strips and retaining nuts.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
-------------	-------------	----------	-----------	-------	-----------

Invoice To:

Deliver To:

SERVICE INVOICE

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**

Invoice Date: 1/20/2015

Branch: 4

Payment Type: Finance

Repair Order Number: 169464

Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600

Meter Reading: 3400

Serial Number: H09600X660571

Equipment Number: 37393W

Page: 3 of 13

//9600 CMBW8 Retail

14M7296 M10 FLANGE N

H148187 ANGLE-9600 N

Labor

//9600 CMBW155 Retail

CORRECTION:

05 -Feeder house lower RH shaft bearing, Replace

Technician Comments: Replaced the feeder house lower shaft right hand bearing, lock collar, and double sprocket.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH125782	SPROCKET-960	1			N
JD9201	LOCK/COLLAR	1			N
JD9202	BALL BEARI-9760STS	1			N

Labor

//9600 CMBW808 Retail

CORRECTION:

06 -Feeder house drive chain, R&R & adjust

Technician Comments: Replaced and adjusted the feeder house drive chain.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH145029	LINK CHAIN-9	1			N

Labor:

//9600 CMBW13 Retail

CORRECTION:

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 4 of 13

//9600 CMBW13 Retail

07 - Remove Feederhouse drum and install feederhouse floor patch

Technician Comments: Disconnected and removed the feeder house eyebrow. Disconnected the feeder house conveyor chain and moved it out of the way. Disconnected and removed the feeder house drum. Cleaned the feeder house floor to be able to install the patch. Positioned the floor patch and tack welded it in place making sure it was tight against the floor. Welded the patch panel to the floor solid. Ground down any spots of the weld that might catch product. Installed and connected the feeder house drum. Connected the feeder house conveyor chain using new "J" hooks. Installed and connected the feeder house eyebrow. Adjusted the feeder house conveyor chain.

Feederhouse floor patch panel.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
H84026	HOOK-9600	1	100.00	100.00	N

Labor:

//9600 CMBW12 Retail

CORRECTION:

08 - Feeder house primary drive belt, R&R

Technician Comments: Replaced and adjusted the feeder house primary drive belt.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
H151952	BELT-9600	1	100.00	100.00	N
M84309	5/16 PUSH NUT	1	100.00	100.00	Y

Labor:

//9600 CMBW547 Retail

CORRECTION:

09 - Header electromagnetic clutch, R&R, Recondition

Technician Comments: Disconnected and removed the header electromagnetic clutch and sheave. Inspected the clutch assembly. Cleaned the dirt and debris from the clutch assembly. Replaced the sheave bushings and seals. Checked the clutch air gap on the bench with the original shims and adjusted as needed. Installed the header electromagnetic clutch and sheave. Checked the sheave end play and found it to be fine using the original shims.

Invoice To:

Deliver To:

SERVICE INVOICE

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 5 of 13

//9600 CMBW547 Retail

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
24H1616	WASHER				N
AB5070R	SEAL-9610				N
H126716	BUSHING-9600				N

Labor:

//9600 CMBW27 Retail

CORRECTION:

10 - Beater drive belt set, Replace

Technician Comments: Replaced the beater belt set and the adjuster rod bushing. Adjusted the beater belt set.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
AH139436	BELT SET-961				N
H129207	PIVOT				N

Labor:

//9600 CMBW277 Retail

CORRECTION:

11 - Cleaning fan drive upper outer & inner sheaves, R&R

Technician Comments: Disconnected and removed the cleaning fan upper outer and inner drive sheaves. Sent the sheaves to Snake to be repaired. Replaced the outer sheave roll pin, seals, and throw out bearing. Installed and connected the cleaning fan upper inner and outer sheaves. Greased the outer sheave and throw out bearing.

Repair sheaves for cleaning fan.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
AH14080	SEAL-9760STS				N
AH229175	THROW-OUT-9600				N

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 6 of 13

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
//9600 CMBW277 Retail H100796	SPRING PIN-9	1.00	6.99	\$6.99	N

Labor:

//9600 CMBW575 Retail
CORRECTION:
12 - Grain tank vertical sump front wear plate, Install

Technician Comments: Installed the grain tank sump front wear plate (patch) panel using silicone along the edges. Drilled the holes needed to secure the panel on the sides and installed the hardware.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH207779	UNLOADING AUGER REPAIR KIT	1.00	78.66	\$78.66	N

Labor:

//9600 CMBW328 Retail
CORRECTION:
13 - Unloading auger drive chain, R&R

Technician Comments: Replaced and adjusted the unloading auger drive chain.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH126837	LINK CHAIN				N

Labor:

//9600 CMBW389 Retail
CORRECTION:
14 - Tailings elevator upper & lower drive chains, Replace

Technician Comments: Removed a half link from the tailings elevator paddle chain and adjusted the paddle chain. Replaced and adjusted the tailings upper and lower drive chains.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
-------------	-------------	----------	-----------	-------	-----------

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 7 of 13

//9600 CMBW389 Retail

AH126007	ROLLER CHA	N
AH126239	ROLLER CHA	N
H84026	HOOK-9600	N

Labor:

//9600 CMBW628 Retail

CORRECTION:
15 - Tailings lower 2 sprockets

Technician Comments: Replaced both of the tailings lower drive sprockets.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH121047	SPROCKET-961				N
AH130572	CHAIN SPRO-9				N

Labor:

//9600 CMBW41 Retail

CORRECTION:
16 - Straw chopper front drive belt, R&R

Technician Comments: Replaced and adjusted the feeder house front drive belt. Replaced the adjuster rod bushing (pivot).
Removed the front idler shield because it was cracked almost the length of the shield. Welded the crack of the front idler shield.
Painted the welded area and installed the front idler shield.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
H125380	BELT-9610				N
H129208	PIVOT-9610				N

Labor:

//9600 CMBW39 Retail

CORRECTION:

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 8 of 13

//9600 CMBW39 Retail

17 - Straw chopper hammers, Replace (Includes blowing out loop style)

Technician Comments: Removed the straw chopper rotary knife shafts. Blew out the loops on the straw chopper rotor.
Replaced the straw chopper rotary knives and one shaft retaining bolt and lock nut. Installed the rotary knives and shafts.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
AH128359	BLADE-CHOPPE				N
H128357	CAP SCREW				N
H143332	LOCK NUT				N

Labor:

//9600 CMBW973 Retail

CORRECTION:

18 - Clean grain elevator idler, Replace

Technician Comments: Replaced the clean grain elevator drive belt tightener pulley.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
AN15237	IDLER				N

Labor:

//9600 CMBW696 Retail

CORRECTION:

19 - Rotary screen drive belt, Replace

Technician Comments: Replaced the rotary screen drive belt (on the rotary screen).

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
H145158	BELT-9610				N

Labor:

//9600 CMBW176 Retail

CORRECTION:

20 - Radiator, condenser, & oil cooler, Wash

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 9 of 13

//9600 CMBW176 Retail

Labor:

//9600 CMBW574 Retail

CORRECTION:

21 - Clean grain elevator upper wear plate (rear curve of elevator), Weld in place

Technician Comments: Removed the clean grain upper shield, upper deflector door, and paddle chain adjuster linkage. Cut out the upper rear corner where the elevator was worn. Positioned and tack welded the elevator upper corner patch (hood). Made sure it was in place and welded the patch (hood) securely. Cleaned and painted the repaired area. Installed and connected the clean grain elevator paddle chain adjuster linkage, shield, and deflector door. Adjusted the clean grain elevator paddle chain.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH142629	HOOD-9600				N

Labor:

//9600 CMBW122 Retail

CORRECTION:

22 - Primary separator gear case input seal, Replace

Technician Comments: Disconnected and removed the separator drive shaft shields and shaft. Removed the panel in the grain tank above the primary separator drive gear case. Removed the primary separator drive gear case input nut, yoke, and seal. Replaced the seal and lock washer. Installed the input yoke, washers, and nut. Tightened the nut to specifications and locked one tab on the lock washer. Installed and connected the separator drive shaft and shields. Greased the separator drive shaft universal joints.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH137771	SEAL-9600,9760STS				N
H118920	LOCK WASHE				N

Labor:

//9600 CMBW881 Retail

CORRECTION:

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 10 of 13

//9600 CMBW881 Retail

23 - Light bulb warning/tail lights, R&R X 2

Technician Comments: Removed both of the tail lights. Inspected the tail light and side marker light bulb sockets. Replaced the left hand side marker light bulb and socket. Replaced the right hand tail light bulb and socket. Checked the light operations and installed the tail lights.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AH140120	KIT				N
AR62407	BULB				N
H133384	BULB				N

Labor:

//9600 CMBW101 Retail

CORRECTION:

24 - Service engine: Includes changing engine oil/filter, engine air filters, & fuel filters (bleed fuel system)

Technician Comments: Changed the engine oil and filter. Replaced the engine air filters. Replaced the fuel filter and water separator filter. Bled the fuel system.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
24H1307	WASHER				N
AR70106	FILTER ELE				N
AR70107	FILTER ELE				N
AR86745	FILTER ELE				N
AT81478	FILTER ELE				N
E12379	NUT				N
RE57394	OIL FILTER				N
TY26575	COOL-GARD II PRE-MIX GALLON				N
TY26673	15W40 PLUS-50 II 1 GAL.				N
TY26675	PLUS-50 II 2 1/2 GAL 15W40				N

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 11 of 13

//9600 CMBW101 Retail
TY6341 GREASE

N

Labor:

//9600 CMBW258 Retail

CORRECTION:

25 - Hydraulic/hydrostat, engine gear case, & charge pump filters, Replace

Technician Comments: Replaced the hydraulic/hydrostat oil filter, the engine gear case oil filter, and the charge pump oil filter. Replaced the engine gear case dipstick, the cap was broken loose allowing dirt past the cap. Topped off the hydraulic/hydrostat and engine gear case oil levels as needed.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
AH128449	HYD. FILTER				N
AH173464	DIPSTICK				N
TY22000	1 GAL LOW VISC				N

Labor:

//9600 CMBW268 Retail

CORRECTION:

26 - Cab air filters, Replace (Includes vacuuming outside air filter box & cleaning pre-cleaner)

Technician Comments: Replaced the cab air filters. Cleaned the outside air filter housing and precleaner.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
AH115833	FILTER				N
AH115836	FILTER				N

Labor:

//DIAG75 Retail

CORRECTION:

SERVICE INVOICE

Invoice To:

Deliver To:

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 12 of 13

//DIAG75 Retail

27 - Diagnose: Install clean grain elevator lower boot reinforcement

Cause:

Recommendation:

Technician Comments: Cleaned the clean grain lower boot area to have the reinforcement installed. Cleaned the paint from the reinforcement. Positioned and tack welded it in place. Welded the reinforcement securely in the lower boot. Ground down any spots that would catch product or the paddles. Ground the edge so it would not interfere with the door, the end three inches were past the boot.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
H175330	REINFORCEM				N

Labor:

//DIAG100 Retail

CORRECTION:

28 - Diagnose:

Cause:

Recommendation:

The clean grain elevator drivebelt tightener arm pivot is worn.

Technician Comments: Disconnected and removed the clean grain elevator drive belt tightener arm. Inspected the tightener arm pivot shaft and found no wear on the shaft. Replaced the tightener arm bushings and seals. Installed the tightener arm and checked the fit to the shaft. It fit fine. Removed the tightener arm and greased the bushings. Installed and connected the tightener arm.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
AA5607R	SEAL-9600,9760STS				N

Invoice To:

Deliver To:

SERVICE INVOICE

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

JELINEK FARMS
761 SE. 110th. AVE.
BLUFF CITY KS 67018-9012

Invoice Number: **1063458**
Invoice Date: 1/20/2015
Branch: 4
Payment Type: Finance
Repair Order Number: 169464
Technician Number: T444

Make/Model: 1994 JOHN DEERE 9600
Meter Reading: 3400
Serial Number: H09600X660571
Equipment Number: 37393W
Page: 13 of 13

//DIAG100 Retail
H171061

BUSHING-COMB

N

Labor:

Miscellaneous Charges
Service Accessories

Account No.: 11533
Bus. Phone:
Home Phone:
Mobile:
Customer PO No.:
Tax Exempt No.: 2009
Advisor:

Finance Information

Type: Multi-use Acct US Merchant No.: 37000228
Auth. No.: 264427
Card No.:
Bill Code: 705 - JD COMBINE PARTS/SERVICE
Credit Plan: 11311 -

Labor:
Parts:
Sublet:
Misc:
Sales Tax:
Total: \$12,101.54

*Thank you Jeff.
We appreciate your business!*


TERMS AND CONDITIONS

Document Terms: Customer Disclosure This form must be signed by the customer to accept the work and service provided.

Signed: Date: