

INVOICE DATE	
11/14/2017 09:37AM	
INVOICE NO.	PAGE
1273180042	1
CUSTOMER NO.	BRANCH
63463	* 1*

	PRICE/PER	EXTENSION
TERMS: (00) NET 10TH		
COMPLETION DATE: 11/14/2017		
UNIT: 128      YEAR: 2001      MAKE/MODEL: STERLING		
SERIAL: 2FZHAWAK52AJ70027      MILEAGE: 384291.4		
JOB#01 16 000 18 TRUCK/TRACTOR SUSPENSION SYSTEM, GENERAL REPAIR		
BROUGHT UNIT IN. REAR V-ROD BUSHINGS WORN. RAISED BED,		
REMOVED V-ROD. SINGLE BUSHING END WILL NOT HOLD A		
BUSHING. SNAP RING CHANNEL WORN FROM EXCESSIVE MOVEMENT,		
OF BLOWN OUT BUSHING. ADVISED CUSTOMER. ALSO RIGHT REAR		
SPRING SADDLE AND INSULATOR PADS NEED REPLACED.		
SADDLE BROKEN. PADS WORN.		
ORDERED PARTS. REPLACED V-ROD. REMOVED RIGHT REAR SADDLE		
ASSEMBLY. INSTALLED NEW SADDLE ASSEMBLY. REPLACED		
U-BOLTS AND TORQUED U-BOLTS. REPLACED LOWER PAD AND TOP		
PAD. REMOUNT SHOCK.		
TUFF TRAC SUSPENSION.		
PULLED UNIT OUT OF SHOP, TEST DROVE. RECHECKED.		
NO DEFECTS.		
1 AM MFL4891	LOWER PAD TUFTRAC	
1 AM MFL4893	UPPER PAD TUFTRAC 40K	
1 AM MFL138	V-ROD TUFTRAC 40K 54"RDA	
	FREIGHT INBOUND	
1 OV MFL46451	END PLATE	BIL
	(REF: 133946.00)	
	FREIGHT INBOUND	
2 DP 8T5820	THREADED ROD	
4 DP DN-58	5/8 DEEP NUT	
4 DP SUW-58	5/8 WASHER	
	MISC SUBTOTAL	
	PARTS SUBTOTAL	
	LABOR SUBTOTAL	
	SHOP SUPPLIES	
	** JOB SUBTOTAL	
JOB#02 01 000 18 CAB HEATING SYSTEM GENERAL REPAIR		
REPLACE HEATER CORE. CUSTOMER SUPPLIED REPLACEMENT IN		
CAB.		

INVOICE DATE	
11/14/2017 09:37AM	
INVOICE NO.	PAGE
1273180042	2
CUSTOMER NO.	BRANCH
63463	* 1 *

		PRICE/PER	EXTENSION
DRAINED COOLANT. REMOVED PANEL FROM PASSENGER SIDE.			
DISCONNECT LINES. REMOVED HEATER CORE. INSTALLED NEW			
HEATER CORE. RECONNECT LINES. SECURE CORE. FILLED			
COOLANT RESEVOIR. PRESSURE TEST, NO LEAKS. REMOUNT			
PANEL.			
2 EN	9404206021	ANTI-FREEZE 50/50 ROTELLA	
1 GA	84-8008	10PK RUBBER 2" CLAMP	
		PARTS SUBTOTAL	
		LABOR SUBTOTAL	
		SHOP SUPPLIES	
		** JOB SUBTOTAL	
		*TOTAL PARTS:	
		*TOTAL LABOR:	
		*TOTAL OTHER:	
		*TOTAL SHOP SUPPLIES:	

PLEASE PAY
# 2076.36
TERMS

PARTS INVOICE

F110146052:01

DATE INVOICE

06/12/2013

Payment

QTY SHP	QTY B/O	ITEM	DESCRIPTION	BIN 1	LIST PRICE	UNIT PRICE	EXTD PRICE
1		110X/64F8D250SB	REMAN DROP IN 250-300 HP	NOLOC			
1		110X/64F8D250SB-CORE	CORE	NOLOC			
		C	SN 64F8D250SB				

SUB-TOTAL	16,700.00
TAX	0.00
TOTAL	<del>16,700.00</del>

INVOICE DATE	
09/21/2015 11:19AM	
INVOICE NO.	PAGE
1252640072	1
CUSTOMER NO.	BRANCH
63463	* 1*

	PRICE/PER	EXTENSION
TERMS: (00) NET 10TH		
COMPLETION DATE: 09/21/2015		
UNIT: 128	YEAR: 2001	MAKE/MODEL: STERLING
SERIAL: 2FZHAWAK52AJ70027	MILEAGE: 350613.9	
JOB#01 11 000 18 STEERING AXLE, GENERAL, REPAIRS		
TEAR DOWN STEER AXLE FOR KING PIN REPLACEMENT. AXLE EYES ARE GOOD. RIGHT SPINDLE IS WIPED OUT, WILL NOT HOLD A BUSHING. CUSTOMER SUPPLIED A REPLACEMENT SPINDLE. SWAPPED ARMS OVER FROM OLD SPINDLE. REBUSHED SPINDLE. MOUNT RIGHT SPINDLE. REBUSHED AND MOUNT UP LEFT SPINDLE. CLEANED AND INSPECTED BEARINGS. BRAKE SHOES ARE ALMOST NEW. DRILLED COTTER PINS OUT FROM TIE ROD ENDS. REMOUNT TIE BAR, REPLACED COTTER PINS. REMOUNT BACKING PLATES. MOUNT UP HUB/WHEEL ASSEMBLIES, REPLACING WHEEL SEALS. MOUNT AND SEAL HUB CAPS. FILLED HUBS WITH LUBE, ADJUSTED BRAKES. GREASED KING PINS. CHECKED TOE SETTING.		
2 PE 4520	NON CHLOR BRK CLEAN 12.5OZ	
2 ST 383-0164	VOYAGER SEAL 6461A/555S	
2 ST 330-3009	GASKET CAN USE 330-3067	
1 EN 550022426	16GL SHELL SPIRAX 85W140	
	PARTS SUBTOTAL	
12.83 HOURS	LABOR SUBTOTAL	
	SHOP SUPPLIES	
	** JOB SUBTOTAL	
*TOTAL PARTS:		
*TOTAL LABOR:		
*TOTAL SHOP SUPPLIES:		

PLEASE PAY
# 1341.35
TERMS