## REQUEST FOR PO

**EXP** 

REQUESTIF	INIO		R. O. Number:	R00293700016014
Customer Number:	98272	Phone:	R. O. Number.	1100200.00
		50#	Service Date	Date Printed
Tax Status	Terms	P.O.#	2/27/2017	3/02/2017
EXP	CHARGE	N/A	2/2//2011	

Atchison Trucking 129 Walnut St Reading KS 66868-9037

# REQUEST FOR PO

Sortel Number Unit Number	Make / Model	Year Licen	se Number Mileage
Serial Number Unit Number 2HSEBASR5VC023979 11	NAVST/9300	1996	1

OPERATION

COMPLAINT: VIBRATION IN REAR - CHECK RIDE HEIGHT, DRIVELINE ANGLES,

AXLE ANGLES, TRANSMISSION ANGLES. PERFORM ALIGNMENT

VMRS CODE: 08-016-002-049-03-44

CORRECTION: REPLACE WITH NEW-TORQUE ROD-FRONT SPRINGS-WORN

BROUGHT TRUCK INTO SHOP. CHECKED SYSTEM. FOUND REAR DRIVE AXLES SHIFTED . BEGAN DISASSEMBLY. FOUND DOWELS ON LEAF SPRINGS WORN AND BRACKETS SHIFTED. HAD TO CUT, HEAT AND HAMMER TO GET HARDWARE LOOSE. CUT U BOLTS OFF. TORQUE RODS WERE WORN. AFTER DISASSY, CLEANED AND PREPPED AREA FOR NEW PARTS, WELDED BRACKETS ON. REASSEMBLED WITH NEW COMPONENTS

AND HARDWARE AS NEEDED. ALIGN VEHICLE. TEST DRIVE.

Labor Total --

TORQUE ROD S14653 STOCK U BOLT 8T1430 8 U BOLT NUT. DN78 8 U BOLT NUT. SUW78 LABOR BENDUBOLTS BEND-UBOLT

CONTINUED

## REQUEST FOR PO

Customer Numbe	r: 98272	Phone:	(620) 699-3325	R. O. Number:	R00293700016014
		PO#		Service Date	Date Printed
Tax Status	Terms CHARGE	N/A		2/27/2017	3/02/2017
EXP	CHARGE	1477			

OPERATION 1		
S14653 501535C2 579240C2 8T1430 DN78 SUW78	TORQUE ROD BUSHING SHOCK SPACER U BOLT STOCK U BOLT NUT. U BOLT NUT. LABOR BENDUBOLTS HEX CAP HEX CAP LOCK NUT 344806 LOCK NUT 1/2-13 34480 SAE FLAT GR8 3/8 SAE FLAT GR8 1/2 WASHER COTTER PIN 1/8X1 MACHINE ALIGN MACHIN FREIGHT CHARGE	1 4 1 4 8 8 8 4 16 4 16 4 32 8 8 8 4 1 1 60.00 Parts Total Total Operation 1 4,558.87

Labor Total
Parts Total
Shop Supplies
Sales Tax
Freight
Machine Charge

TOTAL DUE

5,400.95

DC 3563

SOLD TO:

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NU	MBER	INVOICE DA	TE	CUSTON	IER NO.	CUSTO	MER PUR	CHASE ORDER	NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
EB3127	73	02-22-	17	8751	100	* M	ARK A	TCHISON	*	KE	E		1	2
PSO/WO	NO.	DOC. DATE		PC	LC	MC			SHIP V	Α			INVOICE S	EQ. NO.
EB3127	73	02-10-	17	10	10	10								1
MAKE	MC	ODEL		S	ERIAL N	JMBER		EQUIPMENT	NUMBER	N	ETER RE	ADING	MACH.	ID NO.
AA	3406		05E	K9320	5			11		120	7752	2.0		
QUANTITY		ITEM		*N	/R		DES	SCRIPTION			UNIT P	RICE	EXTEN	SION

\* \* PROFORMA INVOICE \*

\* \* \*

- 1-INSTALL DRIVE LINE
- 2-REPLACE TRANSMISSION
- ---- TROUBLE SHOOTING ----
- 1-THE DRIVE LINE WAS REMOVED WHEN THE TRUCK WAS TOWED INTO THE SHOP AND WILL HAVE TO HAVE IT PUT BACK ON SO THAT IT CAN BE MOVED.
- 2-THE TRUCK TRANSMISSION HAS GONE OUT AND WILL HAVE TO BE REPLACED.
- ---- CAUSE ----
- 1-INSTALL TRUCK DRIVE LINE
- 2-TRANSMISSION
- ---- CORRECTION ----
- 1-THE DRIVE LINE WAS TIED DOWN THE SIDE OF THE TRUCK AND WILL HAVE TO BE TAKEN OFF AND PUT BACK ON.I HAD TO THEN ALIGN THE DRIVE LINE BACK IN PLACE AND BOLT THE U-JOINTS BACK IN PLACE.ONCE THE BACK DRIVE LINE IS SECURED AND IN PLACE I CAN THEN PUT THE MOVE THE TRUCK INTO THE SHOP.

  2-I WILL HAVE TO LIFT THE TRUCK AND PLACE IT ON JACK STANDS.I WOULD THEN HAVE TO REMOVE THE BOTTOM UNDER BRACKET ON THE FRAME.I THEN WAS ABLE TO REMOVE THE FRONT DRIVE LINE ON THE TRANSMISSION AND THEN REMOVE THE TRUCKS AIR LINES AND WIRE CONNECTORS TO THE TRANS.THE CLUTCH LEVER IS THEN REMOVED AND THE AIR LINES TO THE SHIFTER TOWER.

  I HAD TO THEN REMOVE THE MOUNTING BOLTS TO THE \*\*\* COVER ON THE SHIFTER TOWER.THE ONCE I AM ABLE TO

Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

\* - NOT RETURNABLE

PAY THIS
AMOUNT

CREDIT
AMOUNT

CREDIT

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NUM	//BER	INVOICE DATE	CUSTO	MER NO.	CUSTO	MER PURCH	ASE ORDER	R NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
EB31273	3	02-22-1	7 875	1100	* M	ARK AT	CHISON	*	KE	E		1	-
PSO/WO N	10.	DOC. DATE	PC	LC	MC			SHIP V	ΊΑ			INVOICE S	EQ. NO.
EB3127	3	02-10-1	7 10	10	10								
MAKE	M	ODEL		SERIAL NU	JMBER		EQUIPMEN	IT NUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	3406	0:	5EK932	05			11		120	7752	2.0		
QUANTITY		ITEM	*	N/R		DESC	RIPTION			UNIT P	RICE	EXTEN	SION

\* \* \* PROFORMA INVOICE \* \*

THANK YOU FOR PARTNERING WITH HOLT. IF YOU HAVE QUESTIONS REGARDING THIS INVOICE PLEASE CALL OUR EDINBURG SERVICE MANAGER AT (956) 289-7621

********	*******
* HOLT TRUCK SHOP	- SERVICE REPORT *
*******	******
( ) 1.STEAM CLEAN	( )19.CROSSMEMBER
(S) 2.ROAD TEST W/DRIVER	()20.EVACUATE A/C
(S) 3.ROAD TST WO/DRIVER	
( ) 4.RUN TEST	( )22.CAB MOUNTS
( ) 5.STD JAKE	( )23.MANUEVER INTO SHOP
( ) 6.349A JAKE	( )24.POWER TAKE OFF
() 7.PAINT	( )25.RAISE & LOWER CAB
(S) 8.INSTALL DRIVELINE	( )26.AIR TANKS
( ) 9.R & I FENDERS	
******	
( )11.RADIATOR BRKTS,	( )29.ECM HISTOGRAM
( )12.FLUSH COOLING SYS	
( )13.OIL COMTAMINATE	
( )14.SOUND SUPPRESSIONS	( )32.TEST PISTON
( )15.LINER PROJECTION	SPRAY TUBES
( )16.REAM ING. SLEEVE	( )33.ENGINE ENCLOSURE
( )17.BLOCK UNDERFRAME	( )34.DRAIN FUEL TANKS
( )18.FLUSH AFTERCOOLER	( )35.EXHAUST PIPE
CORE	
COMPLAINT	

Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

\* - NOT RETURNABLE

PAY THIS AMOUNT	>	CONT'D
CREDIT AMOUNT	>	

A SERVICE CHARGE OF 1.5% PER MONTH WILL BE CHARGED ON THE UNPAID BALANCE IF NOT PAID WITHIN TERMS.

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NU	MBER	INVOICE DA	ATE	CUSTON	ΛER NO.	CUSTO	MER PUR	CHASE ORDER	NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
EB3127	73	02-22-	17	8751	100	* M	ARK A	TCHISON	*	KE	E		1	3
PSO/WO	NO.	DOC. DAT	E	PC	LC	MC			SHIP V	lA			INVOICE S	EQ. NO.
EB3127	73	02-10-	17	10	10	10								1
MAKE	M	ODEL		S	ERIAL N	JMBER		EQUIPMEN	T NUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	3406		05E	K9320	5			11		120	7752	2.0		
QUANTITY		ITEM		*N	/R		DES	CRIPTION			UNIT P	RICE	EXTEN	SION

\* \* \* PROFORMA INVOICE

CLEAR ALL THE PART OFF THE TRANSMSSION I HAD TO DRAIN THE OIL AND REMOVE THE COOLER LINES ON THE BOTTOM OF IT. THEN I COULD PUT THE TRANSMISSION JACK UNDER AND SECURE IT.ALL OF THE TRANS HOUSING BOLTS ARE REMOVED AND I CAN PULL IT OUT. THE CUSTOMER WILL NOT REPLACE THE CLUTCH AND WILL STAY WITH SAME ONE ON. I HAD TO THEN REMOVE THE OLD TRANS AND PUT IT ON THE PALLET.I WAS ABLE TO FIND ALOT OF METAL ON THE OIL PUGS AND ALSO A LOCKING PIN FOUND AT THE BOTTOM. WOULD HAVE TO THEN PUT THE NEW TRANSMISSION ON THE JACK AND SECURE IT ON.I CAN NOW PUT THE NEW TRANS IN AND GET IT INTO PLACE AND MOUNT IT BACK ON. ONCE I HAVE IT IN I WOULD BOLT EVERTHING BACK IN PLACE AND PUT ALL THE PARTS BACK ON IN THE REVERSE ORDER THAT THEY WERE TAKEN OFF.A NEW OIL COOLER FOR THE TRANS IS PUT ON ALSO AND IS MOUNTED INTO PLACE OF THE OLD ONE.NEW OIL IS PUT INTO THE TRANS AND TOPPED OFF TO THE PROPER LEVEL.ALL OFF THE PARTS ARE NOW BACK ON AND SECURED. THE TRUCK IS NOW OK AND READY TO GO.

INSTALL DRIVE LINE/SHAFT

\* INSTALL DRIVE SHAFT (TRUCK TOWED IN)

F/R LBR

1.00

WRECKER FEE

Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

\* - NOT RETURNABLE

PAY THIS AMOUNT CONT'D

CREDIT AMOUNT

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NU	JMBER	INVOICE D	ATE	CUSTO	MER NO.	CUSTO	MER PURCH	ASE ORDER	R NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
EB3127	73	02-22-	-17	8751	100	* M	ARK AT	CHISON	*	KE	E		1	
PSO/WO	NO.	DOC. DAT	TE	PC	LC	MC			SHIP V	IA			INVOICE S	EQ. NO.
EB3127	73	02-10-	-17	10	10	10								
MAKE	M	ODEL			ERIAL NU	JMBER		EQUIPMEN	IT NUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	3406		05E	K9320	)5			11		120	7752	2.0		
QUANTITY		ITEM		*1	I/R		DESC	RIPTION			UNIT P	RICE	EXTEN	SION

\* \* \* PROFORMA INVOICE \* \*

TOTAL MISC CHGS

SEG. DL

SEGMENT DL TOTAL

-

#### TROUBLESHOOT TRANSMISSION

\* T/S; CHECK TRANSMISSION (POSSIBLE INTERNAL DAMAGE)

3	112812	SYN50 GAL TRANS F	LS
2	F59-10-8	FLARED MAKE 45 EL	NS
1	PSO16510SPWELL	TRANS PSO165 10S	S
1		CORE CHARGE	S
1-		CORE RETURN	N
1	528659C1	COOLER	S
4	803-130	CAP SCREWS	S

TOTAL PARTS SEG. TR

F/R LBR

1.00 IN-FREIGHT CHGS

TOTAL MISC CHGS SEG. TR

SEGMENT TR TOTAL

T

Fuel service charges do not include Texas state motor fuel taxes.

\* - NOT RETURNABLE

PAY THIS AMOUNT CONT'D

CREDIT AMOUNT

PLEASE REMIT TO:

A SERVICE CHARGE OF 1.5% PER MONTH WILL BE CHARGED ON THE UNPAID BALANCE IF NOT PAID WITHIN TERMS.

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NU	MBER	INVOICE DA	TE	CUSTON	MER NO.	CUSTO	MER PUP	RCHASE ORDE	R NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
EB3127	73	02-22-	17	8751	100	* M	ARK A	TCHISON	1 *	KE	E		1	ŗ
PSO/WO	NO.	DOC. DAT	E	PC	LC	MC			SHIP V	IA :			INVOICE S	EQ. NO.
EB3127	73	02-10-	17	10	10	10			4					
MAKE	MC	DDEL		S	ERIAL N	JMBER		EQUIPMEN	NT NUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	3406		05E	K9320	5			11		120	7752	2.0		
QUANTITY		ITEM		*N	/R		DE	SCRIPTION			UNIT P	RICE	EXTEN	SION

\* PROFORMA INVOICE

\* \*

SHP SUPPLY CHG

TX SALES TAX-EDIN. CITY SALES TAX (2%)

\* \* \* C A S H

\* \* \*



Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

\* - NOT RETURNABLE

PAY THIS AMOUNT	>	7769.20
CREDIT AMOUNT	>	

#### SALES RECEIPT

Date: February 22, 2017 Time: 11:31 AM

Authorization #: 001352

Your Cat Financial Commercial Account has been authorized for the amount below and will be charged to your account by your Dealer

when complete.

DEALER CUSTOMER PO AUTH CODE INVOICE/DOC CHARGE TRANSACTION **AMOUNT** NUMBER TYPE NUMBER NUMBER TYPE eb31273 \$7,769.20 eb31273 001352 Service Sale \$ 7,769.20 TOTAL

**Cat Financial Commercial Account** 

Company Name: ATCHISON TRUCKING INC

Account Name: MARC ATCHISON

Account #:

SHIP TO:

MARK ATCHISON UNIT #11

AA	3406	ITEM	05EK93205				11	1207775.0		.0		
MAKE	M	IODEL:	A 23 A	S	ERIAL NL	MBER	EQUIPMENT NUMBER	M	ETER RE	ADING	MACH.	ID NO.
		02-21-	17	7 10 10 10								
PSO/WO		DOC. DAT	E	PC	LC	MC	SHIP V	'IA			INVOICE S	EQ. NO
EB31297 02-22-17			8751	100	* MARK ATCHISON *		KE	K	260	1	1	
INVOICE NUMBER INVOICE DATE		ATE	CUSTO	MER NO.	CUSTOME	STORE	DIV	SALESMAN	TERMS	PAGE		

\* \* PROFORMA INVOICE

THANK YOU FOR PARTNERING WITH HOLT. IF YOU HAVE QUESTIONS REGARDING THIS INVOICE PLEASE CALL OUR EDINBURG SERVICE MANAGER AT (956) 289-7621

***************	****
* HOLT TRUCK SHOP - SERVICE REPORT	*
***********	****
( ) 1.STEAM CLEAN ( )19.CROSSMEMBER (X) 2.ROAD TEST W/DRIVER ( )20.EVACUATE A/C (X) 3.ROAD TST WO/DRIVER ( )21.RECHARGE A/C (X) 4.RUN TEST ( )22.CAB MOUNTS ( )5.STD JAKE ( )23.MANUEVER INTO ( )6.349A JAKE ( )24.POWER TAKE OFF ( )7.PAINT ( )25.RAISE & LOWER (	SHOP
( ) 8.INSTALL DRIVELINE ( )26.AIR TANKS ( ) 9.R & I FENDERS ( )27.P/S RESERVOIR ************************************	
( )11.RADIATOR BRKTS ( )29.ECM HISTOGRAM ( )12.FLUSH COOLING SYS ( )30.BUMPER ( )13.OIL COMTAMINATE ( )31.FLUSH LUB. SYST ( )14.SOUND SUPPRESSIONS ( )32.TEST PISTON ( )15.LINER PROJECTION SPRAY TUBES ( )16.REAM ING. SLEEVE ( )33.ENGINE ENCLOSUM ( )17.BLOCK UNDERFRAME ( )34.DRAIN FUEL TANK ( )18.FLUSH AFTERCOOLER ( )35.EXHAUST PIPE CORE	rem Re
COMPLAINT	

Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

\* - NOT RETURNABLE PAY THIS AMOUNT

PAY THIS
AMOUNT

CREDIT
AMOUNT

CONT'D

A SERVICE CHARGE OF 1.5% PER MONTH WILL BE CHARGED ON THE UNPAID BALANCE IF NOT PAID WITHIN TERROR

SHIP TO:

MARK ATCHISON UNIT #11

C

INVOICE NUMBER INVOICE DATE		ATE	CUSTO	MER NO.	CUSTOME	R PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE	
	EB31297 02-22-17		875	1100		K ATCHISON *	KE	K	260	1	FAGE	
PSO/WO		DOC. DA		PC	LC	MC	SHIP				INVOICE S	EQ. NO.
EB3129		02-21	- 1.7   	10	10	10   MBER	EQUIPMENT NUMBER	N/A	ETER RE	ADING		
AA 3406 051				K9320	)5		11	11 12077			MACH,	ID NO.

\* \* PROFORMA INVOICE

\* \* \*

- 1-CHECK ADJUSTMENT OF DRIVE LINE ANGLES.
- ---- TROUBLE SHOOTING ----
- 1-THE TRUCK IS MAKING A GRINDING SOUND WHEN DRIVING AT HIGH SPEEDS DOWN THE ROAD.WILL HAVE TO INSPECT AND CHECK TO SEE IF THE DRIVE LINES ARE NOT DAMAGED OR IF THERE IS A PROBLEM WITH THE ANGLES ON THE TRUCKS DRIVE LINE.THE TRUCK SHOWS TO HAVE SOME PROBLEMS AND MAY NEED TO HAVE SOME WORK DONE TO THEM.
- ---- CAUSE ----
- 1-ALL OF THE AXLE AND SPRINGS ARE LOOSE, EVERTHING HAS SHIFTED AND IS DAMAGED.
- ---- CORRECTION ----
- 1-I WOULD TEST DRIVE THE TRUCK AND WHEN HEADING AT HIGH SPEEDS THE TRUCK WOULD START TO GRIND. WOULD INSPECT THE DRIVE LINE AND CHECK ALL THE TRUCKS AXLES.THE TRUCK AXLE WERE SHIFTED AND ALL OF THE DRIVE LINES WERE OFF ALIGNMENT.THE REAR AXLES BOTH HAVE MOVED AND ALL OF THE TRUCKS ALIGNMENT AT THE BACK WAS OFF.THAT WAS CAUSING THE TRUCKS TO HAVE PROBLEMS WITH THE DRIVE LINE TO THE TRANS.WE WOULD LOWER THE AIR ON THE BACK DUE TO IT CAUSING THE AXLES TO THROW OFF THE ANGELS ON THE DRIVE LINE WHEN THEY WERE AIRED ALL THE WAY UP ON THE BACK.WHEN THE ALXE WAS LOWERED IN THE BACK ON THE AIR BAGS THE TRUCK DID NOT MAKE THE SOUND OF THE GINDING AS MUCH OR AS LOUD.THE REAR

Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

HOLT Truck Center P.O. BOX 650345 DALLAS, TEXAS 75265-0345 \* - NOT RETURNABLE

PAY THIS AMOUNT CONT'D

CREDIT AMOUNT

A SERVICE CHARGE OF 1.5% PER MONTH WILL BE CHARGED ON THE UNPAID BALANCE IF NOT PAID WITHIN TERMS

C

SOLD TO:

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NU			CUSTO	8751100 *			* MARK ATCHISON *			DIV	SALESMAN	TERMS	PAGE	
EB3129			8751							K	260	1	3	
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC			SHIP VI	A			INVOICE S	EQ. NO.
EB3129	EB31297 02-21-17		-17	10	.0   10   10									
MAKE	M	ODEL	(W/200)	S	ERIAL NU	JMBER		EQUIPMENT NO	JMBER :	M	ETER RE	ADING	MACH.	ID NO.
AA	3406	05EK93205					11			1207775.0				
QUANTITY		ITEM		*N	/R		D	ESCRIPTION			UNIT P		EXTEN	SION

\* \* \* PROFORMA INVOICE \* \*

SUSPESION WAS TO FAR THROWN OFF AND NEEDED TO BE REPAIRED BEFORE BE CAN RUN ANY OTHER TEST.ALL OF THE LIFT SPRING U-BOLTS AND SHACKELS WERE LOOSE AND CAN BE MOVED BY HAD.ALL OF THE AXLES WERE COMPLETLY OFF ALIGNMENT AND THE FRAME WAS CRACKED AT THE BACK. WE WOULD SEND THE TRUCK TO GET A 3 AXLE ALIGNMENT AND THE CUTOMER DID NOT WANT TO MAKE THE REPAIRS TO THE TRUCK. THEY WOULD TAKE THE TRUCK AS IS AND WILL NOT CORRECT THE PROBLM. THE TRUCK IS NOT SAFE TO BE DRIVING AS IS, AND MAY CAUSE DAMAGE TO THE TRANSMISSION. THE AXLES ARE COMPLETELY OFF AND ARE THROWING THE TRUCKS DRIVE LINE OFF AS WELL, BUT THE CUTOMER HAS REFUSED TO HAVE ANY OF THE ALIGNMET DONE AND WILL TAKE THE TRUCK AS IS.AT THIS POINT THE TRUCK IS STILL GOING TO MAKE THE SOUND AND IS NOT FIXED, BUT WILL LEAVE THE SHOP AS IS.AT THIS TIME THE SERVICE IS DONE AND THE TRUCK MAY LEAVE THE SHOP. THE CUSTOMER WILL TAKE THE RISK OF DRIVING THE TRUCK WITH THE PROBLEM AND IS RESPONSIBLE FOR ANYTHING THAT IS DAMAGED AFTER IT LEAVES OUR SHOP. THE TRUCK CAN NOW LEAVE THE SHOP.

NOTES: ALINGMENT SHOP PROVIDED AN ESTIMATE OF \$2,800.00 TO \$3,000.00 FOR THE NEEDED SUSPENSION REPAIRS. THIS ESTIMATE WAS PRESENTED TO THE CUSTOMER FOR REVIEW.

Fuel service charges do not include Texas state motor fuel taxes.

PLEASE REMIT TO:

\* - NOT RETURNABLE

PAY THIS AMOUNT	>	CONT'D
CREDIT AMOUNT	>	

SHIP TO:

MARK ATCHISON UNIT #11

C

INVOICE NU	NUMBER INVOICE DATE			CUSTOMER NO. CUSTOMER				RCHASE ORDER NU	STORE	DIV	SALESMAN	TERMS	PAGE	
EB3129	EB31297 02-22-17 8		8751	8751100 *			* MARK ATCHISON *			K	260	1	4	
PSO/WO	NO.	DOC, DA	ΓE	PC	LC	MC			SHIP VI	A ····			INVOICE S	EQ. NO.
EB3129	EB31297 02-21-17		-17	10 10 10									1	
MAKE	M	ODEL		S	ERIAL N	JMBER		EQUIPMENT N	UMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	3406	05EK93205						11		120	7775	5.0		
QUANTITY		ITEM		*N	/R		DE	SCRIPTION			UNIT P	RICE	EXTEN	SION

PROFORMA INVOICE

THE CUSTOMER DECIDED TO PERFORM THE NEEDED REPAIRS AT THEIR HOME BASE LOCATION. THE CUSTOMER WILL TAKE THE TRUCK AS IS, WITH AN UNDERSTANDING THAT THERE IS NO WARRANTY ON ANY OF THE WORK PERFORMED DUE TO THE DENIAL OF THE NEEDED SUSPENSION WORK.

CHECK DRIVE LINE/SHAFT

\* CHECK & ADJUST DRIVE LINE ANGLES

TOTAL LABOR SEG. DL

SEGMENT DL TOTAL

CHECK SUSPENSION SYSTEM REAR

\* CHECK REAR SUSPENSION

TOTAL LABOR SEG. RS

Fuel service charges do not include Texas state motor fuel taxes. PLEASE REMIT TO:

\* - NOT RETURNABLE

PAY THIS AMOUNT CONT'D CREDIT AMOUNT

SHIP TO:

MARK ATCHISON UNIT #11

INVOICE NU	INVOICE NUMBER INVOICE DATE EB31297 02-22-17		CUSTON	MER NO.	CUSTON	MER PURCHASE ORDE	STORE	DIV	SALESMAN	TERMS	PAGE		
EB3129			8751	100	* MA	RK ATCHISO	N *	KE	K	260	1 1	5	
PSO/WO	NO,	DOC, DA	ΓE	PC	LC	MC		SHIP V	IA.:			INVOICE S	EQ. NO.
EB3129	EB31297 02-21-17		-17	10	10	10							
MAKE	M	ODEL	335.000	S	ERIAL N	UMBER	EQUIPME	NT NUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	3406 05EK9320				205 11					1207775.0			
QUANTITY	3 100	ITEM	JOSE	*N			DESCRIPTION		120	UNITP		EXTEN:	SION

PROFORMA INVOICE

SEGMENT RS TOTAL

SHP SUPPLY CHG

TX SALES TAX-EDIN. CITY SALES TAX (2%)

CASH

PAID

FEB 2 2 2017

BY:=

Fuel service charges do not include Texas state motor fuel taxes.

\* - NOT RETURNABLE

PAY THIS 503.85 AMOUNT CREDIT **AMOUNT** 

PLEASE REMIT TO:

A SERVICE CHARGE OF 1.5% PER MONTH WILL BE CHARGED ON THE UNPAID BALANCE IF

NOT PAID WITHIN TERMS.

## SALES RECEIPT

Date: February 22, 2017 Time: 11:32 AM

Authorization #: 048581

You when complete.

has been authorized for the amount below and will be charged to your account by your Dealer

TRANSACTION

CODE

CHARGE TYPE INVOICE/DOC NUMBER DEALER CUSTOMER NUMBER PO NUMBER

AMOUNT

Sale

048581

Service

eb31297

8751100

eb31297

. . . . .

TOTAL

\$ 503.85

Cat Financial Commercial Account

Company Name: ATCHISON TRUCKING INC

Account Name: MARC ATCHISON

Account #: