

TRUCK #	YEAR	MILES	HOURS	DATE	WORK PERFORMED
52	2005	433		05 01 05	
52		6777	333	07 28 05	Service
52		15878		12 06 05	Replace Bolts In Hydraulic Pump
52		17997	787	01 20 06	Replace Fuel Filter & Water Seperator
52		20635	894	03 07 06	Service, Replace Fuel Filter & Water
					Seperator
52		26595	1109	05 31 06	Replace bucket & Calibrate Speedometer
		27884	1164	06 15 06	Replace outrigger interlock switch on
					right outrigger
52		29927		07 11 06	Replace hose at upper controls
52		32671	1389	08 01 06	Replace bucket, service, air filter
52		47880	2086	03 01 07	Replace radiator, service, fuel, air,
					water-fuel seperator
52		199066	9025	12/4/2014	repair left fuel tank
52		201239	9140	02 16 15	Replace transmission output speed
					sensor
52		203467	9238	3/31/2015	DOT Inspection
52		203757	9250	4/8/2015	Service, Replace Fuel Filter & Water
					Seperator, Replace fan hub
52		203934	9257	4/9/2015	repair air leak
52		204273	9271	4/15/2015	road call. Make temp repair for air leak
52		205846	9345	5/11/2015	replace front shocks,firewall air manifold
					and rear brake fittings
52		208185	9415	06 03 15	Repair upper control linkage and replace
					o-rings in 2 spool valves
52		208982	9503	08 03 15	Repair wiring at low pressure switch.
52		209070	9508	08 04 15	Replace blower motor and motor resistor
52		210951	9604	9/1/2015	Service, DOT Inspection
52		216379	9878	12 09 15	Repair fuel tank sending unit wiring, drill
					out broken cab bolt and install new bolt
52		216397	9878	12 18 15	Repair and adjust right door latch,
					replace radiator
52		218183	9970	02 10 16	Replace batteries, check charging system
					repair battery hold down and spot light
					wiring.
52		219921	10065	03 02 16	Service,replace oil, fuel, air filters, water/