

03/07/2018 10:45:25 am

Page: 1

Fleet Management

Fleet Asset Service History

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Type	Service Technician
18	2005 STERLING/ALTEC BUCKET	12 - ENGINE REPAIR/TUNE UP	06/30/2017	159,513.00	Hours	
	Service Detail: Vendor: 23112 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: DISGNOSE OIL LEAK: REPLACED HOSE ASSEMBLY TO HIGH PRESSURE PUMP, RESEAL OIL MANIFOLD.					
18	ENG HRS = 12,077 2005 STERLING/ALTEC BUCKET	13 - OIL & FILT	06/30/2017	159,513.00	Hours	
	Service Detail: Vendor: 23112 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: LUBE, OIL, & OIL FILTER CHANGE					
18	ENG HRS = 12,077 2005 STERLING/ALTEC BUCKET	14 - BRAKES	06/02/2017	158,611.00	Hours	
	Service Detail: Vendor: 5101 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
18	Comments: REMOVE AND REPLACE RIGHT FRONT STEER AXLE SHOES; ADJUSTED BRAKES 2005 STERLING/ALTEC BUCKET	15 - BATTERY	01/18/2018	12,354.00	Hours	46 - TERRY LYON
	Service Detail: Vendor: Cost: 0.00 SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
18	Comments: install recharged batteries, check and order heater motor switch. 2005 STERLING/ALTEC BUCKET	15 - BATTERY	01/15/2018	12,354.00	Hours	46 - TERRY LYON
	Service Detail: Vendor: Cost: 0.00 SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: remove, clean and charge batteries, load test batteries					
18056						128md

03/07/2018 10:45:25 am

Page: 2

Fleet Management

Fleet Asset Service History

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
18	2005 STERLING/ALTEC BUCKET	16 - FUEL SYST	06/30/2017	159,513.00	Hours	
	Service Detail: Vendor: 23112 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: REPLACE FUEL FILTERS					
	ENG HRS = 12,077					
18	2005 STERLING/ALTEC BUCKET	17 - ELECT SYST	06/02/2017	158,611.00	Hours	
	Service Detail: Vendor: 5101 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: REMOVE AND REPLACE REAR CENTER MARKER LIGHT; REPLACE RIGHHAND SIDE TURN LIGHT LENS					
18	2005 STERLING/ALTEC BUCKET	18 - COOLING SY	07/20/2017	160,460.00	Hours	
	Service Detail: Vendor: 23112 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: RAN DIAGNOSTIC COMPUTER SCAN; REMOVED AND REPLACED LOW COOLANT MODULE					
18	2005 STERLING/ALTEC BUCKET	18 - COOLING SY	06/30/2017	159,513.00	Hours	
	Service Detail: Vendor: 23112 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: SERVICE A/C: REPLACED A/C COMPRESSOR, REPAIR LEAKS, & RECHARGE SYSTEM					
	ENG HRS = 12,077					
18	2005 STERLING/ALTEC BUCKET	24 - MISC PARTS	11/09/2017	0.00	Hours	
	Service Detail: Vendor: 5101 Cost: SR:	Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:				
	Comments: PART - SOLENOID HEATER (TL)					
	18056*					128md

03/07/2018 10:45:25 am

Page: 3

Fleet Management

Fleet Asset Service History

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
18	2005 STERLING/ALTEC BUCKET	24 - MISC PARTS	11/08/2017	0.00	Hours	
	Service Detail:	Standard Service Information:				
	Vendor: 5101	System Level:				
	Cost:	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
	Comments: PARTS- AIR DRYER AND AIR GOVERNOR (TL)					
18	2005 STERLING/ALTEC BUCKET	25 - ASSOC EQUI	02/01/2017	0.00	Hours	
	Service Detail:	Standard Service Information:				
	Vendor: 12020	System Level:				
	Cost:	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
18	Comments: REPAIRS TO HEATER DAMPER 2005 STERLING/ALTEC BUCKET	27 - BODY REPAI	06/01/2017	0.00	Hours	
	Service Detail:	Standard Service Information:				
	Vendor: 1044	System Level:				
	Cost:	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
18	Comments: REPAIRED HEADLIGHT BEZEL AND AIR VENT. 2005 STERLING/ALTEC BUCKET	29 - MISC EXPNS	11/08/2017	12,259.00	Hours	46 - TERRY LYON
	Service Detail:	Standard Service Information:				
	Vendor:	System Level:				
	Cost: 0.00	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
	Comments: Troubleshoot low air pressure, air governor is bad and air dryer is leaking air. go to emporia to get parts, replaced air governor and air dryer, check operations. air consistently builds to 125 PSI.					

18056 .

128md

03/07/2018 10:45:25 am

Page: 4

Fleet Management

Fleet Asset Service History

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
18	2005 STERLING/ALTEC BUCKET	29 - MISC EXPNS	06/02/2017	158,611.00	Hours	
	Service Detail:	Standard Service Information:				
	Vendor: 5101	System Level:				
	Cost:	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
	Comments: ANNUAL D.O.T. INSPECTION					
18	2005 STERLING/ALTEC BUCKET	34 - HYD MISC	04/17/2017	158,222.00	Hours	
	Service Detail:	Standard Service Information:				
	Vendor: 20042	System Level:				
	Cost:	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
	Comments: REMOVED AND REPAIRED LEAKING HYDRAULIC TANK; REINSTALLED & CHECKED FOR LEAKS					
	ENG HRS = 11,992					
18	2005 STERLING/ALTEC BUCKET	36 - BUCKET	01/23/2017	0.00	Hours	
	Service Detail:	Standard Service Information:				
	Vendor: 1053	System Level:				
	Cost:	Repair Reason:				
	SR:	Part Failure:				
		Work Accomplished:				
	Comments: QTY 1 - BUCKET TOOL TRAY (SECTIONAL)					

18056.

128md

03/07/2018 10:45:25 am

Page: 5

Fleet Management
Fleet Asset Service History**PARAMETERS ENTERED:****Fleet Asset:** 18**Location:** All**Class:** All**Service Code:** 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 25, 26, 27, 29, 31, 32, 33, 34, 35, 36, 37, 38**Closed Date:** 01/02/2017 To 03/07/2018**Service Technician:** All**Vendor:** All**Service Detail:** Yes**Standard Service Information:** Yes**Comments:** Yes

?

18056 .

128md