

PC0915

Invoice

Date	Invoice #
10/3/2017	122031

Bill To
American Iron Construction

Year/Make/Model/Mileage		VIN	P.O. No.
Quantity	Description	Rate	Amount
	Belly Dump Trailer Tag# 781-732 Dot inspect trailer. Replaced leaking wheel seals on LR & RF of trailer, brake shoes at both locations, brake drum on RF, replaced bad brake chamber on RR of trailer, all four axle hub caps 1 DOT Inspection-Trailer 2 Brake Kit - 4707/Q-Plus 1 Brake Drum 2 Wheel Seal 4 Hub Cap 2 QT 75W 90W SYN 3 Can Of Cleaner 1 Shop Charge 1 DOT Inspection-Trailer 1 Semi-Truck Flat/Mount 1 Brake Chamber 5 Labor		
Signature:		Subtotal	
		Sales Tax (5.313%)	
		Total \$1,386.90	

A finance charge of 2% per month will be assessed on accounts not paid in full by due date.
 When purchasing new tires, flat, or services you the customer will need to tighten the lug nuts after 50-100 miles of service