PC 8920

Invoice

Date	Invoice #	
2/3/2017	120221	

Bill To		
American Iron	Construction	

	Year/Make/Model/Mileage VIN		P.O. No.
Quantity	Description	Rate	Amount
	Peterbilt Dump Truck Vin# 287710 Miles 570,128 The front steer axle, drive line & rear ends do not match the Vin# of truck, front diff is a SQ100 Dot inspect truck, repair as need pass Dot. Replaced brake shoes on all three axles, replaced hub left front steer axle due to bearing races have spun and damaged hub, wheel seal on right front steer axle, both torque rods at both rear ends, tie rod end & tube assembly, repair lights on truck, moreverse lights on rear, wire in city horn, repair air leaks in dash, replaced two u-joints on drive line, front diff input seal, yoke & replace al four air bags on rear Wiper blades Low Air Pressure Switch Flasher Heavy Duty Back Up Light Switch Torque Rod Air Bag STUD NUT Wheel Stud NUT Steer Axle Brake Kit Drive Axle Brake Kit Wheel Seal Pinon NUT STUD Steer Axle Hub	i to on h ount	
		Subtotal	
Signature:	Signature:		13%)
		Total	

Invoice

Date	Invoice #	
2/3/2017	120221	

Year/Make/Model/Mileage		Year/Make/Model/Mileage VIN	
Quantity	Description	Rate	Amount
40	Labor	90.00	3,600.00
		Subtotal	\$7,414.92
Signature:		Sales Tax (5.313%	\$189.14 \$7,604.06

A finance charge of 2% per month will be assessed on accounts not paid in full by due date.

When purchasing new tires, flat, or services you the customer will need to tighten the lug nuts after 50-100 miles of service

90 0920



INVOICE

Bill To	
American Iron Construction	
Account #	

Due Date	P.O. No.	Terms		Job#	Invoice #
11/15/2016	Verbal	COD	НО	1163370	9429
Item	Descrip	tion	Qty	Rate	Amount
RR/Cylinder RR/Equipment NS/Hydraulic Oil RR/Equipment Labor Incoming Freight Environmental an	Telescopic cylinder Remove air circuits and clos Hydraulic Oil AW 46 Refurbish cylinder base pin Labor Charges Incoming Freight Environmental and Supplies Dump truck expense		1 15 16 1 1	Subtotal Sales Tax (8.3	
Phone #	Fax #	E-ma	il	Total	200 C C C C C C C C C C C C C C C C C C
				Balance Due	\$0.00

000920 933692 2-17-17 Statement American TRON CONST. Chisholm TRAIL PainT SANdblasT PREP materials Lphor To Paint Pd IN Full TUTAL AMOUNT 4000

DC0920

Invoice

Invoice Number:

143899

Invoice Date: 12/6/2016

Terms

Net 30

Bill To:

SPORTS FACILITY RESOURCES

		P.O. Number	Due Date	Ship Via
		383	1/5/2017	
Quantity	Unit	Description	Price Each	Amount
1990 Pet Dump True	FIX DRIVER I ON TAILGATI NEW CLIPS F PUT NEW PIF MADE TAILG.	I BED, FIX CRACK AT FRONT, CUT TOOLBOX OF COOR, FIX LATCH FOR TAILGATE, PUT NEW HIS, OR SPRING FOR TARP OR SPRING FOR TARP OF FOR TARP AND HINGES ATE WIND CRACK IN GATE SON BACK BLOW TAILGATE	NGES .	
You can pay invoices online!!! Call us for details. Please Note: All Unpaid Balances Over 30 Days will be subject to a Finance Charge of 1.5%		Subtotal		
REMIT TO: PO		Month.	Sales Tax (5.313%)	
STII	LLWATER, OK 74076		Total	*
Purchaser certifies that under penalty of perjury that he is engaged in:farmingresalemfg and property will be for said operations.		Payments/Credits		