Branch Ship fo: ABILEZ CONSTRUCTION OKC ANYYYY Date Time Page 07/12/16 15:14:12 (0) 01 Account No. Phone No. ABILE001 PICPAK Ship Via Purchase Order Invoice To: ABILEZ CONSTRUCTION UPS RED Tax ID No. Salesperson TL1 PACKING SLIP - NOT AN INVOICE ONDER#: 014694.02

WE APPRECIATE YOUR BUSINESS!!

Part# Description Bin ORD ISS SHP B/O UTTT Price Amount

276467001 SWITCH - LIMIT D-8 1 1 * **

SUB TOTAL==>
OKLAHOMA STATE 4.5%
CIMARRON COUNTY
BOLSE CITY
ON ACCOUNT

PLEASE REMIT TO:

www

lains.com

Invoice To: ABILEZ CONSTRUCTION

OKC		CNNYYY
Date	Time	Page
07/01/16	11:21:04 (0	0)
Account No.	Phone No.	Invoice No.
ABILE001		P14556
Ship Via	Purchase Ord	der
Tax ID No.		
Terms		Salesperson
NET 30	WAC	RP1

PARTS INVOICE

ORDER#: 014547

WE APPRECIATE YOUR BUSINESS!!

Part#	Description	Bin	ORD	ISS	SHP	в/о	UTTTT	Price	Amount
358012	BOLT-1/2-13 X 1	H-5	1	1	1		* *		
93370001	RETAINER	NON-STK	1	1	1		* *		
480011	WASHER-1/2 S/T	H-5	1	1	1		* *		
101519003	ULTRA GOLD HY-F	OUTSIDE	2	2	2		* *		

SUB TOTAL ==> OKLAHOMA STATE 4.5% OKLAHOMA CITY ON ACCOUNT

271.25

PLEASE REMIT TO: 8300 N. I-35 SERVICE RD, OKLAHOMA CITY, OK 73131

Invoice To: ABILEZ CONSTRUCTION

Branch		
OKC		CNNYYY
Date	Time	Page
08/19/16	13:44:52 (0) 01
Account No.	Phone No.	Invoice No.
ABILE001		P15345
Ship Via	Purchase O	rder
STOCK		
Tax ID No.		
Terms		Salesperson
NET 30	WAC	TL1

PARTS INVOICE

ORDER#: 015128

WE APPRECIATE YOUR BUSINESS!!

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTT	r Price	Amount
246356001	GEAR - 8 DP 32	S05848-	1	1	1		*	*	
526003	SSS-3/8-16X3/4	S05848-	1	1	1		*	*	
526003	SSS-3/8-16X3/4		1-	1-	1 -		*	*	
277660001	ROCKER SWITCH-F	NON-STK	1			1	*	*	

SUB TOTAL==>
OKLAHOMA STATE 4.5%
OKLAHOMA CITY
ON ACCOUNT

138.95

PLEASE REMIT TO: 8300 N. I-35 SERVICE RD, OKLAHOMA CITY, OK 73131

Invoice To: ABILEZ CONSTRUCTION

OKC	-	CNNYYY
Date	Time	Page
08/05/16	13:36:33 (0	01
Account No.	Phone No.	Invoice No.
ABILE001		P15082
Ship Via	Purchase Or	der
CPU	NICK	
Tax ID No.		
Terms		Salesperson
NET 30	WAC	TL1

PARTS INVOICE

ORDER#: 015089

WE APPRECIATE YOUR BUSINESS!!

Part# Description Bin ORD ISS SHP B/O UTTTT Price Amount

1615 MICRO-MIST 1-4 3 3 3 * * *

SUB TOTAL==
OKLAHOMA STATE 4.5
OKLAHOMA CII
ON ACCOUNT 27.64

PLEASE REMIT TO: 8300 N. I-35 SERVICE RD, OKLAHOMA CITY, OK 73131

NO RETURNS WITHOUT INVOICE NO RETURNS AFTER 30 DAYS 25% RESTOCK FEE ON ALL SPECIAL ORDERED ITEMS

CASH TICKET

Date	REF. #	
10/3/2016	39885	

SALE

Sold To	
Abilez Construction (csh)	

Check No.	Pn	n't. Method		P.O.	#
	M	aster Card			
Item	Qty	1	, , , , , , , , , , , , , , , , , , ,	List	Amount
MAR 251	1	2517 MARTIN taper-lok bushing X 1 1/2" bore		49.20	
Ber B-12	1	Berryman B-12 Chemtool		24.50	
S & H	1	S & II Shipping & Handling			
		Į.			
				12.	

Received by:

Subtotal

Sales Tax (8.375%)

Total

Z\$60.43

Phone #	Fax #	E-mail
•	-	

Invoice To: ABILEZ CONSTRUCTION

Branch				
OKC			Cl	NYYY
Date	Time			Page
10/10/16	08:	56:56 (0))	01
Account No.	Phone No	o.	Inv	oice No.
ABILE001			P	L6169
Ship Via		Purchase Or	der	
CPU		BUTLER		
Tax ID No.				
Terms		5	Salesper	son
NET 30	WAC		TLI	L

PARTS INVOICE

ORDER#: 016139

WE APPRECIATE YOUR BUSINESS!!

Part# Description Bin ORD ISS SHP B/O UTTTT Price Amount

282642001 MAGNET - 1.25" D-6 2

SUB TOTAL:--OKLAHOMA STATE 4.5% OKLAHOMA CITY ON ACCOUNT

PLEASE REMIT TO:

Ship To: Abilez Construction

Invoice To: ABILEZ CONSTRUCTION

OKC Date	Time			Page
06/30/17	11:	33:33	(0)	01
Account No. ABILE001	Phone No		Inv	oice No.
Ship Via		Purchase (73231
Tax ID No.				

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

C9000347

D33X44 NAVIGATOR W

3986 1VTR180R4Y1000368

D33X44

WE APPRECIATE YOUR BUSINESS!!

REPAIR# 1 C HO34 A006V

03/29/17 04/06/17

A006 - BASIC EQUIPMENT INSPECTION

COMPLAINT:

Courtesy machine inspection

CORRECTION:

Tech completed courtesy machine inspection.

ADDITIONAL DESCRIPTION:

NJ - SHOP - 3/29/17

OWNED: Abilez Construction CONTACT: Ruben Abilez @

No Warranty Remaining No Open Campaigns

10100001

REPAIR# 2 C HO34 MULTIPLE

03/29/17 04/06/17

NJ - SAFETY FEATURES INOPERABLE

COMPLAINT:

Customer says safety features not working (when drilling it would not change to high or low gear; when pulling drill head back arm would not retract; front pipe would come back in but back would stay out)

CAUSE:

Internal failure of anticrash switch, speed coils burned, and failed thrust speed coil

CORRECTION:

Tech inspected machine; found rod arm anticrash switch had

CONTINUED ON PAGE 02

Ship To: Abilez Construction

Invoice To: ABILEZ CONSTRUCTION

Branch OKC				
Date	Time		Page	
06/30/17	11:	33:33 (0) 02	
Account No.	Phone No		Invoice No.	
ABILE001			W05257	
Ship Via		Purchase O		
Tax ID No.				
Terms NET 30	WAC		Salesperson	
			NJ1	

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

C9000347

D33X44 NAVIGATOR W 3986 1VTR180R4Y1000368

failed. Also found bad wire to rod arm in coil; arm will not go in. Tech able to apply power to wire and arm will go in; found to be broken in wire harness (loom). Tech also found wires to three speed coils to be burnt and not working right properly; also to two speed coil for thrust. Tech replaced front wiring harness, anticrash switch, and rear arm barrier switch. Tested; working normally.

NOTE: Tech had difficulty removing old harness due to age of machine, harness, and past "add-in" repairs; had to cut in several places.

ADDITIONAL DESCRIPTION:

- 1. 0000 Diagnostics (0000V)
- 2. 1L00 ELECTRICAL REPAIR (1L00V)

Quantity

251117009	COIL - #8	1
276467001	SWITCH - LIMIT	1 S
277733001	HARNESS - FRONT	1 N
281844001	SWITCH - LIMIT	1 N

PARTS

LABOR

10100001

REPAIR TOTAL ==>

REPAIR# 3 C HO34 MULTIPLE

03/29/17 04/07/17

4L00 - HYDRAULIC LABOR

COMPLAINT:

Machine has hydraulic leak

CONTINUED ON PAGE 03

An Employee Owned Company

Ship To: Abilez Construction

Invoice To: ABILEZ CONSTRUCTION

OKC Date	Time	Page			
06/30/17	11:33:33 (0	03			
Account No.	Phone No.	Invoice No.			
ABILE001		W05257			
Ship Via	Purchase Or	Purchase Order			
Tax ID No.					
Terms		Salesperson			
NET 30	WAC	NJ1			

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

C9000347

D33X44 NAVIGATOR W 3986 1VTR180R4Y1000368

D33X44

CAUSE:

Failed o-ring on dump valve fitting

CORRECTION:

Tech found failed o-ring on fitting on dump valve. Tech replaced o-ring as needed and tested; no leaks detected. ADDITIONAL DESCRIPTION:

- 1. 0000 Diagnostics (0000V)
- 2. 4L00 HYDRAULIC LABOR (4L00V)

Quantity

10100001

LABOR

REPAIR TOTAL ==>

***** WORK ORDER TOTALS *****

PARTS

LABOR

ENVIROMENTAL

SUB TOTAL ==>

OKLAHOMA STATE 4.5%

OKLAHOMA CITY

ON ACCOUNT

2791.67

PLEASE REMIT TO:

An Employee Owned Company

Ship To: SAME AS BELOW

Invoice To: ABILEZ CONSTRUCTION

Branch OKC		C	NYYY		
Date	Time	C.	Page		
07/25/17	13:47	:38 (0)	01		
Account No.	Phone No.	Inv	Invoice No.		
ABILE001		P	20647		
Ship Via STOCK	Pui	chase Order			
Tax ID No.					
Terms		Salesper	son		
NET 30	TL	TL1			

PARTS INVOICE

ORDER#: 020203

WE APPRECIATE YOUR BUSINESS!!

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTT	TT	Price	Amount
296264832	ROCKER SWITCH -	S07597-	1	1	1		*	*		
296264833	ROCKER SWITCH -	S07597-	1	1	1		*	*		
277660001	ROCKER SWITCH-F	S07597-	1	1	1		*	*		
277701001	SWITCH - ROCKFI	C-8	1	1	1		*	*		

SUB TOTAL==>
OKLAHOMA STATE 4.5%
OKLAHOMA CITY

ON ACCOUNT

314.86

TL

PLEASE REMIT TO: