

EI 98354

#20---2005 FORD THOMAS 16 PASS

1FDXE45P66HA12818

	DATE	Amount	Repair/Maintenance/Vendor
2005-2006	3/7	642.00	1 new radio 436.00, installed radios 150.00, power cord 19.00
			2 antennas 36.00
	TOTALS	642.00	
2006-2007	11/28	8.50	flat repair
	TOTALS	8.50	
2007-2008	7/11	460.40	replace and install radio, replace turbo and down pipe, replace catalytic converter
	8/22	15.00	flat repair
	1/21	662.23	inspect and repair brake pads
	3/7	580.17	service transmission, 2 wiper blades, replace fuel filters, replace air filter
	4/4	270.50	2 new tires and flat repair
	6/24	561.00	4-225/75/16 tires
	TOTALS	2,549.30	
2008-2009	8/25	158.95	replace 2 blown fuses, wash condenser, added 2 lbs of freon, found bad ground on relay panel.
	8/25	78.97	Installed mud flaps
	1/21	45.47	repair gear shift
	4/24	872.64	upper bal joints, lower bal joints, bushings, alignment 2 tires
	5/8	102.45	replace fuel filters
	6/10	89.75	2 front clearance lights
	Totals	1,348.23	
2009-2010	8/13	67.93	stop arm and amber lights are inop
	8/19	589.52	battery light comes on when you slow down
	10/22	192.02	service 1of med duty
	12/22	112.66	strobe light on top of bus is inop, reverse buzzer is inop
	5/21	338.53	2 batteries
	5/10	178.04	loose battery cable
	Totals	1,478.70	
		6,026.73	

#20---2005 FORD THOMAS 16 PASS

1FDXE45P66HA12818

	DATE	Amount	Repair/Maintenance/Vendor
2010-2011	8/12	54.95	tailpipe bracket broken
	8/23	627.66	installed no child left behind buzzer
	9/13	89.10	checked stop arm and light operation
	10/1	235.00	windshield
	11/3	12.00	flat repair
	12/1	17.78	2 windshield wipers
	11/30	50.00	rewire child reminder
	1/27	682.17	front brakes are growling, replaced brake pads and rotors
	3/23	254.91	new fuel filter
	4/21	206.60	stop arm does not work
	5/18	593.00	4 tires
	TOTALS	2,823.17	
2011-2012	9/11	397.47	stop arm not working, rear blower not working
	1/31	398.41	buzzer would not shut off, strobe light not working. Oil chg and replace fuel filter
	2/17	298.85	install strobe light assembly
	4/18	95.58	burnt wire smell
	6/7	579.74	installed 2 new batteries, installed new brake pads on rear
	6/25	124.90	10f/sma 6120 k module, 6 ser control
	TOTALS	1,894.95	
2012-2013	7/3	396.98	132.75 stop arm
	10/5	251.37	installed new turn signal
	12/6	629.67	replaced alternator
	1/7	367.18	broken wire on block heater cord
	4/5	270.23	installed fuel filter
	TOTALS	1,915.43	
2013-2014	9/12	188.83	fuel pressure regulator leaking fuel at o-ring, replaced
	10/31	299.88	fuel tank will not take fuel
	2/20	86.95	new fuel filter
	2/20	63.70	new air filter
	5/22	357.19	inspected driveline and found u joint felt tight. Installed 3 new u joints
	5/21	147.42	stop arm and warning lights ar inop
	4/14	12.00	flat repair
	6/12	648.84	installed new radius arm bushings and spacers on left and right front.
	Totals	1,804.81	
2014-2015	12/30	555.34	cooling system repair
	1/23	249.29	blower motor bad, replaced
	Totals	804.63	
		9,242.99	

#20---2005 FORD THOMAS 16 PASS

1FDXE45P66HA12818

	DATE	Amount	Repair/Maintenace/Vendor
2015-2016	7/21	1,563.47	rear door buzzer is inop
	7/21	1,046.74	front and rear brake pads thin and replaced
	10/19	297.41	lube oil change--35.00, gasket kit 99.91, radio and speed
			control does not operate 48.00, install new fuel filter 38.40
			element 66.39, mis chrges 9.71
	10/13	1,009.61	reman module--engine con
	10/7	408.32	stop arm is inop
	11/6	155.52	cruise control and radio are inop
	2/1	25.00	hanger & clamp
	3/24	4,208.55	coolant leak
	6/9	402.13	repair steering or suspension, installed new outer tie rod
			on right side and new draglink collar and ends
	6/9	99.99	perform alignment
	TOTALS	9,216.74	
2016-2017			
	TOTALS	0.00	
2017-2018	11/30	554.40	2 new batteries
	TOTALS	554.40	
2018-2019			
	Totals	0.00	
2019-2020			
	Totals	0.00	
		9,771.14	

25,040.86