EI 9835

2009 Ford Collins #1 old

1FD4E45P68DB43194

		DATE Amou	nt Repair/Maintenace/Vendor
		\$242	25 Strobe light is INOP
	- 1	\$110	00 Install new bolt kit
8			00 flat tire
2008-2009	1		
80			
20	- 1		
	TOTALS	\$364.	25
		\$31.	02 repair left brake light
		\$119.	00 tire
		\$35.	79 replace right side brake light
		\$42.4	7 rear upper left light inop
	1	\$540.0	00 4-2257516 tires
		\$29.1	3 new bulb on rf top flashing light
		\$135.0	00 alignment, and c/c bushings
		\$310.5	0 2-lt-225/75r16 tires
	TOTALS	1242.9	
		\$15.9	0 wiper blade
	1 1		0 check brake problem, replaced brakes
-			and support kit
5	1 [\$315.0	0 installed child reminder
0-7	1 [\$42.1	2 installed new tag light
2010-2011	1 1		
7			
	TOTALS	\$677.1	2
		\$12.0	0 flat repair
7		\$973.5	0 6 tires 225/75/16
2		\$12.0	flat repair
7		\$1,211.3	rear bumper repair
2011-2012		\$64.90	Service a/c
			upper and lower baljoints , bushings
		4011.00	labor and alignment
		406.88	Prepaired brakes & caliper slide pins
	Totals	3322.49	Tropance brakes a camper since pins
		3322.43	
		05400	ale clutch and in a mit to
	 	\$34.05	a/c clutch cycling switch
က		\$74.85	service a/c
5		\$93.25	can oil charge
2012-2013			2 hankook tires
5		\$25.00	clearance light replaced
2		\$25.00	h3-55 bulb installed
			hood asy
	Totals	\$1,361.00	
		\$6,967.77	

1FD4E45P68DB43194

		DATE	Amount	Repair/Maintenace/Vendor
М			\$20.91	installed new bulb on left front
				vibration
4				
2013-2014				
5				
201	00			
	TOTALS		\$111.91	
2014-2015				a/c wont cool
				a/c wont cool
				child left behind button doesn't work
	1		\$28.00	mounted and balanced
	Mr.			
2				
7				
	TOTALS	3	\$582.80)
			2005 5	Secretary module, engine con
9	1		\$905.50	o remain module engine con O wiper blade
	1	-		repair tire
		-	\$10.5	4 Tepair tire
8	1	-	+	
2015-2016			+	
8				
	TOTAL	s	\$940.3	0
\vdash	1			
2016-2017	-	10/		0 repaired strobe light bulb
		12/2	29 294.4	8 rear heater inop
		2/	10 319.5	3 lube oil and filter 147.31, replace fuel filter 108.79,
				repair check engine light 53.00, misc parts 10.43
3		6/1	1,657.7	1 perform annual inspection, 2 caliper pins 66.10, 4 tires 504.92
7				2 tire stems 7.88, 2 seals 38.88, 1 brake pads 73.95, 2 plate ass 200.98, 2 housing 203.18, 2 rotors 235.06, 2 gaskets 6.76, 10.00 shop chgs
	Totals		\$2,291.7	2
<u>∞</u>				
Š				
3				
2017-2018		1		
		+		
` †				
	Totals	+	\$0.0	0

10,894.50