

DB8351

R/O	VIN 1 G C S K S E 3 3 A Z 1 8 2 8 4 2			HURRICAN SERVICES	DATE IN 02/14/17
YEAR 2010	MAKE CHEVROLET	MODEL SILVERADO	COLOR WHITE		TIME IN 00:00
MILES IN 250957	MILES OUT 250957	FIRST USE 00/00/00	LISC. KS		CLOSED 02/17/17
SEE ALSO	RES. H: (620) 432-3775 BUS. W: (785) -				WRITER 1355 TOM\09

(1) VEHICLE DIAGNOSIS
 TRANSMISSION SEEM TO HAVE A PROBLEM SHIFTING
 WE CHECKED THE VEHICLE OUT AND FOUND THAT IT
 NEEDS A NEW TRANSMISSION ASSEMBLY AND THE RAD
 IATOR AND AUX COOLER--WE REPLACED THE TRANSMI
 SSION ASSEMBLY, THE RADIATOR ASSEMBLY, THE TR
 ANSMISSION COOLER LINES AND THE AUX COOLER AS
 SEMBLY

DIAG	T86	
24233898	(SEAL)	1
15779543	(PIPE)	1
25999419	(PIPE)	1
19328898	(REMAN TRANSMIS)	1
20935856	(RADIATOR)	1
20880895	(COOLER)	1
88865602	(FLUID)	1
12346290	(COOLANT)	1
Total Repair (Customer)		4488.68

(Tech:86) A

21
 R/M
 Dm
 2-17-17

RECEIVED
 2-17-17 RQ

We Gladly Accept:  

*Please See Our
 Special Message
 On Back!*

W/C	INT.	CUSTOMER
.00	.00	Labor
.00	.00	Parts
.00	.00	Sublet
.00	.00	Shop Supplie
.00	.00	Oil/Grease
.00	.00	Sub Total
.00	.00	Tax
.00	.00	Total (Due) 4870.22

X Page 1 of 1 CUSTOMER'S SIGNATURE



Customer Copy

CF

R/O	VIN 1GCSKSE33AZ182842			HURRICAN SERVICES	DATE IN 03/24/17
YEAR 2010	MAKE CHEVROLET	MODEL SILVERADO	COLOR WHITE	O	TIME IN 09:18
MILES IN 253710	MILES OUT 253712	FIRST USE 00/00/00 00/00/00	LISC. KS 1038	104 PRAIRIE PL GARNETT KS 66032	CLOSED 14:20 03/28/17
SEE ALSO	RES. H: (620) 432-3775	BUS. W: (785) -			WRITEN MIKE\15

(1) SERVICE ENGINE SOON LAMP ON
 WE SCANNED THE VEHICLE FOR CODES AND PULLED
 CODES P0523;P0521.SEE LINE 2
 (Tech:86) A

SES T86
 Total Repair (Customer).....

(2) CHECK THE VEHICLE FOR THE OIL PRESSURE GAUGE
 IS RUNNING AT OPSI
 WE CHECKED THE OIL PRESSURE SENDING UNIT AND
 IT IS BAD.WE REPLACED THE OIL PRESSURE SENDIN
 G UNIT AND WE CLEARED THE CODES.WE REMOVED TH
 E OIL PAN AND REPLACED THE OIL PRESSURE RELIE
 F VALVE.WE REPLACED THE OIL PAN GASKET AND RE
 INSTALLED THE OIL PAN

MISC T86
 12673134 (SENSOR) 1
 12585328 (FILTER) 1
 12612350 (GASKET) 1
 12608835 (VALVE) 1
 15203889 (GASKET) 1
 12639759 (DEFLECTOR) 1
 19303974 (FILTER) 1
 12345610 (OIL) 6
 Total Repair (Customer)..... 729.47

(Tech:86) A

21
 RIM
 DM
 3-28-17

RECEIVED
 3-28-17 PM

We Gladly Accept:  

	W/C	INT.	CUSTOMER
	.00	.00	Labor
	.00	.00	Parts
	.00	.00	Sublet
	.00	.00	Shop Supplie
	.00	.00	Oil/Grease
	.00	.00	Sub Total
	.00	.00	Tax
	.00	.00	Total (Due) 878.22

R/O	VIN 1GCSKSE33AZ182842				HURRICANE SERVICES INC	DATE IN 06/22/17
YEAR 2010	MAKE CHEVROLET	MODEL SILVERADO	COLOR WHITE	O	250N WATER SUITE 200 WICHITA KS 67202	TIME IN 07:48 16:45
260279	260280	FIRST USE/00 00/00/00	LIC KS			06/30/17
SEE ALSO	RES H: () - BUS W: (620) 432-3775					WAITED

CUSTOMER TO PICKUP

(1) C/S ENGINE MAKING NOISE & HAS NO POWER
 FOUND BAD CYLINDER #4 AFM LIFTER. CAMSHAFT &
 LIFTER SHOW PITTING.
 REPLACED CAMSHAFT & LIFTERS. HAD VALVE JOB
 DONE ON BOTH CYLINDER HEADS. REPLACED ALL
 NEEDED GASKETS & SEALS FOR JOB.

Labor		T30	
12645725	(LIFTER)	8	
12648846	(LIFTER)	8	
12669185	(GUIDE)	2	
12669184	(GUIDE)	2	
12589226	(GASKET)	2	
19258707	(BOLT)	20	
12558840	(BOLT)	10	
12637683	(GASKET)	2	
89060413	(GASKET KIT)	1	
12585328	(FILTER)	1	
89017690	(GASKET)	1	
12617944	(GASKET)	2	
12625436	(CAMSHAFT)	1	
12630223	(GASKET)	2	
12602541	(SEAL)	2	
12633904	(GASKET)	1	
12609269	(TUBE)	1	
12584922	(SEAL)	1	
12588151	(VALVE)	1	
12626407	(TENSIONER KIT)	1	
12585673	(SEAL)	1	
12612350	(GASKET)	1	
19303975	(FILTER)	1	
12345621	(OIL)	6	
12346290	(COOLANT)	1	
12680072	(SPARK PLUG)	8	
11547135	(BOLT)	2	
AUTOMOTIVE 17148			
Total Labor		
Total Parts		
Total Sublet		
Total Repair (Customer)		4031.00

C McJ...
 7.10.17
 #21

(Tech:30) A

(2) C/S POWER MIRRORS DO NOT WORK.
 SHORTED MIRROR SWITCH CAUSED FUSE TO BLOW.
 REPLACED POWER MIRROR SWITCH & FUSE.
 CHECKS GOOD AT THIS TIME.

Labor		T27	
22883768	(SWITCH)	1	
Total Labor			
Total Parts			
Total Repair (Customer)		121.57

(Tech:27) A

VIN 1GCSKSE33AZ182842		HURRICANE SERVICES INC		DATE IN 06/22/17
YEAR 2010	MAKE CHEVROLET	MODEL SILVERADO	COLOR WHITE	TIME IN 07:48
250N WATER SUITE 200 WICHITA KS 67202		TIME OUT 16:45		
MILES IN 260279	MILES OUT 260280	FIRST USE/00 00/00/00	LIC KS	CLOSED 06/30/17
SEE ALSO	H:()	-	BUS W: (620) 432-3775	WATER

CUSTOMER TO PICKUP

(3) C/S LH REAR DOOR IS HARD TO OPEN NEEDS LH REAR DOOR EXTENSION HANDLE. APPROX COST OF REPAIR \$180.00 (Tech:27) A	Labor	T27	.00
	Total Repair (Customer)		.00
(4) C/S HAS A VIBRATION BETWEEN 70-75 MPH. CAN NOT DUPLICATE AT THIS TIME. (Tech:30) A	Labor	T30	.00
	Total Repair (Customer)		.00



W/C	INT.	CUSTOMER
		Labor
		Parts
		Sublet
.00	.00	Shop Supplie
		Oil/Grease
		Sub Total
.00	.00	Tax
		Total (Due) 4521.81

R/O	1	GCSE33AZ182842	HURRICANE SERVICES INC	12/13/17
2010	CHEVROLET	SILVERADO	WHITE	O
2173769	2173771	F169/08/00 00/00/00	LRS	
SEE ALSO	H: (620) - BUS: W: (620) 432-3775		250N WATER SUITE 200 WICHITA KS 67202	

TIME IN 4:37
12:57
TIME OUT 14/17

CALL WHEN READY

(1) FRONT AXLE LEAKING REPLACED LEFT FRONT AXLE SEAL (Tech:30) A	Labor 22761722 (SEAL) Total Labor Total Parts Total Repair (Customer)	T30 1
(2) EXHAUST RATTLE INSTALLED CENTER EXHAUST CLAMP AND ADJUSTED PER BULLITIN CHECKS OK (Tech:30) A	Labor 20779889 (CLAMP) Total Labor Total Parts Total Repair (Customer)	T30 1
(3) REPLACE STARTER COMPLETED (Tech:30) A	Labor 19180529 (*REMAN STARTER) Total Labor Total Parts Total Repair (Customer)	T30 1
(4) REPLACE REAR SHOCKS COMPLETED (Tech:30) A	Labor 25870984 (*ABSORBER) Total Labor Total Parts Total Repair (Customer)	T30 2
(5) C/S HOOD WILL COME OPEN WHEN DRIVING AT TIME. REPLACED HOOD LATCH CHECKS OK (Tech:30) A	Labor 20763454 (LATCH) Total Labor Total Parts Total Repair (Customer)	T30 1
(6) REAR AXLE PINION SEAL LEAKING REPLACED BOTH REAR AXLE WHEEL SEALS AND PINION SEAL CLEANED REAR BRAKES RESEALED DIFF AND FILLED WITH FLUID CHECKS OK (Tech:30) A	Labor 12471686 (SEAL) 26064029 (SEAL) 88900401 (LUBRICANT) Total Labor Total Parts Total Repair (Customer)	T30 2 1 2

#21
R/M
DM
12-18-17

Good

W/C	INT.	
		Labor
		Parts
		Sublet
.00	.00	Shop Supplie
		Oil/Grease
		Sub Total
.00	.00	Tax
		Total (Due) 1785.72