























INVOICE PAGE 1 SERVICE ADVISOR: COLOR YEAR MAKE/MODEL LICENSE MILEAGE IN/ OUT 07 FREIGHTLINER CL 1FUJA6CK87LZ22597 589132/589132 DEL DATE PROD. DATE WARR, EXP. PROMISED PO NO. RATE INV. DATE PAYMENT 13APR07 DI 12:00 30APR14 2597 CHG 22APR14 R.O. OPENED READY OPTIONS: DLR: VHMD ENG: 06R0922910 TRN:RTO-16910B-DM3 AXL:DS-404 10:46 14APR14 17:06 22APR14 LINE OPCODE TECH TYPE HOURS C/A FOR HARD SHIFTING BETWEEN 7TH AND 8TH AND IN BETWEEN 3RD AND 4TH--SOMETIMES WHEN UNIT IS PUT IN REVERSE IT KICKS BACK IN TO NEUTRAL AND TRANS HAS TO BE PUT IN TO MANAUL MODE TO GET IT IN REVERSE--WHEN TRANS REPAIRS HAVE BEEN MADE FOR THE SHIFTING ISSUE CUST WANT TRANS FLUID CHANGED 342-0000T TROUBLESHOOT TRANSMISSION 651 CPT ITT/086-0068-011 TERMINATE RESISTOR 1 FUL/4305309 PTO GASKET 1 FUL/4305310 GASKET 1 FUL/5588210 HOSE ASSEMBLY OIL 10.88 15 PHM/8-44147 TIE STRAP-15IN BLACK NYLON.100 100/BAG CHANGE TRANS FLUID 651 CPT MBL/98KH10 TRANS FLUID 50 GAL BOTTLE LABOR: OTHER: TOTAL LINE A: 589132 651 PULL TRUCK IN AND CONNECT TOOL, CHECK FOR TRANS
CODES;35/2 WITH 2 COUNTS, J1939 DATA LINK INCORRECT, 37/5 WITH 2 COUNTS
POWER SUPPLY BELOW NORMAL, 71/2 WITH 2 COUNTS UNABLE TO DISENGAGE GEAR MECHANICAL SYSTEM NOT RESPONDING, 75/14 WITH 210 COUNTS POWER DOWN IN GEAR.. CHECK J1939 AND DIAG PORT 120 OHMS, SHOULD BE 60 OHMS.. CHECK CONNECTIONS AT FIREWALL, OK. DROP DR/LINE TO TRACE BAD TERMINATING RESISTOR, FIND BAD ONE GOING INTO TRANS TCU. R/R, CHECK AT DIAG PORT, 60 OHMS.. T/S CODE 37 FOR POWER SUPPLY; CHECK BATTERY CONNECTIONS OK BUT FRAME GROUND CORRODED, R/R STUD AND ALSO CLEAN SURFACE AND TERMINALS.. LOCATE DIAG PORT AND CK VOLTAGE C TO GROUND 13 V,, C TO B 12.23V,C TO A 12.23V ALL WITH IN SPECS. REINSTALL DRIVE LINE. DRAIN TRANS OIL TO CLEAN PAN AND REMOVE INERTIA BRAKE AND PLATE FOR ACCESS TO CHECK SLIDING CLUTCH FOR WEAR, LOOKS OK. . CLEAN MATING SURFACE AND REPLACE BOTH GASKETS AND REINSTALL INERTIA BRAKE UNIT. FILL TRANS WITH NEW FLUID 4 GALS SYNTH.. CHECK SOFTWARE 872 AND 912 IS AVAIL.. UPDATE SOFTWARE AND TEST DRIVE TRUCK AND ABLE TO DUPLICATE PROBLEM. PULL TRUCK BACK TO SHOP AND REMOVE INSPECTION COVER AND CHECK CLUTCH, LOOKS STATEMENT OF DISCLAIMER DESCRIPTION The Terms and Conditions of this transaction are set forth in the Term The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The and Conditions which may be viewed on the Web at www.kcfreightliner.com ("Web Terms and Conditions"). The Web Terms and Conditions are incorporated by reference herein and are hereby made a part of the contractual relationship between Customer (you) and Dealer (us). If you do not have access to the Web, please ask our representative to print out a copy of the Web Terms and Conditions for your review before entering into this contractual relationship. LABOR AMOUNT of the warranties with respect to the sale of this itemitiems. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. PARTS AMOUNT GAS. OIL. LUBE SUBLET AMOUNT MISC. CHARGES TOTAL CHARGES By signing this page, Customer hereby authorizes the repair work listed to LESS INSURANCE done (above) with the necessary materials. SALES TAX CUSTOMER SIGNATURE (SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON PLEASE PAY THIS AMOUNT CUSTOMER COPY

- /					Pat.	14 100		
				INVOICE				
				PAGE 2				
COLOR	YEAR	MAKE/MODEL		SERVICE ADVIS	50	LICENSE	MILEA	AGE IN/ OUT TAG
WHITE DEL DATE	07 FRE	IGHTLINE	I consider the same of the sam	1FUJA6CK87LZ2	2597		THE RESERVE OF THE PARTY OF THE	2/589132 T259
		WARR, EXP.	PROMISED	PO NO.		RATE	PAYMENT	
R.O. OPEN		READY	12:00 30A OPTIONS:	PR14 2: DLR:VHMD EN	597 G:06R0	0.00	CHG	22APR14
10:46 14AI	PR14 17	06 22ADD	TRN: RTO	-16910B-DM3 A				
OR CHAFFI WIRE, FINI TERMINAL HARNESS	CT POWER CT POWER CT POWER CT HOT WIF AND RECC REINSTL CTO TECU	LINE FROM OHM EACH RE TO BATT ONNECT TO POWER HAI J AND CK I	LINE651 M BATTS TO WIRE OK .6 IS BEING TILE BATTSALSO RNESS AND SPINS 26/28,	HE INERTIA BRA R/REPL LINEI TECU AND REMO OHMSUPON RI ED AWAY FROM I O REPL 1 TERM ECUREDISCONI BOTHO OK, 12.60	DROP I VECK EMOVIN BATTS INAL C NECT F VOLTS	ORIVE L ( FOR B NG POWE BOXR OF POWE HARNESS EALSO	ROKEN W R EPL BRO R 38 PIN FIND A	KEN
OISCONNECTOR OR CHAFFI WIRE, FINITERMINAL HARNESS CONNECTOR GRD CABLE DR/LINE A SHOP AND MANUAL MCCK AND AL AND XY CO REMOVE XY COS OF NO B FREIGHT FREIG	T POWER ED, NONE. D HOT WIF AND RECC. REINSTL TO TECU NOT CON AND ERASE CONNECT DDE. 651 SO CK SH STHERE T, CK AND METAL S ***** CHARGES HT FREIG FRT FREI	LINE FROM OHM EACH RE TO BATT ONNECT TO POWER HAI J AND CK I NECTING CODE. TH TOOL, CK I CALL EATC LIFT BAR I IS NO HIS NO OBVIOL CHAVING PE ************************************	LINE651  M BATTS TO  WIRE OK .6  IS BEING TI  BATTSALSO  RNESS AND S.  PINS 26/28,  TO STARTER I  EST DR/TRK,  FOR CODE, NO  ON AND TALK  HSGALSO S.  STORY OF BE  JS FINDCK  RESENTS	R/REPL LINE1 TECU AND REMOTO OHMSUPON RI ED AWAY FROM I O REPL 1 TERM. ECUREDISCONI	DROP IN VECHEMOVING BATTS INAL CONTEST CARRESTED DACT GGEST LBOTH .DROP	DRIVE L C FOR E BOX.R DF POWE HARNESS S.ALSC BLE.RE PULL T THE SA TO REM TRANS DR/LIN	ROKEN W. R LEPL BRO. R J 8 PIN J FIND A CINSTL RK BACK ME IN LOVE XY HARNESS LE AND	KEN LT TO AND SEL
OR CHAFFI WIRE, FINI TERMINAL HARNESS CONNECTOR GRD CABLE DR/LINE A SHOP AND MANUAL MC CK AND AL AND XY CO REMOVE XY COS OF NO B FREIGHT FREIG	ET POWER ED, NONE. ED, NONE. D HOT WIF AND RECC REINSTL TO TECU NOT CON AND ERASE CONNECT ODE. 651 SO CK SF SO THERE CHARGES HT FREIG FRT FREI V# EIGHT	LINE FROM OHM EACH OH	LINE651 M BATTS TO WIRE OK .6 IS BEING TI: BATTSALS: RNESS AND S. PINS 26/28, TO STARTER I EST DR/TRK, FOR CODE, NO ON AND TALK HSGALSO SI STORY OF BE US FINDCK RESENTS	R/REPL LINE. 1 TECU AND REMOTO OHMSUPON RI ED AWAY FROM 1 O REPL 1 TERM. ECUREDISCONI BOTH OK,12.60 MOTOR, RECONNE PROBLEM PERSI NETRANS ALSO UGGEST TO REPL ING REPLACED. SHIFT BAR HSO ************************************	DROP I VECH EMOVIN BATTS INAL C NECT I VOLTS CT CAR STED O ACT GGGEST LBOTH DROP G IT S	ORIVE IN COMMENT OF POWER HARNESS ALSO BLE. REDULL THE SATE TO REMEMBER TO REMEMBER TO THE SEEMS	ROKEN W. REPL BRO. REPL BR	KEN LT TO AND SEL
DISCONNECTOR OR CHAFFI WIRE, FINITERMINAL HARNESS CONNECTOR GRD CABLE DR/LINE A SHOP AND MANUAL MC CK AND AL AND XY COS OF NO B FREIGHT FREIG IN PARTS: 589132 FR.  1 1 1 3X-SHOP AND A SHOP A SH	T POWER ED, NONE. D HOT WIF AND RECC REINSTL TO TECU NOT CON AND ERASE CONNECT DE. 651 SO CK SF STHERE T, CK AND METAL S **** CHARGES HT FREIG FRT FREI V# EIGHT SHIFTER 000T TROI 10044 FUL/K378 Y DW 1	LINE FROM OHM EACH RE TO BATT ONNECT TO POWER HAI J AND CK I INECTING TO CALL EATO LIFT BAR II IS NO OBVIOUS HAVING PE *********  CALL BATC LABOR:  ********  AND HARN UBLESHOOT CPT 4RX KIT-R	LINE651 M BATTS TO MIRE OK .6 WIRE OK .6 IS BEING TILL BATTSALSO RNESS AND S. PINS 26/28, TO STARTER IN EST DR/TRK, FOR CODE, NO DN AND TALK HSGALSO S. STORY OF BE JS FINDCK RESENTS ***********************************	R/REPL LINE. 1 TECU AND REMOTO OHMSUPON RI ED AWAY FROM 1 O REPL 1 TERM. ECUREDISCONI BOTH OK,12.60 MOTOR, RECONNE PROBLEM PERSI NETRANS ALSO UGGEST TO REPL ING REPLACED. SHIFT BAR HSO ************************************	DROP I VECH EMOVIN BATTS INAL C NECT H VOLTS CT CAB STED D ACT GGEST LBOTH DROP J IT S	ORIVE IN COMMENT OF POWER HARNESS ALSO BLE. REDULL THE SATE TO REMEMBER TO REMEMBER TO THE SEEMS	ROKEN W. REPL BRO. REPL BR	KEN LT TO AND SEL
DISCONNECTOR OR CHAFFI WIRE, FINITERMINAL HARNESS CONNECTOR GRD CABLE DR/LINE ASHOP AND MANUAL MC CK AND AT AND XY COS OF NO BEFREIGHT FREIG IN PARTS:  589132 FR.  1 1 3X-SHO SHO	T POWER ED, NONE. D HOT WIF AND RECC REINSTL TO TECU NOT CON AND ERASE CONNECT DE. 651 SO CK SF CK AND METAL S ***** CHARGES HT FREIG FRT FREI U# EIGHT SHIFTER 000T TRO 10044 FUL/K378 Y DW 1 FUL/K368:	LINE FROM OHM EACH RE TO BATT ONNECT TO POWER HAI J AND CK I NECTING TO CALL EATO LIFT BAR I IS NO OBVIOUS HAVING PE ********** HT CHARGE CPT GHT LABOR:  ********* AND HARN UBLESHOOT CPT 4RX KIT-R  I KIT HAR	LINE651 M BATTS TO WIRE OK .6 IS BEING TITE BATTSALS RNESS AND STARTER IN	R/REPL LINE. ITECU AND REMOTO OHMS. UPON RI ED AWAY FROM ITED AWAY	DROP I VECH EMOVIN BATTS INAL C NECT H VOLTS CT CAB STED O ACT GGEST LBOTH	DRIVE I C FOR F C FOR F D F POWE BOXR D F POWE HARNESS SALSC BLERE PULL T TO REM TRANS DR/LIN SEEMS T	ROKEN W.R. REPL BRO. REPL	KEN LT TO AND SEL
DISCONNECTOR OR CHAFFINITERMINAL HARNESS CONNECTOR GRD CABLE DR/LINE ASHOP AND MANUAL MCCK AND AI AND XY CC REMOVE XY COS OF NO B FREIGHT FREIG IN PARTS: 589132 FR  1 X 342-0  1 I X 3X SHO AI AI AND XY CC REMOVE XY COS OF NO COS OF N	T POWER ED, NONE. ED, NONE. O HOT WIF AND RECC. REINSTL TO TECU. ENOT COM AND ERASE CONNECT ONE. ENOT COM AND ERASE CONNECT ONE. SO CK SF OS THERE O METAL S ***** CHARGES HT FREI U# EIGHT **** SHIFTER OOOT TROU 10044 FUL/K368: OW 1 FUL/K368: OW 2 Inditions of this t which may com ("Web Terr incorporated by cutual relationship not have accountering into this Customer here the necessary	LINE FROM OHM EACH RE TO BATT LABOR TO LABO	LINE651 M BATTS TO WIRE OK .6 IS BEING TI: BATTSALS: RNESS AND S. PINS 26/28, TO STARTER I EST DR/TRK, FOR CODE, NO DN AND TALK HSGALSO SI STORY OF BE US FINDCK RESENTS  **********************************	R/REPL LINE. ITECU AND REMOTO OHMS. UPON RIPON RIPON RIPON RIPON RIPON RIPON RIPON RECURE. DISCONDEN RECONNER RECONNER RECONNER RIPON RIPO	DROP I VECR EMOVIN BATTS INAL C NECT H VOLTS CT CAR STED O ACT GGGEST LBOTH DROP J IT S ******  EN  LAIMER stitutes all espect to minplied biblity or purpose. les nor limplied biblity or purpose. les nor limplied biblity or purpose. les nor limplied biblity or li	DESIDER IN CONTROL IN	ROKEN WERE AND SERVICE AND SER	KEN  TO  AND  SEL C

INVOICE PAGE 3 SERVICE ADVISOR MAKE/MODEL LICENSE MILEAGE IN/ OUT TAG FREIGHTLINER DEL DATE 1FUJA6CK87LZ22597 PROD. DATE WARR. EXP. PROMISED 589132/589132 T2597 PO NO. RATE PAYMENT 13APR07 DD 12:00 30APR14 R.O. OPENED 2597 READY 22APR14 OPTIONS: DLR: VHMD ENG: 06R0922910 TRN:RTO-16910B-DM3 AXL:DS-404 10:46 14APR14 17:06 22APR14 LINE OPCODE TECH TYPE HOURS PARTS: LABOR: LIST TOTAL OTHER: 589132 //10044 REMOVED WIRING HARNESS. INSTALLED NEW HARNESS PER TOTAL LINE C: EATON INSTRUCTIONS. INSTALLED X Y SHIFTER PER EATON INSTRUCTIONS. TEST SHOP SUPPLIES THE TAX THE SECOND PROPERTY OF THE Terms and Conditions of this transaction are set forth in the Terms and Conditions which may be viewed on the Web at www.kcfreightliner.com ("Web Terms and Conditions"). The Web Terms and Conditions are incorporated by reference herein and are hereby made a part of the contractual relationship between Customer (you) and Dealer (us). If you do not have access to the Web, please ask our representative to print out a copy of the Web Terms and Conditions for your review before entering into this contractual relationship. STATEMENT OF DISCLAIMER STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item\tems. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. DESCRIPTION LABOR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES By signing this page, Customer hereby authorizes the repair work listed to be done (above) with the necessary materials. TOTAL CHARGES LESS INSURANCE SALES TAX (SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE) CUSTOMER SIGNATURE PLEASE PAY THIS AMOUNT 2592.57 CUSTOMER COPY