INVOICE

BILL TO

Darrell Teeter Teeter Irrigation TORO RT 1200

DATE	ACTIVITY	HRS/QTY	RATE	AMOUNT
10/02/2017	Machine Toro RT1≥∞Trencher HRS: 855	1		
10/02/2017	Labor Drive to location. Remove chain, disassemble planetary gearbox. install new oil seals and wear rings in gearbox. Clean	4		
	and inspect parts. Go over issue found with flaking gears with Darrel. Box up all the parts.			
10/17/2017	Labor Drive to location. Unbox new parts. Clean and install new planetary assembly. Install all other removed parts. Fill gearbox with oil.	3.75		
10/17/2017	Misc Parts	1		

BALANCE DUE

\$668.75

Installed New Planetary Greats
Tranchese