

#405

Work Order

Priority : 0-Critical Work Type : REPAIR	Assigned :	Created : 4/19/2018 Due : Completed : 3/22/2018
---	------------	---

Service Code	Service Description	Estimated Hours		
Part #	Unit ID	Unit Cost	Quantity	Total Cost
2N-2766	[LOCK NUT]	EACH		
1P-0451	[GASKET]	EACH		
7L-3195	[BOLT]	EACH		
6L-8562	[STUD]	EACH		
1P-1255	[GASKET]	EACH		
8H-9788	[GASKET]	EACH		
10R-0921	[TURBO]	EACH		
5L-8855	[RING]	EACH		
6N-0009	[RING]	EACH		

Contact Name	Equipment Used	Hours	Labor Rate	Labor Total
DAVID GARRETT				
SCOTT NAGEL				
SCOTT NAGEL				
SCOTT NAGEL				

Note Type	Service Code	Note	Modified By	Note Date
GENERAL		03/20/18 - Scott Lot of Black Smoke Intake Propeller Shattered Removed Turbo	Administrator	4/19/2018
GENERAL		03/21/18 - Scott • Install Turbo 03/21/18 - David • Knocked Out Rings On Exhaust Extension • Make Sure New Rings Lift & Move Freely	Administrator	4/19/2018
GENERAL		03/22/18 - Scott • Visual, General Inspection	Administrator	4/19/2018

Part Total :
Labor Total :
CORE CHARGE :
CORE CHARGE :
Grand Total : \$2,581.45