

SCT #	SOLD TO		DATE	TIME	STORE #	EMP #	INVOICE #
7389	5280 TOWING LLC		10/01/2014	10:29	500001005	3	419031
SR #			PURCHASE ORDER #		ATTENTION		
15					3406C kit		
AD			TAX EXEMPTION:		REPRINT		
1			TERMS:		Visa		
			ANTICIPATED:				

PART NUMBER	LN	DESCRIPTION	QUANTITY	PRICE	NET	TOTAL
FPIFK3406HO	KIT	IN-FRAME OVERHAUL KIT () Coming factory direct, gasket set 2 days later	1.00			

Subtotal
TAXTABLE 2 7.6200%
TOTAL

	2,232.73
	170.13
	0.00
	2,402.86***
Visa	2,402.86

I N V O I C E

Page 1

Invoice
Job Number
PO#

1 095170
1 108667

:WILL CALL DOCK

SA Code LW
Y



GLD

4/10/2015

11:24:00

* CASH *

S 01 00 60184
O 5280 TOWING, LLC
D

S
H
I
P 5280 TOWING, LLC
T
O

Unit

DV TRAN/GEAR DENVER TRANSMISSION/GEAR J
CREDIT CARD # ON FILE

<u>Operation</u>	<u>Description</u>	<u>Seq</u>	<u>Tax</u>	<u>Price</u>
TRN	TRANSMISSION	1	N	

wants 13 speed, RTLO16713A core will be super 10 RTLO11610B

<u>Part Number</u>	<u>Description</u>	<u>Ret</u>	<u>Qty</u>	<u>Each</u>	<u>Core</u>	<u>Tax</u>	<u>Total</u>
TB 206FF	BEARING		1			Y	
LE BK-313	2 CL BRAKE		1			Y	
CL 35-P-15-1	SHIM		4			Y	
CL 35-P-15-2	SHIM		2			Y	
SN 6-4-6931-1X	END YOKE		1			Y	
FL 84005	CONNECTOR		4			Y	
FL A-6913	VALVE	N	1			Y	
FL 20191	SPEEDO GEAR	N	1			Y	
FL 4300764	STICKER	N	1			Y	
WP 767527	RTLO16713A-13 L		1			Y	
SI CORE	CORE		1			Y	

<u>Operation</u>	<u>Description</u>	<u>Seq</u>	<u>Tax</u>	<u>Price</u>
------------------	--------------------	------------	------------	--------------

TOTAL UNITS	PART TOTAL	CORE TOTAL	FREIGHT	HANDLING	OTHER	TAX
PAY THIS AMOUNT						\$

I N V O I C E

Page 2

Invoice
Job Number
PO#
CALL DOCK

1 095170
1 108667
SA Code LW
Y

S 01 00 60184
O 5280 TOWING, LLC
L
T
O

S
H
I
P

T
O

5280 TOWING, LLC

GLD
4/10/2015
11:24:00

<u>Operation</u>	<u>Description</u>	<u>Seq</u>	<u>Tax</u>	<u>Price</u>
BRK	BRAKE SHOP	2	N	

<u>Part Number</u>	<u>Description</u>	<u>Ret</u>	<u>Qty</u>	<u>Each</u>	<u>Core</u>	<u>Tax</u>	<u>Total</u>
LB 1-EPA/FLY	FLYWHEEL WASH		1			N	
LB 1-493	REFACE FLYWH		1			Y	

PAID

☐ Cash ☐ Check ☒ Cr. Card

Cashier HR Date 1/1/10

Labor Total

Misc. Total

QB

20						
TOTAL UNITS	PART TOTAL	CORE TOTAL	FREIGHT	HANDLING	OTHER	TAX

PAY THIS AMOUNT

\$

5660.42

REPAIR & MAINTENANCE RECORD					
1996 PETERBILT VIN# 341999 TIRE SIZE 11R 24.5					
DATE	TASK	MECHANIC	MILEAGE/HOURS	EXPENSES	LABOR
8/22/18	U-JOINT 1/4 FENDE REPLACE HYDRAULIC LEAK 10-15 GL	4-15			
7/27/18	Fire Extinguisher Mounting case / Windshield Cracked on left side	Jordon	30m		
7/25/18	HYDRAULIC LEAK COMING FROM PTO	JORDAN		96.75	2.5
7/20/18	Spedo stopped working	adrian	1 Hr		
7/18/18	Passenger Seat belt reattached drivers side Cracked	Adrian	15m		
7/2/18	TRUCK LEAKING OIL	Adrian		418.04	3.5
6/14/18	Service call to P8 for belts	Adrian		92.64	2.5
6/13/18	NO MUDFLAPS	adrian			1 HR
6/5/18	INSTALLED A NEW END ON THE HYDRAULIC LINE	ADRIAN		101.74	1.5 HRS
6/4/18	BR1 EMISSIONS TEST	JAKE	510846	155.00	
5/1/18	REPAIR BEACONS, WIND SHIELD CRACK IS STILL LEGAL TO DRIVE	ADRIAN	506978	78.82	4h
4/5/18	Installed new clutch brake	ADRIAN	504189		2
3/29/18	ANNUAL VEHICLE INSPECTION	ADRIAN	503546	0	1.5
3/22/18	Exhaust has a hole need wheel seal cover, left side mudflap, 5th wheel	adrian	503191	70.73	3.5
3/16/18	PM SERVICE B AND INSPECTED	ADRIAN	502893	65.76	
3/12/18	A LOT OF SMOKE AND OIL THROUGH THE EXHAUST	ADRIAN	502864	3620.32	
2/19/18	CLEARANCE LIGHT NOT WORKING	ADRIAN		41.17	
11/12/17	R&R REAR TAIL LAMP	RAY	496766		
11/16/17	R&R LF DRIVING LIGHT	RAY	496833	15.36	
11/7/17	R&R WIPER NOZZLES	RAY	495576	32.19	
10/17/17	Checked tires	RAY	492911		
10/11/17	Remove old hoses and fittings installed new	RAY	492260		
10/4/17	Replaced two mudflap bracket assembly	RAY	49076		
10/3/17	Repaired hydro leak at pump	RAY	49077		
9/25/17	Replaced Hydro filter	RAY	490373		
9/29/17	REPLACED PTO PUMP	RAY	48941 MILES 2717 HOURS	97.75	
9/28/17	ORDER NEW TIRE CHAINS	RAY		\$175.94	
9/21/17	A SERVICE CHANGED AIR FILTER & OIL INSTALLED NEW SERVICE STICKERS WIRES AIR LINES AND FUEL LINES RUBBING ZIPPED TIED CORRECTLY	RAY	48901 MILES 2716 HOURS	\$103.94	
9/20/17	STRAIGHTENED ARMS AND MOUNT ON LEVEL VALVE AND REATTACHED REPAIRED LEFT MUD FFLAP HANGER REMOVED AND REINSTALLED AIR TANK DRAIN CABLES GREASED FIFTH WHEEL INSTALLED SAFETY LATCH ON RT JOCKEY BOX INSTALLED NEW CAPTER PINS ON 5TH WHEEL	RAY	488851 MILES 2707 HOURS		
9/19/17	CHECKED FLUIDS TOPPED OFF AS NEEDED	RAY	488550 MILES 2707 HOURS		
9/14/17	REINSTALLED OVERSIZE LOAD SIGN ON FRONT BUMPER REPAIRED LT REAR STOP TAIL LAMP CHECKED TORSION ROD ON FRONT DRIVE AXLE FIFTH WHEEL OKAY	RAY	487883 MILES		
8/30/17	PTO INSTALLED FIRE EXTINGUISHER REATTACHED CAT WALK TIGHTNED REPAIRED TIRE LT REAR OUTER REPAIR FAN CLUTCH	RAY	487883 MILES	\$603.73	
8/16/17		KRIS			
8/1/17	REPAIR HARNESS R&R RRI REPAIR TIRE	KRIS			
7/31/17	REPAIR CONNECTOR FOR AC CLUTCH INSTALLED ALTERNATOR TENSIONER ROD	KRIS	403215 MILES	\$48.33	
7/27/17	REPLACED HYDRAULIC PUMP WITH ONE ON SHEF INSTALLED NEW PUMP FROM FORCE AMERICA ALSO REPLACED FILTER AND HYDRAULIC FLUID	NG	484786 MILES 2494 HRS		
7/20/17	INSPECT FIFTH WHEEL REBUILD FIFTH WHEEL VERIFY REPAIR INSTALL FIFTH WHEEL	KRIS		\$287.80	
7/12/17	ADJUST CABLE R&R CABLE BRACKET BEND BRACKET FOR STOP OUT IS OK ADJUST THROTTLE LINKAGE	KRIS			
7/8/17	INSTALL NEW WINDOW	KRIS		\$272.74	
7/7/17	REPLACED HEADLIGHT	KRIS			
7/6/17	INSTALLED NEW TAILLIGHT AND DRILL NEW MOUNTING HOLES WIRE INTO HARNESS AND SECURE VERIFY REPAIR	KRS		\$45.97	
7/1/17	REPLACED HYDRAULIC LINES	KRIS			
7/1/17	REPLACED SPOT MIRROR	KRIS			
6/27/17	REPAIRED WIRE HARNESS AND REAR RUN WIRE LOOM AND SECURE FABRICATE MUD FLAP BRACKET AND WELD TO TRUCK BODY R&R BATTERY CABLES	KRIS	481977 MILES 2339HRS		
6/26/17	PERFORMED A SERVICE	KRIS	481977MILES 2340HRS		
6/22/17	A SERVICE	KIRS	48171 MILES 2318 HRS	\$34.15	
12/14/16	REPLACED BOTH MUDFLAPS & INSTALLED REFLECTIVE STRIP ON BOTH, REPAIRED RR INNER TIRE, INSTALLED PASSENGER SEAT, PERFORMED B SERVICE, WELDED STORAGE BOX TO HYDRAULIC TANK, DETAILED INSIDE OF CAB AND WASHED WINDOWS AND MIRRORS	NG	476007MILES 1932HRS	\$60.63	

11/2/16	REMOVED HYDRAULIC PUMP, DISASSEMBLED PUMP, REPLACED BOTH GEARS, REPLACED BOTH THRUST PLATES, REPLACED REAR COVER ALONG WITH 2 ROLLER BEARINGS, DID NOT REINSTALL PUMP YET ITS SITTING ON THE SHELF IN THE SHOP	NG		\$339.02	
10/7/16	EMMISSIONS TEST DONE AT TRANSWEST	DO		\$144.00	
9/12/16	R&R RF DRIVE AXLE AIR BAGS	NG		\$139.76	
8/29/16	REPLACED RF DRIVE AXLE BRAKE CHAMBER, ADJUSTED BRAKES	DO	474788	\$46.81	
8/15/16	PERFORMED FULL SERVICE, CHANGED OUT FRONT DRIVE AXLE DRUMS AND BRAKE SHOES	DO		\$317.92	
6/27/16	INSTALLED NEW FLEX PIPE AND 2 CLAMPS ON PASSENGER SIDE UNDER STACK, INSTALLED 2 NEW HOOD CABLES	RW	470425/ 1675 HRS	\$68.48	
6/11/16	PERFORMED FULL SERVICE	JIMBO	1570 HRS	\$135.18	
6/7/16	FOUND AC HAD NO FUSE INSTALLED, INSTALLED FUSE AND TESTED SYSTEM, REMOVE AND INSTALL NEW FAN SWITCH SOLENOID, INSTALLED CB ANTENNA, INSTALLED NEW WORK LIGHTS	DO/RW	468236/ 1580 HRS	\$358.96	
5/21/16	TIGHTENED DRIVER SIDE CONVEX MIRROR, PLUGGED REAR DRIVE TIRE, TIGHTENED OIL PAN BOLTS, INSTALLED QUARTER TURN VALVES ON HEATER HOSES, REPLACED 5" EXHAUST CLAMP ON DOWN PIPE FROM TURBO, CLEAN CONTACTS AND REMOVE FILTER ON FAN CLUTCH SOLENOID, STEAM CLEAN ENGINE.	DO			
4/19/16	REMOVED AND INSTALLED NEW GASKETS ON AIR COMPRESSOR, FIXED MOUNT ON RADIATOR SUPPORT, REPLACED U-JOINT IN STEERING SHAFT, REPLACED ALTERNATOR, INSTALL HEATER CONTROL VALVES	DO		\$391.29	
4/14/16	PERFORMED FULL SERVICE, REPLACED TAILLIGHT BULBS, REPLACED REVERSE BULBS, INSTALLED 4 NEW TIRES ON DROP AXLE, REPLACED DROP AXLE HUB CAP	MR	1317.8	\$993.29	
3/22/16	R&R BOTH TAIL LIGHT LENSES	NG		\$24.20	
3/3/16	PERFORMED FULL SERVICE ON TRUCK, PERFORMED ANNUAL INSPECTION, INSTALLED NEW AIR RIDE SEAT ON PASSENGER SIDE, INSTALLED NEW FISHER AND IT SEEMS TO HAVE FIXED THE TURN SIGNAL ISSUE, REPLACED CB WITH ONE WE HAD IN THE SHOP, REPLACED CB ANTENNA, REPLACED LF WHEEL SEAL	NG, RW	542460, 1058	\$926.70	
2/14/16	REPLACED HEADLIGHT AND BULB INSIDE TURN SIGNAL	AW		\$1.49	
2/14/16	REPLACED HEADLIGHT	AW			
2/9/16	FOUND AIR LEAK ON DRYER SO AIR DRYER WAS R&R'D	AW			
2/8/16	INSTALLED 2 NEW BATTERIES	AW			
1/25/16	FABRICATED AND INSTALLED PINTAL HITCH WITH GLAD HANDS AND RV STYLE PLUG (7 WAY BLADE) AND SEMI STYLE PLUG (7 WAY ROUND) ALSO INSTALLED ELECTRIC TRAILER BRAKE CONTROLLER	RW			
1/9/16	CHANGED BULB IN FRONT DRIVER SIDE TURN SIGNAL	AW			
1/17/16	PUT NEW SPEAKERS IN TRUCK FOR RADIO	AW			
12/29/15	INSTALLED NEW RADIO	NG			
12/7/15	SERVICED TRUCK, CHANGED OIL AND FILTERS, PUT THREE DRAIN VALVES IN AIR TANKS, REPLACED TEMP SENSOR IN FRONT DRIVE DIFFERENTIAL, RAN AN OVERHEAD ON ENGINE, SET JAKE BRAKES, REPLACED LEFT REAR WHEEL SEAL, MOVED TOOLBOX OFF OF CATWALK AND MOUNTED ON TOP OF HYDRAULIC TANK, FIXED CATWALK	RW	801 HOURS		
11/14/15	REPLACED MUD FLAP HANGERS, REPLACED BAD BULBS, PASSENGER SIDE CLEARANCE LIGHT ON ROOF NEED WHOLE NEW LIGHT ASSEMBLY. INSTALLED NEW LIGHT ASSEMBLY.	NG			
10/22/15	CHANGED ALL 8 DRIVE TIRES WITH NEW REPLACED WIPER BLADES	RW			
10/5/15	CHANGED OIL AND FUEL FILTERS/REPLACED CLEARANCE LIGHT BULBS/REPLACED FUSE FOR BEACONS/ REPLACED STEER TIRES	NG			
9/16/15	REPAIRED TURN SWITCH AND FLASHER ELEMENT	RW			
9/8/15	REPLACED AC COMPRESSOR AND ALTERNATOR	NG			
9/2/15	INSTALLED 3 NEW BATTERIES	NG			
8/28/15	REPLACED D2 GOVERNER	RW			
8/28/15	REBUILT AIR DRYER AND REPLACED PURGE VALVE	RW			
8/18/15	REPLACED CAB FILTER	BM			
8/14/15	CHANGED FUEL AND OIL FILTERS	NG			
8/13/15	REPLACED JAKE SWITCH	NG			
7/23/15	INSTALLED NEW BRAKE SHOES	NG			
7/21/15	REPLACED WINDSHIELD FLUID RESERVOIR	NG			
7/18/15	REPLACED BINARY SWITCH	NG			
7/1/15	REPLACED AIR COMPRESSOR GASKET AND LOW AIR ALARM	NG			
6/29/15	REPLACED LEAKING WHEEL SEAL ON LF DRIVE AXLE REPLACED ALL FOUR DRIVE BELTS REPLACED AIR LINE TO FAN CLUTCH	NG			
6/22/15	REPLACED PINION SEAL ON REAR DIFFERENTIAL FILLED DIF	NG			
6/22/15	REPLACED WHEEL SEAL ON PASSENGER SIDE	NG			
6/22/15	REPLACED FRONT DRIVE AXLE BREAKS	NG			
6/18/15	REPLACED OIL AND FUEL FILTERS	NG			
6/17/15	REPLACED TAIL LIGHT AND MARKER LIGHT	JM			
6/2/15	REPLACED TURBO GASKET AND BOLTS/NEW MUD FLAPS AND HANGERS	NG			
62/15	REPLACED HYDRAULIC FILTER	NG			
6/2/15	ROTATED TIRES	JM			
5/26/15	REPLACED WHEEL SEAL ON RIGHT SIDE TAG AXLE	JM			
5/26/15	REPLACED POWER STEERING PUMP & GASKET FOR PUMP	JM			

P8

1996 PETERBILT VIN# 1XP5PBEX6TN403215

	5/16/15	INSTALLED TOOL BOX	NG		
	5/16/15	REPLACED FUEL TANK DIVIDER	NG		
*	4/20/15	REPLACED 9 SPEED TRANSMISSION WITH 13 SPEED	RW	Receipt Attached	
	3/31/15	CHANGED HEIGHT CONTROL VALVE	RW		
	3/12/15	INSTALLED GLAD HAND HANGER	RW		
	3/12/15	FLAT REPAIR	RW		
	3/12/15	REPLACED BOTH JAKE BRAKE SWITCHES	RW		
	3/12/15	INSTALLED PTO SWITCH	RW		
	3/12/15	REPLACED STEERING GEAR BOX	RW		
	3/11/15	INSTALLED GLAD HAND & LIGHT CORD HANGER	NG		
	3/11/15	INSTALLED PTO SWITCH	NG		
	3/11/15	FLAT REPAIR LRIT	NG		
	3/11/15	INSTALLED NEW STEER BO, R&R JAKE SWITCHES	NG		
	3/5/15	REPLACED O-RING ON TURBO OIL DRAIN TUBE	NG		
	3/5/15	PM & SERVICE-- 416,376 mls	NG		
	3/4/15	REPLACED CITY HORN	NG		
	3/4/15	REPLACED BOTH FRONT BRAKE AIRLINES	NG		
	3/4/15	FIXED THROTTLE CONTROL CABLE	NG		
	3/4/15	REPLACED HYDRAULIC PUMP	NG		
	2/26/15	REPLACED BAD AIR HORN	NG		
	2/23/15	REPLACED HEAD LIGHT BULB	NG		
	2/13/15	REPLACED TAIL LIGHT	NG		
	2/12/15	REPLACED BACK GLASS	NG		
	1/23/15	REPLACED DRIVER SIDE WINDSHIELD	NG		
	12/15/14	PM & SERVICE-	NG		
	11/7/14	REPLACED BOTH REAR DRIVE AXLE WHEEL SEALS & BRAKES	NG		
	11/7/14	INSTALLED NEW STEREO	NG		
	11/7/14	INSTALLED WORK LIGHT & BEACONS	NG		
	11/7/14	INSTALLED NEW DRIVER SEAT	RW		
	10/3/14	PM & SERVICE-	NG		
*	10/1/14	IN FRAME MOTOR JOB	NG/RW	Receipt Attached	