

T4

2002 LANDOLL 610B VIN# 1LW610WJX21B12178

REPAIR & MAINTENANCE RECORD				
DATE	TASK	MECHANIC	EXPENSE	LABOR
7/18/18	BLOWN AIRBAG	JORDAN	\$159.87	4 HRS
6/5/18	REPLACED NEW VALVE STEM TIRE IS GOOD	ADRIAN	\$7.64	2.5 HOURS
5/25/18	SERVICE CALL FOR FLAT TIRES ON 3RD AXEL LEFT SIDE.	ADRIAN	\$480.86	4 HRS
4/14/18	Install new mud flap	Adrian		1h
3/19/18	HYDRAULIC LINE FITTING SNAP OFF FROM TRAILER	ADRIAN	\$29.24	1h 30m
3/4/18	Trailer brakes not working right	Adrian	\$153.96	
11/12/17	R&R Broken Shock Mount Lt Front	Ray		
7/20/17	REPAIR SCREW IN TIRE	KRIS		
7/10/17	SCREW BLACON AND BUMPER LIGHT BAR	KRIS		
7/10/17	ANNUAL	KRIS		
7/8/17	REPLACED 48" OF DECK REPLACED 9" OF DECK	KRIS		
7/7/17	REPAIR AIR LEAK ON AIRBAG LR AXLE REPLACED FITTING 10' SECTION OF AIR LINE	KIRS		
5/22/17	FIXED BROKEN HYDRAULIC FITTING	SH	\$13.64	
5/16/17	INSTALLED 4 NEW TIRES, REPLACED #2 AXLE RIGHT AIR BAG, REPLACED LEVELING VALVE LINKAGE	DO, SH	\$1017.76	
5/10/17	REPAIRED LIGHTING ISSUE, REPAIRED HYDRAULIC LEAK, ADJUSTED BRAKES AND GREASED	SH	\$133.87	
3/17/17	TESTED UNIT AND FOUND BAD HOSE REMOVED HAD ONE MADE AND INSTALLED IT	SH	\$99.42	
3/14/17	REPLACED HYDRAULIC FITTING ADAPTER ON FRONT OF TRAILER	SH	\$11.63	
2/23/17	REPLACED BLOWN TAIL LIGHT	SH	2.56	
1/4/17	R&R BULKHEAD FITTINGS ON BULKHEAD	NG	\$23.06	
	REMOVED HYDRAULIC CYLINDER THAT MOVES SUBFRAME, DISASSEMBLED & HAD ELECTRO FLUID POWER COME AND TAKE BACK TO THEIR SHOP TO RUFF THE RODS AND REPACK AND RESEAL THE CYLINDER, INSTALLED REBUILT CYLINDER ONTO TRAILER	NG, DO	\$1625.00	
11/21/16	REMOVED AND REBUILT HYDRAULIC MOTOR FOR WINCH AND REINSTALLED, R&R LEAKING HYDRAULIC HOSE, INSTALLED NEW WINCH CABLE	DO/NG	\$440.40	
8/15/16	INSTALLED 4 NEW TIRES ON BACK, PUT 4 WORST TIRES TO FRONT AXLE, CHANGED MIDDLE AXLE BRAKES, ADJUSTED ALL BRAKES AND GREASED TRAILER, INSTALLED NEW WHEEL SEAL ON MIDDLE AXLE LEFT SIDE.	DO	\$1187.37	
8/9/16	REPLACED LEAKING AIR BAG ON LEFT SIDE RRR AXLE FOR LEAKING AT STUD. NOT REPAIRABLE	DEREK	\$200.00	
8/5/16	REPLACED ELECTRICAL SOCKET	NG	\$10.88	
6/15/16	PERFORMED ANNUAL INSPECTION	RW	--	
6/13/16	REPLACED MISSING DECK BOARD, SERVICED TRAILER AS WELL.	JIMBO	\$19.99	
5/20/16	FIXED GROUND FOR ABS INDICATOR LIGHT	MR		
	REMOVED ALL LEVELING VALVES AND MADE IT SO ALL AXLES RUN OFF ONE VALVE WHICH IS ON THE CENTER AXLE, FIXED TENSION ON WINCH	DO	\$49.95	
4/26/16	INSTALLED 2 NEW TIRES	DO/MR	\$450+TAX	
4/20/16	REPLACED LR AIRBAG, WELDED SHOCK MOUNTS BACK ON AND REINSTALLED SHOCKS, INSTALLED NEW LEVELING VALVE ON FRONT AXLE, REPLACED BROKEN DECK BOARDS	DO	\$262.06	
4/11/16	R&R LICENSE PLATE LIGHT, R&R MALE HYDRAULIC HOOKUP ON TRAILER	NG	\$223.27	
3/10/16	R&R AIR BAG ON REAR AXLE PASSENGER SIDE, WELDED SHOCK BRACKET BACK INTO PLACE AND PLATED BOTH FRONT AND BACK OF BRACKET	AW	\$126.71	
3/2/16	R&R AIR BAG ON REAR AXLE PASSENGER SIDE	AW	\$126.71	
2/28/16	R&R BRAKE SHOES ON FRONT AXLE, R&R LEVELING VALVE ON MIDDLE AXLE	AW	\$220.06	
2/10/16	REMOVED BROKEN BOARDS ON TRAILER DECK AND REPLACED WITH NEW BOARDS	AW		
1/23/16	REPLACED PASSANGER SIDE MIDDLE AXLE AIR BAG	AW		
1/20/16	ADJUSTED LEVELING VALVE SO IT WOULDN'T CATCH ANYTHING AND SO IT WOULD INFLATE BAGS AND NOT LEAK OUT AIR	AW		
1/17/16	Replaced left middle airbag	Rw		
12/10/15	removed 3 axle subframe from trailer replaced both scams and bushings on rear axle welded chains on front and middle axle to keep the air bags from over extending replaced broken wabco valve replaced 1 abs sensor and 2 abs lines replaced all air hoses connecting to brake cans replaced all 6 shocks welded 1 shock hanger back on replaced all big lug nuts with the newer smaller sized ones installed grease whips on all rollers on inside of sub frame replaced 2 tires that were under 2/32 tread replaced leveling valve for middle axle replaced broken e-chain added electrical plugs and quick connect air fittings for easier removal of sub frame in the future.	ng/rw/rf		
11/21/15	REPLACED PLASTIC ZIP TIES WITH METAL ONES BECAUSE THEY BROKE AND ELECTRICAL WIRING GOT RIPPED OUT.	NG		
11/14/15	INSTALLED NEW 7 WIRE TRAILER WIRE TROUGH SUBFRAME TRACKING SYSTEM	NG/RW		
10/28/15	GREASED ALL GREASE POINTS/REPLACED 3 TIRES ON REAR AXLE	NG/RW		
10/14/15	CHANGED RIGHT FRONT AXEL TIRES	RW		
8/4/15	REPLACED REAR AXLE BRAKE SHOES AND RR WHEEL SEAL	NG		
7/21/15	REPLACED TIRES ON REAR DRIVER SIDE	NG		
7/13/15	PERFORMED ANNUAL INSPECTION	NG		
6/8/15	REPLACED ELECTRICAL CONNECTOR ON FRONT OF TRAILER	NG		
6/8/15	REPLACED HYDRAULIC FITTING ON FRONT OF TRAILER	NG		
6/2/15	REPLACED RIGHT SIDE BRAKE LIGHT	JM		
6/2/15	REPLACE SLACK ADJUSTERS ON MIDDLE AXEL AND LEFT REAR	JM		
6/2/15	MONTHLY SERVICE	JM		
6/1/14	REPLACED HUB ASSEMBLY ON DRIVER SIDE MIDDLE AXLE	NG		
6/1/14	REPLACED BEARINGS, BRAKE SHOES, DRUM, TIRES & RIMS	NG		
5/20/14	REPLACED HUB REPLACED 8 LUG STUDS & NUTS ON RR AXLE	NG		
5/1/14	2 NEW TIRES ON RR AXLE	NG		
5/1/14	REPLACED BOTH DRUMS ON FRONT AXLE & RIGHT SIDE SHOES ON FRONT AXLE	NG		
3/12/15	REPLACED 2 TIRES ON LEFT REAR AXLE & 2 ON RIGHT MIDDLE AXLE	NG		
3/2/15	CHECKED ALL BRAKES & READJUSTED	NG/ED		
3/1/15	INSTALLED CABLES SO AIRBAGS WOULDN'T EXTEND	NG		
3/0/15	REPLACED 4 TIRES AND FIXED HOLES IN DECKING	RW		
3/3/15	REPLACED WINCH CABLE	NG		
3/2/15	REPLACED OIL BATH ON REAR PASSENGER AXLE	NG		