

21

EV9194
1778




529-0643

ROCHESTER ASPHALT

ROCHESTER, MN,
USA

Ship Method	Date	PO #	Truck #	Term
COUNTER WILL CALL	9/17/2015			COD

Part Number	Description	Qty: Ordered	Ship	BO	Sale Price	Amount
DS404REB370 1-64609	Rears (Front) (ETN DS404) Rebuilt front diff, All new bearings seals and critical wear components 1 year warranty Ratio: 3.70 Cond: REBUILT Locker: NO Same As: DS405	1.00	1	0	\$1,595.00	
DS404REB370 1-64609	Core	1.00	1	0	\$100.00	



Subtotal: 1,695.00

Tax (7.3750%): 125.01

Total: 1,820.01

Payment: Card (1,820.01)

Invoice Balance: 0.00

ER #: 16649
02

CHESTER ASPHALT INC

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG	
	01	MACK VISION	1M1AE06Y11W009274	RA02	509439/509439	1132	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO	RATE	PAYMENT	INV. DATE
01JAN01 DD			23:00 30SEP15	CASH	0.00	AR	18SEP15
R.O. OPENED		READY		OPTIONS:			
17SEP15		18SEP15					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CHECK AND ADVISE FRONT MAKING POPPING, CLUNKING NOISE HAD TO LOCK
POWER DIVIDER IN TO MOVE

99 FOUND FRONT DRIVE AXLE CARRIER BAD ADVISED
ROYAL, ROYAL FOUND REAREND AND DELIVERED TO
SYSVERSON, R&R CARREIER, TEST DROVE GOOD.

101 CC

1 5199300 SPEEDEE SLEEVE

4 7485 DISC

2 TDA/KT17SB STRAP & BOLT KIT FOR EASY SERVICE
YOKE

1 C3164067 SEALANT

2 433-016 NUT16X1.5

32 OIL-15 75W90 OIL

101 CHECK OUT AND DRAIN OIL OUT OF FRONT REAR AND THEIR IS ALOT OF
BIG METAL PART IN THE BOTTOM REMOVE OLD REAR END REMOVE REAR END AND
WASH OUT HOUSING REMOVE YOKE AND INSTALL SLEEVE AND INSTALL ON NEW REAR
END AND INSTALL REAR END AND AXLES AND REFILL AND ROAD TEST

CUSTOMER PAY SHOP MATERIALS FOR REPAIR ORDER

PLEASE REMIT PAYMENT TO:

P.O. BOX 182
ALBERT LEA, MN 56007-0182

*** THANK YOU FOR YOUR BUSINESS! ***

DESCRIPTION	
LABOR AMOUNT	
PARTS AMOUNT	
GAS OIL LUBE	
SUBLET AMOUNT	
MISC CHARGES	
TOTAL CHARGES	
LESS ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	1282.95

CUSTOMER COPY

TER #: 16649
02

HESTER ASPHALT INC

COLOR		YEAR		MAKE/MODEL		LICENSE		MILEAGE IN/OUT		TAG	
		01		MACK VISION		1M1AE06Y11W009274		RA02		509439/509439 T32	
DEL DATE		PROD. DATE		WARR. EXP.		PROMISED		PO NO.		RATE	
01JAN01 DD						23:00 30SEP15		CASH		0.00	
R.O. OPENED		READY		OPTIONS:				PAYMENT		INV. DATE	
17SEP15		18SEP15						AR		18SEP15	

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

A CHECK AND ADVISE FRONT MAKING POPPING, CLUNKING NOISE HAD TO LOCK
POWER DIVIDER IN TO MOVE

99 FOUND FRONT DRIVE AXLE CARRIER BAD ADVISED
ROYAL, ROYAL FOUND REAREND AND DELIVERED TO
SYSVERSON, R&R CARREIER, TEST DROVE GOOD.

101 CC
1 5199300 SPEEDEE SLEEVE
4 7485 DISC
2 TDA/KT17SB STRAP & BOLT KIT FOR EASY SERVICE
YOKE
1 C3164067 SEALANT
2 433-016 NUT16X1.5
32 OIL-15 75W90 OIL

...., 101 CHECK OUT AND DRAIN OIL OUT OF FRONT REAR AND THEIR IS ALOT OF
...., BIG METAL PART IN THE BOTTOM REMOVE OLD REAR END REMOVE REAR END AND
...., WASH OUT HOUSING REMOVE YOKE AND INSTALL SLEEVE AND INSTALL ON NEW REAR
...., END AND INSTALL REAR END AND AXLES AND REFILL AND ROAD TEST

CUSTOMER PAY SHOP MATERIALS FOR REPAIR ORDER

PLEASE REMIT PAYMENT TO:

P.O. BOX 182
ALBERT LEA, MN 56007-0182

*** THANK YOU FOR YOUR BUSINESS! ***

DESCRIPTION	
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	1282.95

CUSTOMER COPY

ER # 16649

CHESTER ASPHALT INC

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	CUT	TAG
	01	MACK VISION	1M1AB06Y11W009274	RA02	537592/537592	T9274	
DEL DATE	PROD DATE	WARR EXP	PROMISED	POND	RATE	PAYMENT	INV. DATE
01JAN01 DD			23:00 30AUG17	32	0.00	AR	30AUG17
RO OPENED		READY	OPTIONS				

03AUG17 30AUG17

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

A MOCK DOT

99 MOCK DOT

594 CET

SUBL CLEAN THE TRUCK

CSUB

////#594 PERFORMED MOCK DOT GAVE CODY LIST.

B PLATINUM SERVICE

99 PLATINUM SERVICE

612 CET

614 CET

12 OIL-14 SPIRAX GSX50

1 999766 ZIEGL-OIL SAMPLE

1 DN/P550287 CART LUBE BYPAS

2 FG/LF667 PACKAGE. LUBRICATION FILTER

1 SLO/550027631 GADUS S2

1 LBF/LFF4470 FUEL FILTER

1 DN/P554471 FLTR FUEL

50 OIL-07 15W40 CJ-4 ROTELLA

1 WSW SOLVE

//// PERFORMED SERVICE, FILLED OUT SHEET, TRANY WAS LOW, ADDED OIL, LEFT
//// BOX HINGE WOULD NOT TAKE GREASE. RIGHT HINGE GREASE ZERT MISSING
//// #614 NOTICED OIL LEAK AT TOP OIL FILTER WHILE REPLACING STEER
//// SLACKS, REMOVED BOLT & CAP AND FOUND THAT THERE WAS TWO O-RINGS,
//// REMOVED ONE PUT CAP BACK ON AND CLEANED OFF OIL

C REPLACE SLACKS ON STEER AXLE

99 REPLACED STEER AXLE SLACK ADJUSTER

612 CET

236.50 236.50
122.22 122.22 244.44

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

SHIPPED TO ROCHESTER ASPHALT INC

SHIP TO ROCHESTER ASPHALT INC
ROCHESTER ASPHALT INC

CHECK NO.	VIN	CID	YEAR	MAKE MODEL	ODOMETER	TERMS
	1M1AE06Y11W009274	32	2001	MAC CX613	543438	NET 30

PURCHASE ORDER NO.	CONTACT NAME AND PHONE NO	CUST. NO.	SALESMAN
# 32	ROYAL PTO #32	502397	5789

PROBLEM PTO IS LEAKING.

OP# 1 065 001 08 HYDRAULIC IN VEHICLE REPAIRS
PTO WAS LEAKING BECAUSE THE PUMP HAD NO
REAR SUPPORT BRACKET. GOT GO AHEAD TO
REPLACE PTO. ROYAL REQUESTED WE LEAVE
PUMP AS IS. HE WOULD TAKE HIS CHANCES
INSTALLED REAR PUMP SUPPORT BRACKET.
TRANS OIL LOOKED A BIT SHINEY, MOST
LIKELY FROM PTO GEARS, WE CHANGED THE OIL

QTY	POOL PART NUMBER	DESCRIPTION	PRICE	EXT
1.00	2100 TG8S-KIT07-X1KX	MUNCIE -TG- SERIE		
1.00	2100 03T34284	TG-INPUT - U68		
1.00	2100 16MK3803P-A	AIR SHIFT COVER -		
1.00	2100 20MKM801	8-BOLT METRIC STU		
1.00	8141 SBKF918-1	BRACKETS & BOLT K		
23.00	8167 MP50S-LB	50W SYN G/L, LB		

PARTS SUBTOTAL:
LABOR SUBTOTAL:
SHOP SUPPLIES :

TOTAL PARTS :
TOTAL LABOR :
TOTAL OTHER :
TAX AMOUNT :
INVOICE TOTAL :

FLEETPRIDE
P.O. BOX 9156 CORPUS CHRISTI TX 78469

Phone 361-883-4358
Fax 361-883-3323

INVOICE TOTAL \$****1,534.76

ENTERED

SHIP TO ROCHESTER ASPHALT INC

SHIP TO ROCHESTER ASPHALT INC
ROCHESTER ASPHALT INC

CHECK NO.	VIN	CID	YEAR	MAKE	MODEL	ODOMETER	TERMS
	1M1AE06Y11W009274	32	2001	MAC	CX613	547676	NET 30

PURCHASE ORDER NO.	CONTACT NAME AND PHONE NO	CUST. NO.	SALESMAN
#32	ROYAL 208.1736	502397	5789

PROBLEM DOT
TEST DRIVE, FRONT ENDS SHAKES, DIAGNOSE
AND ADVISE.


OP# 1 999 003 97 FEDERAL DOT TRUCK INSPECTION

MECHANICS: 3740 HOURS 1.00 PARTS SUBTOTAL:
LABOR SUBTOTAL:

SHOP SUPPLIES :

OP# 2 011 001 07 FRONT AXLE INSPECTION
THE LEAF SPRINGS WERE NOT A MATCH. RH
SIDE HAD A PART # TAG ON IT AND LOOKED
FAIRLY NEW. WE MATCHED THAT PART # AND
INSTALLED NEW SET ON THE DRIVER SIDE.
CURB SIDE GOT NEW PIN/BUSHING ASSEMBLYS
3 LOCATIONS, NEW UBOLTS ETC.
HAD TO ADD ANOTHER LEAF TO DRIVER SIDE
SPRING PACK, REQUIRED NEW CENTER BOLT
AS WELL.

QTY	POOL PART NUMBER	DESCRIPTION	PRICE	EXT
8.00	5 E2545	WASHER 3/4" ID X 1		
8.00	5 E3001	3/4"-16 X 1-1/16"		
4.00	185 8T3426	3/4 X 26 THREADED		
3.00	5115 RB189	MACK BUSH-RPL.10Q		
1.00	556 BUSHING	BUSHING		
2.00	555 NUT	NUT		
2.00	555 BOLT	BOLT		
1.00	261 62-968	TRUCK SPRING MACK		



ter Asphalt

FT 9981

6-13-17

DATE

Washplant

PART NUMBER	DESCRIPTION OF PART	AMOUNT
	bearing	
	race	
	1" x 6" bolt	
	1" washer	
	1" locknuts	
	input shaft seal	
	output shaft seal	
	1" x 3 1/2" SHCS	
TOTAL PARTS		417.52
	Freight	
TOTAL ACCESSORIES		7.85

SERIAL NO.

MOTOR NO.

PROMISED DATE & TIME

CALL WHEN READY?

☐ YES ☐ NO

WRITTEN BY

DESCRIPTION OF SERVICES

- Output shaft does not turn
input shaft is turned -
- Remove output shaft rear
bearing. The gear and output shaft
It was necessary to remove the
the plant. Disassemble the gear box
gear from output shaft. Remove
from the output shaft. Install a
and press gear onto the output shaft
the gear box with new shaft seal
output shaft bearing. Reinstall
plant and fill the box with 17
220 gear oil.

Labor 60.0 hrs

	AMOUNT	TOTAL
		TOTAL
		TOTAL
		TOTAL
		TOTAL
		SUBTOTAL
TOTAL SUBLET		OLMST

TAX
TOTAL
ALL PA
& SERV

To: Rochester Asphalt, Inc.

Ship

To: Rochester Asphalt, Inc.

Ship Via PPY & ADD
Carrier FEDEXPRTY
Ship Date 5/8/2018
Due Date 6/8/2018
Terms Net 30 days

Customer ID 181539
P.O. Number VERBAL ROYAL
P.O. Date 4/9/2018
Our Order No. SO-024164

Salesperson/Client

Item No.	Description	Unit	Order Qty	Ship/BO Qty	Unit Price	Disc. %	Total Price
TAN-063	44" EAGLE CLASSIFIER SHOE TAN-063	EA	198	198	24.00	100	
TAN-063	44" EAGLE CLASSIFIER SHOE TAN-063	EA	35	35	24.00		

Total: 1,034.32
Payment Received: 0.00
Balance Due: 1,034.32