

asphalt

Byron, MN
CITY

BUSINESS PHONE

DESCRIPTION OF PART	AMOUNT
---------------------	--------

new cyl head
gasket set
stud kit
after cooler gskt
oring & hose
renan injector

TOTAL PARTS 2471 21

TOTAL ACCESSORIES

Machine shop

DATE

10.3.17

LICENSE NO.

CAT
YEAR/MAKE

MILEAGE

330
MODEL

SERIAL NO.

3306

MOTOR NO.

PROMISED DATE & TIME

CALL WHEN READY?

☐ YES ☐ NO

WRITTEN BY

DESCRIPTION OF SERVICES

- cooling system has excess
pushes out coolant -
- Cylinder head gasket is leak
Remove the cylinder head and
The ~~cylinder~~ cylinder head is cracked
Replace the cylinder head, resue
exhaust manifold, install new
studs and replace the gasket
the cylinder head. Replace
Refill with coolant, start and

Labor 20.0 hrs

AMOUNT

TOTAL LABOR

TOTAL PARTS

TOTAL ACCESSORIES

TOTAL SUBTOTAL

SUBTOTAL

TOTAL SUBLET

80.00

OLMSTED COU

TAX

TOTAL

ALL PARTS

& SERVICES

Asphalt

Byron, MN
CITY

BUSINESS PHONE

QTY	DESCRIPTION OF PART	AMOUNT
	gasket kit	
	isolators kit	
	oring	
	1/2 x 2 bolt	
TOTAL PARTS		439.35

QTY	DESCRIPTION OF PART	AMOUNT
TOTAL ACCESSORIES		

10.25.17
DATE

LICENSE NO.

CAT
YEAR/MAKE

MILEAGE

330
MODEL

SERIAL NO.

3306
MOTOR NO.

PROMISED DATE & TIME

CALL WHEN READY?

☐ YES ☐ NO

WRITTEN BY

DESCRIPTION OF SERVICES

- engine oil leaking from the housing -
Drain hyd oil and remove pump, muffler, flywheel and the housing bolts are loose and dowels slid out of the block clean the surfaces of the and housing, install a new gasket and dowels, torque housing bolts 100 ft lbs. Reinstall flywheel torque to 170 ft lbs. Install new insulator drive hub for the main pump. Reinstall the muffler, pump, and refill t

Labor 12.0 hrs

QTY	DESCRIPTION OF PART	AMOUNT	TOTAL LABOR
			TOTAL PARTS
			TOTAL ACCESSORIES
			TOTAL SUBLET
			SUBTOTAL
			OLMSTED COUNTY TAX
			TOTAL ALL PARTS & SERVICES

ter Asphalt

Byron, MN
CITY

9.23.17
DATE

LICENSE NO.

CAT

YEAR/MAKE

MILEAGE

3306

MODEL

SERIAL NO.

MOTOR NO.

PROMISED DATE & TIME

CALL WHEN READY?

☐ YES ☐ NO

WRITTEN BY

DESCRIPTION OF SERVICES

INTEREST

LABOR

LUBRICATE

CHANGE OIL

CHANGE: ☐ TRANS.

REPLACE OIL FILTER

CLEAN AIR FILTER

REPACK FRONT WHEEL

ADJUST BRAKES

ROTATE TIRES

☐ WASH ☐ POLISH

TUNE MOTOR

RT NUMBER DESCRIPTION OF PART AMOUNT

Water pump
oring

TOTAL PARTS 47225

TOTAL ACCESSORIES

- The engine is leaking coolant & engine oil -

- The coolant leak is from the pump vent - replace the water pump and refill with coolant.

Labor 5.0 hrs @ 100/hr

- the engine oil leak is from engine oil filter housing - replace orings from the housing.

Labor 1.0 @ 100/hr

AMOUNT

TOTAL LABOR

TOTAL PARTS

TOTAL ACCESSORIES

TOTAL SUBLET

SUBTOTAL

TOTAL SUBLET

OLMSTED COUNTY TAX

TAX

TOTAL
ALL PARTS
& SERVICES



CITY

DATE _____

CAT
YEAR/MAKE

330
MODEL

3306

CALL WHEN READY?

☐ YES ☐ NO

WRITTEN BY

DESCRIPTION OF SERVICES

-Service call to Cinemagic T

Remove engine oil pans.

housing is not setting flu

the block, the gasket is blo

on the pan and the flywheel

Install pans and refill w/ oil

oil. - Repair will need +
made to the 1st 5th 10th

made to the ~~best~~ flywhorl

Labor 5.0 hrs

TOTAL PARTS	90	32
-------------	----	----

mileage

TOTAL ACCESSORIES	2500
-------------------	------

AMOUNT

TOTAL LABOR

TOTAL PARTS

TOTAL ACCESSORIES

TOTAL SUBLET

SUBTOTAL

OLMSTED COUNT

TAX

TOTAL
ALL PARTS

& SERVICES