

Date: 05/31/2016

Year		Make/Model		Vehicle Identification	
1993		AGC 7600		1221	
Stock No	PO	License	Tag	Customer	Telephone
10908				12944	

Cond	OpCode	Description	Quantity	List	Net	Total
------	--------	-------------	----------	------	-----	-------

F REPLACED BAD A/C LINES,DRIER,AND EXPANSION VALVE. PULLED VACUUM AND FILLED SYSTEM WITH FREON. REPAIRED WIRING TO COMPRESSOR CLUTCH,AND REPLACED FUSE TO FAN. A/C TESTED OK
REPLACED 2 STRUTS ON REAR WINDOW,AND 1 ON DOOR.
READJUSTED AND RETIGHTEN EXHAUST CLAMP TO FIX EXHAUST LEAK.

- L LABOR
- LABOR
- P OTHER PARTS
- 5250-165217 LIFT SUPPORTS (STRUTS)
- P OTHER PARTS
- NAPA 198872 A/C HOSES AND FITTINGS
- P 70937297 O-RING-0.0
- P 3010471X1 O-RING-X 7
- P 70924003 O-RING
- P OTHER PARTS
- 5250-166025 PUSH TYPE RETAINER FOR A/C
- P R134A FREON
- P 72245878 ABSORBER/S
- P OTHER PARTS
- 72259305 FLASHER SWITCH
- P FREIGHT FREIGHT

008 HAULING

- L LABOR
- LABOR
- O TKC CUSTOMER HAULING
- HAULED TRACTOR FROM CUSTOMER LOCATION NEAR MARION, KS TO LDI-HILLSBORO.
- 4/21/16. TRK. #1. PER BRIAN MCMILLAN

Subtotal charges this section

M SHOP SUPPLIES

VISIT US ONLINE AT WWW.LANGDIESELINC.COM

PAGE 1		
CASH	CHG.	F.P.
CHK		
ACCT. NO. 12944		

SALESMAN DM	PURCHASE ORDER NO.	R.O. NO.	P.L. NO. 49015	INVOICE DATE 06/08/2016	TIME 08:19 AM	INVOICE NO. 41572A
----------------	--------------------	----------	-------------------	----------------------------	------------------	-----------------------

QUANTITIES			PART NUMBER	DESCRIPTION	VENDOR BIN LOC.	PRICES
ORDERED	B/O	SHIPPED				
1		1	N V837079718	FUEL FILTE	1914	
			N *CASH DISCOUNT	5%		

CHECK

SHIP VIA	DESCRIPTION	ACCOUNT	AMOUNT
TERMS: Account due 10th of month following purchase. Service charge 1.5% per month (18% annual) on unpaid balance. No parts returnable after 30 days. No return on electrical parts. 20 % restocking charge on return of special order parts. Thank You. For Farm Use Only <input type="checkbox"/> Yes <input type="checkbox"/> No ACKNOWLEDGEMENT and RECEIPT OF ABOVE:	PARTS	NONTAXABLE	
	FREIGHT		
	SALES TAX		
	INVOICE TOTAL		76.06

ng-hd_invoice.template

Copyright (c) 2008 H&S Systems

5

Date: 05/31/2016

Year	Make/Model	Vehicle Identification
1993	AGC 7600	1221
Stock No	PO	License
10908		
Tag	Customer	Telephone
	12944	

Send	OpCode	Description	Quantity	List	Net	Total
------	--------	-------------	----------	------	-----	-------

LABOR

P 72273949 KIT, RING

004

EMERGENCY BRAKE

F REMOVED RUSTY CABLE AND FREED UP RUSTY ADJUSTER. INSTALLED NEW CABLE AND ADJUSTED. NOT ENOUGH TRAVEL TO ACTIVATÉ EMERGENCY BRAKE. BRAKE PADS WILL NEED TO BE REPLACED. DRAINED OIL AND REMOVED BRAKE COVER. REPLACED BRAKE PADS AND REINSTALLED ASSEMBLY BACK INTO UNIT. REINSTALLED COVER AND REFILLED TRANSMISSION WITH OIL.

L

L LABOR

LABOR

P 72231804 CABLE,CONT 1.00
P 72223043 SECTOR 2.00
P 72223049 SECTOR 2.00
P 72221824 GASKET 1.00
P OTHER PARTS 1.00
JARVIS 11471 BRAKE LINE

Subtotal charges this section

005

STARTING ISSUE

C BAD CABLE END,WEAK STARTER,AND BATTERY HAD 3 BAD CELLS

F REPAIRED CABLE WITH NEW END,REPLACED STARTER AND BATTERY.

L

L LABOR

LABOR

P 601306-4 TERMINAL 1.00
P 54053-3 TUBING 3.00
P 82272339N STARTERMOT 1.00
P OTHER PARTS 1.00
5250-165988 BATTERY

Subtotal charges this section

006

SERVICE

F CHANGED ENGINE OIL AND FILTER. CHANGED FUEL,HYD,AND AIR FILTERS

L

L LABOR

LABOR

P V836339371 FUEL ELEME
P 72270873 FILTER,OIL
P 72270879 ELEMENT,AI
P 821 HYD. OIL
P SAE15-40W OIL

S

007

A/C,DOOR STRUTS,EXHAUST

long-hill-brooks_service_pg1_template

CUSTOMER FINAL INVOICE

page 2 of 4

Date: 05/31/2016

Year	Make/Model	Vehicle Identification
1993	AGC 7600	1221
Stock No	PO	License
10908		
Tag	Customer	Telephone
	12944	

Cond	OpCode	Description	Quantity	List	Net	Total
------	--------	-------------	----------	------	-----	-------

Type: TRA RO Open Date: 04/18/16 Sold: 10/22/93
Meter In: 2882

001 CLUTCH MASTER CYLINDER
D INSTALL CUSTOMER SUPPLIED MASTER CYLINDER. CUSTOMER NOT SURE IF CLUTCH IS OK.

F JUMP STARTED TRACTOR TO BRING IN THE SHOP. BLEED CLUTCH TO CONFIRM THERE IS AN INTERNAL LEAK. REPLACED AND BLED NEW MASTER CYLINDER. SLAVE CYLINDER TRAVEL IS SUFFICIENT, BUT NOT WORKING CLUTCH. UNIT NEEDS TO BE SPLIT.

L L LABOR
LABOR
P DEXTRON OIL

Subtotal charges and service

002 CLUTCH

F REMOVED LOADER, POWER WASHED UNIT, THEN REMOVED LOADER SUB FRAMES. HAD DIFFICULTY REMOVING THE RUSTED DRIVESHAFT. SPLIT UNIT AND REMOVED CLUTCH ASSEMBLY. CLUTCH DISC EXTREMELY WORN, AND FLYWHEEL WILL NEED TO BE MACHINED. PARTS ORDERED. CLEANED CLUTCH HOUSING. INSTALLED RESURFACED FLYWHEEL AND THE CLUTCH ASSEMBLY WITH NEW PARTS. REASSEMBLED SPLIT UNIT.

L L LABOR
LABOR
P 72479325 BEARING
P M3381122R PR PLATE, R
P CORES: Core Chrgs
P C3381122R CORE, PRES
P D2226743 DISC, REMA
P CORES: Core Chrgs
P C2226743 CORE, DISC
P FREIGHT FREIGHT
P OTHER PARTS
72226317 THROW OUT SLEEVE
P FREIGHT FREIGHT
S OSL OUTSIDE LABOR
FLYWHEEL SURFACING

003 POWER STEERING LEAK

L F INSTALLED REBUILD KIT RH STEERING CYLINDER.
L LABOR

CUSTOMER FINAL INVOICE

page 1 of 4

Date: 05/31/2016

Year	Make/Model	Vehicle Identification
1993	AGC 7600	1221
Stock No	PO	License
10908		
	Tag	Customer
		12944
		Telephone

Cond	OpCode	Description	Quantity	Unit	Net	Total
------	--------	-------------	----------	------	-----	-------

I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE AS DESCRIBED ON MACHINE(S) NAMED HEREON. ALL REPAIR PARTS ARE TO BE BILLED AT YOUR REGULAR PRICES. I AGREE TO PAY CASH FOR SUCH REPAIRS AND LABOR ON DELIVERY OF MACHINE(S) OR ON TERMS SATISFACTORY TO YOU, AND UNTIL PAID IN FULL, ANY UNPAID BALANCE SHALL CONSTITUTE A LIEN ON THIS MACHINERY. I FURTHER AGREE TO PAY ALL COURT COST, ATTORNEY'S FEES AND EXPENSES ON ANY UNPAID BALANCE COLLECTED THROUGH AN ATTORNEY, AND AGREE THAT YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO SAID MACHINERY FROM FIRE, THEFT OR OTHER CAUSES BEYOND YOUR CONTROL.

Received By

DESC	TOTALS
LABOR	
PARTS	
SUBLET	
MISC	
OTHER	
SUBTOTAL	
TAX	
TOTAL	8006.85

CUSTOMER FINAL INVOICE