

VIN		1 F D F E 4 F S X A D A 7 6 0 1 8		DATE IN		07/20/17	
YEAR	MAKE	MODEL	COLOR	TIME IN		06:42	
2010	FORD	E450 SUPER	O	09:59		CLOSED	
MILES IN	MILES OUT	FIRST	00/00	08/07/17			
135257	135257	12/31/77					
SEE ALSO							

CALL WHEN READY

- (1) TOWED IN
=====
- VEHICLE TOWED IN FROM HWY 44 & JEFFERSON.
(Tech:12) D
- Labor T12
SUPERIOR T 27731
Total Sublet
Total Repair (Customer)
- (2) CHECK ENGINE NOISE - C/S THEY HEARD A CLUNK NOISE WHILE DRIVING & THE VEHICLE STOPPED RUNNING. IT WILL RESTART BUT IS MAKING A KNOCKING/RATTLING NOISE FROM THE ENGINE. PLEASE CHECK.
=====
- UPON INITIAL INSPECTION, NOTED LARGE HOLE IN SIDE OF ENGINE BLOCK. WILL REQUIRE ENGINE REPLACEMENT. CAUSE OF ENGINE FAILURE CANNOT BE DETERMINED AT THIS TIME.
(Tech:24) D
- Labor T24
Total Repair (Customer)
- (3) REMOVE & REPLACE ENGINE ASSEMBLY
>> INCLUDES RECOVER & CHARGE BOTH A/C SYSTEMS
SWAP ALL NECESSARY COMPONENTS FROM ORIGINAL ENGINE TO NEW ENGINE, TOP OFF ALL FLUIDS AS NECESSARY <<
**** REMANUFACTURED ENGINE COMES WITH A NATIONWIDE 3 YEAR, UNLIMITED MILEAGE WARRANTY
=====
- TEST DRIVE AFTER REPLACEMENT TO VERIFY ALL REPAIRS & NO ADDITIONAL CONCERNS WERE NOTED AT THIS TIME. CUSTOMER IS TO RETURN EVERY 5000 MILES FOR ENGINE OIL CHANGE MAINTENANCE.
(Tech:14) D
- Labor T14
VP-9C2Z-6006-CARM (ENGINE, F) 1
VP-G-05 (G-05 ANTIFREEZ) 3
VP-5C3Z-6754-DA (OIL DIPSTK) 1
VP-F1AZ-6379-A (FLYWHEEL BOL) 1
VP-59938 (A/C HIGH S/ CA) 2
Total Labor
Total Parts
Total Repair (Customer) 6549.30

W/C	INT.	CUSTOMER