

CITY STATE ZIP

QUAN. PARTS AND ACCESSORIES NET PRICE AMOUNT

1 14-00209-00 Drier
1 50-00018-19 RSC
1 2000000
1 N. frozen
12 2404A RSC

Shop/EPA

Free on loan
X new be

DATE 3-15-19

TYPE

UNIT 32

Repair ref leak @ King Valve / SV4.

SV4 + King Valve not leaking. Oil coming from cracked header tube @ cond. coil at the top. Recovered 8 lbs 2404A. Solder leak & leak check w/ nitrogen. System holding. Replace drier, evac & charge.

Added 12 lbs lost ref. Switches ops OK. Oil recolorant, belts OK.

2nd lower drive belt per cust. request. Belt tip passed.

Lights, ABS, br. kobs, subframe OK.

✓ #1793

TOTAL PARTS

295.63

LABOR

PARTS

TAX

TOTAL

RECEIVED BY

817.0

Vehicle: 1999 Freightliner
Engine: N14
Unit #:

Cell
Work
Mil. In
Mil. O
Plate
VIN:1FUPCDZB5XPB36073

Description of Parts	Part	QTY	Extended
Refer Alternator - Carrier		1	
Freight		1	
Alternator Belt		1	
Oil Filter		1	
Reefer Oil		13	
Right Signal Light		1	

All Parts are NEW Unless Shown as Used.

Description Of Labor or Service	Labor	Hour	Extended
Dot Inspection Trailer			
Dot Inspection Tractor			
Replace Alt, Belt And Change Oil, Replace Right Signal Light			

◆ SUMMARY:

7012.5

----- Thank You For Your Business -----

X _____

ALL REPAIRS PROPERLY PERFORMED P.A. 300

X _____

Invoice #: 0115

Date: 3/1/2019

PARTS AMOUNT:

LABOR AMOUNT:

SUB TOTAL:	830.40
Tax Exempt:	0.00
TOWING:	0.00
DISPOSAL:	0.00
SHOP SUPPLIES:	0.00
Discount:	(0.00)

TOTAL: \$ 830.40

INVOICE

PAGE 1

BUS:		CELL:		SERVICE ADVISOR: 850 LUTHER JEFFERSON		
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	06	CARRIER ULTIMA	KAH90836076		1/9380	TT32
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN06 DI			17:00 27FEB19		0.00	CC
R.O. OPENED	READY	OPTIONS:				
13:32 27FEB19	17:39 27FEB19					
LINE OPCODE TECH TYPE HOURS				LIST	NET	TOTAL

A DIAGNOSTIC & ESTIMATE REPAIRS
 XA1A DIAGNOSTIC & ESTIMATE REPAIRS
 1550 CPC
 EPA EPA CHARGE
 1 50-00178-24 V-BELT, FANSHAFT
 1 50-01173-03 CLUTCH ASSY, COMPLETE
 1 CAR50-00232-24 KEY, RD END, 4MM X 22 MM SST
 10 CARR404A-024 R-404A, 24# DISPOSABLE
 PARTS: 654.82 LABOR: 540.00 OTHER: 5.00 TOTAL LI
 FAN CLUTCH WAS BAD R/R FAN CLUTCH . CHARGED SYSTEM WITH 9LBS C.
 404A . SHIFTED GEAR BOX COUPLER INTO RIGHT POSITION . PRETRIP/PASSED .
 READY TYLER .

EST: 5.35 27FEB19 13:32 SA: 850

CUSTOMER PAY SHOP SUPPLIES FOR REPAIR ORDER

State Tax

DESCRIPTION	
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	1264.62
LESS INSURANCE	0.00
SALES TAX	
PLEASE PAY	

Invoice

Date Invoice #

5/18/2018 6

P.O. Number Terms

COD

Reference #

Year Make Serial # Taxable License Plate # Unit #
2005 UTILITY 6U795419 PARTS/LAB... T32

Qty/Hrs/Ft/SqFt/Lbs	Description	Price Ea	Amount
1.3	FHWA INSPECTION ~ GREASE, SERVICE 7-WAY, CHECK PLACARDS, ADJUST BRAKES, CHECK HUB OIL / TIGHTEN HUB CAP BOLTS		
1	FHWA STICKER		
1	TUBE GREASE		
1	SERVICE REEFER UNIT AND CHECKED OVER UNIT		
1	FUEL FILTER		
1	AIR FILTER		
1	OIL FILTER		
3	15-40 OIL		
3	R & R EQUALIZERS		
2	EQUALIZERS WITH BUSHING		
2	EQUALIZER BOLTS AND NUTS		
2	5/8" X 4" REBOUND BOLTS AND NUTS		
1	SHOP SUPPLIES		

Sales Tax (

Total

Payments/Credits

Balance Due

Due Date

5/18/2018