

| | |
|--------------------|------|
| INVOICE DATE | |
| 06/11/2019 03:43PM | |
| INVOICE NO. | PAGE |
| 1-291620184 | 1 |
| | |

SOLD SLACK FARMS
TO

SHIP SLACK FARMS
TO

| | | | |
|---------------|---------------|-----------|-----------|
| CUSTOMER P.O. | R/S ORDER NO. | PRICE PER | EXTENSION |
|---------------|---------------|-----------|-----------|

TERMS: (00) NET 10TH
 COMPLETION DATE: 06/07/2019
 UNIT: 8 YEAR: 2007 MAKE/MODEL: KW T600
 SERIAL: 1XKADB8X37J093210 MILEAGE: 218090
 Delivery Date:
 Eng. Make/Model:
 Engine Serial:
 CPL/Arrangement:
 OPR#01 14 000 00 AIR CONDITIONING REPAIRS
 A/C DOESN'T WORK
 RECOVERED THE SYSTEM AND GOT 2.68LBS OUT OF A 4LB SYSTEM
 PRESSURIZED THE SYSTEM AND FOUND THE LOW SIDE SHRADER
 VALVE LEAKING. REMOVED AND REPLACED THE SHRADER VALVE.
 REPRESSURIZED THE SYSTEM TO CHECK FOR LEAKS-NONE.
 RECHARGED THE SYSTEM WITH 4LBS OF FREON. FOUND THE
 COMPRESSOR CLUTCH WILL NOT ENGAGE. CHECKED THE
 COMPRESSOR RELAY-NO POWER TO 85 PIN CONNECTOR. REMOVED
 INTAKE DUCT AND PULLED THE HVAC COVER. INSTALLED A
 JUMPER IN THE FREEZE SWITCH AND THE COMPRESSOR CLUTCH
 ENGAGED. REMOVED AND REPLACED THE FREEZE SWITCH-VERIFIED
 STILL GOOD. REINSTALLED THE HVAC COVER AND INTAKE DUCT.
 OPS CHECKED THE SYSTEM ONCE MORE STILL WORKS WELL.
 138
 1 PC SR2000020 SWITCH
 1 PC VH11150 CORE ASSY- VALVE- ACCE
 1 DY D2074-1243 A/C-HDLN VALVE CORE H :
 2 LD R134A-30 LB REFRIGERANT
 PARTS SUBTOTAL
 LABOR SUBTOTAL
 SHOP SUPPLIES
 HAZARDOUS MATERIAL
 ** OPR SUBTOTAL
 OPR#02 17 000 00 MISC. ENGINE REPAIR - SPECIFIED BELOW
 CEL
 PULLED AND PRINTED THE CODES FOUND CODE 385-5(IVA OIL
 PRESSURE VOLTAGE HIGH). REMOVED AND REPLACED THE
 PRESSURE SENSOR CLEARED THE CODES AND SENT THE TRUCK ON
 A ROAD TEST-NO CODES RETURNED.
 171
 1 CT 2842728 SENSOR GP-PR - FIX A :
 1 CT 5P7814 SEAL

| | |
|--------------------|------|
| INVOICE DATE | |
| 06/11/2019 03:43PM | |
| INVOICE NO. | PAGE |
| 1-291620184 | 2 |

SOLD SLACK FARMS
TO

SHIP SLACK FARMS
TO

| | |
|---------------|--------------|
| CUSTOMER P.O. | RS ORDER NO. |
| PRICE/PER | |
| EXTENSION | |

PARTS SUBTOTAL
LABOR SUBTOTAL
SHOP SUPPLIES
** OPR SUBTOTAL

OPR#03 01 000 00 INSPECTION OR SERVICE OPERATIONS
CHECK OUT CLUTCH ADJUSTMENT
INSPECTED THE CLUTCH ADJUSTMENT. FOUND 1/8 AT THE FORK
1/2 AT THE CLUTCH BRAKE AND 1 1/4 PEDAL FREE TRAVEL. NO
ISSUES FOUND.
171

PARTS SUBTOTAL
LABOR SUBTOTAL
SHOP SUPPLIES
** OPR SUBTOTAL

*TOTAL PARTS:
*TOTAL LABOR:
*TOTAL SHOP SUPPLIES:
*TOTAL EPA:

* " WE ARE EAGER TO BE YOUR SERVICE AND PARTS HEADQUARTERS " *
*
* THANK YOU FOR YOUR BUSINESS ! *
*

| | | | | | |
|----------|---------|----------|------------------|----------|------------|
| SHIP VIA | FREIGHT | SUBTOTAL | TAX STATUS/STATE | SALE TAX | PLEASE PAY |
| | | | | | 1073.70 |