

SERVICE INVOICE:

LINQ:

DELIVER TO

RECEIVED

DEC 19 REC'D

BY:

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
12/6/2019 4:00:00PM	12/9/2019							
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	COMPONENT S/N	IN SERVICE	ODOMETER IN	ODOMETER OUT
2010	FREIGHTLINER	M2	1FVACYDT3ADAN7003	260	6510866418		22583	22594

Sold Operations

JOB #1 027-000-000 SC Transmission - Main, Automatic

COMPLAINT Transmission Default - Diagnostic -TOWED IN-WONT START AT TIMES. SHIFT PAD HAS CATEYES. LOSS OF COMMUNICATION W/TCM & ECM.

CAUSE TCM FAILED

CORRECTION UNIT STARTED AND DROVE IN. CONNECTED TO DOC. CODES P0880 AND P0777. VOLTAGE READ OK ON DOC. AFTER RUNNING FOR A FEW MINUTES. TRUCK STARTED JERKING AND THE SHIFTER WENT BLACK. NO TRANS ON DASH. REMOVED TCM FROM TRUCK. PROGRAMMED TEST TCM AND INSTALLED. TEST DROVE. NO PROBLEMS. REMOVED TEST. REINSTALLED ORIGINAL TCM. NO TRANS ON DASH CAME BACK. REMOVED ORIGINAL TCM. PROGRAMMED NEW TCM.

OLD CIN-4A00HAH002S
 NEW CIN-4H00HAH002Z
 OLD TCM SN-BK5536N190200107
 NEW TCM SN-BK1869A992336556
 INSTALLED NEW TCM. TEST DROVE. GOT SHIFTS ADAPTED. NO CODES. OK.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	1132/29523578		KIT-LABEL		
1	1132/29551869		TRANSMISSION CONTROL MODULE, A		
	ATD-1		ALLISON - IN CHASSIS		
	LABOR ATDWLD0596		TCM REPAIR		
	LABOR ATDWLD0619		TROUBLESHOOTING AND DIAGNOSTIC		
1	PROG		COMPUTER HOOKUP FEE		
	VMRS15		29		

SUB TOTAL: 1,540.88

Transmission Repair on #260