

Branch SIDNEY		*REPRINT*	
Date 07/29/19	Time 21:00:47 (B)	Page 01	
Account No.	Phone No.	Invoice No. W19691	
		Jer	
		Salesperson 707	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
 C9008955 COMBINE 333 H07720X625610

SEGMENT# 1 C 603 NA 07/19/19 07/19/19 08/09/19

REPAIR PRIMARY COUNTERSHAFT BROKEN

Replaced shaft and bearings.

Topped off hydraulic oil.

Test ran.

AH76193

SEAL

FRT

FREIGHT CHARGE

H99253

Shaft

JD8668

ECCENTRIC

Eccentric Locking Collar

JD8669

BALL BEARI

JD9428

ECCENTRIC

Eccentric Locking Collar

JD9429

BALL BEARING

TY22062

HYGARD 2.5

24H1577

WASHER

PARTS

LABOR

10700006

SEGMENT TOTAL==>

***** WORK ORDER TOTALS *****

PARTS

LABOR

DEL VEHICLE

SHOP SUPPLIES

628166 XXXXXX3491

TOTAL :

2955.11

ranch			
SIDNEY			
ale	Time	Page	
07/29/19	21:00:47 (B)	02	
ccount No.	Phone No.	Invoice No.	
		W19691	
hip Via		Purchase Order	
		Salesperson	
		707	

SERVICE INVOICE

STK#/FLEET#

C9008955

COMBINE

7720

HRS PIN/EIN

333 H07720X625610

WARRANTY DATE

HRS

Branch SIDNEY		*REPRINT*	
Date 07/18/18	Time 21:00:36 (B)	Page 01	
Account No.	Phone No.	Invoice No. W17626	
Ship via		Purchase Order	
		Salesperson 707	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
 C9008955 COMBINE 145 H07720X625610
 7720

SEGMENT# 1 C 624 NA 06/12/18 06/12/18 06/29/18
 PRE-HARVEST CHECK OVER

LABOR

10700006 SEGMENT TOTAL==>

SEGMENT# 2 C 624 DIAGELECTRIC 06/14/18 06/15/18 06/26/18
 DIAGNOSE ELECTRICAL CIRCUIT
 Checked over.
 Traced wiring.
 Found circuit breaker at fault.
 AR28403 CIRCUIT BR 1 16.08

PARTS
LABOR

10700006 SEGMENT TOTAL==>

SEGMENT# 3 C 624 NA 06/14/18 06/15/18 06/26/18
 DIAGNOSE PRIMARY VIBRATION
 Found primary countershaft bearings at fault.

LABOR

10700006 SEGMENT TOTAL==>

SEGMENT# 4 C 624 NA 06/14/18 06/19/18 06/26/18
 REPLACE HOSE UNDER CAB
 AH104095 LINE 1 N 89.21

PARTS
LABOR

10700006 SEGMENT TOTAL==>

SEGMENT# 5 C 624 NA 06/14/18 06/15/18 06/26/18

CONTINUED ON PAGE 02

Branch SIDNEY		
Date 07/18/18	Time 21:00:36 (B)	Page 02
Account No.	Phone No.	Invoice No. W17626
Group No.		Purchase Order
		Salesperson 707

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	145	H07720X625610	
7720				
REPLACE UNLOADING AUGER TOP PIVOT				
AH97804	Plate		1	N
FRT	FREIGHT CHARGE		1	

10700006

PARTS
LABOR
SEGMENT TOTAL==>

SEGMENT# 6 C 624 ACDIAGNOS 06/14/18 06/28/18 06/26/18

DIAGNOSE A/C SYSTEM

Checked over.

Replaced leaking hose.

Pulled system into a vacuum.

Charged system.

Tested.

AH144793	HOSE	1	N
H87091	Grommet	1	N
P51212	O-RING	2	
TY15949	REFRIGERAN	5	

10700006

PARTS
LABOR
SEGMENT TOTAL==>

SEGMENT# 7 C 624 NA 06/14/18 06/15/18 06/26/18

INSTALL MISSING HYDRAULIC LINE HARDWARE

T21959	Isolator	1	N
12H304	LOCK WASHE	1	M
19H1731	CAP SCREW	1	
24H1682	WASHER	2	M

PARTS
LABOR
CONTINUED ON PAGE 03

Branch SIDNEY		
Date 07/18/18	Time 21:00:36 (B)	Page 03
Account No.	Phone No.	Invoice No. W17626
Shr ...		
		Salesperson 707

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	145	H07720X625610		
COMBINE				
7720				
10700006			SEGMENT TOTAL==>	

SEGMENT# 8 C 624 NA 06/14/18 06/15/18 06/26/18
 HEADER ELECTRIC CLUTCH FACE PLATE AND/OR FIELD COIL, R&R O
 Remove:
 -Electric clutch brush module
 -Belt guide
 -Wiring harness bracket
 Release tension on propulsion drive belts.
 Slip separator drive belt off sheave.
 Release tension on reel drive pump and header drive belts.
 Loosen retaining nut then loosen separator drive sheave.
 Remove nut and lift off separator drive sheave.
 Remove field coil from separator drive sheave.
 Lift off header drive sheave and remove clutch face plate.
 Had to rebuilt pulley as it was no longer available.
 Reinstall to specifications.
 Adjust belt guides.
 Check operation of electric clutch.

AH76193	SEAL	2 N
H96996	BUSHING	2
24H1577	WASHER	5

	PARTS	
	LABOR	
10700006		SEGMENT TOTAL==>

SEGMENT# 9 C 624 NA 06/14/18 06/15/18 06/26/18
 REPLACE ENGINE FAN JACKSHAFT TENSION PULLEY

AH77172	IDLER	1
H79236	V-BELT	1

CONTINUED ON PAGE 04

Branch SIDNEY		
Date 07/18/18	Time 21:00:36 (B)	Page 04
Account No.	Phone No.	Invoice No. W17626
Ship Via		Purchase Order
		Salesperson 707

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE 7720	145	H07720X625610		
H86271	V-BELT			1	
H86273	V-BELT			1	
H86886	PUSH NUT			1 N	
12H301	LOCK WASHER			1 M	
14H1040	NUT			1 M	
19H1831	1/2 X 2 GR-5			1 M	
24H1346	WASHER			1 M	

10700006

PARTS
LABOR
SEGMENT TOTAL==>

SEGMENT#10 C 624	DECLINED	06/14/18	06/26/18
EXHAUST MANIFOLD, R&R - CUSTOMER DECLINED			

SEGMENT#11 C 624	ASSOCIATED	06/14/18	06/15/18	06/26/18
------------------	------------	----------	----------	----------

INSTALL LATCH ON TAILINGS TOP DOOR

FRT	FREIGHT CHARGE	1
H102466	Hinge	1 N
H123940	Hold-Down Clip	1 N
N10213	LOCK NUT	1
N10214	SELF-LOCKI	2 M
	Self-Locking Screw	
N10215	LOCK NUT	2
12H302	LOCK WASHER	2 M
14H786	NUT	2
19H1227	Cap Screw	2 M

PARTS
LABOR
SEGMENT TOTAL==>

10700006

CONTINUED ON PAGE 05

SERVICE INVOICE

Branch SIDNEY		
Date 07/18/18	Time 21:00:36 (B)	Page 06
Account No.	Phone No.	Invoice No. W17626
Ship via		Purchase Order
		Salesperson 707

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	145	H07720X625610	
	7720			

SEGMENT#16 C 624 10-180-010 06/14/18 06/15/18 06/26/18
 DUAL-RANGE CYLINDER DRIVE GEAR CASE COMPLETE, RECONDITION
 Remove and install shields, auger belt, drive shaft sheave,
 slip clutch, wood bearings, and check.
 Remove and install torque wheel, planetary carrier
 assembly, seal, bearings, and inspect.

AH108768	BALL BEARING	1	N
AH108801	BALL BEARI	2	N
AH110887	SEAL	1	N
AH112883	SEAL	2	N
H111041	WASHER	1	N
H111260	SHIM *	10	N
H111261	SHIM *	25	N
H111262	SHIM	5	N
JD10214	BEARING CO	1	N
JD7441	BEARING CU	1	
JD8960	BEARING CO	1	
JD9365	ECCENTRIC	1	
	Eccentric Locking Collar		
U10063	O-RING	1	

PARTS
LABOR

10700006

SEGMENT TOTAL==>

SEGMENT#17 C 624 DIAGELECTRIC 06/14/18 06/19/18 06/26/18
 DIAGNOSE ELECTRICAL CIRCUIT
 Checked over.
 Traced wiring.
 Found breaker at fault.

LABOR
CONTINUED ON PAGE 07

Branch SIDNEY		
Date 07/18/18	Time 21:00:36 (B)	Page 07
Account No.	Phone No.	Invoice No. W17626
Ship via		Purchase Order
		Salesperson 707

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	145	H07720X625610	
	7720			
10700006			SEGMENT TOTAL==>	

SEGMENT#18 C 624	10-050-200	06/12/18	06/18/18	06/29/18
PRIMARY COUNTERSHAFT BEARING, BOTH, R&R OR REPLACE				
Remove and install clutch module, belt guide, wiring harness bracket, belt, sheaves, clutch face plate, side shields, auger drive chain, idler bracket, hydraulic oil line, hydraulic cylinder, sheave halves, second countershaft, cylinder drive belt, sheaves, shaft bearing, and primary countershaft. Check.				
AH76193	SEAL		1	
AH87141	SEAL		1	
AH94853	SEAL		1	
H102533	SHIM		1	
H113890	BEARING HOUS		1	N
	Bearing Housing W/O Bearing			
JD8668	ECCENTRIC		2	
	Eccentric Locking Collar			
JD8669	BALL BEARI		1	N
JD9428	ECCENTRIC		1	N
	Eccentric Locking Collar			
JD9429	BALL BEARING		1	N
PM38657	SEALANT		1	
SUBLET	PRIMARY COUNTER		1	

	PARTS
	LABOR
	SUBLET
10700006	SEGMENT TOTAL==>

SEGMENT#19 C 624	NA	06/12/18	06/19/18	06/29/18
------------------	----	----------	----------	----------

CONTINUED ON PAGE 08

Branch SIDNEY			
Date 07/18/18	Time 21:00:36 (B)	Page 08	
Account No.	Phone No.	Invoice No. W17626	
Ship to		Purchase Order	
		Salesperson 707	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	145	H07720X625610		
	7720				
REPLACE BELTS AS NEEDED					
H108175	V-BELT			1	
H110300	V-BELT			1	
H113565	V-BELT			1 N	
H113749	V-BELT			1	
H137207	V-BELT			1 N	
H23927	V-BELT			1	
H83077	O-RING			1	
H96414	V-BELT			1	

10700006

PARTS
LABOR
SEGMENT TOTAL==>

SEGMENT#20 C 624 ASSOCIATED 06/12/18 06/25/18 06/29/18
CYLINDER BEARINGS, R&R OR REPLACE (WITH DUAL-RANGE CYLINDE
JD10011 BALL BEARI 1
JD9202 BALL BEARI 1

10700006

PARTS
LABOR
SEGMENT TOTAL==>

***** WORK ORDER TOTALS *****
PARTS
LABOR
SUBLET
DEL VEHICLE
EPA DISPOSAL FE
SHOP SUPPLIES
CONTINUED ON PAGE 09

Branch SIDNEY		
Date 07/18/18	Time 21:00:36 (B)	Page 09
Account No.	Phone No.	Invoice No. W17626
Ship via	Purchase Order	
		Salesperson 707

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	145	H07720X625610		
	7720				
430851	XXXXXX3491			TOTAL 1	9616.50

Branch SIDNEY		*REPRINT*	
Date 09/30/17	Time 20:28:36 (B)	Page 01	
Account No.	Phone No.	Invoice No. W16377	
Ship Via		Purchase Order	
		Salesperson 707	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	3498	H07720X625610		
	7720				

SEGMENT# 1 C 628 10-030-140 09/27/17 09/27/17 10/06/17

THROTTLE CABLE, REPLACE

BMC - HAS NEW HOURMETER, SHOWS 48 HRS PLUS 3450 AS OF

2-28-17 = 3498

Removed and installed fuel filters, console cover, and throttle cable. Checked.

AH92695

PUSH PULL

1 N

PARTS

LABOR

10700006

SEGMENT TOTAL==>

SEGMENT# 2 C 628 NA 09/27/17 09/29/17 10/06/17

LOOK OVER FOR CORN

LABOR

10700006

SEGMENT TOTAL==>

***** WORK ORDER TOTALS *****

PARTS

LABOR

EPA DISPOSAL FE

SHOP SUPPLIES

TOTAL

496069

XXXXXX3491

495.08

Branch SIDNEY		*REPRINT*	
Date 02/28/17	Time 19:24:41 (B)	Page 01	
Account No.	Phone No.	Invoice No. W14861	
Ship Via		Purchase Order	
		Salesperson 642	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	3450	H07720X625610	
	7720			

REPAIR# 1 C 628 JDCOMBINE 12/28/16 12/29/16 01/31/17
 2016/17 PRIORITY SERVICE PROGRAM - JD COMBINE
 TY26860 SCAN TEST KIT 1

PARTS
LABOR

10700006 REPAIR TOTAL==>

REPAIR# 2 C 628 NA 01/13/17 01/13/17 01/31/17
 REPLACE FEEDER HOUSE FLOOR
 AH83620 SHEET 1 N

PARTS
LABOR

10700006 REPAIR TOTAL==>

REPAIR# 3 C 628 NA 01/13/17 02/08/17 01/31/17

REPAIR FEEDERHOUSE RETURN FLOOR

Remove feeder house, conveyor chain and middle section of
 return floor.

Cut return floor chain guide.

Grind feeder house frame smooth.

Weld new pieces in place.

Reassemble.

Test.

H84026 HOOK 6

SUBLET METAL 1

PARTS
LABOR
SUBLET

10700006 REPAIR TOTAL==>

1311.79

CONTINUED ON PAGE 02

Branch SIDNEY			
Date 02/28/17	Time 19:24:41 (B)	Page 02	
Account No.	Phone No.	Invoice No. W14861	
Ship via		Purchase Order	
		Salesperson 642	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	3450	H07720X625610	
	7720			

REPAIR# 4 C 628 NA 01/13/17 01/13/17 01/31/17

REPLACE FEEDER HOUSE REAR FEED PLATE

H102470 PLATE 1 N

PARTS

LABOR

10700006 REPAIR TOTAL==>

REPAIR# 5 C 628 10-050-110 01/13/17 01/13/17 01/31/17

PLANETARY FINAL DRIVE, RECONDITION

Disconnect and remove cab and hydraulic lines.

Remove and install final drive.

Disassemble and assemble final drive.

Check operation.

AH81622 SEAL 1 N

H76441 CAP 1 N

H94885 SEAL 1 N

RE31702 SEAL 1 S

R59074 OIL CUP 1

PARTS

LABOR

10700006 REPAIR TOTAL==>

REPAIR# 6 C 628 12030BA 01/13/17 01/13/17 01/31/17

UPPER TAILINGS AUGER DRIVE CHAIN, REPLACE

SW50COUS CHAINLINK 1

SW50OLUS CHAIN LINK 1

SW50X50US ROLLER CHA 51

PARTS

LABOR

CONTINUED ON PAGE 03

Branch SIDNEY		
Date 02/28/17	Time 19:24:41 (B)	Page 03
Account No. BOND0001	Phone No. 3084835336	Invoice No. W14861
Ship Via	Purchase Order	
		Salesperson 642

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE	3450	H07720X625610	

7720

10700006

REPAIR TOTAL==>

REPAIR#	7 C 628	14015P	01/13/17	01/13/17	01/31/17
CLEANING SHOE AND STRAW WALKER DRIVES SPROCKET, R&R OR REPL					
AH115268	CHAIN SPRO	1	N		
AH87207	THRUST BEA	1			
SW60COUS	CHAIN LINK	2			
SW60OLUS	CHAINLINK	1			
SW60X50US	ROLLERCHAIN	155			

PARTS
LABOR

10700006

REPAIR TOTAL==>

REPAIR#	8 C 628	NA	01/13/17	01/13/17	01/31/17
REPLACE VERTICAL AUGER INSPECTION DOOR					
H96579	DOOR	1	N		

PARTS
LABOR

10700006

REPAIR TOTAL==>

REPAIR#	9 C 628	NA	01/13/17	01/13/17	01/31/17
REPLACE UPPER FEEDER HOUSE STRIPPER PLATE					
H82633	SEAL	1	N		

PARTS
LABOR

10700006

REPAIR TOTAL==>

REPAIR#	10 C 628	11010E	01/13/17	01/13/17	01/31/17
FEEDER CONVEYOR DRUM BEARING(S) R&R OR REPLACE					
Feeder Conveyor Drum Float Arms, R&R					

CONTINUED ON PAGE 04

Branch SIDNEY			
Date 02/28/17	Time 19:24:41 (B)	Page 05	
Account No.	Phone No.	Invoice No. W14861	
Ship via		Purchase Order	
		Salesperson 642	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
C9008955 COMBINE 3450 H07720X625610

10700006

LABOR
REPAIR TOTAL==>

REPAIR# 13 C 628 NA 01/13/17 01/13/17 01/31/17
REPLACE HYDROSTAT DRIVE BELTS
AH84633 BELT SET 2

10700006

PARTS
LABOR
REPAIR TOTAL==>

REPAIR# 15 C 628 4020R 01/13/17 01/13/17 01/31/17
ENGINE HOUR METER, REPLACE
AM125053 HOUR METER 1 N

10700006

PARTS
LABOR
REPAIR TOTAL==>

REPAIR# 16 C 628 NA 01/13/17 02/14/17 01/31/17
REPAIR WIRING TO STRAW WALKER LOSS IMPACT PADS
Left sensor bracket is no longer available.
Ordered shoe bracket and made it work.
Repaired wiring from sensor to cross harness on both straw
walkers.
Tested and walker sensors worked but shoe did not.
Tested wiring.
Repaired break in wiring.
Tested.
Replaced left sensor.
Tested.
AH109794 SENSOR 2 N

CONTINUED ON PAGE 06

Branch SIDNEY			
Date 02/28/17	Time 19:24:41 (B)	Page 06	
Account No.	Phone No.	Invoice No. W14861	
Ship via		Purchase Order	
		Salesperson 642	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE 7720	3450	H07720X625610		
AH119132	Bracket	1	N		
R77461	ELEC. CONNE	1	M		
10H1167	BOLT	1			
12M7060	WASHER	4			
21H1427	SCREW	4	N		

PARTS
LABOR

10700006 REPAIR TOTAL==>

REPAIR# 17 C 628 NA 01/13/17 02/16/17 01/31/17
ADJUST DOOR LATCH

LABOR

10700006 REPAIR TOTAL==>

REPAIR# 18 C 628 1020E 01/13/17 02/16/17 01/31/17

COOLING SYSTEM FLUSH

AN110020	CAP	1	M
PMCC2638	COOLANT FLUSH	1	
	Shop Cleaner Supply Item		
TY26575	COOL-GARD TM	1	
TY26576	COOL-GARD	3	

PARTS
LABOR

10700006 REPAIR TOTAL==>

***** WORK ORDER TOTALS *****

PARTS
LABOR
SUBLET

CONTINUED ON PAGE 07

Branch SIDNEY		
Date 02/28/17	Time 19:24:41 (B)	Page 07
Account No.	Phone No.	Invoice No. W14861
Ship Via	Purchase Order	
		Salesperson 642

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C9008955	COMBINE 7720	3450	H07720X625610		
			DEL VEHICLE		
			EPA DISPOSAL FE		
			PRIORITY SVC DI		
			SHOP SUPPLIES		
707228	XXXXXX3491		TOTAL		9426.96