Billing Customer: Owning Customer:

Phone:

Fax:

Customer P/O:

Unit Number: N-11

479,159 Miles

Year:

2008 PETERBILT

Manufacturer: Model:

VIN:

1XPWDB0X48D760359.

Unit Components:

Manufacturer

Model

C-15

Description ENGINE

Serial Number SDP07243

Comments:

CAT

Job: 1 Dept: SERVICE 91110-100 REPAIR AS NEEDED

Complaint: POSSABLE HEAD GASKET, OIL LEAK.

Cause:

THE BLOCK IS CRACKED ON #4 LINER FLANGE. MADE ESTIMATE TO REPLACE THE

SHORT BLOCK AND PUT THE TRUCK BACK TO FACORY CONDITION.

Correction: PULLED THE TRUCK IN THE SHOP AND VERIFIED THE COMPRESSION IN THE COOLING SYSTEM. DRAINED THE COOLANT OUT AND REMOVED THE CYLINDER HEAD. FOUND. THE LINER FLANGE WAS CRACKED ON #4, FURTHER TROUBLESHOOTING FOUND THE BLOCK WAS CRACKED ON THE LOWER FLANGE SEAT AREA. SENT ALL THE PICTURES AND WARRANTY REPORT TO CATERPILLAR TO GET THE WARRANTY PROCESS STARTED AND THEY INFORMED US THE ENGINE HAD BEEN DELETED AND THAT WARRANTY WOULD NOT APPLY. ADVISED THE CUSTOMER OF THE SITUATION AND THEY ELECTED TO REPAIR THE ENGINE BACK TO FACTORY CONDITION UNDER CUSTOMER PAY, REMOVED THE RADIATOR AND THE HOOD, REMOVED THE TRANSMISSION AND ENGINE FROM THE CHASSIS DISSASSEMBLED THE ENGINE DOWN TO SHORT BLOCK AND REPLACED THE SHORT BLOCK WITH CATERPILLAR REMAN. REPLACED THE SPACER PLATE AND THE HEAD. ASSEMBLED THE ENGINE BACK TOGETHER TO FACTORY CONDITION AND INSTALLED THE ENGINE BACK INTO CHASSIS. STABBED THE TRANSMISSION AND RADIATOR. REPLACED ALL THE FILTERS ON THE ENGINE AND FILLED WITH FRESH OIL AND COOLANT. INSTALLED THE HOOD BACK ON THE TRUCK AND REPROGRAMED THE ENGINE BACK TO THE FACTORY PROGRAMING WHEN OPT OVERHUALED. REPLACED THE DPF FILTER WITH REMAN. THE OLD ONE HAD THE CENTER CUT OUT OF IT AND COULD NOT BE TURNED BACK IN FOR A CORE CREDIT. RAN THE ENGINE, NO LEAKS ALL OK. STEAM CLEANED THE ENGINE GOOD AND PAINTED CATERPILLAR YELLOW. TEST DROVE THE TRUCK ALL OK NO PROBLEMS. RAN A STATIONARY REGEN AND REGEN COMPLETED. SUCCESSFULLY, NO CODES ALL OK. RETURNED THE TRUCK TO SERVICE

## Comments:

			Un	it of		
Supplier/Emp	Part/Labor	Description/Reference		sure Quantity	Price	Extended Price
0119	15W40 ROTELLA B - QUART	SHELL 15W-40 TRIPLE T	QT	40.00		
0124	FUL 4305294	SHIFT TOWER GASKET	EA	1.00		
0124	PHM 1 1936	EYELET YELLOW	EA	1.00		
0124	PHM 1 1937	EYELET YELLOW	EA	1.00		
0124	PHM 1 1962	BUTT SPLICE-BLUE	EA	2.00		
0124	PHM 5 025	WIRE LOOM	FT	7.00		
0124	SP 127760	2" CLUTCH BRAKE	EA	1.00		
0124	SP 5007417	BOLT FOR STAP KIT takes 4	EA	2.00		
0124A	BRZ CT 200 L SS	CLAMP 1 1/4 X 2 1/8	EA	1.00		
0124-T	FG AF25248	AIR FILTER	EA	2.00		
0124-X	PHM 2 145	10G RED	EA	1.00		
0124-X	PHM 8 43147	TIES	EA	6.00		
0124-X	PHM 8 43147	TIES	EA	8.00		
0124-X	PHM 8 44147	TIES	EΑ	12.00		
1214	05-16401	FRONT MOTOR MOUNT	EA	2.00		
1214	92429TS	BOLT, 5/8-18X41/2 8GD	EA	4.00		
1214	92504TS	BOLT, 3/4 10X4-1	EA	2.00		
1214	94585TS	5/8-18 LOCK	EA	4.00		
1214	94586TS	3/4-10 LOCK	EA	2.00		
1214	MR1001	MOTOR MOUNT	EA	4.00		
1510	BRY 0120	BRAKE AND PARTS CLEANER	EA	4.00		
1510	GAT 27004	FUEL HOSE	EA	1.00		
1510	GT 060690HD	BELT	EA	1.00		
1510	GT K121049HD	BELT	EA	1.00		
1510	PEX 82194	GREY SILICONE	EA	1.00		
2311	DW1	DISTILLED WATER	EA	6.00		
2312	10R-6089	C15 DPF FILTER	EA	1.00		
2312	10R-6089-C	C15 DPF FILTER (CORE)	CHG EA	1.00		
2312	10R-9173	CYL BLOCK	EA	1.00		
2312	10R-9173-C	CYL BLOCK	RET EA	-1.00		
2312	10R-9173-C	CYL BLOCK (CORE)	CHG EA	1.00		
2312	110-0004	O-RING	EA	1.00		
2312	165-6170	PLUG	EA	3.00		
2312	1802776	GREEN CEMENT	EA	1.00		
2312	1P-0436	PRIMER PUMP GASKET	EA	1.00		
2312	1P-8362	O-RING	EA	1.00		
2312	1U-5516	2" BUFFING DISC	EA	5.00		
2312	20R-0409	HEAD GP CYL	EA	1.00		
2312	20R-0409-C	HEAD GP CYL	RET EA	-1.00		
2312	20R-0409-C	HEAD GP CYL (CORE)	CHG EA	1.00		
2312	223-3505	SEAL-PRESS/COMP	EA	1.00		
2312	242-3360	BULK HOSE BLUE SILICONE SOLD		17.00		
2312	248-1394	GASKET KIT	EA	6.00		
2312	281-8261	SLEEVE EXHAUST	EA	6.00		
2312	336-2952	KIT - GASKET	EA	1.00		
2312	330-2802	NI - GASKET	EA	1.00		

## Comments:

			Unit of			
Supplier/Emp	Part/Labor	Description/Reference	Measure	Quantity	Price	Extended Price
2312	339-3768	ANTIFREEZE, REGULAR	EA	6.00		
2312	342-9547	KIT - GASKET	EA	1.00		
2312	437-3252	KIT GASKET	EA	1.00		
2312	437-3323	KIT GASKET	EA	1,00		
2312	438-8150	KIT GASKET	EA	1.00		
2312	445-6792	KIT GASKET	EA	1.00		
2312	458-9587	CAT YELLOW PAINT	EA	3.00		
2312	479-0860	KIT GASKET	EA	1.00		
2312	5M-2894	3/8 FLAT WASHER	EA	8.00		
2312	6D-1004	GASKET-POWER STEERING	EA	1.00		
2312	6I-4421	SPACER PLATE CYL-BLOCK	EA	1.00		
2312	6V-1197	SEAL	EA	1.00		
2312	6V-5266	O-RING DRAIN TUBE	EA	1.00		
2312	6V-5759	IVA SEAL O-RING	EA	1.00		
2312	6V-8225	M6 X 1.00 NUT	EA	2.00		
2312	8T-4994	3/4 FLAT WASHER	EA	2.00		
2312	8T-7751	HAND PAD	EA	1.00		
2312	9M-1974	5/16 WASHER	EA	2.00		
2312C	0S-1594	3/8 X 1 P&O BOLT	EA	8.00		
2312C	0S-1617	5/16 X 3/4 BOLT	EA	1.00		
2312C	1A-9579	5/16 X 1 1/2 P&O BOLT	EA	2.00		
2312F	1R-0749	FUEL FILTER	EA	1.00		
2312F	1R-1808	OIL FILTER	EA	1.00		
2312F	256-8753	FUEL/WATER SEPERATOR	EA	1.00		
SUBLT	SUBLET	ECM RERATE/CAT	ĒΑ	1.00		
		Labor Summary		140.00		

Job: 2 Dept: SERVICE 91610-300 ECM DIAG

Complaint: AFTER THE REPAIR OF THE ENGINE THE CHECK ENGINE LIGHT WAS ON WITH ACTIVE

CODES IN THE ECM

Correction: FOLLOWED THE TROUBLESHOOTING STEPS AND FOUND THE ARD HEAD IS FAILED

AND NEEDS REPLACED. REPLACED THE ARD HEAD AND FILTER FITTINGS. CLEARED ALL CODES AND RAN A STATIONARY REGEN. REGEN COMPLETED AND NO CODES RETURNED. TEST DROVE THE TRUCK AND AN ACTIVE EVENT CAME UP FOR LOW FLOW TO THE CLEAN GAS INDUCTION SYSTEM. FOLLOWED THE TROUBLESHOOTING STEPS AND FOUND THE BELLOWS PIPE BETWEEN THE DPF FILTER AND THE COOLER WAS WELDED TO BLOCK OFF THE FLOW OF GASES TO THE COOLER. REPLACED THE PIPE WITH NEW AND TEST DROVE THE TRUCK AGAIN, RUNS GREAT NOW, NO CODES,

NO EVENTS, RUNS LIKE IT SHOULD NOW.

			Unit of			
Supplier/Emp	Part/Labor	Description/Reference	Measure	Quantity	Price	Extended Price
1214	078-0245	GASKET-EXHUAST	EA	2.00		
1214	90-0011TCP	CLAMP-V BAND 2	EA	2.00		
1214	EBKW11866	BELLOW-EXHUAST	EA	1.00		

## Comments:

Supplier/Emp	Part/Labor	Description/Reference	Unit of Measure	Quantity	Price Extended Price
		the state of the s			Filos Extended Filos
2312	214-7567	O-RING	EA	1.00	
2312	289-3107	GASKET	EA	1.00	
2312	296-7780	GASKET	EA	1,00	
2312	353-8397	CONNECTOR	EA	1.00	
2312	353-8398	CONNECTOR	EA	1,00	
2312	419-5656	HEAD AS COMB	EA	1.00	
		Labor Summary		15.92	

Customer Tax ID:

Detail Tax Information SALES TAX

Total Parts: Total Core Charges: Total Core Returns: Total Labor: Total Miscellaneous:

Total Shop Supplies: Total Environmental Charge:

Invoice Subtotal:

Total Tax:

\$50,887.75 Invoice Total:

Payment Terms:

Sale Type:

!! ~ Indicates non-returnable parts.

Quotes are good for 30 days only.

All quotes are estimates only, actual price may vary.

Customer signature of the quote will indicate authorization to proceed.