Invoice: 005-23882R

Date / Hour: 2/27/2019 11:43:52AM

Repair Order: 23882 Customer: 16241 Branch: 005

Total Invoice: \$ 14,286.56

\*\*\*COD\*\*\*

Page 1 of 2

Customer P/O:

nblair

Orig R/O: 0

Meter: 1680691 Miles

Unit Number: 105

Model Year: 2005

Make/Model:

Completion Date: 2/27/2019

Department: Trk Svc

VIN: 4V4NC9GH65N389867

Type: Class 8 Truck

ENGINE MODEL: D12D395

In-Service Date: 03/22/2005

ENGINE S/N: 441029

Task: 1 1400000 FRAME ASSEMBLY

Complaint: REPLACE PASSENGER FRAME RAIL

Correction: 2/27/2019 11:38:33 AM 5690 replace passenger side framerail

Extended Supp. Part Description / Ref Number U/M Quantity Price Price VOL 20370265D FRAME RAIL EΑ 1.0 ٦L 3186973 BRACKET EA 1.0 8397802 JL FITTING EA 1.0 VOL 994523 FLANGE LOCK NUT EA 2.0 VOL 994527 FLANGE LOCK NUT EA 2.0 VOL 990953 FLANGE LOCK NUT EA 16.0 VOL 994522 FLANGE LOCK NUT EA 27.0 VOL 8397200 **NUT 1142** EA 15.0 VOL 990941 FLANGE NUT EA 4.0 VOL 992328 FLANGE NUT EA 1.0 VOL 992344 USE 982391 EA 11.0 VOL. 984853 FLANGE SCREW EA 3.0 VOL 984855 FLANG SCREW EA 7.0 VOL 984762 FLANGE SCREW EA 2.0 VOL 8079751 HEX. SOCKET SCREW EA 2.0 VOL 992340 FLANGE SCREW EΑ 4.0 VOL 992340 FLANGE SCREW EA 4.0 VOL 992345 FLANGE SCREW 7122 EA 4.0 VOL 992336 FLANGE SCREW EA 23.0 MIS CRC5312 #12 HOSE CLAMPS EA 1.0 MIS CRC5340 CLAMP EA 1.0 VOL 8071857 U-BOLT EA 2.0 VOL 21823706 WHEEL NUT KT 4.0 VOL 8071883 CLAMP 2527 EΑ 5.0 VOL 85102478 RADIATOR HOSE EA 5.0 DCO DCO80241GL HEATER HOSE - GOLD LABEL EA 2.0 VOL 20504754 U-BOLT 7233 EA 2.0 3186814 EXHAUST PIPE 2522 EA 1.0 VOL 8086648 SPRING LEAF EA 1.0 VOL 85102664 GASKET 4317 EA 1.0 SP 35061 1/16 FREIGHTLINER HANGER EA 2.0 SP SPC35060 1/32 SHIM EA 2.0

<sup>\*\*</sup> See Last Page for Invoice Total \*\*

Invoice: 005-23882R

Date / Hour: 2/27/2019 11:43:52AM

Repair Order: 23882 Customer: 16241 Branch: 005

Total Invoice: \$ 14,286.56 \*\*\*\*COD\*\*\*

Dana	2	of	2	
------	---	----	---	--

Customer P/O:	nblair	Orig F	R/O: 0	Completion Date: 2/27/2019	
VOL 85107600 VOL 85108980 VOL 984871 VOL 20457104 SEQ SEQ9404206021 ENVIRON CH SHOP SUP	SCREW 4519 TUBE 4135 FLANGE SCREW EXHAUST PIPE 2522 SHELL ROTELLA 50/50 EXT LIFE ENVIRONMENTAL CHARGE SHOP SUPPLIES	EA EA EA EA EA	8.0 1.0 2.0 1.0 1.0 1.0	Sumperior Date. 2/2//2019	

Total Parts:

Total Labor:

Total Miscellaneous: Total TECHNOLOGY

FEE:

Invoice Subtotal: **Total Tax:** 

> Total Invoice: \$14,286.56

Payment Method COD

Terms COD

Due Date 2/27/2019

\*\* Reprint \*\*

Invoice: 05-16145R.02

Date / Hour: 10/12/2015 10:03:39AM

Repair Order: 16145 Customer: 16241 Branch: 005

Total Invoice: \$ 17,076.58 \*\*\*COD\*\*\*

Page 1 of 3

Customer P/O:

nbenack

Orig R/O: 0

Completion Date: 10/9/2015

Unit Number: 105

Model Year: 2005

Make/Model:

Type: Class 8 Truck

VIN: 4V4NC9GH65N389867

Meter: 1220084 Miles

In-Service Date: 03/22/2005

ENGINE MODEL: D12D395

ENGINE S/N: 441029

TRANSMISSION S/N: K0376113

Task: 1 0010000 GENERAL Complaint: D12 GUARANTEED OVERHAUL.

Department: Trk Svc

LEVEL 2 (GO PLUS) - INFRAME KIT, PREMIUM OIL, VOLVO FILTERS, VOLVO REMAN CYLINDER HEAD

Correction: 10/2/2015 1:51:53 PM 3001 Drain coolant and oil. Removed air breather, piping, valve cover, top timing cover, exhaust manifold, intake manifold, rocker shaft, injectors and cam.

10/9/2015 2:32:38 PM 3001 Removed head, oil pan, oil pump, stiffing plate, piston cooling jets, pistons, and liners. Cleaned block and inspected for reuse. Installed new liners and check liner protrusion and it was .007 average. Installed pistons on rods and put in. Torqued rod bearings. Installed and torqued main bearings. Installed new head with spacer blocks and torqued. Installed cam and timed . Checked gear lash from cam gear to idler gear and it was .004, checked lash from idler gear and it was .004. Installed injectors with new orings and torqued using new cup torque spec. Reinstalled rocker shaft and torqued. Adjusted valves, injectors, and engine brakes. Reinstalled componets removed and filled with new coolant and oil. Replaced all filters. Started engine and checked for leaks. Test drove and rechecked fluid levels and checked for leaks.

Supp.	Part	Description / Ref Number	U/M	Quantity	Extended Price Price
VOL	984740	FLANGE SCREW	EA	11.0	
VOL	984741	FLANGE SCREW	EA	4.0	
VOL	994445	FLANGE SCREW	EA	6.0	
VOL	984748	FLANGE SCREW	EA	1.0	
VOL	22397140	OIL PUMP	EA	1.0	
VOL	22397140-C	OIL PUMP CORE	EA	1.0	
VOL	22397140-C	OIL PUMP CORE	EA	-1.0	
VOL	85000191-C	CORE CYLINDER HEAD	EA	-1.0	
VOL	85000191	CYLINDER HEAD, EXCH	EA	1.0	
VOL	85000191-C	CORE CYLINDER HEAD	EA	1.0	
VOL	85110455	ENGINE OVERHAUL KIT	EA	1.0	
VOL	21344774	FLANGE SCREW	EA	6.0	
VOL	1547967	ADJUSTING WASHER 2149	EA	1.0	
VOL	944126	O-RING	EA	1.0	
VOL	8170519	GASKET 2629	EA	1.0	
VOL	20532272	SEALING STRIP 2172	EA	1.0	
VOL	21937327	COOLANT FILTER	EA	1.0	
VOL	20976003	FUEL FILTER	EA	1.0	
VOL	21707132	OIL FILTER	EA	1.0	
VOL	21707133	OIL FILTER	EA	2.0	
VOL	1547252	SEALING RING 2129	EA	1.0	
VOL	1547254	SEALING RING 2629	EA	2.0	
VOL	1677370	SEALING RING 2539	EA	2.0	
SEQ	SEQ9404206021	SHELL ROTELLA 50/50 EXT LIFE	EA	10.0	
VOL	21715813	AIR FILTER	EA	1.0	

<sup>\*\*</sup> See Last Page for Invoice Total \*\*

\*\* Reprint \*\*

Invoice: 05-16145R.02

Date / Hour: 10/12/2015 10:03:39AM

Repair Order: 16145 Customer: 16241 Branch: 005

Total Invoice: \$ 17,076.58

\*\*\*COD\*\*\*

Page 2 of 3

Custome	r P/O:	nbenack	Orig	R/O: 0	Completion Date: 10/9/2015
VOL VOL VOL VPO	471708 8149301 20702522 VPO98KQ90 ENVIRON CH HAND TRK SHOPSUP MA	SEALING RING 2239 GASKET 2629 OIL PAN 2171 VOLVO PREM MOTOR OIL 15W- ENVIRONMENTAL CHARGE CC CHARGE SHOP SUPPLIES MANUAL Task 1 Subt	EA EA EA GA	6.0 1.0 1.0 10.0 1.0 1.0 1.0 Part	
				Core Ch Core Re Labo Miscellaneou Task 1 Subtota	g: et: or: s:
Cau	int: ADDITIONAL WARRA	ENGINE ASSEMBLY  NTY COVERAGE FOR GO OVERHAUL  NTY COVERAGE FOR GO OVERHAUL  NTY COVERAGE FOR GO OVERHAUL		De	partment: Trk Svc

**Total Parts:** 

Quantity

Parts:

Labor: Miscellaneous: Task 2 Subtotals

Total Miscellaneous:

Total Tax:

\$17,076.58

Extended

Price

Payment Method COD

Supp. Part

PASS THRU

Terms Net 0

Due Date 10/12/2015

Description / Ref Number

WARRANTY COVERAGE

**Total Core Charge:** Total Core Ret:

U/M

Task 2 Subtotals

Total Labor:

**Total Technology Fees:** Invoice Subtotal:

Total Invoice:

### PAGE 1

-			The first dark dark &		SER\	VICE ADVISOR				
COLOR	YEAR	YEAR MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG	
-	05	WHI	TE VNL641	7	4V4NC	9GH65N389867		1085710	1085710	T105
DEL. DATE	PROD.	DATE	WARR, EXP.	PROMIS		PO NO.	RATE	PAYMENT	INV.	
22MAR05 D	-			17:00 1	5SEP14			VISA	18SEP1	
20:23 12S	EP14 DE TE	22:								
A TOWED I			YPE HOURS				LIST	NET		TOTAL
	725 751	01 T	CP	INSTALL		INE)				w 1 1 1 1 1 1 1

# 8 85107600 SCREW

1085/10 Technician installed driveshaft with new bolts and torqued to specifications.

B CHECK AND ADVISE ALL--TRANSMISSION ISSUES-WONT GO INTO HIGH
RANGE-CUSTOMER WAS TOLD OF UNIT MAY HAVE EXCESSIVE METAL DEBRIS
IN TRANSMISSION\\

99-000-0001 CHECK AND ADVISE ALL--TRANSMISSION
ISSUES-WONT GO INTO HIGH RANGE-CUSTOMER WAS
TOLD OF UNIT MAY HAVE EXCESSIVE METAL DEBRIS
IN TRANSMISSION\\
40914 CNSG

40914 CNSG 72514 CNSG 46714 CNSG

- 1 FULS2818RX REMAN EXCHANGE, LIGHTENING CORE CHARGE C
  - -1 FULS2818RX CORE RETURN
  - 1 85107599 END YOKE
    - 2 MG8849 CLEANER
- 1 FRLO16410C TRANNY
  - 1 208925-82 INSTL 1552 2.-10 SPLINE
- 50.8EP
  - 1 85108980 TUBE
- 1 CP63062RS2HT BEARING- PILOT
  - (2.833X1.179), HT

	DESCRIPTION	TOTALS
1	LABOR AMOUNT	
١	PARTS AMOUNT	
>	GAS, OIL, LUBE	
1	SUBLET AMOUNT	
В	MISC. CHARGES*	
8	TOTAL CHARGES	
E	LESS INSURANCE	
9	SALES TAX	
	PLEASE PAY THIS AMOUNT	

### PAGE 2

COLOR	Increase 1					SER	VICE ADVISOR	R:			
COLOR	YEAR	200	MAKE/MODEL				VIN	LICENSE	MILEAG	E IN / OUT	TAG
DEL. DATE	05 PROD.		TE VNL647	2	0000		9GH65N3898	The state of the s	1085710		
22MAR05 IS		DATE	WARR, EAF.	11.1	PROMISE	ED	PO NO.	RATE	PAYMENT	INV.	
R.O. OPEN		1 1	READY	17	7:00 15 OPTIONS				VISA	18SEP	14
20:23 12SE LINE OPCOL		22: CH T	44 18SEPI	4				T. T.O.M.			
1 2	SP-1 8513	2776 7529	0 TORQUE KIT	LIM					NE	Berry.	TOTAL
26	50W 2045	-SYN	50W OIL SLAVE CY		IDER						
MISC FLYWH	LEEL .		NSG								
1085710											

APULLED TRUCK INTO SHOP, NOTICED THE SERVICE LIGHT WAS FLASHING ON GEAR SHIFTER. HOOKED ONTO TRUCK USING EATON SOFTWARE. FOUND 1 CODE ACTIVE. TECHNICAIN T/S TRANSMISSION F/C. HAVE TO REPLACE THE TRANSMISSION ECM.

40914- INSPECTED TRANS FOR LEAKS. FOUND THE PTO COVERS AND REAR COVERS ARE LEAKING. DRAINED FLUID TO REPAIR TRANS. FOUND ROLLER BEARING AND HEAVY METAL COME OUT IN FLUID. TRANSMISSION IS BAD. TOOK PICTURES AND GOT QUOTE. CUSTOMER APPROVED TRANSMISSION REPLACEMENT. 72514- REMOVED DRIVE LINE, LOSSEND THE CARRIER BEARING TO GET THE DRIVE SHAFT AWAY FROM THE TRANNY, THEN REMOVED THE TRANNY FORM UNDER THE TRUCK, . TECHNICIAN GROOMED NEW TRANS WITH CORRECT FITTINGS . TECH REMOVED FLYWHEEL AND RESURFACED FLYWHEEL. TECH REINSTALLED FLYWHEEL , AND THEN INSTALLED NEW CLUTCH, TRANSMISSION WITH NEW TRANS ECU. AND INSTALLED INTO CHASSIS. TECH THE CONNECTED ALL NECESSARY COMPONETS AND CONNECTED TRANS COOLER LINES. TECH THEN REMOVED JACKS AND TOOK UNIT ON A TEST DRIVE TO VERIFY REPAIR. UNIT IS COMPLETE AND READY FOR CUSTOMER PICKUP.

\*\*\*\*\*\*\*\*\*\*\*\*\*\* C\*\* CHECK BOTH DOOR LIGHTS

101 MISCELLANEOUS

75114 CNSG

2 81523-3 GE 211-2 DOM E BULB

1 20703053 INTERIOR LAMP

1 20703049 INTERIOR LAMP

0 0 TOTAL LINE DESCRIPTION TOTALS LABOR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES\* TOTAL CHARGES LESS INSURANCE SALES TAX PLEASE PAY THIS AMOUNT

### PAGE 3

SERVICE ADVISOR:	
COLOR YEAR MAKE/MODEL VIN LICENSE MILEAGE IN / OUT	TAG
05 WHITE VNL64T 4V4NC9GH65N389867 1085710/1085710	771.05
DEL. DATE PROD. DATE WARR, EXP. PROMISED PO NO PATE DAYAGEST ONLY	
22MAR05 IS PONO. RATE PAYMENT INV. I	DATE
22MAR05 DD 17:00 15SEP14 VISA 18CPD	
R.O. OPENED READY OPTIONS: VISA 18SEP:	.4
20:23 12SEP14 22:44 18SEP14	
LINE OPCODE TECH TYPE HOURS LIST NET	TOTAL
1085710 NEED TO REPLACE BOTH TOP AND DOOR LIGHTS ON DRIVERS SIDE. TECH REPLACED AS NEEDED.	TOTAL
*************	

D\*\* CHECK ALL AND REPAIR BAD WHEEL SEALS 101 MISCELLANEOUS

40914 CAMC

70110 CAMC

75114 CAMC

1 21404020 SEALING

1 3199066 SEALING RING

1 GUN3922XTL BRAKE DRUM

1 EN4707QPK SHOE BOX

CORE CHARGE C

-1 EN4707QPK CORE RETURN

1 EN4702QPK SHOE BOX

CORE CHARGE C

-1 EN4702OPK CORE RETURN

TECHNICAIN FOUND SECONDARY DRIVE AXLE (PASSENGER SIDE) WHEEL SEAL LEAKING. TECH REMOVED ALL NECESSARY COMPONETS NEEDED AND REPALCED SEAL. TECH REINSTALLED ALL REMOVED COMPONENTS AND ADJUSTED BRAKES.

40914- INSPECTED FRONT STEER AXLE AND NO LEAKING SEALS AT THIS TIME. FOUND BAD BREAKS ON PASS STEER. REMOVED TIRE AND DRUM. REMOVED BAD BREAKS AND REPLACED WITH NEW. INSTALLED DRUM AND TIRE. ADJUSTED BREAKS. INSPECTED 1 DRIVE AXLE LEFT. REMOVED TIRE AND DRUM. HAS NEW SEAL IN. DID NOT SEE ANY LEAKS AT THIS TIME. CLEANED AND PUT BACK TOGETHER. ADJUSTED BREAK.

\*\*\*\*\*\*\*\*\*\*

DESCRIPTION TOTALS

LABOR AMOUNT
PARTS AMOUNT
GAS, OIL, LUBE
SUBLET AMOUNT
MISC. CHARGES\*
TOTAL CHARGES
LESS INSURANCE
SALES TAX
PLEASE PAY
THIS AMOUNT

# PAGE 4

COLOR	YEAR				SER\	/ICE ADVISOR:				
COLON	TEAR		MAKE/MODEL		100	VIN	LICENSE	MILEAG	E IN / OUT	TAG
DEL. DATE	05 PROD.		TE VNL641		4V4NC	9GH65N389867	7	1085710	/1085710	
22MAR05 I	g PROD.	DATE	WARR. EXP.	PROM	MISED	PO NO.	RATE	PAYMENT	INV.	
22MAR05 DI R.O. OPEI 20:23 12SI	NED EP14	22:	READY 44 18SEP1	OPTIO	15SEP14 DNS:			VISA	18SEP1	L4
EST: 0.00 CONTACT	Γ: P		15SEP1	4 10:33			LIST			TOTAL

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER

DESCRIPTION TOTALS

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES\*

TOTAL CHARGES

LESS INSURANCE

SALES TAX

PLEASE PAY
THIS AMOUNT

11422.00

Invoice: 5-241990028

Date / Hour: 7/18/2014 2:06:24PM

Repair Order: 13370 Customer: 16241 Branch: 5

Total Invoice: \$3,487.78 \*\*\*COD\*\*\*

Page 1 of 2

Customer P/O: nhlair 000 Orig R/O: 0 Completion Date: 7/18/2014 Unit Number: 105 Model Year: 2005

Make/Model:

Type: Class 8 Truck

VIN: 4V4NC9GH65N389867

Meter: 1064214 Miles

In-Service Date: 03/22/2005

Engine SN: 441029

Task: 1 0010000 GENERAL

Department: Trk Svc

Complaint: NO DIAG R&R TURBO

Correction: 7/17/2014 8:58:25 PM 7621 POSITIONED UNIT IN SHOP, REMOVED TURBO AND FOUND THE EXHAST MANIFOLD IS LEAKING ON EVERY CYLINDER. REMOVED MANIFOLD AND FOUND IT TO BE WARPED. INSTALLED NEW EXHAUST MANIFOLD WITH NEW GASKETS TORQUED TO SPEC. INSTALLED NEW TURBO WITH NEW GASKETS. NEED TO FILL WITH NEW COOLANT AND INSTALL NEW COOLANT FILTER AND NEED TO INSTALL AIR CLEANER ASEMBLY AND NEW FILTER.

7/18/2014 8:54:15 AM 5690 REPLACED COOLANT FILTER, REPLACED COOLANT, INSTALLED AIR BREATHER ASSEMBLY, REPLACED FILTER, TAKE FOR TESTDRIVE, ALL WAS WORKING CORRECTLY AND NO LEAKS WERE FOUND. PLEASE NOTE THAT CUSTOMER WILL SMELL AN ODOR FOR SOME MILES LINTH THE BUST PREVENTATIVE ON THE OUTSIE

Supp.	Part	OME MILES UNTIL THE RUST PREVENTATIVE  Description / Ref Number	U/M	Quantity	Price	Extended
VOL	20451156	LOCK BRACE 2549	EA	1.0		1 1100
VOL	20743488	EXHAUST MANIFOLD	EA	1.0		
VOL	8170959	GASKET 2512	EA	6.0		
VOL	20938963	SEAL	KT	1.0		
VOL	977581	STUD 1126	EA	3.0		
VOL	981000	FLANGE SCREW 1122	EA	1.0		
VOL	20516147	TURBO	EA	1.0		
VOL	20516147-C1	CORE TURBO		1.0		
VOL	85116275	KIT	KT	1.0		
VOL	984760	FLANGE SCREW 1122	EA	20.0		
VOL	20787384	SEALING RING 2652	EA	1.0		
VOL	20787386	SEALING RING 2652	EA	1.0		
VOL	994441	FLANGE SCREW 1122(PK=20)	EA	1.0		
VOL	8081733	BOLT	EA	1.0		
VSD	SEQ9406706021	SHELLZONE 50/50 GREEN	EA	10.0		
VOL	21937327	COOLANT FILTER	EA	1.0		
DN	DN P606720	AIR FILTER 20411815	EA	1.0		
VOL	20516147-C1	CORE TURBO	EA	-1.0		
	ENVIRON CH	ENVIRONMENTAL CHARGE		1.0		
	SHOP SUP	SHOP SUPPLIES		1.0		

Total Parts: Total Core Charge:

> Total Core Ret: Total Labor:

Total Miscellaneous:

<sup>\*\*</sup> See Last Page for Invoice Total

Invoice: 5-241990028 Date / Hour: 7/18/2014 2:06:24PM

Repair Order: 13370 Customer: 16241

Branch: 5

Total Invoice: \$ 3,487.78 \*\*\*COD\*\*\*

Page 2 of 2

Customer P/O:	nblair	000	Orig R/O: 0	Completion Date: 7/18/2014
		To	otal Technology Fees:	
			Invoice Subtotal: Total Tax:	
Payment Method Terms COD Net 0	<u>Due Date</u> 7/18/2014		Total Invoice:	\$3,487.78