

28325

OUR REF	YOUR REF	INV DATE	INV AMOUNT	Check: INV TOTAL
056583	56583	03/10/15	8,118.75	8,118.75
		ENGINE 2010 FORD F250		

Check Total: 8,118.75

PRODUCT SDLM102 USE WITH 91500 ENVELOPE

PRINTED IN U.S.A.

A

INSPECT ALL MERCHANDISE. IF DEFECTIVE AND RETURNED TO US  
WITHIN 90 DAYS IN SAME CONDITION OF PURCHASED. WE WILL  
REPLACE THE MERCHANDISE. WE MAKE NO OTHER PROMISE  
GUARANTEE, OR WARRANTY. WE ARE NOT RESPONSIBLE FOR  
DAMAGE OR ANY LOSS CAUSED FROM INSTALLATION. NO GUARANTEE  
ON ELECTRICAL PARTS.

*Paid cb# 28325*

Thank You for your order. No returns on electrical pa  
Please circle Payment Type: Cash Check C/Card D/Card  
Delivery Date Sub Total 7500.00  
Discount .00 Taxable 7500.00

TAX

TOTAL

8118.75

RECEIVED BY \_\_\_\_\_



FILE COPY

REFERENCE #	DATE
	21344 3/6/2015 10:07
P.O. #	CUSTOMER #

S  
O  
L  
D  
  
T  
OS  
H  
I  
P  
  
T  
O

2010 Ford PU

Page 1

SALESMAN

TYPE OF SALE

TAX CODE

SHIP VIA

1 - 1 MFK

DELIVERY TICKET

QUANTITY	PART NUMBER AND DESCRIPTION	UNIT PRICE	EXTENSION
1	300-09164 1U-ENGINE ASSEMBLY; Stk# P4222 PO#4222; Requested:2010 F250SD; FORD F250SD PICKUP 08-10 6.4L (VIN R, 8th digit, diesel); Q:110225		
<p>INSPECT ALL MERCHANDISE. IF DEFECTIVE AND RETURNED TO US WITHIN 90 DAYS IN SAME CONDITION OF PURCHASED. WE WILL REPLACE THE MERCHANDISE. WE MAKE NO OTHER PROMISE GUARANTEE, OR WARRANTY. WE ARE NOT RESPONSIBLE FOR DAMAGE OR ANY LOSS CAUSED FROM INSTALATION. NO GUARANTEE ON ELECTRICAL PARTS.</p> <p><i>Paid Cash</i></p> <p>Thank You for your order. No returns on electrical pa Please circle Payment Type: Cash Check C/Card D/Card Delivery Date Sub Total 7500.00 Discount .00 Taxable 7500.00</p>			
TAX			
TOTAL			8118.75

RECEIVED BY \_\_\_\_\_

INVOICE # 6371

QTY	PART NO. & PART NAME	PRICE
	HOSE	
	ANTI FREEZE	
	FUEL FILTER	
	OIL FILTER	
	AIR FILTER	
	ENGINE OIL	
	DIESEL FUEL	
	POWER STEERING FLUID	
	DIESEL TREATMENT	

NAME

ADDRESS

CITY

PHONE

MAKE

FORD

TYPE OR MODEL

F-250

YEAR

2010

SERIAL NO.

0AEA27721

LIC. NO.

OPER. NO.

WORK REQUESTED OR DESCRIPTION OF PROBLEM

1 REPLACED ENGINE AS PER CUSTOMER'S REQUEST.

CUSTOMER SUPPLIED ENGINE. HAD TO REMOVE OIL PAN

FROM OLD ENGINE AND REPLACED IT ON NEW ENGINE.

REMOVED, CLEANED AND REINSTALLED FUEL TANK AND

FLUSHED FUEL SYSTEM. REPLACED FUEL FILTERS, OIL

FILTER AND AIR FILTER. CHANGED ENGINE OIL AND ANTI

FREEZE. CUSTOMER SUPPLIED A USED ENGINE AND 2

BATTERIES

CASH

UNLESS PREVIOUS  
ARRANGEMENTS HAVE  
BEEN MADE

DATE

MAR. 10, 15

ORDER WRITTEN BY

TRUCK NO.

SPEEDOMETER

201628

SERVICE CHARGE

P.O. No.

BY:

TOTAL PARTS

OUTSIDE REPAIRS

TOTAL OUTSIDE REPAIRS

YOUR ATTENTION PLEASE! (ADDITIONAL WORK NEEDED)

TOTAL SERVICE

TOTAL PARTS

SERVICE TRUCK

ENVIRON. FEES

FREON REC. FEE

OUTSIDE REP.

SHOP SUPPLIES

TAX

TOTAL AMOUNT

3714.80

THANK YOU

00001

03/16/2015 1:09PM FAX



QTY	PART NO. & PART NAME	PRICE
	TURBO	
2	INSULATORS	
2	INSULATORS	
2	INSULATORS	
2	INSULATORS	
2	INSULATORS	
2	INSULATORS	
2	INSULATORS	
2	INSULATORS	
	BOLT	
	BOLTS	
	NUTS	
	POWER STEERING PUMP	
	HOSE	
	POWER STEERING FLUID	
<i>Paid Check # 34105</i>		
P.O. No.		
BY:		
TOTAL PARTS		
OUTSIDE REPAIRS		
TOTAL OUTSIDE REPAIRS		
YOUR ATTENTION PLEASE! (ADDITIONAL WORK NEEDED)		

## CASH

UNLESS PREVIOUS  
ARRANGEMENTS HAVE  
BEEN MADE

DATE \_\_\_\_\_

MAR. 06. 18

ORDER WRITTEN BY

TRUCK NO.

**SPEEDOMETER**

304130

SERVICE CHARGE	
----------------	--

MAKE	TYPE OR MODEL	YEAR	SERIAL NO.
FORD	F-250	2010	AEA27721

OPER. NO.	WORK REQUESTED OR DESCRIPTION OF PROBLEM
1	REPLACED BOTH TURBOS BY CUSTOMER'S REQUEST. HAD TO LIFT CAB UP TO REPLACE TURBOS AND CAB MOUNTS
2	REPLACED POWER STEERING PUMP AND HIGH PRESSURE HOSE
	ADVISED CUSTOMER THAT TRUCK HAS AN EXHAUST LEAK ON RIGHT SIDE EXHAUST MANIFOLD. NO ACTION TAKEN. CUSTOMER DECLINED REPAIRS

TOTAL SERVICE				
TOTAL PARTS				
SERVICE TRUCK				
ENVIRON. FEES				
FREON REC. FEE				
OUTSIDE REP.				
SHOP SUPPLIES				
TAX				
TOTAL AMOUNT				5502.70

THANK YOU

# INVOICE # 7085

QTY	PART NO. & PART NAME	PRICE
	EXHAUST GASKET KIT	
	EXHAUST TEMPERATURE SENSORS	
	EXHAUST PRESSURE SENSOR	
	THERMOSTAT KIT	
	ANTI FREEZE	

**CASH**  
UNLESS PREVIOUS  
ARRANGEMENTS HAVE  
BEEN MADE

DATE  
DEC. 27, 17  
ORDER WRITTEN BY

TRUCK NO.

MAKE	TYPE OR MODEL	YEAR	SERIAL NO.	LIC. NO.	SPEEDOMETER
FORD	F-250	2010	AEA27721		298141
OPER. NO.	WORK REQUESTED OR DESCRIPTION OF PROBLEM				SERVICE CHARGE

1 TROUBLESHOOT FOR ENGINE LOW POWER. HOOK UP  
SCANNER AND FOUND CODE P242E, EXHAUST GAS  
TEMPERATURE SENSOR INTERMITENT. CODE P200E,  
CATALYST SYSTEM OVER TEMPERATURE. FOUND DPF  
NEEDED TO BE CLEANED. FOUND SHORTED OUT EGT  
SENSOR. REMOVED, CLEANED AND REINSTALLED DPF AND  
REPLACED EGT SENORS AND EGR TEMPERATURE SENSOR.  
ALSO REPLACED THERMOSTAT AND CHANGED ANTI FREEZE

*PAID*

P.O. No.

Y:

TOTAL PARTS

OUTSIDE REPAIRS

CLEANED DPF

TOTAL OUTSIDE REPAIRS

YOUR ATTENTION PLEASE! (ADDITIONAL WORK NEEDED)

TOTAL SERVICE	
TOTAL PARTS	
SERVICE TRUCK	
ENVIRON. FEES	
FREON REC. FEE	
OUTSIDE REP.	
SHOP SUPPLIES	
TAX	
TOTAL AMOUNT	2219.20

THANK YOU



Paid  
Check #

[illegible]

UNLESS PREVIOUS  
ARRANGEMENTS HAVE  
BEEN MADE

DATE \_\_\_\_\_

APR. 12, 16

ORDER WRITTEN BY \_\_\_\_\_

TRUCK NO.

	SPEEDOMETER
--	-------------

243303

	SERVICE CHARGE
--	----------------

TOTAL SERVICE		
TOTAL PARTS		
SERVICE TRUCK		
ENVIRON. FEES		
FREON REC. FEE		
OUTSIDE REP.		
SHOP SUPPLIES		
TAX		
TOTAL AMOUNT		1829.79

THANK YOU