Date	Invoice #
7/30/2015	2379

	711
Bill To	08:28:2015
	00.

Ship To		

	Terms	Rep	Ship	Via	F.O.B.		Project
	Due on recei	ipt	6/5/2015				
Quantity	Item Code		Descript	ion	Price E	ach	Amount
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PARTS PARTS PARTS LABOR PARTS PARTS PARTS PARTS PARTS	REAR AND L CONDITIONS WINDOW WINDOW FREON LABOR - JOH CONDITIONS CHECKED AI	N DEERE 2755 TR EFT SIDE WINDOV R N DEERE 2755 TR R LINES APART A L FITTINGS THRO LEAK ON HYDRA ONER	ACTOR - REPLACED AIR ACTOR - TOOK A AND REPLACED O DUGHOUT, FIXE	CED R MR ORINGS,		

Dale	Invoice #
10/21/2019	3138

	1111
Bill To	12/24/2019

Ship To		

Total

JABOR FIRST REPAIR - 6/20/20109 - SIIOP - JOHN DEERE 2755 TRACTOR - AIR CONDITIONER NOT WORKING, REMOVED HOOD AND REMOVED CONDENSER AND CLEANED, CHARGED AIR CONDITIONER, AIR CONDITIONER WOULD NOT COME ON, MESSED WITH THERMOSTAT SWITCH AND IT CAME ON, THROTTLE WAS STICKING - REMOVED AND REPLACED SHUTT OFF CABLE, FOUND THAT IF YOU RAISE UP ON FOOT THROTTLE THAT ENGINE WOULD IDLE DOWN, BLEW OUT CAB AIR FILTER AND FOAM FILTER, REPLACED HOUSING THAT HOLDS FOAM FILTER, WASHED RADIATOR AND CONDENSER OUT AND PUT HOOD BACK ON FREON PARTS HOUSING 1 PARTS SHUT OFF CABLE FREIGHT 6.5 LABOR SECOND REPAIR - 7/22/2019 - SHOP - JOHN DEERE 2755 TRACTOR - AIR CONDITIONER QUIT - AIR COMPRESSOR CLUTCH WENT OUT, DISASSEMBLED AND FLUSHED SYSTEM, REMOVED AND REPLACED AIR COMPRESSOR, DRIFE AND EXPANSION VALVE, INSTALLED RELAY KIT TO MAKE SURE AIR COMPRESSOR ALWAYS GETS 12 VOLTS, REMOVED	P.O. Number	Terms	Rep	Ship	Via	• F.0	D.B.	Project
JANUARY LABOR FIRST REPAIR - 6/20/20109 - SIIOP - JOIN DEERE 2755 TRACTOR - AIR CONDITIONER NOT WORKING, REMOVED HOOD AND REMOVED CONDENSER AND CLEANED, CHARGED AIR CONDITIONER, AIR CONDITIONER WOULD NOT COME ON, MESSED WITH THERMOSTAT SWITCH AND IT CAME ON, THROTTILE WAS STICKING - REMOVED AND REPLACED SHUT OFF CABLE, FOUND THAT IF YOU RAISE UP ON FOOT THROTTILE THAT ENGINE WOULD IDLE DOWN, BLEW OUT CAB AIR FILTER AND FOAM FILTER, REPLACED HOUSING THAT HOLDS FOAM FILTER, WASHED RADIATOR AND CONDENSER OUT AND PUT HOOD BACK ON FREON PARTS HOUSING 1 PARTS SHUT OFF CABLE FREIGHT 6.5 LABOR SECOND REPAIR - 7/22/2019 - SHOP - JOHN DEERE 2755 TRACTOR - AIR CONDITIONER QUIT - AIR COMPRESSOR CLUTCH WENT OUT, DISASSEMBLED AND FLUSHED SYSTEM, REMOVED AND REPLACED AIR COMPRESSOR, DRIER AND EXPANSION VALVE, INSTALLED RELAY KIT TO MAKE SURE AIR COMPRESSOR ALWAYS GETS 12 VOLTS, REMOVED	JD 2755	Due on receip	pt	6/20/2019				
TRACTOR - AIR CONDITIONER NOT WORKING, REMOVED HOOD AND REMOVED CONDENSER AND CLEANED, CHARGED AIR CONDITIONER, AIR CONDITIONER WOULD NOT COME ON, MESSED WITH IHERMOSTAT SWITCH AND IT CAME ON, THROTTILE WAS STICKING - REMOVED AND REPLACED SHUT OFF CABLE, FOUND THAT IF YOU RAISE UP ON FOOT THROTTLE THAT ENGINE WOULD IDLE DOWN, BLEW OUT CAB AIR FILTER AND FOAM FILTER, WASHED HOUSING THAT HOLDS FOAM FILTER, WASHED RADIATOR AND CONDENSER OUT AND PUT HOOD BACK ON FREON PARTS HOUSING SHUT OFF CABLE FREIGHT 6.5 LABOR SECOND REPAIR - 7/22/2019 - SHOP - JOHN DEERE 2755 TRACTOR - AIR CONDITIONER QUIT - AIR COMPRESSOR CLUTCH WENT OUT, DISASSEMBLED AND FLUSHED SYSTEM, REMOVED AND REPLACED AIR COMPRESSOR, DRIER AND EXPANSION VALVE, INSTALLED RELAY KIT 10 MAKE SURE AIR COMPRESSOR ALWAYS GETS 12 VOLTS, REMOVED	Quantity	Item Code		Descript	ion		Price Each	Amount
AND REPLACED THERMOSTAT SWITCH, REMOVED AND REPLACED CIRCUIT BOARDS IN DASH AND CLEANED ELECTRICAL CONNECTORS 1 PARTS COMPRESSOR 1 PARTS RECEIVER DRIER 1 PARTS EXPANSION VALVE 1 PARTS RELAY KIT	2 1 1 1 6.5	PARTS PARTS PARTS PARTS PARTS PARTS PARTS PARTS PARTS	TRACTOR - AI REMOVED HO CLEANED, CH CONDITIONE THERMOSTAL WAS STICKIN CABLE, FOUN THROTTLE TH OUT CAB AIR HOUSING THE RADIATOR AI BACK ON FREON HOUSING SHUT OFF CA FREIGHT SECOND REP. TRACTOR - A COMPRESSOI AND FLUSHE AIR COMPRES INSTALLED R COMPRESSOI AND REPLAC AND REPLAC CLEANED EL COMPRESSOI RECEIVER DI EXPANSION Y	R - 6/20/20109 - SH IR CONDITIONER DOD AND REMOVE LARGED AIR CON R WOULD NOT CO F SWITCH AND IT G - REMOVED AS ID THAT IF YOUT HAT ENGINE WOU LEILTER AND FOL AT HOLDS FOAM ND CONDENSER BLE AIR - 7/22/2019 - S IR CONDITIONER R CLUTCH WENT D SYSTEM, REMO SSOR, DRIER AND ELAY KIT TO M/ R ALWAYS GETS ED THERMOSTA ED CIRCUIT BOA ECTRICAL CONN R RIER	OP - JOHN DEE NOT WORKING ED CONDENSE DITIONER, AIR OME ON, MESS CAME ON, TH ND REPLACED RAISE UP ON FO JULD IDLE DOW AM FILTER, REI FILTER, WASH OUT AND PUT I AND PU	G, ER AND E ED WITH ROTTLE SHUT OFF OOT N, BLEW PLACED HOOD SERRE 2755 MBLED LACED	Price Each	Amount

Date	Invoice #
10/21/2019	3138

Bill To	12/24/2019
	72

Ship To		

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
Л 2755	Due on receipt		6/20/2019			Tioject
Quantity	Item Code		Description	n .	Dries Cont	
3 1 4	PARTS PARTS	CIRCUIT BOA RELAY FREIGHT FREON PARTS CLEAN	RD		Price Each	Amount
	APPRECIATE	S YOUR BUSIN	ESS! THANK YOU		Total	\$1,789.

Scanned with CamScanner

Date	Invoice #
12/1/2014	2250

	11115
Bill To	01/20/2015

P.O. Number	Terms	Rep	Ship	Via	F.C	D.B.		Project
OHN DEERE 27	55 Due on receip	nt .						
Quantity	Item Code		Descrip	ion		Price Ea	ich	Amount
52 LABOR		LABOR - JOH	N DEERE 2755 TR WORK, DRAINEL	ACTOR - HYDRA HYDRAULIC OI	L AND			
- 1		PULLED SUM	P SCREEN, FOUN	D SCREEN AND	FILTER		- 1	
- 1		PLUGGED UP	WITH BRAKE M.	ATERIAL, REMO	VED		- 1	
		CAB. REMOV	ED THREE POINT	ARMS AND ROO	CKSHAFT		- 1	
- 1		ASSEMBLY.	REMOVED REAR	TIRES AND WHE	ELS,		- 1	
		REMOVED FI	NAL DRIVES FRO	M BOTH SIDES,	SPLIT		- 1	
- 1		TRANSMISSI	ON FROM CLUTC	II HOUSING, SPL	IL			
		CLUTCH HOU	ISING AT ENGINE	, REMOVED FLY	WHEEL		- 1	
		AND HAD RE	SURFACED REPL	ACED CLUTCH A	ND			
- 1		PRESSURE PI	ATE ASSEMBLY,	REPLACED THE	too wor		- 1	
		BEARING AS	SEMBLY, DISASS	EMBLED REAR C	DF		- 1	
- 1		CLUTCH HOU	ISING, INSPECTE	D PTO CLUTCH,	ACED			
1		REPLACED S	EALS AND SEALI	NG KINGS, KEPL	ACED			
- 1		TRANSMISSI	ON PUMP AND LI LL SEALS ALONG	THE WAY CHE	CKED		- 1	
		REPLACED A	ON AND REPLACE	ED PACKINGS AN	VD.			
- 1		CEALS DETW	EEN TRANSMISS	ON AND CLUTC	H		- 1	
]		HOUSING RE	MOVED PARKIN	G BRAKE BAND	AND			
		REPLACED B	EPLACED BRAK	ES. REPLACED P	ro		- 1	
		GASKET AND	SEALS, REPLAC	ED NEUTRAL ST	ART		- 1	
		SWITCH, DIS	ASSEMBLED ROO	CKSHAFT AND			- 1	
		INSTALLED (ASKET KIT, PUT	BACK TOGETHE	R,		- 1	
- 1		STRAIGHTEN	ED FENDER ON I	EFT SIDE THE B	EST WE		- 1	
- 1		COULD, REPI	ACED CAB MOU	NTS, MADE LEVI	ER TO		- 1	
- 1		PUT ON HYD	RAULIC LEVER, I	BLED CLUTCH AN	ND I		- 1	
			ARGED AIR COND	OITIONER				
	PARTS		ATE ASSEMBLY					
	PARTS	CLUTCH DISI						
	PARTS	THROW OUT						
	PARTS	PILOT BEARI						
	PARTS	LOAD SMAFT	RAULIC HOSE					
	PARTS PARTS	HYDRAULIC						
		IIIDKAGLIC	10011				_	
hank you for you	r business.				- 1	Total		

Scanned with CamScanner

Date	Invoice #
12/1/2014	2250

	1 2015
Bill To	01/20/20

Ship To		

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project	
OHN DEERE 275	Due on recei	ipt		¥			
Quantity	Item Code		Description Price Each Arr		Description		h Amount
_		GROMMET					
	PARTS	SPRING PIN					
	PARTS	SNAP RING			1		
	PARTS	LEVER					
	PARTS	FREIGHT					
	PARTS	ORING					
	PARTS	ORING					
	PARTS	ORING					
	PARTS	ORING					
	PARTS	CAP			1		
	ARTS	BUSHING					
	ARTS	ORING					
	ARTS	ORING			1		
	ARTS	GASKET			- 1		
	ARTS	GASKET			- 1		
	ARTS	PIN			ı		
	ARTS	BEARING					
	ARTS	WASHER			1		
	ARTS	ISOLATOR			1		
	ARTS	ISOLATOR			ı		
	ARTS	ISOLATOR			1		
	ARTS	RING			ı		
	ARTS	SHIM			1		
	ARTS	SPRING			1		
	ARTS	SEAL.					
	ARTS	SEAL					
	ARTS	ELBOW FITTING	ì				
	ARTS	GASKET KIT					
	ARTS	GASKET KIT					
	ARTS	BRAKE DISK					
	ARTS	GROUND CABLE	3				
	ARTS	TRANSMISSION	OIL PUMP				
	ARTS	OIL LINE					
	ARTS	ELBOW FITTING					
hank you for your b	ousiness.				Total		

Date	Invoice #
12/1/2014	2250

			12/1/2014
Bill To	01:20:2015	Ship To	

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
OHN DEERE 27:	55 Due on rec	eeipt				Project
Quantity	00em Code		Descript	ion	Price Each	Amount
1 1 2 2 1 6 1 1 1 1 12.5	PARTS	DIPSTICK FILTER SWITCH ORING SEALING WAS BRAKE BAND PARTS CLEAN GAUGE BALL BEARING FREIGHT SWITCH KIT HYDRAULIC OFREON SHOP SUPPLIE PAYMENT	ER G JIL			
hank you for you	r business.				Total	\$5,035.