

2009 John Deere 7850 Forage Harvester

New IVLOC Transmission Output Shaft Seals

New Fuel Sender

New Spout Stops

New Hydraulic Hose for Spout

New Idler and Belt for Rear Rotary Screen

New Accelerator Bearings

Replaced Leaking Hydraulic Lines

Full Machine Service

New Knock Sensors

New Coolant Temp Sensor

New Hydraulic Steering Hoses

Replaced some O-Rings and Gaskets on Hydraulic System

\$16,000 in repairs