

# INVOICE

Invoice #

SO #

Date 10/16/2020

Writer

Page 1 of 2

Invnt:Cust

Cust acct#

Cust PO# UNIT #7

Sold  
to:

Ship  
to:

Contact

Contact phone

Payment terms

Primary phone

Ship via

Vehicle info:

Year/Make/Model 2000 / PTRB / 378

Cust Unit # 7

VIN/Short VIN 1XPFD89X9YD488930 / YD488930

Miles/Hours 639233 / 0

Repair Order no.

Operation #

Condition

QUOTE CHECK AND ADVISE TRANSMISSION ONLY

Correction

ZW- CHUNK TESTED TRANSMISSION AND BOTH DIFFERENTIALS. FOUND METAL FLAKE IN THE TRANSMISSION, AND A COUPLE SMALL CHUNKS OF METAL IN THE REAR DRIVE DIFF. TRANSMISSION DOSE HAVE ISSUE WITH REVERSE GEAR NOT FULLY GRABBING. REMOVED DRIVELINE. DRAINED TRANSMISSION FLUID. REMOVED SHIFT TOWER, REMOVED LINKAGE. REMOVED AIR LINES. REMOVED ELECTRICAL CONNECTIONS. REMOVED TRANSCOOLER LINES. REMOVED PTO. REMOVED TRANSMISSION. INSPECTED CLUTCH AND FOUND PIECES OF THE THROWOUT BEARING BUSHINGS INSIDE THE CLUTCH. RECOMEND REPLACING THE CLUTCH DUE TO THE MISSING BUSHINGS. SENT TRANSMISSION TO GEAR SHOP FOR INSPECTION  
ZW- REMOVED AND REPALED REAR MAIN SEAL. INSTALLED FLYWHEEL. INSTALLED CLUTCH. INSTALLED TRANSMISSION. INSTALLED PTO AND SHIMMED, INSTALLED PTO PUMP. INSTALLED SHIFT TOWER. REPLACED AIR LINES THAT ARE TOO SHORT. INSTALLED DRIVELINE. INSTALLED ELECTRICAL CONENCTIONS. INSTALLED AIR LINES. FILLED TRANSMISSION. TOPPED OFF DIFFS. REISNTALELD AXLE SHAFTS. ADJUSTED CLUTCH. AND ROADTESTED TRUCK. FOUND NO PROBLEMS WITH THE DIFF NO NOISE. ADVISED MARCUS ON THE DIFF. SITUATION.

Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
116_RTLO18918BX	REMAN FULLER ""SUPER"" 18SPD WO Unit #	1	1	0			
**Core exchange**							
072_MU-155698-12XB10	15.5 CLUTCH	1	1	0			
**Core exchange**							
022_CLT009P	9" CLUTCH LUBE TUBE	1	1	0			
077_SCB200	.375" STANDARD HINGED 2" CLUTCH BRAKE	1	1	0			
345_550044796	BULK GME 40W SYN	16	16	0			
332_FP-1425868	REAR MAIN SEAL CAT.	1	1	0			
029_306VV	PILOT BRG W/VITON SEAL	1	1	0			

# INVOICE

Invoice #

SO #

Date 10/16/2020

Writer

Page 2 of 2

Cust acct# Cust PO# UNIT #7

Est: Cusi

Labor

Imported labor from WO-0159283

460_06-01093	CLUTCH SHAFT 9-5/8"	1	1	0
GRX_05089PS	29 OZ. CRC BRAKE CLEAN	2	2	0
017_N6.5-3-1371KX	SLIP YOKE 11.875"	1	1	0
010_5-676X	7.5" WIDE 1810 1/2RD	1	1	0

Labor

Imported labor from WO-0158776

033_13MK5708	8 BOLT .010 GASKET	2	2	0
033_13MK5709	8 BOLT .020 GASKET	1	1	0
031_35-P-8	PTO SHIFTER GASKET	1	1	0
110_52601	HARNESS TUBING (50 FT.)	4	4	0
010_6.5-70-18X	1710,1760,1810 STRAP KIT	1	1	0
245_330-3111	DRIVE AXLE GASKET	2	2	0
345_550026918	SPIRAX ASXR 75W90 BY QUART	9	9	0

Labor

Shop supplies

Total merchandise

Total cores

Total labor

Tax amount

Invoice total

\$8,687.83