voice To Account No:	Deliver To:		Invoice Number:	
			Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:	
			Page:	1 of 2
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8760	12062	RW8760H002800	31857W	
OTH/WE/H68/DIAG05 Retail COMPLAINT: 01 DIAGNOSTICS AND TROUBLESHOOTING				
CORRECTION:				
Engine overheating. Operate engine to check fan clutch. Fan clutch was bad.				
-				Sub-Total:
ALL/TDB/01 Retail COMPLAINT: 02 CORRECTION: 3 service calls. Check heat on water jacket with heat gun. Check connectors in wiring harness.				
				Sub-Total:
8760F915543 Retail COMPLAINT: 03 FAN VISCOUS DRIVE, R&R				
CORRECTION: Loosen belts. Remove fan.				
Replace viscous fan drive. Install fan. Tighten belts.				
Part Number Description		2	Quantity List Price	Net Price Extended Price Taxed

Invoice To Account No:	Delive	er To:		SERVICE INVOICE				
invoice to Account No.				v	Invoice Numl Invoice D Local Vork Order Num Payment T	ate: tion: ber: ype:	7.	/27/2020
						age:	Fleet No:	
Make/Model:		Meter:	Serial Number:		Eq ID:		FIEGUIVO.	
JOHN DEERE 8760		12062	RW8760H002800)	31857W			
8760F915543 Retail RE30168 Miscellaneous 3750	VISCOUS FA Description FREIGHT			1.00 Quantity 1.00	<u>L</u> ist Price	Net Price	Extended Price	Taxed Ind
					_	Sub-T	otal:	1
		1						
						P OL N Sales		2,359.85
						Grand T	otal:	2,308.00

nvoice To Account No:	Deliver To:		SER	VICE INVOICE
IIIVOIGE 15 AGGGGIA AGG			Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:	7/15/2020
			Page:	1 of 3
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8760	12038	RW8760H002800	31857W	

OTH/WE/H68/DIAG05 Retail

COMPLAINT:

01 DIAGNOSTICS AND TROUBLESHOOTING

CORRECTION:

Check voltage at compressor, 12.5 volts.

Remove dust cover from compressor, clutch had failed.

Sub-Total:

8760-1801/CRD/51 Retail

COMPLAINT:

02 AIR CONDITIONER A/C COMPRESSOR RECEIVER DRYER ORIFICE TUBE - REPLACE

REPLACE AIR CONDITIONER COMPRESSOR RECEIVER DRYER & ORIFICE TUBE

Recover Freon, remove compressor and receiver dryer.

Flush system using dual stage flush procedure.

Install new compressor, receiver dryer, & orifice tube.

Evacuate system and verify it holds a vacuum.

Charge with R134A Freon.

Leak test at compressor, dryer, and exposed lines.

Run in and test for proper operation. (28 to 30 degree F drop from ambient temperature)

Note: To qualify compressor for warranty, system must be flushed using dual stage flush procedure, expansion valve must be removed and flushed or replaced, and receiver dryer must be replaced.

CORRECTION:

Replaced air conditioner compressor, receiver dryer, and oriRecovered Freon, removed compressor, receiver dryer, and oriFlushed system using dual stage flush procedureInstalled new compressor, receiver dryer, & orifice tubeEvacuated system and verified it held a vacuumCharged with R134A FreonLeak tested at compressor, dryer, and exposed linesRan in and tested for proper operation (28 to 30 degree F dr

Part Number A3917R	Description O-RING	Quantity 1.00	List Price	Net Price	Extended Price	Taxed Ind
A4365R	O-RING	1.00				
P50883	RING	2.00				
P51212	O-RING	1.00				

Invoice To Account No:	Deliver To:		SER	VICE INVOICE
Invoice to Account No.			Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:	7/15/2020
			Page:	2 of 3
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8760	12038	RW8760H002800	31857W	
R33259 R73189 RE10981 RE10982 RE24619 RE51918 RE51969 SE503052 SE503052-CR	AIR FILTER O-RING V-BELT MANIFOLD VALVE AIR FILTER HYDRAULIC TUBE COMPRESSOR CORE for:Compressor Reman FOAMING COIL CLEANER		1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00	

Invoice To Account No:	Deliver T	o:		SERVICE INVOICE			
				Invoice Number Invoice Date Location Work Order Number Payment Type	:	7/15/2020	
				Page		3 of 3	
Make/Model:		Meter:	Serial Number:	Eq ID:	Fleet N	0:	
JOHN DEERE 8760		12038	RW8760H002800	31857W			
8760-1801/CRD/51 Retail TY25600Z	I D DED AC FLUSH			1.00	Sub-Total:		
					Labor: Parts: OL&M: Misc: Sales Tax:		
					Grand Total:	\$2,219.45	

Invoice To Account No:	Deliver To:		SER	VICE INVOICE
			Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:	7/8/2020
			Page:	1 of 2
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8760	12033	RW8760H002800	31857W	

OTH/WE/H68/DIAG05 Retail

COMPLAINT:

01 DIAGNOSTICS AND TROUBLESHOOTING TWO SERVICE CALLS,

A/c not cooling.

CORRECTION:

Sub-Total:

ALL/TDB/01 Retail

COMPLAINT:

02

CORRECTION:

Pressure system with nitrogen.
Found 2 lines leaking.
Charge system.
R&R 2 lines from condenser.
Vacuum system.

Charge system.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
A3917R	O-RING	1.00				
P50883	RING	1.00				
P51212	O-RING	2.00				
R10093	O-RING	1.00				
R33259	O-RING	1.00				
RE212795	FITTING	1.00				
RE51918	HYDRAULIC	1.00				
RE61926	REFRIGERAN	1.00				
RE61927	REFRIGERAN	1.00				
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

Invoice To Account No:		Deliver To:		SERVICE INVOICE			
				Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:		7/8/2020	
				Page:		2 of 2	
Make/Model:		Meter:	Serial Number:	Eq ID:	Fleet	No:	
JOHN DEERE 8760		12033	RW8760H002800	31857W			
ALL/TDB/01 Retail 3750	FREIGHT			1.00	Sub-Total:	N	
					Labor: Parts: OL&M: Misc: Sales Tax:		
					Grand Total:	\$1,881.80	

nvoice To Account No:	Deliver T	o:		SERVICE INVOICE			
				Invoice Number Invoice Date Location Work Order Number Payment Type	te: on: er:	6/22/2020	
	2.5			Pag	je:	1 of 1	
Make/Model:		Meter:	Serial Number:	Eq ID:	Fleet N	lo:	
JOHN DEERE 8760		11947	RW8760H002800	31857W			
CORRECTION: drive time and had to go to altu	is and pickup starter.				Sub-Total:		
					Labor: Parts: OL&M: Misc: Sales Tax:		
					Grand Total:	\$146.0	

Invoice To Account No:		Deliver To:				SERVI	CE INVO	JICE
Invoice to Account No.					Invoice Numb		6	3/8/2020
					Locat	ion:		
				l v	Work Order Num			
					Payment Ty	/pe:		
					Pa	ige:		1 of 1
Make/Model:		Meter:	Serial Number:		Eq ID:		Fleet No:	
JOHN DEERE 8760		11991	RW8760H002800)	31857W			
CORRECTION: Charge a/c with 2 cans of freon Part Number R134A	Description 12 OZ CANS			Quantity 4.00		Net Price	Extended Price	Taxed Inc
					_	Sub-To	otal:	
							bor:	
							arts:	
							&M:	
							lisc:	
						Sales	Tax:	
						Grand To	otal:	\$246.80

Lucias To Associat No.	Deliver	r To:		SER\	VICE INVOICE
Invoice To Account No:				Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:	12/7/2019
				Page:	1 of 2
Make/Model:		Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8760		11909	RW8760H002800	31857W	

OTH/WE/H68/DIAG05 Retail COMPLAINT:

01 DIAGNOSTICS AND TROUBLESHOOTING

Blower motor very noisy. Remove side cover.

Remove blower motor, bearing out in motor.

CORRECTION:

Sub-Total:

8760F699505 Retail COMPLAINT:

02 BLOWER MOTOR, R&RONE

CORRECTION:

Remove side cover.

R&R resistor and connector pins.

R&R blower motor.

Remove blower motor and adjust fan on shaft.

Operate to verify repair.

Clean cab filter and housing, very dusty.

Part Number AT456900	Description RESISTOR	Quantity 1.00	List Price	Net Price	Extended Price	Taxed Ind
R65595	ELEC. CONN	4.00				
RE53219	MOTOR	1.00				
U46662	ELEC. CONN	4.00				
10276	SCREWS	1.00				
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

		Deliver To:		SERVICE INVOICE			
Invoice To Account No:		Select to:			umber: ce Date: ocation:	e:	12/7/2019
				Work Order N	Number: nt Type:		
					Page:		2 of 2
Make/Model:		Meter:	Serial Number:	Eq ID:		Fleet N	0:
JOHN DEERE 8760		11909	RW8760H002800	31857W			
8760F699505 Retail 3750	FREIGHT			15.00			
						Sub-Total:	
						Labor: Parts:	
						OL&M: Misc: Sales Tax:	
					G	rand Total:	\$1,314.53