

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	12	MERCEDES-BENZ LIGHT	WDPPF4CC0C9511842		20263/20382	TT673A	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN12 DE		02JAN2015	17:00 15JUL19		0.00	CREDIT	23JUL19

R.O. OPENED	READY	OPTIONS:
10:13 24JUN19	11:38 23JUL19	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A MISC REPAIR.. CUST STATES THAT THE VEHICLE WILL NOT START

148 COMPLETED PER TECH NOTES

11060 CPS

1 000-982-33-08 BATTERY

1 000-906-24-02-80 REMAN STARTER MOTOR

,,,2.00 TECHNICIAN REPLACED FAULTY STARTER

B Moved to: 838559C Line: A

SPLT Moved to: 838559C Line: A

99 ISPO

(N/C)

C Moved to: 838559C Line: B

SPLT Moved to: 838559C Line: B

99 ISPO

(N/C)

D** MISC REPAIR.. Diagnosis to trace wiring and see why the vehicle is not engaging

148 COMPLETED PER TECH NOTES

11060 CPS

,,,5.00 TECHNICIAN DIAGNOSED AS CDI CONTROL UNIT REPLACED ON LINE B

E** MISC REPAIR.. Replace CDI on the truck

148 COMPLETED PER TECH NOTES

11060 CPS

1 642-900-71-00-80 REMAN CONTROL UNIT

,,,1.00 TECHNICIAN REPLACED FAULTY CDI CONTROL UNIT

F** MISC REPAIR.. Remove and replace ignition and key module..

148 COMPLETED PER TECH NOTES

11060 CPS

,,,2.30 TECHNICIAN REPLACED IGNITION SWITCH AND KEY

G** CHANGE OIL AND FILTER *****MOBIL 1 OIL*****

M313P CHANGE OIL AND FILTER *****MOBIL 1 OIL*****

ALL PARTS NEW ORIGINAL EQUIPMENT, UNLESS OTHERWISE SPECIFIED

SERVICE & PARTS HOURS
Monday - Friday 7:30am - 5:30pm
Saturday 9:00am - 5:00pm
CLOSED SUNDAY

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
MISCELLANEOUS	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
DISCOUNT	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Thank you for this opportunity to serve you. It is our aim to perform all the repairs requested on this repair order to your complete satisfaction. If our service was satisfactory tell your friends. If not please tell us immediately.

Any warranties on the products sold hereby are those made by the manufacturer. The seller Walser Mercedes-Benz of Wichita hereby expressly disclaims all warranties, neither express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

X
CUSTOMER SIGNATURE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	12	MERCEDES-BENZ LIGHT	WDPPF4CC0C9511842		20263/20382	TT673A	
DEL. DATE	PROG. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN12 DE		02JAN2015	17:00 15JUL19		0.00	CREDIT	23JUL19

R.O. OPENED	READY	OPTIONS:
10:13 24JUN19	11:38 23JUL19	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

	11060	CPS					
--	-------	-----	--	--	--	--	--

	1	642-180-00-09	TS FILTER INSERT				
--	---	---------------	------------------	--	--	--	--

	13	001-989-37-01-USA9	MB GENUINE ENGINE OIL				
--	----	--------------------	-----------------------	--	--	--	--

	5W-30	MB229.52	BUL				
--	-------	----------	-----	--	--	--	--

	1	007603-014106	SEAL RING,VLRUB				
--	---	---------------	-----------------	--	--	--	--

	0.80	CHANGED ENGINE OIL AND FILTER					
--	------	-------------------------------	--	--	--	--	--

--	--	--	--	--	--	--	--

H**	MISC REPAIR..	Remove and Replace Turbo Heatshield					
-----	---------------	-------------------------------------	--	--	--	--	--

	148	COMPLETED PER TECH NOTES					
--	-----	--------------------------	--	--	--	--	--

	11060	CPS					
--	-------	-----	--	--	--	--	--

	1	642-096-19-68	HEAT SHIELD				
--	---	---------------	-------------	--	--	--	--

	1	000-990-69-03	SCREW				
--	---	---------------	-------	--	--	--	--

	3	000000-004310	SCREW				
--	---	---------------	-------	--	--	--	--

	0.50	TECHNICIAN INSTALLED MISSING TURBO HEATSHIELD					
--	------	---	--	--	--	--	--

--	--	--	--	--	--	--	--

I**	MISC REPAIR..	Remove and replace Adblue element					
-----	---------------	-----------------------------------	--	--	--	--	--

	148	COMPLETED					
--	-----	-----------	--	--	--	--	--

	11060	CPS					
--	-------	-----	--	--	--	--	--

	1	906-900-57-01	CONTROL UNIT				
--	---	---------------	--------------	--	--	--	--

	1	906-490-03-39	DELIVERY LINE				
--	---	---------------	---------------	--	--	--	--

	1	906-470-04-53	HEATING UNIT				
--	---	---------------	--------------	--	--	--	--

	8	000-583-01-07	ADBLUE				
--	---	---------------	--------	--	--	--	--

	2.00	REPLACED ADBLUE HEATING ELEMENT					
--	------	---------------------------------	--	--	--	--	--

--	--	--	--	--	--	--	--

J**	MISC REPAIR...	Regeneration or replacement of Diesel Particulate					
-----	----------------	---	--	--	--	--	--

	Filter						
--	--------	--	--	--	--	--	--

	148	MISC REPAIR... Regeneration or replacement of					
--	-----	---	--	--	--	--	--

	Diesel Particulate Filter						
--	---------------------------	--	--	--	--	--	--

	11060	CPS					
--	-------	-----	--	--	--	--	--

	1.00	TECHNICIAN REGENERATED DIESEL PARTICULATE FILTER AT THIS TIME					
--	------	---	--	--	--	--	--

--	--	--	--	--	--	--	--

K**	REPLACED SRS CONTROL UNIT						
-----	---------------------------	--	--	--	--	--	--

	85073	REPLACED SRS CONTROL UNIT					
--	-------	---------------------------	--	--	--	--	--

	11060	CPS					
--	-------	-----	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--

Thank you for this opportunity to serve you, it is our aim to perform all the repairs requested on this repair order to your complete satisfaction. If our service was satisfactory tell your friends, if not please tell us immediately.

Any warranties on the products sold hereby are those made by the manufacturer. The seller Walser Mercedes-Benz of Wichita hereby expressly disclaims all warranties, neither express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorized any other person to assume for it any liability in connection with the sale of said products.

X
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
MISCELLANEOUS	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
DISCOUNT	
SALES TAX	
PLEASE PAY THIS AMOUNT	

					DATE	PAYMENT	INV. DATE
01JAN12 DE		02JAN2019	17:00	15JUL19	0.00	CREDIT	23JUL19

R.O. OPENED	READY	OPTIONS:
10:13 24JUN19	11:38 23JUL19	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

2.10 TECHNICIAN REPLACED SRS CONTROL UNIT DUE TO INTERNAL FAULT

L** R&R TURBOCHARGER

S29112 R&R TURBOCHARGER

11060 CPS

1 Q-1-03-0004 ANTICORROSION/ANTIFREEZE G48

1 642-090-89-80-80 REMAN TURBOCHARGER

1 014-997-64-45 O-RING

1 642-142-06-81 GASKET

1 642-142-04-81 GASKET

4 910143-008017 SCREW

1 642-142-07-81 GASKET

3 000-990-68-03-64 SCREW

3 000-990-67-03 SCREW

1 219-492-00-80 FLANGE GASKET

1 Q-1-03-0004 ANTICORROSION/ANTIFREEZE G48

3 000-990-68-03-64 SCREW

1 642-142-31-80 MULTI-HOLE SEAL

2 001-990-31-07 FITTED BOLT

3 000-990-68-03-64 SCREW

8.90 Technician found fault codes causing limp home mode 16E100,

123900, AND 126800, FOR CHARGE PRESSURE TOO LOW, CHARGE PRESSURE

CONTROL IS FAULTY, AND BOOST PRESSURE POSITIONER REPORTS A FAULT.

TECHNICIAN DIAGNOSED TURBOCHARGER WITH CHARGE PRESSURE CONTROL FAULTY

AT THIS TIME DUE TO BAD TURBOCHARGER BEARINGS CAUSING TURBO TO

OVER/UNDER BOOST AT TIMES. TECHNICIAN REPLACED TURBOCHARGER AND TEST

DROVE VEHICLE TO VERIFY FAULTS RECTIFIED AT THIS TIME.

M** UPSTREAM NOX SENSOR

148136 UPSTREAM NOX SENSOR

11060 CPS

1 000-905-35-03 NOX SENSOR

0.80 TECHNICIAN REPLACED FAULTY UPSTREAM NOX SENSOR

ALL PARTS NEW ORIGINAL EQUIPMENT, UNLESS OTHERWISE SPECIFIED		DESCRIPTION	TOTALS
SERVICE & PARTS HOURS Monday - Friday 7:30am - 5:30pm Saturday 9:00am - 5:00pm CLOSED SUNDAY		LABOR AMOUNT	
		PARTS AMOUNT	
		MISCELLANEOUS	
		SUBLET AMOUNT	
		SHOP FEES	
		TOTAL CHARGES	
		DISCOUNT	
		SALES TAX	
		PLEASE PAY THIS AMOUNT	

Thank you for this opportunity to serve you. It is our aim to perform all the repairs requested on this repair order to your complete satisfaction. If our service was satisfactory tell your friends, if not please tell us immediately.

Any warranties on the products sold hereby are those made by the manufacturer. The seller Walter Mercedes-Benz of Wichita hereby expressly disclaims all warranties, neither express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

X
CUSTOMER SIGNATURE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	12	MERCEDES-BENZ LIGHT	WDPPP4CC0C9511842		20263/20382	TT673A	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN12 DE		02JAN2015	17:00 15JUL19		0.00	CREDIT	23JUL19

R.O. OPENED	READY	OPTIONS:					
10:13 24JUN19	11:38 23JUL19						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

N** R+R EXHAUST MANIFOLD

1404A R+R EXHAUST MANIFOLD

11060 CPS

1 642-140-08-09-80 REMAN EXHAUST ELBOW

1 642-142-32-80 MULTI-HOLE SEAL

1 642-142-00-80 GASKET

6 120-142-00-72 HEXAGON NUT

4 642-142-18-80 GASKET

,,,4.00 REPLACED RIGHT EXHAUST MANIFOLD DUE TO BROKEN BOLTS CONNECTING

,,,TO TURBO MANIFOLD

*** THE FOLLOWING WORK NOT DONE-TRANSFERRED TO RO#838559C ***

B Moved to: 838559C Line: A

C Moved to: 838559C Line: B

EST: 4,756.33 12JUL19 16:37 SA: 13198

THANK YOU FOR YOUR BUSINESS

MERCEDES BENZ OF WICHITA IS WORKING HARD TO
DELIVER YOU THE BEST IN CUSTOMER SERVICE
IF FOR ANY REASON YOU ARE NOT 100% SATISFIED
WITH THE PRODUCTS OR SERVICE YOU RECEIVE
PLEASE LET US KNOW

ALL PARTS NEW ORIGINAL EQUIPMENT, UNLESS OTHERWISE SPECIFIED		DESCRIPTION	TOTALS
SERVICE & PARTS HOURS Monday - Friday 7:30am - 5:30pm Saturday 9:00am - 5:00pm CLOSED SUNDAY Thank you for this opportunity to serve you. It is our aim to perform all the repairs requested on this repair order to your complete satisfaction. If our service was satisfactory tell your friends. If not please tell us immediately. *Any warranties on the products sold hereby are those made by the manufacturer. The seller Walser Mercedes-Benz of Wichita hereby expressly disclaims all warranties, neither express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.*		LABOR AMOUNT	
		PARTS AMOUNT	
		MISCELLANEOUS	
		SUBLET AMOUNT	
		SHOP FEES	
		TOTAL CHARGES	
		DISCOUNT	
		SALES TAX	
		PLEASE PAY THIS AMOUNT	13764.14

X
CUSTOMER SIGNATURE