

HD9599	111-3019	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, GENERAL DYNAMICS COMM. SYST, MDL. R2670B, '05 SN: 496LFE0051, FDMA digital communications system analyzer, NEEDS CALIBRATED
HD9599	411-3012	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670A, '00 SN: 496LAL0040, FDMA digital communications system analyzer, NOT WORKING - SERVICEABLE
HD9599	411-4001	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670B, '02 SN: 496LCL0028, FDMA digital communications system analyzer, NOT WORKING - SERVICEABLE