

Throttle Body Invoice

2007 Polaris Ranger

FP9263

Detail

Unit 2007 POLARIS R07RH68AK 4X4,700 EFI,
SLV,LE
VIN/Serial No:4XARH68A874113396

Color:

Keyboard:550.8 HRS

Plate:

Odom/Hrs In:2,611

Out:2,612

BARELY STAYS RUNNING?

Description:

Resolution: FUEL PRESSURE IS 47 PSI. CHECKED COMPRESSION (145PSI PTO, 175PSI MAG), CHECKED SPARK. ALL GOOD. THROTTLE PLATE PIVOT SHAFT WORN IN THROTTLE BODY. THROTTLE BODY WILL NEED REPLACED AS WELL AS THROTTLE CABLE.

REPLACED THROTTLE CABLE, REPLACED THROTTLE BODY. UNIT STARTS AND IDLES PERFECTLY. EVEN WHEN COLD. IT DOES HAVE A BIT OF A STUMBLE OFF IDLE WHEN COLD BUT GETS BETTER AS THE UNIT WARMS UP

Parts

Part #	Qty	Description	Price	Discount	Total
7081247	1.00	CABLE-THROTTLE			
2203925	1.00	KIT-THROTTLE BODY, 1203160			
			Parts Subtotal		

Labor

Description	Technician	Hours
DIAGNOSE		0.75
REPAIR		1
		Labor Subtotal

Job Subtotal

All Jobs Subtotal:

Shop Supplies:

Hazardous Waste Disposal:

Tax:

Total:

\$692.38

Less Deposits:

Visa/Mastercard:

Total Due: