

INVOICE

Org. Est. #

INVOICE

Date: 05/10/2021

1965 Ford - Mustang -

Lic # :

Odometer In : 25648 +

VIN # :

Part Description	Qty	Sale	Ext	Labor Description	Ext
Steering cylinder	1.00			Throttle linkage clip	
Control arms	2.00			repair throttle link	
Sway kit	1.00			done lower control arms, upper ball joints, sway bar links, hydraulic steering cylinder, trans serv, plug wires	
Plug Wires	1.00			Steering damped (hydraulic) leaking, both lower control arm bushing, both lower ball joints have play, linkage clip missing, plug wires have cuts and resting on manifold	
Shop Supplies				Complete Maintenance/Safety Inspection	
				Symptoms: Complete Inspection	
				Trace source of leak - Trans	
				Symptoms: Leaking something Oily	
				Replace steering cylinder and Front lower control arms with balljoints	
				Four wheel alignment	
				Road test vehicle. Check all suspension and steering parts for wear. Check tire pressure and condition. Check riding height. Check alignment of all four wheels. Adjust caster, camber, toe-in, and thrust angle as needed on all four wheels. Center steering wheel.	
				Replace front sway links	
				Replace front sway links	
				Plug Wires	
				Environmental Compliance	

[Payments -]

We Greatly Appreciate Your Business

Labor:

Parts:

HazMat:

Sub:

Tax:

Total: \$2,245.11

Bal Due: \$2,245.11

Customer Number : 4767

Vehicle Received: 5/10/2021

Email Address: