

200 - SkyTrak 8042

[illegible]

ST8990 2005 - SkyTrak 804

7/3/2017	Repaired tranny wire and fluid, repaired electrical wiring and checked over. CB
7/19/2017	Installed new injection pump and relays. CB
10/6/2017	Fixed hydraulic leak and axle service. CB
10/13/2017	Left rear axel seal and tie rods. CB
11/2/2017	Foam filled all four tires. CB
11/9/2017	Front right new u joint and axel. All new drive u joints. CB
1/4/2018	New tranmission cooler line.
1/9/2018	Right rear planetary replacement. CB
4/2/18	Repair boom hoses and temp sensor. CB
4/18/18	Rebuilt hub. CB
5/1/18	Ignition switch and battery cable. CB
6/15/18	New boom in/out cable, boom tilt cable replace and fixed and pressure block. CB
9/18/18	Two new hydralic hoses and solined repair. CB
11/19/18	New starter and switch. CB
11/28/18	New exhaust and muffler. CB
12/19/18	Replace hydraulic hose. CB
1/14/19	Rebuils carrier assembly and new boom chain. CB
1/15/19	New boom hoses and wear plates, inspected and OK, and new left rer tire. CB
1/25/19	Rebuild right rear hub and replace left rear tire. CB
1/31/19	New starter solenid and service. CB
4/29/19	New starter solined and 30 AMP Fuse. TB
5/9/19	Replcae motor mounts, new joy sticks, tune-up rebuild cyclinders and boom pads. CB
5/14/19	Replace flywheel bushings, service transmission, over head and engine. CB
6/11/19	Cylinder repair ,Axle seals, new lights, axle service and wear pads. CB
7/9/19	New alternator and repair wiring. TB
7/15/19	Drain and flush hydraulic tank, axles and hubs. CB
9/3/19	Steering box seal replace. AD
9/30/19	New radiator and coolant. CB
1/22/20	New pressure reducing block. TB/AD
1/31/20	New ignition switch. TB New boow hose. AD
2/3/20	Replaced check valve and washed. AD
2/7/20	Replaced muffler .AD
2/27/20	New insterment cluster 4261/0 hr
3/19/20	Replaced hour meter fuel gauge not working. AD
6/2/20	Replaced steering pump, Replaced left rear tire. AD
6/2/20	Replaced thermostat. CB
6/8/20	Replaced camfollower gasket and checked for leaks. CB
6/29/20	Replaced axle seal. AD
7/17/20	Replaced radiator. AD

7/21/20	Replaced starter.AD
7/22/20	Replaced water pump, upper radiator hose.AD/TB
7/27/20	Replaced ignition switch.AD
7/31/20	Replaced boom hose for tilt cyclinder.AD
10/1/20	New thermostat over heating problem.CB
5/14/21	Rebuilt right rear hub.AD