

SERVICE INVOICE

Invoice To Account No.: 4811

Deliver To:

Invoice Number: [redacted]
 Invoice Date: 6/30/2011
 Branch: 2
 Repair Order Number: 2796
 Payment Type: [redacted]

Make/Model: JD 8850
 Meter Reading: 2048
 Serial Number: H098603711100
 Equipment Number: 16227W
 Page: 2 of 5

GEN - 3 Retail

\$127.50

Remove one set of 1/2 links from feeder chain & adjust tension.
 Top off oil level in reverser (1/2 qt.)
 Adjust F.H. drive chain

Labor: [redacted] Parts: \$0.00 Sublet: [redacted] Misc: \$0.00 Total: [redacted]

GEN - 4 Retail

\$3,441.00

Adjust rotor drive belt to get proper sheave gap
 Adjust fan speed actuator limit nuts to get 1200 RPM on fan speed
 R&R & Replace conveyor auger front plate (R&R concaves, augers, & auger bed)
 Repair/weld cracks & reinforce bearing supports
 Replace drive shaft end bearings
 Add spacer washers between gears & lock collars on augers
 Lock-tite all gears & adjust gear lash
 *Had extra time removing E-Coat paint from front plate
 R&R & Replace shoe drive pitman shaft bearings (convert to re-lube bearings)
 R&R L.H. spreader wheel & weld cracks around hub
 R&R discharge beater wings & replace wear plates as needed, balance when done
 Install separator grate covers on L.H. side
 Set machine for wheat
 Run machine to check repairs & set speeds
 R&R & Replace chaffor frame rear extension (tipped on corners & rubber curtain came loose) Replaced w/ '70 series style.
 Adjust bolts 7 chains

Part Number	Description	Quantity	Unit Price	Value	Tax/Inc
03M7190	10X20 CRG	5.00	0.80	[redacted]	N

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

Invoice Number: **200746**
 Invoice Date: 4/14/2010
 Location: 10
 Work Order Number:
 Payment Type:
 Page: 2 of 4

Bus Phone:

Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 986D	1920	H09860S711100	8150C	

01-GEN-1 Retail

ENGINE HRS 1754

SEP. HRS 1101

Accepted into Work Order by SHELBY BARNETT

Time on 2-27 for building wiring harness for S.F. Receiver

REPLACE "ENTIRE" CLEAN GRAIN SYSTEM WITH '70 SERIES PARTS

R&R & Replace clean grain lower auger

R&R & Replace loading auger housing

R&R & Replace loading auger spout

R&R Jackshaft drive pulley & main drive belt for clean grain
(replace with '70 series)

R&R & Replace clean grain elevator chain

Assemble new elevator, loading auger hsgs. etc.

Cut out section of side sheet that elevator boot mounts to
& cut out / enlarge hole for auger

Make, modify, & weld in flange for auger hole

Modify new boot mount & weld in place

Cut out auger cover supports & weld in new ones

R&R sieve & chaffer for access to other repairs (had a time
removing spreader wheels & also chaffer took longer
because of side hill cleaning kit)

Modify / Trim sieve frame, to clear auger cover supports

Install side sheet stiffener above lower auger LH bearing
(side sheet had a bow in it)

Extend slot in LH side sheet for larger auger

Extend cover (weld on strip) for longer slot

Fit auger for clearance

Had to raise LH bearing when tightening

Had to trim auger at RH opening to clear

Adjust loading auger to fit spout

Adjust loading auger latches

Rollers out

TOWN		STATE	ZIP CODE
COUNTY	PURCHASER ACCT.	PHONE NO.	
CUSTOMER'S NAME - Second Signer			
STREET OR RR			
TOWN	STATE	ZIP CODE	

COMPANY UNIT 06	DEALER ACCOUNT NO.
TRANSACTION TYPE Cash Sale	☐ SOC. SEC. ☐ IRS NO. ☐ EIN. NO.
PURCHASER SALES TAX EXEMPT NO.	
SELLER'S NAME & ADDRESS	DELIVERER'S NAME & ADDRESS
PURCHASER TYPE	MARKET USE 15 Row Crop/Small Grain

QTY	NEW	DEMO	RENTAL	USED	PRODUCT (Give Model, Size & Description)	Hours of Use	PRODUCT IDENTIFICATION NUMBER	DELIVERED CASH PRICE (Or Total Lease Payments)
1	x				John Deere AUTO STEER			
1	x				LAKOTA LANEC100			
1	x				LAKOTA AR100			
1	x				LAKOTA LAN84151			
1	x				LAKOTA LANAP200			
1	x				LAKOTA LANB300			
1	x				LAKOTA LANEC 560			
1	x				HEADSIGHT Stock # A3670			
					HC3JD63-31Q-3			
1	x				HEADSIGHT Stock # A3668			
					HW3JD63-31Q-3			
1	x				HEADSIGHT Stock # A3669			
					HW3JD63-31Q-3T			
1. TOTAL CASH PRICE								\$ 13,707 00

Following is a description and the price to be allowed for each item.

QTY	DESCRIPTION OF TRADE-IN	PRODUCT IDENTIFICATION NUMBER	AMOUNT
COMMENTS:			
2. TOTAL TRADE-IN ALLOWANCE			
1. TOTAL CASH-PRICE			
2. TOTAL TRADE-IN ALLOWANCE			
3. TOTAL TRADE-IN PAY-OFF			
4. BALANCE			
8. SUB-TOTAL			
9. CASH WITH ORDER			
10. RENTAL APPLIED			
11. BALANCE DUE			\$ 13,707 00

REMIT TO:

Invoice To Account No.: 15322

Deliver To:

SERVICE INVOICE

Invoice Number:	269614
Invoice Date:	
Branch:	10
Repair Order Number:	76124
Payment Type:	Finance

Make/Model:	JOHN DEERE 886D
Meter Reading:	2358
Serial Number:	H0886DS/11100
Equipment Number:	81500
Page:	3 of 6

/GEN-2 Retail

H212949	GROMMET	1.00		N
LA25258	RED BUTT	2.00		N
TY26D19	GREEN TOUCH	1.00		Y

Labor:	Parts:	Sublet: \$0.00	Misc:
--------	--------	----------------	-------

Technicians: T1012

/GEN-3 Retail

\$3,549.00

FEEDER HOUSE

R&R front drum & replace center wear ring (cut off old one, weld on new one)

R&R front pivot frame

Weld & reinforce top corners (cracked)

Weld cracks in side shields & top shield

Replace side seals

R&R pivot beam & clean out pin sockets & channels

R&R & Replace fore/aft frame bottom wear plate

R&R & Replace FH floor front plate & steel plate angle

Adjust fore/aft frame clear back & weld washers on bottom slots, straighten turn buckle front pin holes

Repair fore/aft frame bottom corners

Straighten & weld cracks

Modify fore/aft frame to accept larger hit cylinder

Cut hole in frame

Make & weld in drop plate

R&R & Replace pivot wear pads & weld on retainers for top pads, drill pads for wire retainer

Part Number	Description	Quantity	Unit Price	Price	Tax	Line
19M7785	10X25FLG BOLT	3.00				N
19M8319	SCREW	2.00				N
24H1106	WASHER	2.00				N
24M7103	WASHER	4.00				N