INVOICE NO	
REMIT TO: Des Moines	1

BILL TO

OWNER

PAGE 1 OF 4

*** CASH ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
28-OCT-2015		04-APR-2000	QSK19-C525		KOMATSU
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
		16-SEP-2015	37191914	CPL222500	WA600
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
			/ 2453		WA600

		The second second	pale (() p 2 p l (Second e Se l) p r) become	THE RESERVE AND RESERVED AS A SECOND OF THE PARTY OF THE		
QUANTITY			DESCRIPTION	PRODUCT	UNIT PRICE	AMOUNT

OSN/MSN/VIN

COMPLAINT

CAUSE

INSTALL RECON ENGINE. ENGINE IS MADE TO ORDER. ETA 12 WEEKS.

RECON ENGINE

EDS NOT REQUIRED

CORRECTION

MOVE LOADER INTO SHOP, POSITION RECON ENGINE INTO BAY, CLEAN PARTS. SWAP FLYWHEEL NEW FLYWHEEL IS NOT CORRECT FOR THIS APPLICATION. SWAP FRONT PULLEYS. SWAP WATER INLET TUBES. REINSTALL FAN HUB STUDS, SWAP FRONT PULLEYS, INSTALL BELT TENSIONER, INSTALL REAR BRACKET ASSEMBLY. REMOVE FUEL PUMP, WRONG SPEC. INSTALL STARTER SPACER. TIME ENGINE TO PULL ACCESSORY DRIVE, WRONG SPEC. CLEAN RADIATOR, CLEAN BETWEEN COUNTERWEIGHT, FUEL TANK, AND FROM BOTTOM RADIATOR ENGINE COMPARTMENT, CLEAN TORQUE CONVERTOR. INSTALL FAN HUB BELT. INSTALL FRONT MOTOR MOUNT. INSTALL ENGINE IN LOADER, INSTALL TORQUE CONVERTOR TO ENGINE. INSTALL REST OF THE MOTOR MOUNT BOLTS. INSTALL HYDRAULIC LINE PLATES TO BELL HOUSING. INSTALL ACCESSORY DRIVE, A/C COMP LOCKED UP, HAD NO BELT WHEN LOADER SHOWED UP. NO FREON IN SYSTEM, PULL LINES TO REPOSITION BROKEN FITTING ON A/C COMPRESSOR. FINISHED HOOKING UP AIR COMP. HOOKED UP EXHAUST SIDE OF ENGINE. INSTALL AIR COMPRESSOR LINES, FUEL LINES, WIRE HARNESS, COOLANT LINES, AND STARTER. INSTALL FAN GUARD

FILL OIL AND ANTIFREEZE, INSTALL AIR FILTER. INSTALL MUFFLER ASSEMBLY. HOOK UP TOP COOLANT HOSES. CHANGE OUT COOLANT OUTLET CONNECTIONS WRONG SIZE. STEAM CLEAN ENGINE PANELS. INSTALL TOP ENGINE PANEL. INSTALL AIR INTAKE BOX. INSTALL HYDRAULIC PLATES ENGINE TORQUE CONVERTER. REPAIR AIR CLEANER RESTRICTION LINE. BATTERIES WILL NOT TAKE CHARGE. PULL LEFT BATTERY, CLEAN OUT BATTERY BOX, FILLED WITH DIRT HALF WAY UP BATTERY. INSTALL NEW BATTERIES. NEW HOLD DOWN BRACKETS. REPLACE CABLE ENDS. FILL TRANSMISSION FLUID. FILL HYDRAULIC OIL. START AND RUN ENGINE. NO DASH GAUGES. HOOK UP INSITE MONITOR ENGINE TEMP AND PRESSURES. AIR COMPRESSOR DISCHARGE LINE LEAKING AIR. ALTERNATOR NOT CHARGING. GOT UP TO 140 F ENGINE TEMP, HOOK UP SENSOR WIRE TO ALTERNATOR CHARGE AT 27.5

UTHORIZED BY (print name)	SIGNATURE	DATE

INVOICE NO	
REMIT TO Des Moines, sales	

BILL TO


Billing Inquiries:

OWNER

PAGE 2 OF 4

					EQUIPM	ENT MAKE
				PUMP NO.	K	OMATSU
		···· service	ENGINE MODEL			ENT MODEL
	CUSTOMER ORDER NO.	DATE IN SERVICE	QSK19-C525	CPL NO.	EGUIP	WA600
DATE	COSTONER	04-APR-2000	ENGINE SERIAL NO.	CPL222500		
28-OCT-2015		FAIL DATE	37191914	PUMP CODE	UN	WA600
CUSTOMER NO.	SHIP VIA	16-SEP-2015	MILEAGEHOURS	PUMP COST		WABOC
		PARTS DISP.	/ 2453			AMOUNT
REF. NO.	SALESPERSON				UNIT PRICE	2110011
KET. HO.	2.5		PRODUCT			
	QUANTITY PART	DESCRIPTION	CODE			
ORDERED ORDERED	NATIONAL PROPERTY.					
ORDE		ASH GAUGES. INSTALL A\C D E UP NEW FITTING HOOK UP	EVER ALC COMP. CUT OF	FBAD		
OSN/MSN/VIN		ASH GAUGES. INSTALL A\C D E UP NEW FITTING HOOK UP SIDE. TROUBLE SHOOT FOR	AIR SENSOR LINE. INSTA	LL		
	VOLTS. STILL NO D	ASH GAUGES. INSTALL AIGUE E UP NEW FITTING HOOK UP SIDE. TROUBLE SHOOT FOR I SIDE. CHECK POWER WIRES. T ED. CHECK POWER WIRES. T	SAUGES NOT WORKING.	NO		
	AIC FITTINGS HT	SIDE. TROUBLE SHOUT OF	RACE UP TO DASH PANEL	RYER.		
	VALUE REAR AIR I	THE PROPERTY OF THE PROPERTY O	CH CH	ARUSE		
	DASH PANELS. GO	NES ON AIC COMPRESSION.	SESSOR WILL NOT KEEP	UP.		
	VALVE. INSTALL CO	OCE I FAKING ON AIR COMP	(ESSOCIA)			
	A/C SYSTEM. AIR REPLACED HOSE.	STEAM CLEAN.				
	CUSTOMER BILLAB	LE.				
COVERAGE						
REMARK	10/28 800 DAVE	COMPLETED, INVOICED PDATE ON REPAIR PK	WELESS 10/1 400 DAVE			
100			OGNESO. ISI			
	TIPE PEPAIR NOT	PART OF QUOTED AMOUNT. OVED HAVING TIRE COMPANY OF TIRE JOSH, BILL APPROV	DRIVE TO OUR LOT AND)		
	9.14-15 BILL APPRO	VED HAVING TIRE COMPANY	/FD ON 5-26 A	π.		
			F ARRIVES.			
	8:45AM JOSH. I WIL	LUPDAIL				
	1 DR1679RX	ENG QSK 19 T1 C 490@20	Serial#: 60606020			
1	1 DRIB/BIO		CLEAN			
	1 DR1517D	ENG, QSK19				
1 ,		ENG QSK 19 C HPI	DIRTY			
-1	-1 DR1517D	ENG GOIL IS S	Serial#: 37191914			
		SPRAY CLEANER	OTHER			
1	1 84316-02	GASKET, WTR TRF CONNE	CTION CECO			
1	1 205289		CECO			
	1 3031007	GASKET, STARTER	CECO			
1		GASKET, FLYWHEEL HOU	SING CECO			
1	1 207376	GAGRET, ETT.	,			

	•	
AUTHORIZED BY (print name)	SIGNATURE	DÂTE



BILL TO

OWNER

PAGE 3 OF 4

EQUIPMENT MAKE

			ENGINE MODEL	PUMP NO.	KOMATSU
DATE 28-OCT-2015	CUSTOMER ORDER NO.	04-APR-2000 FAIL DATE	QSK19-C525 ENGINE SERIAL NO.	ерь но. СРL222500	EQUIPMENT MODEL WA600
CUSTOMER NO.	SHIP VIA	16-SEP-2015	37191914	PUMP CODE	UNIT NO. WA600
FEF. NO.	ENTECHEON	PARTE DISP.	/ 2453	STATE OF THE PARTY	UNIT PRICE AMOUNT
OUANTITY BACK ORDERED ORDERED	OUANTITY PART SHIPPED NUMBER	DESCRIPTION	PRODUCT CODE		
OSN/MSN/VIN 1 1 1 3 20 1 1 1	1 84316-02 1 3824510 1 236577 3 CC36077 20 VV705290 1 DCA65-L 1 205288 1 205288	TOTAL SURCE LABOR TOTAL MISC.: MISC. TOTAL	COVERAGE CREDIT: PARTS: HARGE TOTAL: COVERAGE CREDIT: LABOR: COVERAGE CREDIT: MISC.: SUPPLIES	LOC	48,134.62 48,134.62 12,540.00

AUTHORIZED		

-	-				_
- 81	rei	м.	•	 IR	=



BILL TO

OWNER

PAGE 4 OF 4

			ENGINE MODEL	PUMP NO.	EQUIPMENT MACE
DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	QSK19-C525		KOMATSU EQUIPMENT MODEL
28-OCT-2015		04-APR-2000	ENGINE SERIAL NO.	CPL222500	WA600
CUSTOMER NO.	SHIP VIA	16-SEP-2015	37191914	PUMP CODE	UNIT NO.
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGEHOURS / 2453	702.	WA600
REF. NO.	CHAN				UNIT PRICE AMOUNT
QUANTITY BACK	QUANTITY PART D SHIPPED NUMBER	DESCRIPTION	PRODUCT		

OSN/MSN/VIN

SUB TOTAL: TOTAL TAX:

TOTAL AMOUNT: US \$

AUTHORIZED BY (print name)

E

SIGNATURE

DATE