Invoice





INVOICE#	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
12866	04/20/2021	\$0.00	05/20/2021	Net 30	

YEAR/MAKE/MODEL

2006 Ford F550

VIN#/MILAGE

1FDAF56P47EA56133/ 140,596

PLAT/ UNIT/ PO

G27494

ACTIVITY	QTY	RATE	AMOUNT
Customer was towed in due to lose of power and won't start			
Labor Cost of Labor to Diagnose and Replace Alternator			
Alternator & Starter Alternator	W 4		
Materials Shop Supplies	1		
Card Fee	1		

Signature

ALL SALES ARE FINAL.

SUBTOTAL

TAX

TOTAL

PAYMENT

BALANCE DUE

\$0.00

Invoice for RO :

Service Advisor:

Date Created: 08/24/21 at 08:11 AM CDT

Vehicle: 2007 Ford F-550 Super Duty Lariat

2007 Ford F-550 Super Duty Lariat 6.0L 8Cyl

DIESEL Turbocharged VIN: 1FDAF56P47EA56133

License: 627 494 Color: White

Odometer In: 142157 / Out: 142157



Client concerns:

· Low power/ wrench light

1 - Inspectio Note: To see t	on the detailed break down of each repair, click on the down arrow at the top right hand corner.		TECH: NY
Labor:	Vehicle Inspection		
✓ Authorize	ed on 08/24/21 at 01:20 PM CDT	0	0

r/ wrench light	TECH: N
Hook up scan tool, troubleshoot low engine power. We found the turbo charger vanes are stuck in one postion and the engine is running too warm from a failed fan clutch. James spoke with Kerry about needed repairs, install a Ford replacement turbo. Turbo is backed by a 1 year parts and labor warranty. Replace fan clutch. Test drive after repairs - OK.	
Replace radiator cap to handle engine coolant leak.	
fan clutch 6.0 radiator cap Turbo parts prep and cleaner	1 1 1
	Hook up scan tool, troubleshoot low engine power. We found the turbo charger vanes are stuck in one postion and the engine is running too warm from a failed fan clutch. James spoke with Kerry about needed repairs, install a Ford replacement turbo. Turbo is backed by a 1 year parts and labor warranty. Replace fan clutch. Test drive after repairs - OK. Replace radiator cap to handle engine coolant leak. fan clutch 6.0 radiator cap Turbo

3 - Clutch Hy	draulics		TECH: NY
Labor:	Clutch pedal feel is not as smooth as it should be. Replace the clutch hydraulics and test operation - OK.		1
Part:	Clutch Hydraulics	1	i
✓ Authorized	d on 08/25/21 at 02:53 PM CDT		

Total Repair Order & Signature:

Total Labor: Total Parts: Total Fees:

Subtotal:

Taxes:

Grand Total:

BALANCE DUE:

\$3,060.07

Authorized by

Where Service is everything

Customer Information			Invoice	Addi	tional Information	n	
			Date: Reference: Salesperson: Route: Delivery Date		Com	Number: c Order#: ment: ment: red By:	
Vehicle: 06 Ford F-550 Desc: 06 Ford F-550		Li	Lic No: 627494 Unit: VIN: 1FDAF56P47EA56133		Mileage IN:136133 Mileage OUT: 136133 *OE I		
Qty	Descript	ion			FET	Unit Price	Ext. Price
2.00	BFG RCS	22570195					
4.00	BFG RCD	22570195					
. 6.00	Dismount	mount 19.5					
6.00	61606, 10	Oz Balancin	g Beads, Wheel Wei	ghts			
		Tax	able			Subtotal:	
				KS Sale	s Tax -		
					5	Shop Supplies:	
	Tern		Terms: Net 25th			Total:	\$2,129.30
						-t D-l	
					Inv	oice Balance:	
			Due Amount	Amt Remain	Inv	oice Balance:	