

Ship To:

Invoice To:

REPRINT

Date	Time	Page
05/27/21	22:30:15 (B)	01
Account No	Phone No	Inv No
Ship Via	Purchase Order	
Tax ID No		
		Salesperson
		GAF

SERVICE INVOICE

STK#/FLEET# HRS PIN/BIN WARRANTY DATE HRS
 C0018254 COMBINE 4764 76051
 17141 R72

SEGMENT# 1 C 313 NA 02/20/21 02/20/21 02/28/21

PM360 INSPECTION

COMPLAINT:

COMBINE BROUGHT IN FOR PM360 PREVENTATIVE MAINTENANCE
 INSPECTION.

CAUSE:

PREVENTATIVE MAINTENANCE.

CORRECTION:

PERFORM PM360 PREVENTATIVE MAINTENANCE INSPECTION.

10360001

LABOR

SEGMENT TOTAL==>

840.00

SEGMENT# 2 C 313 NA 02/20/21 02/24/21 02/28/21

BATTERIES

COMPLAINT:

DURING INSEPCTION WE FOUND BATTERIES FLAT AND CABLES IN
 POOR CONDITION.

CAUSE:

BATTERIES FAULTY. BATTERY CABLES IN POOR CONDITION.

CORRECTION:

CUSTOMER BROUGHT IN NEW BATTERIES. INSTALL BATTERY. REPAIR
 AND MAKE NEW BATTERY CABLES AS NEEDED. INSTALL BATTERY
 SHUTOFF SWITCH. TEST OPERATION.

FRT

FREIGHT

1

200107-050

CABLE/2/0G

RETAIL

5

CABLE/2/0GA. BLACK BATT

3046204

PULLEY

1 M

402294X1

CABLE TIE-

RETAIL

CONTINUED ON PAGE 02

X

Customer Signature

Invoice To:

Date	05/27/21	Time	22:30:15 (B)	Page	02
Account No		Phone No		Inv No	
Shi					
Tax ID No					
				Salesperson	GAF

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				

565872	CABLE TIE-390MM X 7.6MM	12
710605	BATTERY CABLE	1 N
728040	3/4" HEAT SHRIN	4
	BATTERY LUG	4

10360001

SEGMENT TOTAL==>

967.27

SEGMENT# 3 C 313 NA 02/20/21 04/08/21 02/28/21

FINAL DRIVE

COMPLAINT:

DURING INSPECTION WE FOUND RH FINAL DRIVE TO BE LOOSE.

CAUSE:

FINAL DRIVE BEARINGS WORE.

CORRECTION:

REMOVE RH FINAL DRIVE FROM COMBINE. DISASSEMBLE FINAL DRIVE.

CLEAN AND INSPECT PARTS. REASSEMBLE FINAL DRIVE USING ALL

NEW BEARINGS, RACES, SEAL, GASKETS, AND HARDWARE AS NEEDED.

REINSTALL FINAL DRIVE. FILL FINAL DRIVE WITH NEW OIL.

REISNTALL WHEEL TEST OPERATION.

ACP0039340

COMPOUND-G

RETAIL

1

COMPOUND-GASKETING, 50 M

WR129814

HEX HEAD BOLT-3

RETAIL

8 N

3012025X1

HEX HEAD B

RETAIL

3

HEX HEAD BOLT-M16 X 40 C

42599PF

NUT

RETAIL

CONTINUED ON PAGE 03

Ship To:

Invoice To:

Branch

HAYS

Date

05/27/21

Time

22:30:15 (B)

Page

03

Account No

Phone No

Inv No

Ship Via

Purchase Order

Tax ID No

Salesperson

SERVICE INVOICE

STK#/FLEET#

C0018254

COMBINE

17141

R72

HRS PIN/EIN

4764 76051

WARRANTY DATE

HRS

2

NUT

700717365

LIP SEAL-X

RETAIL

1

LIP SEAL-X 47,625 X 69,9

70210011

BEARING CO

RETAIL

1

BEARING CONE

70210012

BEARING CU

RETAIL

1

BEARING CUP

70923816

O-RING-X 3

RETAIL

1

O-RING-X 3,53 X 82,14 MM

70930883

BEARING CU

RETAIL

1

BEARING CUP

70930884

BEARING CO

RETAIL

1

BEARING CONE

70934704

FLAT WASHE

RETAIL

8 N

FLAT WASHER-0.81" X 1.47

71162781

BEARING CO

RETAIL

1

BEARING CONE

71162782

BEARING CU

RETAIL

1

BEARING CUP

71166170

SHIM-0.005

RETAIL

CONTINUED ON PAGE 04

Customer Signature

Thank You For Your Business!

Ship To:

Invoice To:

Branch HAYS		
Date 05/27/21	Time 22:30:15 (B)	Page 04
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				
	SHIM-0.005"				1
71304266	SPACER				RETAIL
					1 N
71304271	BEARING CA				RETAIL
					1
	BEARING CAP				
71314481	BEARING CO				RETAIL
					1
	BEARING CONE				
71391572	PLATE				RETAIL
					1
	PLATE				
7713860	BEARING CO				RETAIL
					1
	BEARING CONE				
7744477	DOUBLE LIP				RETAIL
					1
	DOUBLE LIP SEAL-X 158,75				
79023090	CLEANER/BR				RETAIL
					2
	CLEANER/BRAKE VOC				
80W90	GEAR OIL				8
					PARTS
					LABOR
10360001					SEGMENT TOTAL==>
					2594.27

SEGMENT# 4 C 313 NA
FEEDER HOUSE COUNTERSHAFT
COMPLAINT:

02/20/21 03/25/21 02/28/21

CONTINUED ON PAGE 05

I hereby authorize the repair work to be done as described on machine(s) named hereon. All

X

Ship To:

Invoice To:

Branch HAYS		
Date 05/27/21	Time 22:30:15 (B)	Page 05
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
 C0018254 COMBINE 4764 76051
 17141 R72

DURING INSPECTION WE FOUND FEEDER HOUSE COUNTERSHAFT BEARINGS LOOSE.

CAUSE:

BEARINGS LOOSE AND NOISY.

CORRECTION:

REMOVE FEEDER HOUSE COUNTERSHAFT FROM COMBINE. RH SHEAVE HAD TO BE CUT OFF. CLEAN AND INSPECT PARTS. REINSTALL COUNTER SHAFT USING NEW BEARINGS, FLANGES, AND NEW RH PULLEY. TEST OPERATION.

70905126	WOODRUFF KEY	RETAIL
		1
70923326	SETSCREW-3	RETAIL
		2
	SETSCREW-3/8"-16 X 1"	
71192243	BEARING FL	RETAIL
		4
	BEARING FLANGE-72MM	
71309128	BEARING-1-	RETAIL
		3
	BEARING-1-3/8" ID X 2-27	
71364661	PULLEY	RETAIL
		1
	PULLEY	
71386854	BEARING SP	RETAIL
		1
	BEARING SPACER-1.750" X	

10360001

PARTS
 LABOR
 SEGMENT TOTAL==> 1045.10

CONTINUED ON PAGE 06

X

Customer Signature

Ship To:

Invoice To:

Branch		
Date	Time	Page
05/27/21	22:30:15 (B)	06
Account No	Phone No	
Ship Via	Purchase Order	
Tax ID No		
		Salesperson

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254 COMBINE	4764	76051		
17141 R72				
SEGMENT# 5 C 313 NA	02/20/21	03/25/21	02/28/21	
FEEDER HOUSE FLOOR				
<u>COMPLAINT:</u>				
DURING INSPECTION WE FOUND REAR SECTION OF FEEDER HOUSE FLOOR TO BE WORN THROUGH.				
<u>CAUSE:</u>				
FEEDER HOUSE FLOOR WORN THROUGH.				
<u>CORRECTION:</u>				
REMOVE FEEDER HOUSE FROM COMBINE. REMOVE FEEDER CHAIN AND OTHER COMPONENTS AS NEEDED. CUT OUT REAR SECTION OF FLOOR. WELD IN REPLACEMENT REAR FEED FLOOR. REASSEMBLE FEEDER HOUSE. REISNTALL FEEDER HOUE ON COMBINE. TEST OPERATION.				
ACW3030000	COMPRESS. SPRIN	RETAIL		
		2		
ACW3611490	SPACER-100MM	RETAIL		
		2		
ACW3617360	INDICATOR	RETAIL		
		2		
FRT	FREIGHT	1		
360256X1	NYLON LOCK	RETAIL		
		2		
	NYLON LOCKNUT-1/4"-20, G			
63834	ROLL PIN-1	RETAIL		
		2 S		
	ROLL PIN-1/4" X 2-1/4"			
700711165	WASHER/HAR	RETAIL		
		2		
71397143	FLOOR	RETAIL		
		1		
FLOOR				

CONTINUED ON PAGE 07

Customer Signature

Invoice To:

Branch [REDACTED]		
Date 05/27/21	Time 22:30:15 (B)	Page 07
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship via [REDACTED]	Purchase Order	
Tax ID No	[REDACTED]	
[REDACTED]		Salesperson [REDACTED]

STK#/FLEET#

C0018254	COMBINE
17141	R72

HRS	PIN/EIN
4764	76051

WARRANTY DATE

HRS

71470456

RETAINER

RETAIL

71486519

PIVOT SEAL

RETAIL.

71486843

COUPLING LINK

RETAIL

10360001

PARTS
LABOR
SEGMENT TOTAL==>

2781.84

SEGMENT# 6 C 313 NA

02/20/21 03/25/21 02/28/21

PIVOT JACKSHAFT

COMPLAINT:

DURING INSPECTION WE FOUND PIVOT JACKSHAFT BEARINGS LOOSE.
CAUSE:

CAUSE:

BEARINGS ROUGH AND NOISY.

CORRECTION:

REMOVE PIVOT JACKSHAFT FROM COMBINE. DISASSEMBLE SHAFT AND INSPECT PARTS. REASSEMBLE JACKSHAFT USING NEW BEARINGS AND SEALS. INSTALL NEW JACKSHAFT DRIVE SHEAVE. REINSTALL JACKSHAFT IN COMBINE. TEST OPERATION.

SUBLETL

MACHINE SHEAVE

1

70539158

BEARING

RETAIL

BEARING

1

70923577

O-RING-1/8

RETAIL

O-RING-1/8" X 1-3/4" ID

2

70923598

O-RING-2,9

RETAIL

2

CONTINUED ON PAGE 08

X

Ship To:

Invoice To:

Branch

Date

05/27/21

Time

22:30:15 (B)

Page

08

Account No

Phone No

Inv No

Sh

Tax ID No

Salesperson

SERVICE INVOICE

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				
	O-RING-2.975" X .210"				
70924772	O-RING-4.3			RETAIL	
				1	
	O-RING-4.350" ID X .210"				
70926645	BACK UP WA			RETAIL	
				1	
	BACK UP WASHER-3.018" ID				
70929244	BACKUP RIN			RETAIL	
				1	
	BACKUP RING-4.403" OD				
71130258	BEARING FL			RETAIL	
				2	
	BEARING FLANGE-1-3/4" ID				
71162084	BUSH			RETAIL	
				3	
	BUSH				
71186659	PIN			RETAIL	
				3	
	PIN				
71318051	WIRE HARNE			RETAIL	
				1	
	WIRE HARNESS				
71355232	BELT			RETAIL	
				1	
	BELT				
71363435	BALL BEARI			RETAIL	
				1	
	BALL BEARING				
71366049	SHEAVE-LH			RETAIL	
				1 N	

CONTINUED ON PAGE 09

X

Customer Signature

Ship To:

Invoice To:

Branch

Date

05/27/21

Time

22:30:15 (B)

Page

09

Account No

Phone No

Inv No

Ship via

Purchase Order

Tax ID No

Salesperson

SERVICE INVOICE

STK#/FLEET#

C0018254

COMBINE

HRS

PIN/EIN

WARRANTY DATE

HRS

17141

R72

4764

76051

SHEAVE-LH

71435538

PLATE

RETAIL

1

PLATE

10360001

SUBLET

SEGMENT TOTAL==>

2001.00

SEGMENT# 7 C 806 NA

02/20/21 04/20/21 02/28/21

MAIN SHAFT

COMPLAINT:

DURING INSPECTION WE FOUND MAIN SHAFT BEARINGS DRY.

CAUSE:

BEARINGS DRY AND NOISY.

CORRECTION:

REMOVE MAIN SHEAVE AND VS ROTOR DRIVE SHEAVES. REMOVE MAIN
SHAFT FROM COMBINE. R&R MAIN SHAFT BEARINGS. REINSTALL MAIN
SHAFT. R&R MAIN SHEAVE BEARINGS. REINSTALL MAIN SHAVE WITH
NEW HEADER DRIVE SHEAVE. REINSTALL ROTOR DRIVE SHEAVES.
REISNTALL BELTS. TEST OPERATION.

ACW5240270

BEARING

RETAIL

1

17522

BALL BEARI

RETAIL

1

43361PF

BALL BEARING-50 ID X 90

SCREW

RETAIL

4

70923603

SCREW

O-RING-4.7

RETAIL

CONTINUED ON PAGE 10

X

Customer Signature

Ship To:

Invoice To:

Branch [REDACTED]		
Date 05/27/21	Time 22:30:15 (B)	Page 10
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson GAF

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				
				1	
70923827	O-RING-4.725" X .275"			RETAIL	
	O-RING			2	
	O-RING				
70923932	O-RING-5.4			RETAIL	
				1	
70923991	O-RING-5.484" X .139"			RETAIL	
	O-RING			2	
	O-RING				
70924146	O-RING-3.2			RETAIL	
				1	
70925284	O-RING-3.225" ID X .210"			RETAIL	
	HEX JAM NU			1	
	HEX JAM NUT-1-1/2"-12				
70929126	FLAT WASHE			RETAIL	
				1	
	FLAT WASHER-1-7/8"				
70930414	BACKUP RIN			RETAIL	
				1	
	BACKUP RING-3.273" OD				
70933746	BACKUP RIN			RETAIL	
				1	
	BACKUP RING-4.801 OD				
71335182	BALL BEARI			RETAIL	
				1	
	BALL BEARING				
71335195	MAGNET			RETAIL	

CONTINUED ON PAGE 11

X

Customer Signature

Ship To:

Invoice To:

Branch		
Date	Time	Page
05/27/21	22:30:15 (B)	11
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				

71363434	MAGNET	PULLEY	RETAIL
			1
	PULLEY		
71365063		BEARING W/	RETAIL
			1
71370205		BEARING-65	RETAIL
			1
71412355		BEARING-65.00MM ID X 120	
		WIRE HARNE	RETAIL
			1
	WIRE HARNESS		

10360001

PARTS
LABOR
SEGMENT TOTAL==>

3266.39

SEGMENT# 8 C 313 NA 02/20/21 04/15/21 02/28/21

HVAC

COMPLAINT:

DURING INSEPCTION WE FOUND UPPER SEALS MISSING ON HVAC HOUSING.

CAUSE:

SEALS MISSING BETWEEN HVAC HOUSING AND CAB.

CORRECTION:

REMOVE AND DISASSEMBLE HVAC HOUSING. REPALCE ALL SEALS AND FOAM. CLEAN EVAPERATOR AND HEATER CORE. REASSEMBLE HVAC HOUSING. TEST OPERAITON.

FRT
45444PF

FREIGHT
SELF TAP S

1
RETAIL

CONTINUED ON PAGE 12

X

Ship To:

Invoice To:

Branch [REDACTED]		
Date 05/27/21	Time 22:30:15 (B)	Page 12
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Tax ID No [REDACTED]		Salesperson [REDACTED]

SERVICE INVOICE

STK#/FLEET#

C0018254 COMBINE
17141 R72HRS PIN/EIN
4764 76051

WARRANTY DATE

HRS

		10	
70937424	SELF TAP SCREWS-COMBOPH		
	SPRING NUT	RETAIL	
		7	
	SPRING NUT-#10-24		
71362389	CAB FILTER	RETAIL	
		2	
	CAB FILTER		
71371331	FOAM TAPE-	RETAIL	
		1	
	FOAM TAPE-1/4" X 1-1/2"		
71371333	FOAM TAPE-1/8"	RETAIL	
		1	
71371334	FOAM	RETAIL	
		1	
71371339	SEAL/DRAIN	RETAIL	
		2	
71371341	GASKET	RETAIL	
		1	
71371342	FOAM	RETAIL	
		1	
71371343	SEAL	RETAIL	
		1	
71371344	SEAL	RETAIL	
		1 N	
71373146	SCREW-#10-	RETAIL	
		10	
	SCREW-#10-24		
71397926	DRAIN PAN	RETAIL	
		1 M	

CONTINUED ON PAGE 13

X

Customer Signature

Ship To:

Invoice To:

Branch [REDACTED]		
Date 05/27/21	Time 22:30:15 (B)	Page 13
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via		Purchase Order
Tax ID No		
		Salesperson [REDACTED]

SERVICE INVOICE

STK#/FLEET#

C0018254 COMBINE

17141 R72

71397934

HRS PIN/BIN
4764 76051

WARRANTY DATE

HRS

FOAM TAPE-

RETAIL

1

FOAM TAPE-1/4" X 1/2" X

79023090

CLEANER/BR

RETAIL

2

CLEANER/BRAKE VOC

PARTS

LABOR

10360001

SEGMENT TOTAL==>

964.57

SEGMENT# 9 C 802 NA

02/20/21 04/16/21 02/28/21

SPREADER BEARINGS

COMPLAINT:

DURING INSPECTION WE FOUND SPREADER GEARS WORN.

CAUSE:

GEARS WORN AND BEARINGS LOOSE.

CORRECTION:

REMOVE SPREADER GEARBOX FROM COMBINE. DISASSEMBLE GEARBOX.

REASSEMBLE GEARBOX USING NEW GEARS, BEARINGS AND RACES.

REINSTALL SPREADER IN COMBINE. TEST OPERATION.

G52MSA

BEARING FLANGE

2 N

SA205-16G

1" FLANGE KIT

2 N

363905X1

CARRIAGE B

RETAIL

4

CARRIAGE BOLT-3/8-16X1.2

70905126

WOODRUFF KEY

RETAIL

2

71133361

BEARING FL

RETAIL

4

BEARING FLANGE-2"

CONTINUED ON PAGE 14

X

Customer Signature

Ship To:

Invoice To:

Branch		
Date	Time	Page
05/27/21	22:30:15 (B)	14
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				
71194366	SENSOR COL				
					1
	SENSOR COLLAR				
71308962	BEARING KI				
					2
	BEARING KIT-1" ID				
71355168	GEAR				
					1
	GEAR				
71355169	BEVEL GEAR				
					1
	BEVEL GEAR				
71355828	SHAFT				
					1
	SHAFT				
79016936	OIL/PANTHE				
					1
	OIL/PANTHER PENT.				
				PARTS	
				LABOR	
10360001				SEGMENT TOTAL==>	1242.12

SEGMENT#10 C 806 NA 02/20/21 05/14/21 02/28/21

ROTOR

COMPLAINT:

DURING INSPECTION WE FOUND MUTIPLE ROTOR BARS BENT OR BROKE.

CAUSE:

ROTOR BARS BENT AND BROKEN.

CORRECTION:

WITH ROTOR REMOVE FOR INSPECTION. R&R BROKEN AND BENT ROTOR

CONTINUED ON PAGE 15

X

Customer Signature

Ship To:

Invoice To:

Branch HAYS		
Date 05/27/21	Time 22:30:15 (B)	Page 15
Account No	Phone No	Inv No
Ship via		Purchase Order
Tax ID No		
		Salesperson GAF

SERVICE INVOICE

STK#/FLEET#

C0018254 COMBINE

HRS PIN/EIN

4764 76051

WARRANTY DATE

HRS

17141 R72

BARS USING NEW HARDWARE AS NEEDED. BALANCE ROTOR. REINSTALL
 ROTOR AND TEST OPERATION.

PFP BARS

CYL. BARS

4

PFPIHJD-L154-C LH CHROMED BAR AND FASTE

PFP SHIM

SHIM

2

SHIM- .024 CNR2 CYLINDER BAR SHIM .024

10360001

PARTS

LABOR

SEGMENT TOTAL==>

621.24

SEGMENT#11 C 313 NA

02/20/21 05/14/21 02/28/21

ENGINE BELTS PULLEY AND FAN BEARINGS

COMPLAINT:

DURING INSPECTION WE FOUND ENGINE FAN BEARINGS LOOSE AND
 PULLEYS AND BELTS WORN.

CAUSE:

ENGINE FAN HUB BEARINGS LOOSE AND PULLEYS AND BELTS WORN.

CORRECTION:

REMOVE ENGINE FAN AND HUB. INSTALL NEW FAN HUB ASSEMBLY.
 INSTALL NEW FAN PULLEY. R&R CRANKSHAFT PULLEY. NEW BEARINGS
 WERE INSTALLED IN ALTERNATOR. INSTALL NEW ALTERNATOR
 PULLEY. INSTALL NEW BELTS. TEST OPERATION.

A3288623

BELT/ARAMI

RETAIL

1

BELT/ARAMID

FRT

FREIGHT

2

SUBLETL

REPAIR ALTERNAT

1

3027675

SEAL, OIL

1

3028521V

BELT

RETAIL

1

CONTINUED ON PAGE 16

X

Customer Signature

Ship To:

Invoice To:

Branch

Date

05/27/21

Time

22:30:15 (B)

Page

16

Account No.

Phone No.

Fax No.

Ship Via

Purchase Order

Tax ID No

Salesperson

SERVICE INVOICE

STK#/FLEET#

C0018254

COMBINE

HRS

4764

PIN/EIN

76051

WARRANTY DATE

HRS

17141

R72

BELT

3046207

PULLEY, FAN

1

3063844

HUB COVER

1

3065358

FAN HUB

1 N

3819407

CRNKSHFT PULLEY

1 M

3883324

PULLEY

1 M

PULLEY, ACC. DRIVE

3896996

ROLLER BEARING

1 M

71539PF

SCREW-CAP

RETAIL

1

SCREW-CAP M-CL10.9

79014728

LITH GREASE

RETAIL

1

GREASE

PARTS

LABOR

SUBLET

10360001

SEGMENT TOTAL==>

2100.93

SEGMENT#12 C 313 NA

02/20/21 05/19/21 02/28/21

ENGINE OIL LEAK

COMPLAINT:

DURING INSPECTION WE FOUND ENGINE OIL LEAK ON ENGINE.

CAUSE:

OIL PAN BOLTS LOOSE.

CORRECTION:

TIGHTEN ALL ENGINE OIL PAN BOLTS. WASH AND RUN MACHINE. NO FURTHER LEAKS WERE FOUND.

10360001

LABOR

SEGMENT TOTAL==>

CONTINUED ON PAGE 17

X

Customer Signature

Ship To:

Invoice To:

Branch HAYS		
Date 05/27/21	Time 22:30:15 (B)	Page 17
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

SERVICE INVOICE

STK#/FLEET#

C0018254 COMBINE

17141 R72

HRS PIN/EIN

4764 76051

WARRANTY DATE

HRS

SEGMENT#13 C 313 NA

02/20/21 05/25/21 02/28/21

ELEVATOR JACKSHAFT

COMPLAINT:

DURING INSPECTION WE FOUND ELEVATOR JACKSHAFT DRIVE BELT WORN.

CAUSE:

DRIVE BELT WORN AND CRACKED.

CORRECTION:

REMOVE ELEVATOR JACKSHAFT. INSTALL NEW ELEVATOR JACKSHAFT DRIVE BELT. REINSTALL JACKSHAFT TEST OPERATION.

71367469

BELT, RIGH

RETAIL

1

BELT, RIGHT HAND

PARTS

LABOR

10360001

SEGMENT TOTAL==>

220.87

SEGMENT#14 C 313 NA

02/20/21 05/27/21 02/28/21

FEED CHAIN DRIVE BELTS

COMPLAINT:

DURING INSPECTION WE FOUND FRONT AND REAR FEED CHAIN DRIVE BELTS WORN AND STRETCHED.

CAUSE:

FRONT FEED CHAIN DRIVE BELT STRETCHED. REAR FEED CHAIN DRIVE BELT CRACKED AND WORN.

CORRECTION:

R&R BOTH FRONT AND REAR FEED CHAIN DRIVE BETLS.

71335475

DRIVE BELT

RETAIL

1

CONTINUED ON PAGE 18

X

Customer Signature

Ship To:

Invoice To:

Branch [REDACTED]		
Date 05/27/21	Time 22:30:15 (B)	Page 18
Account No [REDACTED]	Phone No [REDACTED]	Inv No [REDACTED]
Ship Via [REDACTED]		Purchase Order [REDACTED]
Tax ID No [REDACTED]		Salesperson [REDACTED]

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C0018254	COMBINE	4764	76051		
17141	R72				
	DRIVE BELT				
71374306		BELT		RETAIL	
				1	
	BELT				
				PARTS	
				LABOR	
10360001				SEGMENT TOTAL==>	320.54

D0447483 C0044876

***** WORK ORDER TOTALS *****

PARTS	[REDACTED]
LABOR	
SUBLET	
SHOP SUPPLIES	
AGCO PLUS	19236.14

Store ID:
Client ID:
Request ID:

Ship To:

Invoice To:

Branch		
[REDACTED]		
Date	Time	Page
10/08/20	17:08:39 (O)	01
Account No	Phone No	Inv No
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
Tax ID No	[REDACTED]	
[REDACTED]		Salesperson
[REDACTED]		[REDACTED]

PARTS INVOICE

ORDER#: 020055

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTTT	Price	Amount
PFGLP3-R18	PRECISION ROTOR	E004371	1	1	1			[REDACTED]	
FRT	FREIGHT		1	1	1				
H852								A/R CHARGE	7178.39

