

DK8737

Date	Invoice #
3/8/2020	15341

Bill To

PAID
03/12/2020

P.O. Number	TERMS	MILEAGE	VIN#	TECH
KENWORTH	Due on receipt	213,985	615310	AARON S

Quantity	Item Code	Description	Price Each	Amount
	Complaint	Work to be done: TRANSMISSION GRINDING FROM HIGH TO LOW, REPLACE SHIFTER BOOT, REPLACE EXHAUST ELBOW*****THURSDAY*****		
1	RTX13609BWEL	REMAN TRANSMISSION		
1	Core Charge	Core Charge On Part		
-1	Core Charge	Core Charge On Part		
1	IN HOUSE SURF...	SURFACE FLYWHEEL		
1	K042-70-2	SHIFT BOOT		
1	FREIGHT IN	FREIGHT IN		
2	ABP/N35-50PLA	EXHAUST CLAMP		
1	ABP/N49-5FT12S	5" S.S. FLEX PIPE		
1	ABP/N25-63062RS	PILOT BEARING		
1	2264757	MAIN SEAL		
1	ABP/N25-208925...	NEW HD CLUTCH		
4	FUL/12815	BUSHING		
1	ABP/N25-105C137	CLUTCH FORK		
1	ABP/N25-127760	CLUTCH BRAKE		
1	ABP/N25-K210883	CROSS SHAFT		
1	ABP/N25-106C1498	CROSS SHAFT		
3.5	MT 50 Maxtron	50W Synthetic Tranny Lube per gallon		
1	SP-6.5-70-18X	STRAP KIT		
2	280X2	1/8 SPLIT SLEEVE		
2	281X2	1/8 NUT		
0.5	Blue Guard	Tube Grease		
3	26682	CABLE TIE		
2	26684	CABLE TIE		
14.2	Shop Supplies	Shop Supplies/ per labor hour		

THANK YOU, PLEASE PAY FROM INVOICE! NO STATEMENT WILL BE SENT.

Total

Phone #

E-mail

Web Site

Date	Invoice #
3/8/2020	15341

Bill To _____

PAID
03/12/2020

P.O. Number	TERMS	MILEAGE	VIN#	TECH
KENWORTH	Due on receipt	213,985	615310	AARON S

Quantity	Item Code	Description	Price Each	Amount
14.2	Mechanic Hours	Mechanic Hours to check out transmission grinding from high to low shift. Drain gear lube to find heavy metal in oil. Remove driveline, Air lines and tank, Shifter boot and stick assembly, Clutch linkage and transmission from unit. Remove all components from transmission to clean and install onto rebuilt transmission. Remove clutch assembly and flywheel to surface flywheel. Remove rear main seal on engine due to seal leaking and clean up surface to install new main seal. Install flywheel and pilot bearing and run engine to check seal for leaks. Install new clutch assembly, Replace exhaust pipe under cab and install clamps to tighten into place and run engine to check for leaks. Replace cross shafts and bushings in bellhousing with new clutch fork. Install transmission to hook up clutch linkage, Shifter assembly and install new boot. Hook up wiring and air lines, Install air tank and hook up lines. Install drivelines and grease U-joints. Fill transmission with gear lube and adjust up clutch and free travel on pedal. Test drive unit to confirm operation and repairs. Thanks! Sales Tax		

THANK YOU, PLEASE PAY FROM INVOICE! NO STATEMENT WILL BE SENT.

Total \$6,476.91

Phone #	E-mail	Web Site