Date	Invoice #
1/31/2020	15052

Bill To	202
	03/0

P.O. Number	TERMS	MILEAGE	VIN#	TECH
FREIGHTLINER	Due on receipt	535,084	6LW04899	JOSH S.

Quantity	Item Code	Description	Price Each	Amount
	Complaint	Work to be done: OIL LEAKS AND COOLANT LEAK, DRIVER		
		SIDE CUBBY DOOR HARD TO OPEN, WINDSHIELD WASHER		
		NOT WORKING:	ı	
1	ABP/N25-208925	NEW HD CLUTCH	7.75	
1	ABP/N25-6206ZZ	PILOT BEARING		
1	ABP/N25-106C1498	CROSS SHAFT	To the same of	
1	ABP/N25-K2468	CLUTCH INPUT KIT		
1	02-12467-007	CROSS SHAFT LONG KEYED	Control of	
24	DDE-A4579900501	HEAD BOLT		
4	DDE-A4570980180	SEAL	Control of the Contro	
1	DDE-A4579902001	SCREW		
4	DDE-A5419970545	SEAL ERIN	C. 1700	
1	DDE-A0169970646	SEAL RING		
1	DDE-A0259975047	OIL SEAL		
4	DDE-A0009902852	NUT		
4	DDE-A0009906005	STUD		
1	DDE-A5411870080	GASKET		
1	BCD-28945-1	ENGINE MOUNT		
2	BCD-27330-2	MOTOR MOUNT		
2	BCD-28805-1	ENGINE ISOLATOR		
1	DDE-RA4571306715	AIR COMPRESSOR		
1	Core Charge	Core Charge On Part		
-1	Core Charge	Core Charge On Part		
5	DDE-N000000001	SEAL O-RING		
1	DDE-A4600100655	OIL/AIR LINE		
16	DDE-N000000001	SEAL RING	and add	
1	05-22001-001	HOSE		
3	DDE-A4601420580	GASKET SEAL		
1	DDE-A4601420353	EGR FITTING		
1	05-19012-002	FAN SHROUD		
î l	A18-66804-000	DOOR SEAL BAGGAGE	11 11000	
il	DDE-A5410110180	GASKET		
		SEAL		
3	DDE-A4601422180	EXHAUST SEAL		

Total

Phone # E-mail Web Site

Date	Invoice #
1/31/2020	15052

Bill To

P.O. Number	TERMS	MILEAGE	VIN#	TECH	1
FREIGHTLINER	Due on receipt	535,084	6LW04899	JOSH S.	

Quantity	Item Code	Description	Price Each	Amount
2	DDE-A5419970545	SEAL ERIN		
1	DDE-A4570150180	GASKET		
1	DDE-A0000180780	GASKET		
3	DDE-N000000001	SEAL O-RING	-	
1	05-22002-001	LOWER HOSE		
1	DDE-A4602000058	BREATHER LINE		
14	DDE-N000000001	SEAL RING		
4	92500	3/4 BOLT GRADE 8		
	94414	3/4 CROWN NUT		
1.5	765-1189	GASKET SEALER		
1	DDE-A4571400269	WASTE GATE VALVE		
1	18-30769-002	SHIFTER BOOT		
6	DDE-RA4600101720			
6	Core Charge	Core Charge On Part		
-6	Core Charge	Core Charge On Part		
1	PSM-3500082	ENGINE HEATER		
1	DDE-A0000188535	OIL SEPARATOR		
1	23-13301-412	CONNECTOR	es, i	
1	DDE-A4570140222	OIL PAN GASKET		
1	DDE-A40000180980	SEAL RING		
i	DDD	BREATH TUBE		
6	DDL . C	SEAL RING		
1		FREIGHT IN		
3		1/2" CONVOLUTED LOOM (per foot)		
î l		SOLENOID		
	60257	METRIC BOLT	· -	
	67910	METRIC LOCK WASHER		
. 2		METRIC FLAT WASHER	en. ·	
	50903	#300 TORQUE CLAMP		
	NR93710	RING TERMINAL		
- 1	NC93056	RING TERMINAL		
- [				
2		SCREW		
11	DN/P550769	OIL FILTER		
'	Diet soores	VOICELNO STATEMENT WILL BE SENT		
THANK YOU, PL	EASE PAY FROM IN	VOICE! NO STATEMENT WILL BE SENT.		
		7		

Total

E-mail Web Site Phone #

Date	Invoice #
1/31/2020	15052

Bill To	2020
	03/0
1	

P.O. Number	TERMS	MILEAGE	VIN#	TECH
FREIGHTLINER	Due on receipt	535,084	6LW04899	JOSH S.

Quantity	Item Code	Description	Price Each	Amount
12	TMS 15W40 Bulk	15W40 Super lube Bulk-Oil per gallon		т
12	Final Charge	Red Coolant- Extended Life per gallon - bulk		г
1	DN/P550762	FUEL FILTER	1	r
1	ABP/N35-50PLA	EXHAUST CLAMP	1	Г
1	DDE/A4571421080	GASKET	1	rl
8	92200	7/16 BOLT GRADE 8	1	1
8	95353	LOCK WASHER	1	П
3	L1169X2	1/8X1/8P MALE ELBOW	1	1
1	L1168X2	1/8X1/8P MALE CONN	1	r
1	L1162X2	I/8" UNION	1	П
3	SP-6.5-70-18X	STRAP KIT	1	П
1	CHL/35-P-15-2	GASKET	1	П
1	DDE-A4600180716	TUBE GUIDE	1	П
6	DDE-A4600160720	HEAD GASKET	1	П
1	DDE-A4602030015	EGR PIPE	1	П
3	60198	METRIC BOLT	1	r
7	60199	METRIC BOLT	1	1
10	67008	METRIC FLAT WASHER	1	1
1 4	337552	SCREW	1	- 1
12	26681	CABLE TIE	1	
14		CABLE TIE	1	1
65.14999	Shop Supplies	Shop Supplies/ per labor hour		1
65.14999	Mechanic Hours	Mechanic Hours to check over truck for oil leaks and coolant leaks.		- 1
1		Drain engine oil and coolant to remove air intake pipes and charge air	r	ı I
1	1	pipes. Remove oil lines and coolant lines from air compressor,		l 1
1		Cylinder heads, Oil pan and remove all plastic covers to remove		
1		rocker covers and rocker arms to remove head bolts and cylinder		
1	1	heads from engine. Remove oil pan assembly from engine to support		
1	1	rear of engine. Remove wiring to remove starter assembly and remove	·	1
1	1	air compressor assembly from bellhousing to remove drivelines and		1
1	1	shifter assembly along with wiring air lines and tanks to remove		
	1	transmission from engine. Remove rear motor mounts to remove		
1		bellhousing from engine block to replace gaskets and seals. Clean up all components to reassemble bellhousing and install new rear main	'	
		all components to reassemble belinousing and install new rear main		
THANK YOU	PLEASE PAY FROM I	NVOICE! NO STATEMENT WILL BE SENT.		

Total

Phone #	E-mail	Web Site
		Page 3

Date	Invoice #
1/31/2020	15052

Bill To	2020
	03/0
-	

P.O. Number	TERMS	MILEAGE	VIN#	TECH
FREIGHTLINER	Due on receipt	535,084	6LW04899	JOSH S.

Quantity	Item Code	Description	Price Each	Amount
THANK YOU, PL	EASE PAY FROM IN	seal. Surface flywheel to install back onto motor and install new pilot bearing. Replace cross shafts on transmission bellhousing and install new input shaft kit with new bearing and cover to install new clutch brake and fork. Install new clutch assembly, Install new motor mounts and install transmission back into unit to book up shifter, Clutch linkage, Drivelines, Air tanks and lines and make adjustments to clutch and free travel on pedal. Install starter and hook up wiring, Install new air compressor and hook up coolant and air lines. Clean engine block to install new head gaskets and install cylinder heads to torque into place. Install injectors and rocker arms to bar over engine to make adjustment to valves and engine brakes. Install rocker covers, Exhaust manifold, Intake manifold and torque all bolts. Hook up coolant lines and fuel lines. Install all plastic covers and install oil pan with new gaskets. Replace oil filter and fill engine with oil. Replace fuel filter, Remove engine fan blade and radiator supports to remove broken fan shroud assembly and install new one to reassemble fan blade and support rods. Fill cooling system with flush and water to run engine to operating temperature and drain system to flush out debris. Flush with clean water and refill with new coolant to test drive unit and check for leaks to complete repairs on engine. Replace door seal on sleeper door and repair wiring to windshield washer pump to get system to work. Test drive unit to complete repairs and check for any leaks. Top off fluids. Thanks!  Sales Tax		

Total

\$17,361.44

Phone # E-mail Web Site

Date	Invoice #
8/25/2019	14183

Bill To	220
	09/4

P.O. Number	TERMS	MILEAGE	VIN#	TECH
COLUMBIA/TRAILER	Due on receipt	522,900	6LW04899	JASON E.

Quantity	Item Code	Description	Price Each	Amount
	Complaint	Work to be done: PM SERVICE, DOT BOTH, ADJUST UP		0.00
		BRAKES, OIL LEAK, ANTI-FREEZE LEAK, DRIVER SIDE SEAT	l I	
		BELT, CLUTCH ADJUSTMENT	Ι ΄	
_	DOT INSP	Federal Annual Inspection		
	Blue Guard	Tube Grease		
1	DN/P550769	OIL FILTER		
1	DN/P550762	FUEL FILTER		
1	DN/P527682	AIR FILTER		
1	ABP/N122-R50418	FUEL FILTER	l	
1	PA4857	HVAC FILTER	l	
1	wws	WASHER FLUID	l	
10	TMS 15W40 Bulk	15W40 Super lube Bulk-Oil per gallon		
1	RBR K080855HD	BELT		
1	IMM-F13158	SEAT BELT	545.00	
1	FLM-063361	WINDSHIELD WASHER CAP		
2	DDE-A4600160021	GASKET	1	
4	DDE-A4600160021	GASKET		
1	JOS/JSK37USL-A9	FIFTH WHEEL SLIDER ASSEMBLY		
2	JOS/JSK75008-24	FIFTH PLATE MOUNTING IRON	ĺ	
1	NFR/239139	RADIATOR		
2	03-27310-001	TANK FUEL STRAP	l	
3	03-33927-605	TANK ISOLATOR		
23	93342	5/8 FLANGE BOLT	l	
48	93368	5/8 FLANGE NUT		
2	93350	5/8 FLANGE BOLT	I	
24	93354	5/8 FRAME BOLT	l "	
1	VEL/022028	5TH WHEEL HOSE		
1	L1869X4X4	1/4X1/4 DOT PUSH-IN		
ī	03-27310-001	TANK FUEL STRAP		
1	80883	PAINT		
2	1469X4	1/4-1/8 MALE ELBOW	l	
1	3300X2	1/8 BUSHING		
il	L1880X10X6	DOT AIR FITTING	l	
2	L1862X6	3/8 DOT PUSH-IN UNION		

Total

Phone #	E-mail	Web Site

Date	Invoice #
8/25/2019	14183

Bill To	12 201
	Od.

P.O. Number	TERMS	MILEAGE	VIN#	TECH
COLUMBIA/TRAILER	Due on receipt	522,900	6LW04899	JASON E.

Quantity	Item Code		Description		Price Each	Amount
	L1862X4	1/4 DOT PUSH-IN	UNION			
2	26683	CABLE TIE				
2	50766	#425 TBOLT CLAN			L	
2	50903	#300 TORQUE CL				
	HANDLE	USED DOOR HAN			1	
1	STEEL	STEEL FOR REPA	IRS (FUEL TANK)		1	
1	OUTSIDE LABOR		TO MAKE REPAIRS (FUE	L TANK)	1	
1	92010	1/4 BOLT GRADE				
3	92008	1/4 BOLT GRADE				
2	92004	1/4 BOLT GRADE				
1	Final Charge	Red Coolant- Extend	ded Life per gallon - bulk			
1	A22-61340-001	A/C HOSE ASSEM	BLY			
í	23-13205-000	MINI A/C SEAL				
4	26683	CABLE TIE				
4	26682	CABLE TIE				
2	409500	OIL-A/C PER OUN	CE			
4	R134AJ	R134A PER POUN				
in the second second	100086	5TH WHEEL SLICE				
38.18334	Shop Supplies	Shop Supplies/ per la	abor hour		1	
THANK YOU, PI	LEASE PAY FROM IN	VOICE! NO STATEM	MENT WILL BE SENT.		Total	
Phone #	E-	mail	Web Site			

Date	Invoice #
8/25/2019	14183

Bill To	2201
	Odler
I	

P.O. Number	TERMS	MILEAGE	VIN#	TECH
COLUMBIA/TRAILER	Due on receipt	522,900	6LW04899	JASON E.

Quantity	Item Code	Description	Price Each	Amount
38.18334	Mechanic Hours	Mechanic Hours to check over tractor and trailer, Change engine of and filters, Fuel filters, Air filter, HVAC filter, Top off fluids, Check gear lubes, Hub oils, Lights, Tires and brakes. Grease chassis and drivelines, Grease s-cam bushings on trailer. Check out fifth wheel and found to be bad, Remove air line to remove slider from frame. Clean up frame rails to install new mounting irons and install new slider assembly to irons, Install slip disc to new fifth wheel plate. Install new air line to slider and confirm operation and no air leaks. Check out oil leak on engine, Remove air cleaner pipes to remove rocker covers and replace gaskets on covers to reassemble and run engine to check for leaks. Check out coolant leak and found radiate to be bad. Drain coolant and recover a/c system to remove condens and charge air cooler pipes to remove cooler assembly. Remove ho to remove radiator assembly and swap frame work over to new radiator. Install radiator assembly and charge air cooler to hook up hoses and pipes. Replace a/c line and install condenser with new se to vacuum down system to leak test. Charge system and fill cooling system to run engine to confirm operation of a/c system and check cooling system for leaks. Replace grab handle with used part. Pumfuel out of tank on driver side to remove lines and wiring to remove tank from unit to have tank repaired. Install tank back onto unit to hook up lines and wires to fill tank with fuel and tighten into place. Run unit to check for leaks. Check out air leaks on unit and remove lines to replace fittings and hook up lines to build air and check for leaks. Test drive unit to confirm all repairs. Thanks!  Sales Tax	ck  or cer ses all cals c	
THANK YOU, PL	EASE PAY FROM IN	VOICE! NO STATEMENT WILL BE SENT.	Total	\$8,548.72

Total

\$8,548.72

Phone # E-mail Web Site



Date	Invoice #
5/24/2019	13620

Bill To	201
	06/4

P.O. Number	TERMS	MILEAGE	VIN#	TECH
MARTIN SPRULING	Due on receipt	520,738	61.W04899	JOSH S.

Quantity	Item Code		Description		Price Each	Amount	
	Complaint	Work to be done: DOT	INSPECTION AND PM	SERVICE			
		(MARTIN SPRULING	TRUCK)				
1	DOT INSP	Federal Annual Inspect	tion	- 1			
2	MAE-65148	HD SHOCK		1			
4	MAE-65490	HD SHOCK		1			
4	FI-W01-377-8536	AIR SPRING		1			
2	DB154B	DRUM HD		- 1			
2	TDA/XKMG2L470	BRAKE SHOE KIT		- 1			
1	STM/359-5990	PLUG		- 1			
1	CHR/35066	SEAL		1			
1	CHR/1612	OIL HUB CAP		- 1			
0.5	10047	HUB OIL PER QUAR	T	- 1			
4	ABP/N35-50PLA	EXHAUST CLAMP		- 1			
1	ABP/N49-5FT18S	FLEX PIPE		- 1			
1	DN/P550769	OIL FILTER		1			
1	DN/P550762	FUEL FILTER		- 1			
1	DN/P527682	AIR FILTER		1			
ı	ABP/N122-R50418	FUEL FILTER		I			
10	TMS 15W40 Bulk	15W40 Super lube Bul	k-Oil per gallon	- 1			
4	TMS 15W40 Gal	Super lube TMS 15W4	0 - per gallon jug (carry o	ut by Shickley)			
1	Blue Guard	Tube Grease		, , .			
1	3152X2	1/8" PIPE PLUG		- 1			
2	90282	1/2 BOLT		- 1			
2	94408	1/2 CROWN NUT		1			
4	373904	1/4 FLAT WASHER					
1	1868X4X4	DOT PUSH-IN CONN		- 1			
1	1868X6	DOT PUSH-IN CONN	1	1			
2	L1868X8	1/2X3/8 DOT PUSH-II	N CONN	1			
2	3350X4	1/4-1/4 ST ELBOW					
	3350X6	3/8-3/8 ST ELBOW					
_	3152X4	1/4" PIPE PLUG					
	HDX/11902	HOSE FITTING		I			
2	FI-W02-358-7215	AIR SPRING					
5	MAE-66122	SHOCK		1			
•							

Total

Phone #	E-mail	Web Site
	- 16 to 1 Contlook com	Page 1

Date	Invoice #
5/24/2019	13620

		<b>₹ 3</b> 3 2
Ball To	15.	2019
	08/3	<b>1</b>
		l

P.O. Number	TERMS MILEAGE		VIN# TECH		
MARTIN SPRULING	Due on receipt	520,738	6L W04899	JOSH S.	

Quantity	Item Code	Description	Price Each	Amount
ı	BW-065706	TRACTOR PROTECTION VALVE		
1	04-21016-002	ENGINE PIPE		
1	705-1245	HOSE CLAMP	l	
2	CAS ZK7	BOLTS	l	
2	ABP/N35-50PLS	EXHAUST CLAMP	1	
2	L1871X6	DOT PUSH IN FITTING	1	
4	94314	1/2 NYLON NUT	1	
4	95016	1/2 FLAT WASHER		
4	94148	I/2 NUT		
	95309	1/2 LOCK WASHER		
1	L1869X4X4	1/4X1/4 DOT PUSH-IN	1	
1	1868X6	DOT PUSH-IN CONN	l	
1	L1869X6	3/8X1/4 DOT PUSH-IN	1	
	L1862X6	3/8 DOT PUSH-IN UNION	l	
	52000	GREASE FITTING	1	
8	93342	5/8 FLANGE BOLT	1	
8	93368	5/8 FLANGE NUT	l .	
4	24708N608	FEMALE SWIVEL	I	
	K06908	HOSE PER FOOT	1	
	3152X4	1/4" PIPE PLUG	l	
2.5	NT20004	TUBING PER FOOT	l	
1	ABP/N49-50EL901		l	
1	ABP/N49-50EL901		1	
3	ABP/N35-500UBFC		1	
1		FLEX PIPE	1	
	ABP/N49-5FT25S	FLEX EXHAUST PIPE PER FOOT	1	
	ABP/N35-50PLA	EXHAUST CLAMP	1	
	ABP/N35-50PLS	EXHAUST CLAMP		
	26682	CABLE TIE	l	
_	MT 50 Maxtron	50W Synthetic Tranny Lube per gallon	l	
1	BKS-KD2261	RIDE VALVE	l	
1	K180-14766	EXHAUST PIPE	l	
35.94999	Shop Supplies	Shop Supplies/ per labor hour	ı	

Total

Phone # E-mail Web Site
Page 2

Date	Invoice #	
5/24/2019	13620	

Bill To	201
	08/1
l	

Phone #

E-mail

P.O. Number	TERMS	MILEAGE	VIN#	TECH
MARTIN SPRULING	Due on receipt	520,738	6LW04899	JOSH S.

Quantity	Item Code	Description	Price Each	Amount
35.94999	Mechanic Hours	Mechanic Hours to check over tractor, Replace shocks on steering axle and drive axles, Support rear frame to remove air lines to air springs, Replace all air springs on drive axles to swap over air fitting and hook up lines to check for leaks. Back off brakes on steering axt to remove wheels and drums, Remove one wheel hub to replace leaking axle seal. Clean and inspect bearings to reassemble hub with new seal to torque bearings and fill hub with oil. Install new brakes and spring kits to install new drums, Install wheels and adjust up brakes. Drain gear lube and replace cover plate on transmission to fi with new gear lube. Remove all exhaust pipes and clamps from undicab to install new pipes and flex pipes to install clamps and tighten into place to run motor and check for leaks. Remove air lines to remove tractor protection valve and swap fittings to new valve to reassemble and hook up lines. Remove air lines from ride height val and change out valve assembly to hook up linkage and air lines to build air and check for leaks. Change engine oil and filters, Fuel filt Air filter, Check gear lubes, Hub oils, Lights, Tires and brakes. Gree chassis and drivelines. Check out oil leak on left side of motor to reseal and tighten plug on side of engine to stop oil leak. Test drive unit to confirm repairs. Thanks!  Sales Tax	ll er all	
		The second second	Total	\$7,050.83

Web Site