

INVOICE

INVOICE

Ref #: WHITE

Date: 12/18/2020

2012 Ford - F450 Super Duty - 6.8L, V10 (415CI) VIN(Y)

Lic #: 4

Odometer In: 216083

Unit #:

VIN #: 1FDUF4HY9 CEA43854

Hat #: 4WD(Y)

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
REMAN 5R110W TRANSMISSION WITH TORQUE CONVERTER AND FLUID RL058582	1.00			R&R LABOR REMOVE & REPLACE LABOR R&R REAR SHAFT FRONT U-JOINT	
FREIGHT D	1.00				
TRANSFER CASE FLUID TC	2.00				
DODGE ALUM. SHAFT U-JOINT 74081485 Shop Supplies	1.00			ENVIRONMENTAL FEE	

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:
Parts:
HazMat:
SubTotal:
Tax:
Total:
Bal Due: \$3,589.55

[Payments -]

We're Good At What We Do!

Vehicle Received: 12/15/2020

Customer Number : 685

Email Address:

16207

INVOICE

PAGE 1

SERVICE ADVISOR:

SERVICE ADVISOR:									
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
WHITE	12	FORD F450		1FDUF4HY9CEA43854			190729/190742		T3854
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
01JAN12 DE			18:00 31OCT18			0.00	CHECK	02NOV18	
R.O. OPENED		READY		OPTIONS: W-COMP;W ENG:6.8 Liter					

11:10 12SEP18 17:42 01NOV18

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

A CUSTOMER STATES CEL IS ON, DIED WHILE DRIVING. NOW WILL NOT CRANK OR
START. TOWED IN. CHECK AND ADVISE.

DIAG DIAGNOSIS

- 3033 C
- 1 7C3Z*6754*A TUBE - OIL LEVEL INDICATOR
 - 1 HC3Z*9424*A MANIFOLD ASY - INLET
 - 1 8C3Z*6006*BARM REMAN SERVICE ENGINE ASY
 - 1 SER# R07673193
 - 1 7C3Z*6038*BA INSULATOR ASY - ENGINE SUPPORT
 - 1 7C3Z*6038*BC INSULATOR ASY
 - 1 EU2Z*14S411*VA WIRE ASY
 - 1 3L3Z*8C387*AC GASKET
 - 1 3L3Z*8C388*AC GASKET
 - 1 1L2Z*8678*AB PULLEY
 - 1 1L2Z*6B209*C TENSIONER
 - 1 GC3Z*9278*A SWITCH ASY - OIL PRESSURE
 - 1 1W7Z*6C315*AB SENSOR - CRANKSHAFT POSITION -
 - 1 *W707753*S900 STUD
 - 4 *W520514*S440 NUT - ADJUSTING SCREW
 - 1 *W711062*S437 BOLT
 - 10 8L3Z*12A402*A BOOT - IGNITION WIRE
 - PROTECTIO
 - 1 FA*1883*B7 ELEMENT ASY - AIR CLEANER
 - 2 VC*3DIL*B ANTI-FREEZE
 - 2 VC*3*B ANTI-FREEZE
 - 1 XT*5*QMC FLUID - TRANSMISSION
 - 2 XT*10*BLV OIL - AUTOMATIC TRANSMISSION

190729 VERIFY CONCERN, HISTORY DTC'S SHOWED MISSFIRE ON CYLINDER
#4. PULLED SPARK AND PLUG WAS SMASHED. USED SCOPE TO INSPECT CYLINDER,
PISTON IS MISSING AND ROD IS STICKING INTO CYLINDER WALL. REPLACE
ENGINE AND INTAKE. FOUND ENGINE MOUNTS TORE FROM RUBBER ISOLATOR,
INSTALL NEW MOUNTS. INSTALL NEW COIL BOOTS, DIPSTICK TUBE, IDLER
PULLEY, BELT TENSIONER, AND BROKEN CRANK SENSOR. ONE EXHAUST MANIFOLD
TO Y-PIPE STUD BROKE. EXTRACT STUD AND INSTALL A NEW ONE. INSTALL FOUR

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

X

Signature of Person Responsible OR Agent for Person Responsible