

INVOICE

BILL TO**INVOICE #****DATE** 06/03/2020**DUE DATE** 06/03/2020**TERMS** Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Labor 2004 International 4200 VIN 1HTMPAFM04H672616 Engine VT 365. Removed hood, Removed radiator assembly, Removed cab floor, Removed old engine , transfer necessary parts to new engine, assemble new engine with necessary new parts, See parts list. Reassemble all parts removed Installed engine, add fluids and test drove.	70	0.00	0.00
Parts Reman long block	1		
Parts Injector and glowplug set	1		
Parts High pressure injections pump	1		
Parts Turbo	1		
Parts Engine oil	5		
Parts Antifreeze	5		
Parts Oil Filter	1		
Labor	1		

SUBTOTAL

TAX

TOTAL

10,994.19

PAYMENT

BALANCE DUE

BILL TO**INVOICE #****DATE** 12/21/2020**DUE DATE** 12/21/2020**TERMS** Due on receipt**ACTIVITY****QTY****STATE****AMOUNT****Labor**

80

100.00

8,000.00

Make: International Model: 4200

VIN: 1HTMPAFMO04H672616 Year: 2004

Miles: 71678

Customer stated the engine needed replaced. Remove hood, Remove radiator assembly, Removed cab floor, Remove old engine. Transferred necessary parts from old engine to new engine. Reassembled all parts removed, added fluids and test drove. Checked for leaks. Adjusted clutch. The list of parts that were replaced are listed in the parts description. The engine and a few other parts were invoiced on invoice 1313 see that invoice for a complete list.

Parts

1

-2,139.00

-2,139.00T

New injectors were not needed, The current injectors were not that old and were tested and cleaned. Credit from invoice 1313 for new injectors .

Parts

1

800.00

800.00T

Injector inspection , cleaning and reseal.

Parts

1

-824.92

-824.92T

High pressure oil pump credit. The High pressure oil pump price was different than the original invoiced price . Credit from Invoice 1313.

Parts

1

1,159.68

1,159.68T

High pressure oil pump.

Parts

1

99.19

99.19T

High pressure oil pump install seal kit.

Parts

1

776.51

776.51T

The unit needed a new clutch that was not in the original estimate. New clutch

Parts

1

75.00

75.00T

Resurface flywheel

Parts

Engine oil filter

Parts

Fuel filter

Parts

Air Filter

Parts

EGR Valve

Parts

ICP Sensor

Parts

MAT Sensor

Parts

Heavy duty hose clamp

Parts

The inside of the intake manifold was coted in an extreme amount of exhaust soot. Sent the manifold out to a specialty shop to be cleaned internally and resurfaced .

Parts

Misc shop supplies

Parts

Misc credit from Invoice 1313

Parts

Glow plug harness

Make: International Model: 4200
VIN: 1HTMPAFMO04H672616 Year: 2004
Miles: 71678

SUBTOTAL
TAX (7.25%)
TOTAL
BALANCE DUE

\$8,881.24

+ 10000
deposit
paid prior