

SERVICE INVOICE

R/O	VIN	DATE	
53138	1GBJG31K481159504	02/01/2016	
MYEAR	MAKE	MODEL	COLOR
2008	CHEVROLET	EXPRESS CU	WHITE
MILEAGE	WHEELS	WHEELS	WHEELS
170391	170400	5076600	50/60/60
LISC.			TIME IN
			12:13
			15:02
			02/26/16

SEE
ALSO

- (1) CHECK ENGINE FLASHES==ENGINE KNOCKS==COOLANT IS LOW.
INTERNAL ENGINE FAILURE. REPLACED ENGINE ASSEMBLY WITH GM PARTS ENGINE. INSTALLED NEW SPARK PLUGS AND SPARK PLUG WIRE KIT. INSTALLED NEW ENGINE DRIVE BELTS. REASSEMBLED TO SPEC S. LABOR INCLUDED DIAGNOSIS TIME INVOLVED.

Labor		T09
19209705	(REMAN ENGINE)	1
	(CHARGE)	1
12621258	(SPARK PLUG)	8
89018058	(*WIRE KIT)	1
12576447	(BELT)	1
19303975	(FILTER)	1
12345615A	(GM OIL)	6
11546600	(BOLT)	6
12602541	(SEAL)	4
12609269	(TUBE)	1
12617944	(GASKET)	1
12630223	(GASKET)	2
12637204	(BELT)	1
15077362	(SEAL)	2
19207929	(GASKET KIT)	1
12591720	(SENSOR)	1
15203889	(GASKET)	1
12346290	(COOLANT)	2

Total Labor
Total Parts
Total Repair (Customer)

(Tech:09) A

- (2) NEEDS FRONT TIRES==CORD SHOWING (FIREFSTONE TRANSFORCE H/T LT225/75R16E CURRENTLY ON VEHICLE)
MOUNT AND BALANCE (2) HANKOOK DYNAPRO HT RH12 LT225/75R16 E-RATED TIRES

Labor		T32
88877091	(H2257516)	2
TIREDISP	(TIRE DISP FEE)	2
TS	(TIRE SUPPLY)	2

Total Labor
Total Parts
Total Repair (Customer)

(Tech:32) A

- (3) SUBLET TO POWELL AND SONS...
STEERING ALIGNMENT
REPLACED RH FRT HUB BEARING DUE TO LOOSENESS.

Labor		T99
POWELL AND 53138		

Total Sublet
Total Repair (Customer)

(Tech:99) A

W/C INT. CUSTOMER

53138

Job 53138

Customer Copy

SERVICE INVOICE

R/O 53138	VIN 1GBJG31K481159504			DATE 02/01/2016
YEAR 2008	MAKE CHEVROLET	MODEL EXPRESS CU	COLOR WHITE	TIME IN 12:13
PRICE IN 170391	MSRP OUT 170400	50/50/50 50/50/50	USG.	15:02 02/26/16
SEE ALSO				

THANK YOU
ALWAYS CHECK AND TORQUE WHEEL
STUD LUG NUTS AFTER 100 MILES

Due:

Service Service

		W/C	INT.	CUSTOMER
Am ori 331 CU			Labor Parts Sublet Hazardous Wa Oil/Grease Sub Total Tax Total (Due)	7458.28
Page 2 of 2 53138		Reprint (2) Customer Copy		