

4/7/2022 10:13 AM

Invoice

page 1

-fold here -

Vehicle : 1998 Peterbilt 377 14.6 L 893 CID L6 Caterpillar 3406

VIN : 1XPCDB9X2WN447033

Created : 5/19/2021 8:47:59 AM

Complete : 5/27/2021 10:06:04 AM

Invoiced : 5/27/2021 10:06:04 AM

Contact :

Odometer In : 0

Odometer Out : 1034567

Qty	Code / Tech	Reference	Description	Condition	Unit Price	Price
14	57*	LABOR	WET KIT			
1	57*	STATEINSP	STATE INSPECTION			
	FAIL					
1	57*	DOTINSPECTION	DOT INSPECTION			
	FAIL					
5.25	57*	LABOR	MISC LABOR			
			A/C RANDOMLY QUILTS WORKING. FOUND A/C QUILTS DUE TO ENGINE FAN BEING INOPERATIVE. NEED CLUTCH REBUILT. REMOVED FAN HUB, REBUILT AND INSTALL.			
1.75	57*	LABOR	MISC LABOR			
			PYROMOTOR DOESN'T WORK. FOUND NO SENSOR IN EXHAUST, NO WIRES GOING TO GAUGE. INSTALL TEMP PROBE RUN WIRES TO GAUGE.			
0.75	57*	LABOR	MISC LABOR			
			REPLACE FRONT DRIVE TRACK BAR			
0.5	57*	LABOR	MISC LABOR			
			REPLACE RF DRIVE, SMALL U-BOLT AT FRONT HANGER			
1.25	57*	LABOR	WINDOW CRANK			
			REPLACED WINDOW REGULATOR AND CRANK HANDLE ON DRIVERS SIDE			
0.5	57*	LABOR	DIFF LOCK SWITCH			
			R&R SWITCH			
2.5	57*	LABOR	A SERVICE			
1	57*	LABOR	REPLACE MUDFLAPS AND HANGERS			
1.25	57*	LABOR	REPLACE FIFTH WHEEL SLIDE HOSE			
			CHECK OPERATION. NEED NEW AIR CYLINDER. LEAKS AIR AND DOESN'T MOVE LATCHES FAR ENOUGH. REPLACED CYLINDER.			
2	57*	LABOR	REPLACE RR DRIVE WHEEL SEAL			
1.25	57*	LABOR	REPAIR LIGHTS			
2.5	57*	LABOR	MISC LABOR			
			REPLACE REAR SPRING HANGER AND SPRING EYE BUSHINGS AT L STEER SPRING			
0.5	57*	LABOR	REPAIR HORN			
			REPLACED RELAY			
0.75	57*	LABOR	REPLACE WIPERS			
			NOTICED LEFT ARM RESTING ON COWL. ATTEMPT TO TIGHTEN AND STUD BROKE OFF. REPLACED WIPER PIVOT SHAFT.			
14	-	1325-16	SYN 50 TRANS. FLUID (QT)			

4/7/2022 10:13 AM

page 3

Invoice

Vehicle : 1998 Peterbilt 377 14.6 L 893 CID L6 Caterpillar 3406

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
5	-	10143-16-16	1" MNPT FITTING			
1	-	10643-16-16	1" F/JIC FITTING			
31.25	-	451TC-16	SAE100R17 HOSE (FT)			
14	-	811-20	HOSE FT			
34	-	1200-55	HYDRAULIC FLUID (GAL)			
1	-	5406-20-16	ADAPTER			
1	-	CYL-COMP	CYLINDER			

Labor

Parts

Sublet/Misc.

SHOP SUPPLIES

Charges

Sales Tax

Total Due

\$8,426.10

Tech

Certification #

CUSTOMER
SIGNATURE: _____

DATE: _____