

Remit Payment To:

Invoice #		PO#	
Date	6/13/2022	Terms	PAID
Time	09:20	Due Date	6/13/2022

RO#				
RO Date	5/24/2022			
Miles	In	0.0	Out	0.0
Hours	In	986.0	Out	986.5
Service Writer				
Stock#				
Serial#	49269			
Yr Make Model	KUBOTA SVL95-2SHFC			
Description	Kubota SVL95-2SHFC Compact Track Loader with Cab/Heat/AC and Hydraulic Bucket Coupler, High Flow			
License				
Fleet#				
In Service Date	5/28/2020			

Service Invoice

Customer

Memo

Service Issue

Com: Multi Point Machine Inspection
INSPECT TRACKS TO SEE IF THEY NEED TO BE REPLACED

Cause: WOULD RECOMMEND REPLACING TRACKS DUE TO MINIMAL TREAD LIFE LEFT

REPLACED TRACKS ON 6/8/2022

Fix: Full Machine Inspection / Operational Test
Check Fluid Levels
Check and Set Tire Pressures
Check ROPS and Safety Equipment
Check Starting and Charging System
Adjust Controls (where applicable)
Check Transmission Performance
Check Brake Operation
Check Basic Hydraulic Performance

Note:

Mech	Type	Description	Total
195023	Labor	Inspection	
195023	Labor	Inspection	
195023	Labor	DIESEL-HEAVY	
195023	Labor	MISC	
	Misc.	Free Inspection	
	Misc.	MSC	
	Misc.	MSC	
	Item	77700-0217C-620	
	Item	32791-91060-620	
	Deduct		
		Shop Supplies	
		Environmental Fee	
		450X58X86 Kubota-Camsco HXD	
		Extreme Durability Rubber Tract	
		HA B E	
		BULB, 12V 55W (H3)	
			Subtotal
			\$2,131.15

Customer Service Issue # 1

Com: 1,000 HOUR SERVICE

Printed:6/13/2022 1:40 PM

Page 1 of 3 Pages

Customer Name	Invoice#	RO#	Date
Heartland Excavating			06/13/2022

Cause: RECOMMENDING CHANGING ALL FILTERS TO INCLUDE ENGINE OIL/FILTER, HST, HYD SUCTION, HYD RETURN, HYD BREATHER, ALL 3 AIR CONDITIONING FILTERS, FUEL FILTER/ WATER SEPERATOR, DRAIN AND FILL HYD OIL, GREASE MACHINE, DRAIN AND CHANGE FINAL DRIVE GEAR OIL. CHANGE INNER/ OUTER AIR FILTERS.

BELLY OF MACHINE IS FULL OF DIRT. RECOMMEND REMOVING PANS AND FLOOR AND WASHING OUT MACHINE.
LEFT FRONT WORK LIGHT IS BURNT OUTAND BULB NEEDS REPLACED

ix: CHANGED ALL FILTERS TO INCLUDE ENGINE OIL, HST SUCTION, HYD RETURN, HYD BREATHER, ALL 3 AIR CONDITIONING FILTERS. FUEL FILTERS AND FUEL WATER SEPARATOR. DRAIN & FILL HYD FLUID, ENGINE OIL. GREASE MACHINE, DRAIN AND CHANGE FINAL DRIVE GEAR OIL. CHANGE INNER AND OUTER AIR FILTERS

Note:

Mech	Type	Description	Total
195023	Labor	DIESEL-HEAVY	
	Misc.	MSC	Environmental Fee 1.0000
	Item	HH1C0-32430-620	Kubota Oil Filter 1.0000
	Item	V0631-65450-620	FILTER SUCTION * 1.0000
	Item	HHTA0-59900-620	Kubota Hydraulic (HST) High-Pressure Filter 1.0000
	Item	V0511-65150-620	FILTER, RETURN 1.0000
	Item	1K947-43172-620	Kubota Fuel Filter 1.0000
	Item	V0631-51880-620	Kubota Fuel Filter / Water Separator 1.0000
	Item	55231-26150-620	Kubota Air Filter 1.0000
	Item	59700-26112-620	Kubota Air Filter 1.0000
	Item	RD411-62150-620	Kubota Breather Filter 1.0000
	Item	T1855-71600-620	FILTER, CAB AIR 1.0000
	Item	6A671-75090-620	Kubota Cabin (A/C) Air Filter 2.0000
	Misc.	Bulk Oil - Kubota 15W-40 CJ-4 Engine Oil Quart	13.0000
	Misc.	Bulk Oil - Kubota Hydraulic Fluid 46 Gallon	10.0000
	Misc.	Bulk Oil-135H 85W-140 Gear Lube Quart	3.0000
	Misc.	MSC	Shop Supplies 1.0000
Subtotal			\$1,755.35

Customer Service Issue # 2

Com: REPLACE TOP DOOR HANDLE AND TOP RIGHT DOOR CATCH IS BROKEN

Cause: DOOR HANDLE IS OKAY JUST PLASTIC COVER BROKEN AND NEEDS REPLACED. RIGHT HAND DOOR CATCH BROKEN OFF IN CAB FRAME NEEDS EXTRACTED AND REPLACED

Fix:

Note:

Mech	Type	Description	Total
	Misc.	MSC	Environmental Fee 1.0000
	Item	V1311-99830-620	COVER, KIT A HANDLE,LA BEL 1.0000
	Item	V0511-35810-620	ASSY BLADE, WIPER (RUBBER) 1.0000
	Item	5H601-35980-620	HANDRAIL, HOOD 1.0000
	Item	03034-50620-620	SCREW W/ WASHER 2.0000
	Item	V0511-34570-620	GROMMET 2.0000
	Item	V0511-34590-620	PLATE 1.0000
	Item	V0511-34970-620	PLATE 1.0000
	Item	V0511-37710-620	STRIKER 1.0000
	Item	V0511-35910-620	ROLLER 2.0000
Subtotal			\$161.94

Printed:6/13/2022 1:40 PM

Customer Name	Invoice#	RO#	Date
			06/13/2022

Customer Service Issue # 3

Com: TSB-2022-014 SVL95-2S, SVL97-2 Countermeasure of DEF Pump Issues

Countermeasure of DEF Pump Issues

Cause: THIS PSB IS FIX AS FAIL, WILL CHECK FOR STORED CODES AND PERFORM FIX IF NECESSARY. CONNECTED DIAGMASTER AND CHECKED FOR CODES. THERE IS NO PRESENT OR STORED CODES FOR DEF SYSTEM. SO THERE IS NO FIX TO BE MADE

Fix:

Note:

Mech	Type	Description	Total
195023	Labor	DIESEL-HEAVY Diesel / Hydraulic / Heavy Equipment Labor	1.0000
			Subtotal \$0.00

Warranty Service Issue # 4

Com: PSB-2021-027

Operator Presence Controller Logic Update

Cause: PERFORM PSB AS PER INSTRUCTIONS

Fix:

Note:

Mech	Type	Description	Total
195023	Labor	DIESEL-HEAVY	0.5000
			Subtotal \$0.00

Reply Totals

Warranty	Parts:	Labor:	225.00	Misc.:	PreTax Subtotal:
Internal	Parts:	Labor:		Misc.:	PreTax Subtotal:
Customer	Parts:	Labor:	\$2,249.00	Misc.:	\$359.44
					Sales Tax:
					Total Due from Customer:

\$4,257.32

Cash	Check	Check #	CC	CC Type	On Acct.	Mfg Credit	CIT	Deposit	Other
\$0.00	\$4,257.32	1001	\$0.00		\$0.00	\$0.00	\$0.00	\$0.00	\$0.00

Summary of Charges

	Taxable
	Non-Taxable
	Subtotal
	Sales Tax
\$4,257.32	PAY THIS AMOUNT
	Amount Tendered
	Change Due

Customer Signature

Date

Exempt Tax Cert #:

Expiration Date:

Printed:6/13/2022 1:40 PM